

The following discrepancies were encountered in the FBO documents:

1. Sheet S203 "Special Load Plan" is not included in the Title Sheet (G100) of the construction plans sheet index section. S203 drawing sheet is included in the set. The Title sheet S203 should be added in Title Sheet G100
2. Sheet S611 has been removed from the construction plans but it is still included in the Title Sheet (G100) of the construction plans sheet index section. The title sheet S611 should be omitted from Title Sheet G100.
3. Sheet A800 is included in the Title Sheet (G100), plan set, but not named in the Table of Contents Specification book for the project. The title sheet A800 should be added after the sheet A701 "Reflected Ceiling Plan" on the Table of Contents specifications book.
4. Sheet M403 "HVAC B29 Corridor" is not included in the Title Sheet (G100) of the construction plans sheet index section. M403 drawing sheet is included in the set. The Title sheet M403 should be added in Title Sheet G100
5. Sheet E602 is included in the Title Sheet (G100), plan set, but not named in the Table of Contents Specification book for the project. The title sheet E602 should be added after the sheet E601 "Enlarged Electrical Plans" on the Table of Contents specifications book.
6. Sheets T504, T505, and T506 are included in the Title Sheet (G100), plan set, but not named in the Table of Contents Specification book for the project. The title sheets T504, T505, and T506 should be added after the sheet T503 "Technology Details" on the Table of Contents specifications book.