

Construct IT Center Bldg. 108 # 656-14-246 VA263-15-R-0414

Contractor Questions and Answers

In all cases where an existing telecom room is shown on the plans but that room does not receive new fiber, is it shown for reference to indicate location of copper pairs within that building?

A:

Yes it is shown to indicate location of copper pairs within the building

Sheet CP2-1, IT plan room 104A note 2 indicates new fiber and patch panel however this cable is not shown on plan T502 detail 3, is the note 2 to be removed?

A:

Past meeting notes indicated that the fiber cable shall be installed only to room 001.

Can the VA confirm if the fiber is to be installed to room 104A as well?

A:

Run fiber to both rooms (001 and 104A as shown on cabling plans.

Building 29, the correct Telecom room number should be 015 rather than 068A as shown on T502.

A:

Room tags used were provided in the AutoCAD drawing provided to us.

Building 49, the correct Telecom room number should be 177 rather than 139 as shown on T502.

A:

Room tags used were provided in the AutoCAD drawing provided to us.

Building clarification, NRC on the site plan is the Rehab building?

A:

Correct, NRC = New Rehabilitation Center NKB = New Kitchen Building

Building clarification, is the Phsync building numbered 115 on the site plan? If not, where is this located?

A:

Yes: the new Phsync building is numbered 115.

Building clarification, the kitchen is also located in building 95, which has 2 separate telecom rooms as building 95 is already listed.

A:

Question not understand, please provide additional detail.