

| Project# 502-12-102/VA256-15-R-1083 Replace Obsolete HVAC Controls - RFI ANSWERS - AMENDMENT P0007 | | | | | |
|--|------|---------|------|-------------|----------|
| RFI | Item | Section | Para | Description | Response |

| | | |
|-----------------|--------------|--|
| Drawing M2-101 | states exist | <i>The induction unit controls on this floor are</i> |
| Drawing M2-101 | states exist | <i>The induction unit controls on this floor are</i> |
| Drawing M2-104 | states no | <i>The induction unit controls on this floor are</i> |
| Drawing M2-104 | states no | <i>The induction unit controls on this floor are</i> |
| Drawing M8-101 | indicates | <i>AHU-1: 5 HP, AHU-2: 7.5 HP. Field Verifi</i> |
| Drawing M16-201 | indicates | <i>AHU-2: 30 HP, AHU-3: 30 HP. Field Veri</i> |
| Drawing M46-201 | indicates | <i>only states that a new VFD is to be instal</i> |
| Drawing M49-201 | indicates | <i>Yes, they are to remain.</i> |

re outside the scope of this project and are to remain as-is.

re outside the scope of this project and are to remain as-is.

re outside the scope of this project and are to remain as-is.

re outside the scope of this project and are to remain as-is.

y.

fy.

led. There is no existing VFD. New VFD & motor to be installed per M46-101