

0001	Side Load 3 Bed Capacity Bed Lift System	3.00	EA	_____	_____
	Must meet the dimensions set forth in the Salient Characteristics Attachment 3 MFR: VIDAR MFR Part #: V-ST327-96S OR EQUAL				
0002	Platform Inserts (stretcher Adapter)	3.00	EA	_____	_____
	MFR: VIDAR MFR Part #: V-ST96-SA OR EQUAL				
0003	Bed Storage Unit Installation.	1.00	JB	_____	_____
	SEE attachment four (4) titled Statement of Work for installation requirements.				
0004	Provide three (3) days of training, with a minimum of four (4) hours each day.	3.00	Days	_____	_____
	See Attachment four (4) titled Statement of Work.				
				GRAND TOTAL	_____