

TERMINAL LOCATION			OUTLET TYPE			READ		PERFORMANCE								COMMENTS/ FINDINGS	
BUILDING	FLOOR	ROOM/ AREA	MANUFACTURER	CONNECTOR	SYSTEM	PSIG/ HG	FLOW	WALL OUTLET	CEILING OUTLET	COLUMN	HEADWALL	BOOM/ EQUIP	PEDESTAL	HOSE ESSEMBLY	UNAVAILABLE	DEFICIENCY	COMMENTS
SBT	2	16647	HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	V	/	/				X						
			HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	V	/	/				X						
		16648	HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	V	/	/				X						
			HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	V	/	/				X						
		16650	HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	V	/	/				X						
			HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	V	/	/				X						
		16652	HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	V	/	/				X						
			HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	V	/	/				X						
		16653	HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	V	/	/				X						
			HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	V	/	/				X						
		16654	HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	V	/	/				X						
			HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	V	/	/				X						



FACILITY: VAMC- SAN JUAN, PR
TERMINAL PAGE: 3 OF 36
INSPECTION DATE: 10/25/2016
INSPECTOR: C WOJCIK

MEDICAL GAS TERMINAL INSPECTION RECORD

TERMINAL LOCATION			OUTLET TYPE			READ		PERFORMANCE										COMMENTS/ FINDINGS	
BUILDING	FLOOR	ROOM/ AREA	MANUFACTURER	CONNECTOR	SYSTEM	PSIG/ HG	FLOW	WALL OUTLET	CEILING OUTLET	COLUMN	HEADWALL	ROOM/ EQUIP	PEDESTAL	HOSE ESSEMBLY	UNAVAILABLE	DEFICIENCY	COMMENTS		
SBT	6	K6662	HILLROM	QC	O	/	/				X								
			HILLROM	QC	A	/	/				X								
			HILLROM	QC	V	/	/				X								
			HILLROM	QC	O	/	/				X								
			HILLROM	QC	A	/	/				X								
			HILLROM	QC	V	/	/				X								
		K6664	HILLROM	QC	O	/	/				X								
			HILLROM	QC	A	/	/				X								
			HILLROM	QC	V	/	/				X								
			HILLROM	QC	O	/	/				X								
			HILLROM	QC	A	/	/				X								
			HILLROM	QC	V	/	/				X								
		K6666	HILLROM	QC	O	/	/				X								
			HILLROM	QC	A	/	/				X								
			HILLROM	QC	V	/	/				X								
			HILLROM	QC	O	/	/				X								
			HILLROM	QC	A	/	/				X								
			HILLROM	QC	V	/	/				X								
		K6667	HILLROM	QC	O	/	/				X								
			HILLROM	QC	A	/	/				X								
			HILLROM	QC	V	/	/				X								
			HILLROM	QC	O	/	/				X								
			HILLROM	QC	A	/	/				X								
			HILLROM	QC	V	/	/				X								
		K6672	HILLROM	QC	O	/	/				X								
			HILLROM	QC	A	/	/				X								
			HILLROM	QC	V	/	/				X								
			HILLROM	QC	O	/	/				X								
			HILLROM	QC	A	/	/				X								
			HILLROM	QC	V	/	/				X								
		K6673	HILLROM	QC	O	/	/				X								
			HILLROM	QC	A	/	/				X								
			HILLROM	QC	V	/	/				X								
			HILLROM	QC	O	/	/				X								
			HILLROM	QC	A	/	/				X								
			HILLROM	QC	V	/	/				X								
		K6674	HILLROM	QC	O	/	/				X								
			HILLROM	QC	A	/	/				X								
			HILLROM	QC	V	/	/				X								
			HILLROM	QC	O	/	/				X								
			HILLROM	QC	A	/	/				X								
			HILLROM	QC	V	/	/				X								
		K6675	HILLROM	QC	O	/	/				X								
			HILLROM	QC	A	/	/				X								
			HILLROM	QC	V	/	/				X								
			HILLROM	QC	O	/	/				X								
			HILLROM	QC	A	/	/				X								
			HILLROM	QC	V	/	/				X								
			X																
			X																



FACILITY: VAMC- SAN JUAN, PR
TERMINAL PAGE: 4 OF 36
INSPECTION DATE: 10/25/2016
INSPECTOR: C WOJCIK

MEDICAL GAS TERMINAL INSPECTION RECORD

TERMINAL LOCATION			OUTLET TYPE			READ		PERFORMANCE										COMMENTS/ FINDINGS	
BUILDING	FLOOR	ROOM/ AREA	MANUFACTURER	CONNECTOR	SYSTEM	PSIG/ HG	FLOW	WALL OUTLET	CEILING OUTLET	COLUMN	HEADWALL	BOOM/ EQUIP	PEDESTAL	HOSE ESSEMBLY	UNAVIALBLE	DEFICIENCY		COMMENTS	
SBT	6	K6676	HILLROM	QC	O	/	/				X								
			HILLROM	QC	A	/	/				X								
			HILLROM	QC	V	/	/				X								
		K6676	HILLROM	QC	O	/	/				X								
			HILLROM	QC	A	/	/				X								
			HILLROM	QC	V	/	/				X								
		K6678	HILLROM	QC	O	/	/				X								
			HILLROM	QC	A	/	/				X								
			HILLROM	QC	V	/	/				X								
		K6680	HILLROM	QC	O	/	/				X								
			HILLROM	QC	A	/	/				X								
			HILLROM	QC	V	/	/				X								
		K6681	HILLROM	QC	O	/	/				X								
			HILLROM	QC	A	/	/				X								
			HILLROM	QC	V	/	/				X								
		K6682	HILLROM	QC	O	/	/				X								
			HILLROM	QC	A	/	/				X								
			HILLROM	QC	V	/	/				X								
		K6684	HILLROM	QC	O	/	/				X								
			HILLROM	QC	A	/	/				X								
			HILLROM	QC	V	/	/				X								
		K6685	HILLROM	QC	O	/	/				X								
			HILLROM	QC	A	/	/				X								
			HILLROM	QC	V	/	/				X								
		K6689	HILLROM	QC	O	/	/				X								
			HILLROM	QC	A	/	/				X								
			HILLROM	QC	V	/	/				X								
		K6691	HILLROM	QC	O	/	/				X								
			HILLROM	QC	A	/	/				X								
			HILLROM	QC	V	/	/				X								
		K6693	HILLROM	QC	O	/	/				X								
			HILLROM	QC	A	/	/				X								
			HILLROM	QC	V	/	/				X								
SBT	5	J5521	HILLROM	QC	O	/	/				X								
			HILLROM	QC	A	/	/				X								
			HILLROM	QC	V	/	/				X								
		J5523	HILLROM	QC	O	/	/				X								
			HILLROM	QC	A	/	/				X								
			HILLROM	QC	V	/	/				X								
		J5525	HILLROM	QC	O	/	/				X								
			HILLROM	QC	A	/	/				X								
			HILLROM	QC	V	/	/				X								
		J5529	HILLROM	QC	O	/	/				X								
			HILLROM	QC	A	/	/				X								
			HILLROM	QC	V	/	/				X								
		J5530	HILLROM	QC	O	/	/				X								
			HILLROM	QC	A	/	/				X								
			HILLROM	QC	V	/	/				X								

FACILITY: VAMC- SAN JUAN, PR
 TERMINAL PAGE: 5 OF 36
 INSPECTION DATE: 10/25/2016
 INSPECTOR: C WOJCIK

MEDICAL GAS TERMINAL INSPECTION RECORD

TERMINAL LOCATION			OUTLET TYPE			READ		PERFORMANCE										COMMENTS/ FINDINGS	
BUILDING	FLOOR	ROOM/ AREA	MANUFACTURER	CONNECTOR	SYSTEM	PSIG/ HG	FLOW	WALL OUTLET	CEILING OUTLET	COLUMN	HEADWALL	BOOM/ EQUIP	PEDESTAL	HOSE ESSEMBLY	UNAVAILABLE	DEFICIENCY		COMMENTS	
5	5	J5532	HILLROM	QC	O	/	/				X								
			HILLROM	QC	A	/	/				X								
			HILLROM	QC	V	/	/				X								
		J5533	HILLROM	QC	O	/	/				X								
			HILLROM	QC	A	/	/				X								
			HILLROM	QC	V	/	/				X								
		J5534	HILLROM	QC	O	/	/				X								
			HILLROM	QC	A	/	/				X								
			HILLROM	QC	V	/	/				X								
		J5536	HILLROM	QC	O	/	/				X								
			HILLROM	QC	A	/	/				X								
			HILLROM	QC	V	/	/				X								
		J5538	HILLROM	QC	O	/	/				X								
			HILLROM	QC	A	/	/				X								
			HILLROM	QC	V	/	/				X								
		J5539	HILLROM	QC	O	/	/				X								
			HILLROM	QC	A	/	/				X								
			HILLROM	QC	V	/	/				X								
		J5540	HILLROM	QC	O	/	/				X								
			HILLROM	QC	A	/	/				X								
			HILLROM	QC	V	/	/				X								
		J5541	HILLROM	QC	O	/	/				X								
			HILLROM	QC	A	/	/				X								
			HILLROM	QC	V	/	/				X								
			HILLROM	QC	O	/	/				X								
			HILLROM	QC	A	/	/				X								
			HILLROM	QC	V	/	/				X								
		J5542	HILLROM	QC	O	/	/				X								
			HILLROM	QC	A	/	/				X								
			HILLROM	QC	V	/	/				X								
			HILLROM	QC	O	/	/				X								
			HILLROM	QC	A	/	/				X								
			HILLROM	QC	V	/	/				X								
		J5547	HILLROM	QC	O	/	/				X								
			HILLROM	QC	A	/	/				X								
			HILLROM	QC	V	/	/				X								
			HILLROM	QC	O	/	/				X								
			HILLROM	QC	A	/	/				X								
			HILLROM	QC	V	/	/				X								
		J5548	HILLROM	QC	O	/	/				X								
			HILLROM	QC	A	/	/				X								
			HILLROM	QC	V	/	/				X								
			HILLROM	QC	O	/	/				X								
			HILLROM	QC	A	/	/				X								
			HILLROM	QC	V	/	/				X								
		J5550	HILLROM	QC	O	/	/				X								
			HILLROM	QC	A	/	/				X								
			HILLROM	QC	V	/	/				X								

FACILITY: VAMC-SAN JUAN, PR
 TERMINAL PAGE: 6 OF 36
 INSPECTION DATE: 10/25/2016
 INSPECTOR: C WOJCIK

MEDICAL GAS TERMINAL INSPECTION RECORD

TERMINAL LOCATION			OUTLET TYPE		READ		PERFORMANCE										COMMENTS/ FINDINGS
BUILDING	FLOOR	ROOM/ AREA	MANUFACTURER	CONNECTOR	SYSTEM	PSIG/ HG	FLOW	WALL OUTLET	CEILING OUTLET	COLUMN	HEADWALL	BOOM/ EQUIP	PEDESTAL	HOSE ESSENBLY	UNAVIALBLE	DEFICIENCY	COMMENTS
SBT	5	J5550	HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	V	/	/				X						
		J5552	HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	V	/	/				X						
			HILLROM	QC	O	/	/				X				X		
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	V	/	/				X						
		J5553	HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	V	/	/				X						
			HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	V	/	/				X						
		J5554	HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	V	/	/				X						
			HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	V	/	/				X						
		K5560	HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	V	/	/				X						
			HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	V	/	/				X						
		K5561	HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	V	/	/				X						
			HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	V	/	/				X						
		K5562	HILLROM	QC	O	/	/				X				X		
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	V	/	/				X						
			HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	V	/	/				X						
		K5564	HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	V	/	/				X				X		
			HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	V	/	/				X						
		K5566	HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	V	/	/				X						

FACILITY: VAMC-SAN JUAN, PR
 TERMINAL PAGE: 7 OF 36
 INSPECTION DATE: 10/25/2016
 INSPECTOR: C WOJCIK

MEDICAL GAS TERMINAL INSPECTION RECORD

TERMINAL LOCATION			OUTLET TYPE			READ		PERFORMANCE								COMMENTS/ FINDINGS	
BUILDING	FLOOR	ROOM/ AREA	MANUFACTURER	CONNECTOR	SYSTEM	PSIG/ HG	FLOW	WALL OUTLET	CEILING OUTLET	COLUMN	HEADWALL	BOOM/ EQUIP	PEDESTAL	HOSE ESSEMBLY	UNAVIALBLE	DEFICIENCY	COMMENTS
SBT	5	K5566	HILLROM	QC	O	/	/					X					
			HILLROM	QC	A	/	/					X					
			HILLROM	QC	V	/	/					X					
		K5567	HILLROM	QC	O	/	/					X					
			HILLROM	QC	A	/	/					X					
			HILLROM	QC	V	/	/					X					
			HILLROM	QC	O	/	/					X					
			HILLROM	QC	A	/	/					X					
			HILLROM	QC	V	/	/					X					
		JK5567	HILLROM	QC	O	/	/					X					
			HILLROM	QC	A	/	/					X					
			HILLROM	QC	V	/	/					X					
			HILLROM	QC	O	/	/					X					
			HILLROM	QC	A	/	/					X					
			HILLROM	QC	V	/	/					X					
			HILLROM	QC	O	/	/					X					
			HILLROM	QC	A	/	/					X					
			HILLROM	QC	V	/	/					X					
		K5572	HILLROM	QC	O	/	/					X					
			HILLROM	QC	A	/	/					X					
			HILLROM	QC	V	/	/					X					
			HILLROM	QC	O	/	/					X					
			HILLROM	QC	A	/	/					X					
			HILLROM	QC	V	/	/					X					
			HILLROM	QC	O	/	/					X					
			HILLROM	QC	A	/	/					X					
			HILLROM	QC	V	/	/					X					
		JK5573	HILLROM	QC	O	/	/					X					
			HILLROM	QC	A	/	/					X					
			HILLROM	QC	V	/	/					X					
			HILLROM	QC	O	/	/					X					
			HILLROM	QC	A	/	/					X					
			HILLROM	QC	V	/	/					X					
			HILLROM	QC	O	/	/					X					
			HILLROM	QC	A	/	/					X					
			HILLROM	QC	V	/	/					X					
		K5574	HILLROM	QC	O	/	/					X					
			HILLROM	QC	A	/	/					X					
			HILLROM	QC	V	/	/					X					
			HILLROM	QC	O	/	/					X					
			HILLROM	QC	A	/	/					X					
			HILLROM	QC	V	/	/					X					
			HILLROM	QC	O	/	/					X					
			HILLROM	QC	A	/	/					X					
			HILLROM	QC	V	/	/					X					
		K5575	HILLROM	QC	O	/	/					X					
			HILLROM	QC	A	/	/					X					
			HILLROM	QC	V	/	/					X					
			HILLROM	QC	O	/	/					X					
			HILLROM	QC	A	/	/					X					
			HILLROM	QC	V	/	/					X					
		K5576	HILLROM	QC	O	/	/					X					
			HILLROM	QC	A	/	/					X					
			HILLROM	QC	V	/	/					X					
			HILLROM	QC	O	/	/					X					
			HILLROM	QC	A	/	/					X					
			HILLROM	QC	V	/	/					X					
		K5578	HILLROM	QC	O	/	/					X					
			HILLROM	QC	A	/	/					X					
			HILLROM	QC	V	/	/					X					
			HILLROM	QC	O	/	/					X					
			HILLROM	QC	A	/	/					X					
			HILLROM	QC	V	/	/					X					
		K5580	HILLROM	QC	O	/	/					X					
			HILLROM	QC	A	/	/					X					
			HILLROM	QC	V	/	/					X					

FACILITY: VAMC-SAN JUAN, PR
 TERMINAL PAGE: 8 OF 36
 INSPECTION DATE: 10/25/2016
 INSPECTOR: C WOJCIK

MEDICAL GAS TERMINAL INSPECTION RECORD

TERMINAL LOCATION			OUTLET TYPE			READ		PERFORMANCE										COMMENTS/ FINDINGS	
BUILDING	FLOOR	ROOM/ AREA	MANUFACTURER	CONNECTOR	SYSTEM	PSIG/ HG	FLOW	WALL OUTLET	CEILING OUTLET	COLUMN	HEADWALL	BOOM/ EQUIP	PEDESTAL	HOSE ESSENBLY	UNAVIALBLE	DEFICIENCY		COMMENTS	
SBT	5	K5581	HILLROM	QC	O	/	/					X							
			HILLROM	QC	A	/	/					X							
			HILLROM	QC	V	/	/					X							
		K5582	HILLROM	QC	O	/	/					X							
			HILLROM	QC	A	/	/					X							
			HILLROM	QC	V	/	/					X							
		K5584	HILLROM	QC	O	/	/					X							
			HILLROM	QC	A	/	/					X							
			HILLROM	QC	V	/	/					X							
		K5585	HILLROM	QC	O	/	/					X							
			HILLROM	QC	A	/	/					X							
			HILLROM	QC	V	/	/					X							
		K5589	HILLROM	QC	O	/	/					X							
			HILLROM	QC	A	/	/					X							
			HILLROM	QC	V	/	/					X							
		K5591	HILLROM	QC	O	/	/					X							
			HILLROM	QC	A	/	/					X							
			HILLROM	QC	V	/	/					X							
		K5593	HILLROM	QC	O	/	/					X							
			HILLROM	QC	A	/	/					X							
			HILLROM	QC	V	/	/					X							
SBT	4	J4411	HILLROM	QC	O	/	/					X							
			HILLROM	QC	A	/	/					X							
			HILLROM	QC	V	/	/					X							
		J4421	HILLROM	QC	O	/	/					X							
			HILLROM	QC	A	/	/					X							
			HILLROM	QC	V	/	/					X							
		J4423	HILLROM	QC	O	/	/					X							
			HILLROM	QC	A	/	/					X							
			HILLROM	QC	V	/	/					X							
		J4425	HILLROM	QC	O	/	/					X							
			HILLROM	QC	A	/	/					X							
			HILLROM	QC	V	/	/					X							
		J4429	HILLROM	QC	O	/	/					X							
			HILLROM	QC	A	/	/					X							
			HILLROM	QC	V	/	/					X							
		J4430	HILLROM	QC	O	/	/					X							
			HILLROM	QC	A	/	/					X							
			HILLROM	QC	V	/	/					X							
		J4432	HILLROM	QC	O	/	/					X							
			HILLROM	QC	A	/	/					X							
			HILLROM	QC	V	/	/					X							
		J4433	HILLROM	QC	O	/	/					X							
			HILLROM	QC	A	/	/					X							
			HILLROM	QC	V	/	/					X							
		J4434	HILLROM	QC	O	/	/					X							
			HILLROM	QC	A	/	/					X							
			HILLROM	QC	V	/	/					X							

FACILITY: VAMC- SAN JUAN, PR
 TERMINAL PAGE: 9 OF 36
 INSPECTION DATE: 10/25/2016
 INSPECTOR: C WOJCIK

MEDICAL GAS TERMINAL INSPECTION RECORD

TERMINAL LOCATION			OUTLET TYPE			READ		PERFORMANCE										COMMENTS/ FINDINGS
BUILDING	FLOOR	ROOM/ AREA	MANUFACTURER	CONNECTOR	SYSTEM	PSIG/ HG	FLOW	WALL OUTLET	CEILING OUTLET	COLUMN	HEADWALL	BOOM/ EQUIP	PEDESTAL	HOSE ESSEMBLY	UNAVIALBLE	DEFICIENCY		COMMENTS
SBT	4	J4436	HILLROM	QC	O	/	/				X							
			HILLROM	QC	A	/	/				X							
			HILLROM	QC	V	/	/				X							
		J4438	HILLROM	QC	O	/	/				X							
			HILLROM	QC	A	/	/				X							
			HILLROM	QC	V	/	/				X							
		J4439	HILLROM	QC	O	/	/				X							
			HILLROM	QC	A	/	/				X							
			HILLROM	QC	V	/	/				X							
		J4440	HILLROM	QC	O	/	/				X							
			HILLROM	QC	A	/	/				X							
			HILLROM	QC	V	/	/				X							
		J4441	HILLROM	DI	O	/	/				X							
			HILLROM	DI	A	/	/				X							
			HILLROM	DI	V	/	/				X							
			HILLROM	QC	O	/	/				X							
			HILLROM	QC	A	/	/				X							
			HILLROM	QC	V	/	/				X							
		J4442	HILLROM	QC	O	/	/				X							
			HILLROM	QC	A	/	/				X							
			HILLROM	QC	V	/	/				X							
			HILLROM	QC	O	/	/				X							
			HILLROM	QC	A	/	/				X				X			
			HILLROM	QC	V	/	/				X							
		J4447	HILLROM	QC	O	/	/				X							
			HILLROM	QC	A	/	/				X							
			HILLROM	QC	V	/	/				X							
			HILLROM	QC	O	/	/				X							
			HILLROM	QC	A	/	/				X							
			HILLROM	QC	V	/	/				X							
		J4448	HILLROM	QC	O	/	/				X							
			HILLROM	QC	A	/	/				X							
			HILLROM	QC	V	/	/				X							
			HILLROM	QC	O	/	/				X							
			HILLROM	QC	A	/	/				X							
			HILLROM	QC	V	/	/				X							
		J4450	HILLROM	QC	O	/	/				X							
			HILLROM	QC	A	/	/				X							
			HILLROM	QC	V	/	/				X							
			HILLROM	QC	O	/	/				X				X			
			HILLROM	QC	A	/	/				X				X			
			HILLROM	QC	V	/	/				X				X			
		J4451	HILLROM	QC	O	/	/				X							
			HILLROM	QC	A	/	/				X							
			HILLROM	QC	V	/	/				X							
			HILLROM	QC	O	/	/				X							
			HILLROM	QC	A	/	/				X							
			HILLROM	QC	V	/	/				X							

FACILITY: VAMC-SAN JUAN, PR
 TERMINAL PAGE: 10 OF 36
 INSPECTION DATE: 10/25/2016
 INSPECTOR: C WOJCIK

MEDICAL GAS TERMINAL INSPECTION RECORD

TERMINAL LOCATION			OUTLET TYPE			READ		PERFORMANCE										COMMENTS/ FINDINGS	
BUILDING	FLOOR	ROOM/ AREA	MANUFACTURER	CONNECTOR	SYSTEM	PSIG/ HG	FLOW	WALL OUTLET	CEILING OUTLET	COLUMN	HEADWALL	BOOM/ EQUIP	PEDESTAL	HOSE ESSENBLY	UNAVIALBLE	DEFICIENCY		COMMENTS	
		14453	HILLROM	QC	O	/	/					X							
			HILLROM	QC	A	/	/					X							
			HILLROM	QC	V	/	/					X							
			HILLROM	QC	O	/	/					X							
			HILLROM	QC	A	/	/					X							
			HILLROM	QC	V	/	/					X							
		14454	HILLROM	QC	O	/	/					X							
			HILLROM	QC	A	/	/					X							
			HILLROM	QC	V	/	/					X							
			HILLROM	QC	O	/	/					X							
			HILLROM	QC	A	/	/					X							
			HILLROM	QC	V	/	/					X							
		K4460	HILLROM	DI	O	/	/					X							
			HILLROM	DI	A	/	/					X							
			HILLROM	DI	V	/	/					X							
		K4461	HILLROM	QC	O	/	/					X							
			HILLROM	QC	A	/	/					X							
			HILLROM	QC	V	/	/					X							
			HILLROM	QC	O	/	/					X							
			HILLROM	QC	A	/	/					X							
			HILLROM	QC	V	/	/					X							
		K4462	HILLROM	QC	O	/	/					X							
			HILLROM	QC	A	/	/					X							
			HILLROM	QC	V	/	/					X							
			HILLROM	QC	O	/	/					X							
			HILLROM	QC	A	/	/					X							
			HILLROM	QC	V	/	/					X							
		K4464	HILLROM	QC	O	/	/					X							
			HILLROM	QC	A	/	/					X							
			HILLROM	QC	V	/	/					X							
			HILLROM	QC	O	/	/					X							
			HILLROM	QC	A	/	/					X							
			HILLROM	QC	V	/	/					X							
		K4466	HILLROM	QC	O	/	/					X							
			HILLROM	QC	A	/	/					X							
			HILLROM	QC	V	/	/					X							
			HILLROM	QC	O	/	/					X							
			HILLROM	QC	A	/	/					X							
			HILLROM	QC	V	/	/					X							
		K4467	HILLROM	QC	O	/	/					X							
			HILLROM	QC	A	/	/					X							
			HILLROM	QC	V	/	/					X							
			HILLROM	QC	O	/	/					X							
			HILLROM	QC	A	/	/					X							
			HILLROM	QC	V	/	/					X							
		K4472	HILLROM	QC	O	/	/					X							
			HILLROM	QC	A	/	/					X							
			HILLROM	QC	V	/	/					X							

FACILITY: VAMC- SAN JUAN, PR
 TERMINAL PAGE: 11 OF 36
 INSPECTION DATE: 10/25/2016
 INSPECTOR: C WOJCIK

MEDICAL GAS TERMINAL INSPECTION RECORD

TERMINAL LOCATION			OUTLET TYPE			READ		PERFORMANCE										COMMENTS/ FINDINGS	
BUILDING	FLOOR	ROOM/ AREA	MANUFACTURER	CONNECTOR	SYSTEM	PSIG/ HG	FLOW	WALL OUTLET	CEILING OUTLET	COLUMN	HEADWALL	BOOM/ EQUIP	PEDESTAL	HOSE ESSEMBLY	UNAVIALBLE	DEFICIENCY		COMMENTS	
SBT	4	K4472	HILLROM	QC	O	/	/				X								
			HILLROM	QC	A	/	/				X								
			HILLROM	QC	V	/	/				X								
		K4473	HILLROM	QC	O	/	/				X				X				
			HILLROM	QC	A	/	/				X								
			HILLROM	QC	V	/	/				X								
			HILLROM	QC	O	/	/				X								
			HILLROM	QC	A	/	/				X								
			HILLROM	QC	V	/	/				X								
		K4474	HILLROM	QC	O	/	/				X								
			HILLROM	QC	A	/	/				X								
			HILLROM	QC	V	/	/				X								
			HILLROM	DI	O	/	/				X								
			HILLROM	DI	A	/	/				X								
			HILLROM	DI	V	/	/				X								
		K4476	HILLROM	QC	O	/	/				X								
			HILLROM	QC	A	/	/				X								
			HILLROM	QC	V	/	/				X								
		K4478	HILLROM	QC	O	/	/				X								
			HILLROM	QC	A	/	/				X								
			HILLROM	QC	V	/	/				X								
		K4480	HILLROM	QC	O	/	/				X								
			HILLROM	QC	A	/	/				X								
			HILLROM	QC	V	/	/				X								
		K4481	HILLROM	QC	O	/	/				X								
			HILLROM	QC	A	/	/				X								
			HILLROM	QC	V	/	/				X								
		K4482	HILLROM	QC	O	/	/				X								
			HILLROM	QC	A	/	/				X								
			HILLROM	QC	V	/	/				X								
		K4484	HILLROM	QC	O	/	/				X				X				
			HILLROM	QC	A	/	/				X								
			HILLROM	QC	V	/	/				X				X				
		K4485	HILLROM	QC	O	/	/				X								
			HILLROM	QC	A	/	/				X								
			HILLROM	QC	V	/	/				X								
		K4489	HILLROM	QC	O	/	/				X								
			HILLROM	QC	A	/	/				X								
			HILLROM	QC	V	/	/				X								
		K4491	HILLROM	QC	O	/	/				X								
			HILLROM	QC	A	/	/				X								
			HILLROM	QC	V	/	/				X								
		K4493	HILLROM	QC	O	/	/				X								
			HILLROM	QC	A	/	/				X								
			HILLROM	QC	V	/	/				X								
SBT	3	J3321	HILLROM	QC	O	/	/				X								
			HILLROM	QC	A	/	/				X								
			HILLROM	QC	V	/	/				X								

FACILITY: VAMC- SAN JUAN, PR
 TERMINAL PAGE: 12 OF 36
 INSPECTION DATE: 10/25/2016
 INSPECTOR: C WOJCIK


MEDICAL GAS TERMINAL INSPECTION RECORD

TERMINAL LOCATION			OUTLET TYPE			READ		PERFORMANCE										COMMENTS/ FINDINGS	
BUILDING	FLOOR	ROOM/ AREA	MANUFACTURER	CONNECTOR	SYSTEM	PSIG/ HG	FLOW	WALL OUTLET	CEILING OUTLET	COLUMN	HEADWALL	BOOM/ EQUIP	PEDESTAL	HOSE ESSENBLY	UNAVIALBLE	DEFICIENCY		COMMENTS	
SBT	3	J3323	HILLROM	QC	O	/	/					X							
			HILLROM	QC	A	/	/					X							
			HILLROM	QC	V	/	/					X							
		J3325	HILLROM	QC	O	/	/					X				X			
			HILLROM	QC	A	/	/					X				X			
			HILLROM	QC	V	/	/					X							
		J3329	HILLROM	QC	O	/	/					X							
			HILLROM	QC	A	/	/					X							
			HILLROM	QC	V	/	/					X							
		J3330	HILLROM	QC	O	/	/					X							
			HILLROM	QC	A	/	/					X							
			HILLROM	QC	V	/	/					X							
		J3332	HILLROM	DI	O	/	/					X							
			HILLROM	DI	A	/	/					X							
			HILLROM	DI	V	/	/					X							
		J3333	HILLROM	QC	O	/	/					X				X			
			HILLROM	QC	A	/	/					X							
			HILLROM	QC	V	/	/					X							
		J3334	HILLROM	QC	O	/	/					X							
			HILLROM	QC	A	/	/					X				X			
			HILLROM	QC	V	/	/					X				X			
		J3336	HILLROM	QC	O	/	/					X							
			HILLROM	QC	A	/	/					X							
			HILLROM	QC	V	/	/					X							
		J3338	HILLROM	QC	O	/	/					X							
			HILLROM	QC	A	/	/					X							
			HILLROM	QC	V	/	/					X							
		J3339	HILLROM	QC	O	/	/					X							
			HILLROM	QC	A	/	/					X							
			HILLROM	QC	V	/	/					X							
			HILLROM	QC	O	/	/					X							
			HILLROM	QC	A	/	/					X							
			HILLROM	QC	V	/	/					X							
		J3340	HILLROM	QC	O	/	/					X							
			HILLROM	QC	A	/	/					X							
			HILLROM	QC	V	/	/					X							
			HILLROM	QC	O	/	/					X							
			HILLROM	QC	A	/	/					X							
			HILLROM	QC	V	/	/					X							
		J3341	HILLROM	QC	O	/	/					X							
			HILLROM	QC	A	/	/					X							
			HILLROM	QC	V	/	/					X							
			HILLROM	QC	O	/	/					X							
			HILLROM	QC	A	/	/					X							
			HILLROM	QC	V	/	/					X							
		J3342	HILLROM	QC	O	/	/					X							
			HILLROM	QC	A	/	/					X							
			HILLROM	QC	V	/	/					X							

FACILITY: VAMC-SAN JUAN, PR
 TERMINAL PAGE: 13 OF 36
 INSPECTION DATE: 10/25/2016
 INSPECTOR: C WOJCIK

MEDICAL GAS TERMINAL INSPECTION RECORD

TERMINAL LOCATION			OUTLET TYPE			READ		PERFORMANCE								COMMENTS/ FINDINGS	
BUILDING	FLOOR	ROOM/ AREA	MANUFACTURER	CONNECTOR	SYSTEM	PSIG/ HG	FLOW	WALL OUTLET	CEILING OUTLET	COLUMN	HEADWALL	BOOM/ EQUIP	PEDESTAL	HOSE ESSEMBLY	UNAVAILABLE	DEFICIENCY	COMMENTS
SFT	3	13342	HILLROM	QC	O	/	/					X					
			HILLROM	QC	A	/	/					X					
			HILLROM	QC	V	/	/					X					
		13347	HILLROM	QC	O	/	/					X					
			HILLROM	QC	A	/	/					X					
			HILLROM	QC	V	/	/					X					
			HILLROM	QC	O	/	/					X					
			HILLROM	QC	A	/	/					X					
			HILLROM	QC	V	/	/					X					
		13348	HILLROM	QC	O	/	/					X					
			HILLROM	QC	A	/	/					X					
			HILLROM	QC	V	/	/					X					
			HILLROM	DI	O	/	/					X					
			HILLROM	DI	A	/	/					X					
			HILLROM	DI	V	/	/					X					
		13350	HILLROM	QC	O	/	/					X					
			HILLROM	QC	A	/	/					X					
			HILLROM	QC	V	/	/					X					
			HILLROM	QC	O	/	/					X					
			HILLROM	QC	A	/	/					X					
			HILLROM	QC	V	/	/					X					
		13352	HILLROM	QC	O	/	/					X					
			HILLROM	QC	A	/	/					X					
			HILLROM	QC	V	/	/					X					
			HILLROM	QC	O	/	/					X					
			HILLROM	QC	A	/	/					X					
			HILLROM	QC	V	/	/					X					
		13353	HILLROM	QC	O	/	/					X					
			HILLROM	QC	A	/	/					X					
			HILLROM	QC	V	/	/					X					
			HILLROM	QC	O	/	/					X					
			HILLROM	QC	A	/	/					X					
			HILLROM	QC	V	/	/					X					
		13354	HILLROM	QC	O	/	/					X					
			HILLROM	QC	A	/	/					X					
			HILLROM	QC	V	/	/					X					
			HILLROM	QC	O	/	/					X					
			HILLROM	QC	A	/	/					X					
			HILLROM	QC	V	/	/					X					
		K3360	HILLROM	QC	O	/	/					X					
			HILLROM	QC	A	/	/					X					
			HILLROM	QC	V	/	/					X					
			HILLROM	QC	O	/	/					X					
			HILLROM	QC	A	/	/					X					
			HILLROM	QC	V	/	/					X					
		K3361	HILLROM	QC	O	/	/					X					
			HILLROM	QC	A	/	/					X					
			HILLROM	QC	V	/	/					X					



FACILITY: VAMC- SAN JUAN, PR
TERMINAL PAGE: 14 OF 36
INSPECTION DATE: 10/25/2016
INSPECTOR: C WOJCIK

MEDICAL GAS TERMINAL INSPECTION RECORD

TERMINAL LOCATION			OUTLET TYPE			READ		PERFORMANCE								COMMENTS/ FINDINGS	
BUILDING	FLOOR	ROOM/ AREA	MANUFACTURER	CONNECTOR	SYSTEM	PSIG/ HG	FLOW	WALL OUTLET	CEILING OUTLET	COLUMN	HEADWALL	BOOM/ EQUIP	PEDESTAL	HOSE ESSEMBLY	UNAVIALBLE	DEFICIENCY	COMMENTS
SBT	3	K3361	HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	V	/	/				X						
		K3362	HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	V	/	/				X						
			HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	V	/	/				X						
		K3364	HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	V	/	/				X						
			HILLROM	DI	O	/	/				X						
			HILLROM	DI	A	/	/				X						
			HILLROM	DI	V	/	/				X						
		K3367	HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	V	/	/				X						
			HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	V	/	/				X						
		K3368	HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	V	/	/				X						
			HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	V	/	/				X						
		K3373	HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	V	/	/				X						
			HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	V	/	/				X						
		K3386	HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	V	/	/				X						
		K3388	HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	V	/	/				X						
		K3389	HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	V	/	/				X						
		K3392	HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	V	/	/				X						
		K3394	HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	V	/	/				X						



FACILITY: VAMC- SAN JUAN, PR
TERMINAL PAGE: 15 OF 36
INSPECTION DATE: 10/25/2016
INSPECTOR: C WOJCIK

MEDICAL GAS TERMINAL INSPECTION RECORD

TERMINAL LOCATION			OUTLET TYPE			READ		PERFORMANCE								COMMENTS/ FINDINGS	
BUILDING	FLOOR	ROOM/ AREA	MANUFACTURER	CONNECTOR	SYSTEM	PSIG/ HG	FLOW	WALL OUTLET	CEILING OUTLET	COLUMN	HEADWALL	BOOM/ EQUIP	PEDESTAL	HOSE ESSEMBLY	UNAVIALBLE	DEFICIENCY	COMMENTS
SBT	3	K3396	HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	V	/	/				X						
SBT	2	J2220	HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	V	/	/				X						
			HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	V	/	/				X						
		J2221	HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	V	/	/				X						
			HILLROM	DI	O	/	/				X						
			HILLROM	DI	A	/	/				X						
			HILLROM	DI	V	/	/				X						
		J2224	HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	V	/	/				X						
		J2226	HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	V	/	/				X				X		
		J2227	HILLROM	QC	O	/	/				X				X		
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	V	/	/				X						
			HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	V	/	/				X						
		J2228	HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	V	/	/				X						
			HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	V	/	/				X						
		J2229	HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	V	/	/				X						
		J2231	HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	V	/	/				X						
		J2232	HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	V	/	/				X						
			HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	V	/	/				X						
		J2233	HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	V	/	/				X				X		



FACILITY: VAMC- SAN JUAN, PR
TERMINAL PAGE: 16 OF 36
INSPECTION DATE: 10/25/2016
INSPECTOR: C WOJCIK

MEDICAL GAS TERMINAL INSPECTION RECORD

TERMINAL LOCATION			OUTLET TYPE			READ		PERFORMANCE								COMMENTS/ FINDINGS	
BUILDING	FLOOR	ROOM/ AREA	MANUFACTURER	CONNECTOR	SYSTEM	PSIG/ HG	FLOW	WALL OUTLET	CEILING OUTLET	COLUMN	HEADWALL	BOOM/ EQUIP	PEDESTAL	HOSE ESSENBLY	UNAVIALBLE	DEFICIENCY	COMMENTS
SBT	2	J2233	HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	V	/	/				X						
		J2234	HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	V	/	/				X						
			HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	V	/	/				X						
		J2235	HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	V	/	/				X						
			HILLROM	DI	O	/	/				X						
			HILLROM	DI	A	/	/				X						
			HILLROM	DI	V	/	/				X						
		J2240	HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	V	/	/				X						
			HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	V	/	/				X						
		J2241	HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	V	/	/				X						
			HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	V	/	/				X						
		K2269	HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	V	/	/				X						
			HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	V	/	/				X						
		K2270	HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	V	/	/				X						
			HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	V	/	/				X						
SBT	1	J1129	HILLROM	QC	V	/	/				X						
			HILLROM	QC	V	/	/				X						
			HILLROM	QC	O	/	/				X						
			HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	O	/	/				X						

FACILITY: VAMC-SAN JUAN, PR
 TERMINAL PAGE: 17 OF 36
 INSPECTION DATE: 10/25/2016
 INSPECTOR: C WOJCIK

MEDICAL GAS TERMINAL INSPECTION RECORD


TERMINAL LOCATION			OUTLET TYPE			READ		PERFORMANCE								COMMENTS/ FINDINGS	
BUILDING	FLOOR	ROOM/ AREA	MANUFACTURER	CONNECTOR	SYSTEM	PSIG/ HG	FLOW	WALL OUTLET	CEILING OUTLET	COLUMN	HEADWALL	BOOM/ EQUIP	PEDESTAL	HOSE ESSEMBLY	UNAVAILABLE	DEFICIENCY	COMMENTS
SBT	1	J1130	HILLROM	QC	V	/	/				X						
			HILLROM	QC	V	/	/				X						
			HILLROM	QC	O	/	/				X						
			HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	O	/	/				X						
			HILLROM	QC	V	/	/				X						
		J1131	HILLROM	QC	V	/	/				X						
			HILLROM	QC	V	/	/				X						
			HILLROM	QC	O	/	/				X						
			HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	DI	O	/	/				X						
			HILLROM	DI	V	/	/				X						
		J1132	HILLROM	DI	V	/	/				X						
			HILLROM	QC	V	/	/				X						
			HILLROM	QC	O	/	/				X						
			HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	O	/	/				X						
			HILLROM	QC	V	/	/				X						
		J1133	HILLROM	QC	V	/	/				X						
			HILLROM	QC	V	/	/				X						
			HILLROM	QC	O	/	/				X						
			HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	O	/	/				X						
			HILLROM	QC	V	/	/				X						
		J1134	HILLROM	QC	V	/	/				X				X		
			HILLROM	QC	V	/	/				X				X		
			HILLROM	QC	O	/	/				X						
			HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	O	/	/				X						
			HILLROM	QC	V	/	/				X						
		J1135	HILLROM	QC	V	/	/				X						
			HILLROM	QC	V	/	/				X						
			HILLROM	QC	O	/	/				X						
			HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	O	/	/				X						
			HILLROM	QC	V	/	/				X						
		J1150	HILLROM	QC	V	/	/				X						
			HILLROM	QC	V	/	/				X						
			HILLROM	QC	O	/	/				X						
			HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	O	/	/				X						
			HILLROM	QC	V	/	/				X						



FACILITY: VAMC- SAN JUAN, PR
TERMINAL PAGE: 18 OF 36
INSPECTION DATE: 10/25/2016
INSPECTOR: C WOJCIK

MEDICAL GAS TERMINAL INSPECTION RECORD

TERMINAL LOCATION			OUTLET TYPE			READ		PERFORMANCE										COMMENTS/ FINDINGS	
BUILDING	FLOOR	ROOM/ AREA	MANUFACTURER	CONNECTOR	SYSTEM	PSIG/ HG	FLOW	WALL OUTLET	CEILING OUTLET	COLUMN	HEADWALL	BOOM/ EQUIP	PEDESTAL	HOSE ESSEMBLY	UNAVAILBLE	DEFICIENCY		COMMENTS	
SBT	1	J1151	HILLROM	QC	V	/	/				X								
			HILLROM	QC	V	/	/				X								
			HILLROM	QC	O	/	/				X								
			HILLROM	QC	O	/	/				X								
			HILLROM	QC	A	/	/				X								
			HILLROM	QC	O	/	/				X								
			HILLROM	QC	V	/	/				X								
		J1152	HILLROM	QC	V	/	/				X								
			HILLROM	QC	V	/	/				X								
			HILLROM	QC	O	/	/				X								
			HILLROM	QC	O	/	/				X								
			HILLROM	QC	A	/	/				X								
			HILLROM	DI	O	/	/				X								
			HILLROM	DI	V	/	/				X								
		J1153	HILLROM	DI	V	/	/				X								
			HILLROM	QC	V	/	/				X								
			HILLROM	QC	O	/	/				X								
			HILLROM	QC	O	/	/				X								
			HILLROM	QC	A	/	/				X								
			HILLROM	QC	O	/	/				X								
			HILLROM	QC	V	/	/				X								
		J1154	HILLROM	QC	V	/	/				X								
			HILLROM	QC	V	/	/				X								
			HILLROM	QC	O	/	/				X								
			HILLROM	QC	O	/	/				X								
			HILLROM	QC	A	/	/				X								
			HILLROM	QC	O	/	/				X								
			HILLROM	QC	V	/	/				X								
		J1168	HILLROM	QC	V	/	/				X								
			HILLROM	QC	V	/	/				X								
			HILLROM	QC	O	/	/				X								
			HILLROM	QC	O	/	/				X								
			HILLROM	QC	A	/	/				X								
			HILLROM	QC	O	/	/				X								
			HILLROM	QC	V	/	/				X								
		J1166	HILLROM	QC	V	/	/				X								
			HILLROM	QC	V	/	/				X								
			HILLROM	QC	O	/	/				X								
			HILLROM	QC	O	/	/				X								
			HILLROM	QC	A	/	/				X								
			HILLROM	QC	O	/	/				X								
			HILLROM	QC	V	/	/				X								
		J1165	HILLROM	QC	V	/	/				X								
			HILLROM	QC	V	/	/				X								
			HILLROM	QC	O	/	/				X								
			HILLROM	QC	O	/	/				X								
			HILLROM	QC	A	/	/				X								
			HILLROM	QC	O	/	/				X								
			HILLROM	QC	V	/	/				X								



TERMINAL LOCATION			OUTLET TYPE			READ		PERFORMANCE								COMMENTS/ FINDINGS	
BUILDING	FLOOR	ROOM/ AREA	MANUFACTURER	CONNECTOR	SYSTEM	PSIG/ HG	FLOW	WALL OUTLET	CEILING OUTLET	COLUMN	HEADWALL	BOOM/ EQUIP	PEDESTAL	HOSE ESSEMBLY	UNAVAILABLE	DEFICIENCY	COMMENTS
SBT	1	J1163	HILLROM	QC	V	/	/				X						
			HILLROM	QC	V	/	/				X						
			HILLROM	QC	O	/	/				X						
			HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	O	/	/				X						
			HILLROM	QC	V	/	/				X						
		J1162	HILLROM	QC	V	/	/				X						
			HILLROM	QC	V	/	/				X						
			HILLROM	QC	O	/	/				X						
			HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	DI	O	/	/				X						
			HILLROM	DI	V	/	/				X						
		J1161	HILLROM	DI	V	/	/				X						
			HILLROM	QC	V	/	/				X						
			HILLROM	QC	O	/	/				X						
			HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	O	/	/				X						
		J1160	HILLROM	QC	V	/	/				X						
			HILLROM	QC	V	/	/				X						
			HILLROM	QC	O	/	/				X						
			HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	O	/	/				X						
		J1159	HILLROM	QC	V	/	/				X						
			HILLROM	QC	V	/	/				X						
			HILLROM	QC	O	/	/				X						
			HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	O	/	/				X						
		J1158	HILLROM	QC	V	/	/				X						
			HILLROM	QC	V	/	/				X						
			HILLROM	QC	O	/	/				X						
			HILLROM	QC	O	/	/				X						
			HILLROM	QC	A	/	/				X						
			HILLROM	QC	O	/	/				X						
			HILLROM	QC	V	/	/				X						

FACILITY: VAMC- SAN JUAN, PR
 TERMINAL PAGE: 20 OF 36
 INSPECTION DATE: 10/26/2016
 INSPECTOR: C WOJCIK

MEDICAL GAS TERMINAL INSPECTION RECORD

TERMINAL LOCATION			OUTLET TYPE			READ		PERFORMANCE										COMMENTS/ FINDINGS	
BUILDING	FLOOR	ROOM/ AREA	MANUFACTURER	CONNECTOR	SYSTEM	PSIG/ HG	FLOW	WALL OUTLET	CEILING OUTLET	COLUMN	HEADWALL	BOOM/ EQUIP	PEDESTAL	HOSE ESSEMBLY	UNAVIALBLE	DEFICIENCY		COMMENTS	
SBT	1	K1202	HILLROM	QC	O	/	/					X							
			HILLROM	QC	A	/	/					X							
			HILLROM	QC	V	/	/					X							
			HILLROM	QC	O	/	/					X							
			HILLROM	QC	A	/	/					X							
			HILLROM	QC	V	/	/					X							
		K1203	HILLROM	QC	O	/	/					X							
			HILLROM	QC	A	/	/					X							
			HILLROM	QC	V	/	/					X							
		K1204	HILLROM	QC	O	/	/					X							
			HILLROM	QC	A	/	/					X							
			HILLROM	QC	V	/	/					X							
		K1206	HILLROM	DI	O	/	/					X							
			HILLROM	DI	A	/	/					X							
			HILLROM	DI	V	/	/					X							
			HILLROM	QC	O	/	/					X							
			HILLROM	QC	A	/	/					X							
			HILLROM	QC	V	/	/					X							
		K1210	HILLROM	QC	O	/	/					X							
			HILLROM	QC	A	/	/					X							
			HILLROM	QC	V	/	/					X							
			HILLROM	QC	O	/	/					X							
			HILLROM	QC	A	/	/					X							
			HILLROM	QC	V	/	/					X							
		K1211	HILLROM	QC	O	/	/					X							
			HILLROM	QC	A	/	/					X							
			HILLROM	QC	V	/	/					X							
			HILLROM	QC	O	/	/					X							
			HILLROM	QC	A	/	/					X							
			HILLROM	QC	V	/	/					X							
		K1209	HILLROM	QC	O	/	/					X							
			HILLROM	QC	A	/	/					X							
			HILLROM	QC	V	/	/					X							
		K1212	HILLROM	QC	O	/	/					X							
			HILLROM	QC	A	/	/					X							
			HILLROM	QC	V	/	/					X							
			HILLROM	QC	O	/	/					X							
			HILLROM	QC	A	/	/					X							
			HILLROM	QC	V	/	/					X							
		K1214	HILLROM	QC	O	/	/					X							
			HILLROM	QC	A	/	/					X							
			HILLROM	QC	V	/	/					X							
			HILLROM	QC	O	/	/					X							
			HILLROM	QC	A	/	/					X							
			HILLROM	QC	V	/	/					X							
		K1216	HILLROM	QC	O	/	/					X							
			HILLROM	QC	A	/	/					X							
			HILLROM	QC	V	/	/					X							