

Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	1	6	Basement	BK-102A	Surfacing	Plaster	Throughout ceiling	740	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	1	6	Basement	BK-102A	Miscellaneous	Red fire stop	Throughout	6	SF	Good		NAD	Medium	n/a	H6-2	n/a	
DC	1	6	Basement	BK-102A	Miscellaneous	Fire door	North wall	1 @ 4' x 7'	Doors	Good	Labeled/Wood	Assumed ACM	High	O & M	H6-2	N/A	
DC	2	6	Basement	BK-102	TSI	Mag pipe hanger	Throughout	100	Hangers	Damaged		NAD	High	n/a	H6-2	n/a	
DC	2	6	Basement	BK-102	Miscellaneous	White pipe seam sealant on paper	Throughout	1800	LF	Good		NAD	High	n/a	H6-2	n/a	
DC	2	6	Basement	BK-102	Miscellaneous	White duct seam sealant on metal	Throughout	1400	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	2	6	Basement	BK-102	Miscellaneous	Tan pin mastic	Throughout	10000	SF	Good	Under White duct seam sealant on paper	NAD	Low	n/a	H6-2	n/a	
DC	2	6	Basement	BK-102	Miscellaneous	White duct seam sealant on paper	Throughout	10000	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	2	6	Basement	BK-102	Miscellaneous	Tan duct seam sealant on metal	Throughout	10000	SF	Good		2% Chrysotile	Low	O & M	H6-2	04	
DC	2	6	Basement	BK-102	Miscellaneous	Fire door	Throughout	1 @ 4' x 7' 1 @ 3' x 7' 2 @ 3' x 8'	Doors	Good	Labeled/Wood; Labeled/Metal	Assumed ACM	High	O & M	H6-2	N/A	
DC	2	6	Basement	BK-102	Miscellaneous	Flange gaskets	Throughout	200	Flange Gaskets	Good		Assumed ACM	Low	O & M	H6-2	N/A	
DC	2	6	Basement	BK-102	Miscellaneous	White AHU caulk	Throughout	2700	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	2	6	Basement	BK-102	Miscellaneous	Green duct seam sealant on metal	Throughout	4800	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	2	6	Basement	BK-102	Surfacing	Plaster	Throughout	10000	SF	Damaged		NAD	Low	n/a	H6-2	n/a	
DC	2	6	Basement	BK-102	Miscellaneous	Red fire stop	Throughout	10	SF	Good		NAD	Medium	n/a	H6-2	n/a	
DC	3	6	Basement	Stair #13	Miscellaneous	Fire door	North wall	1 @ 4' x 7'	Doors	Good	Labeled/Metal	Assumed ACM	High	O & M	H6-2	N/A	
DC	3	6	Basement	Stair #13	Surfacing	Gray spray-on fire proofing	Throughout	100	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	3	6	Basement	Stair #13	Miscellaneous	Drywall and joint compound	Throughout	1200	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	3	6	Basement	Stair #13	Miscellaneous	Red fire stop	Throughout	12	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	4	6	Basement	BH-134	Miscellaneous	Fire door	South wall	2 @ 3' x 7'	Doors	Good	Labeled/Metal	Assumed ACM	High	O & M	H6-2	N/A	
DC	4	6	Basement	BH-134	Surfacing	Gray spray-on fire proofing	North and West walls	300	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	4	6	Basement	BH-134	Miscellaneous	Drywall and joint compound	Throughout	600	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	4	6	Basement	BH-134	Miscellaneous	Gray duct seam sealant on metal	Throughout	160	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	4	6	Basement	BH-134	Miscellaneous	Tan baseboard mastic	Throughout	40	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	4	6	Basement	BH-134	Miscellaneous	Red fire stop	Throughout	5	SF	Good		NAD	Medium	n/a	H6-2	n/a	
DC	5	6	Basement	BH-128		Room Inaccessible								n/a	H6-2	n/a	
DC	6	6	Basement	BH-129	Miscellaneous	Yellow ceramic tile mastic	Throughout	90	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	6	6	Basement	BH-129	Miscellaneous	Drywall and joint compound	Throughout	380	SF	Good	No Access above fixed ceiling	NAD	High	n/a	H6-2	n/a	
DC	7	6	Basement	BH-130	Miscellaneous	Yellow ceramic tile mastic	Throughout	90	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	7	6	Basement	BH-130	Miscellaneous	Drywall and joint compound	Throughout	380	SF	Good	No Access above fixed ceiling	NAD	High	n/a	H6-2	n/a	
DC	8	6	Basement	BH-131	Surfacing	Gray spray-on fire proofing	Throughout	75	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	8	6	Basement	BH-131	Miscellaneous	Drywall and joint compound	Throughout	410	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	8	6	Basement	BH-131	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	70	SF	Good		NAD	Medium	n/a	H6-2	n/a	

Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	8	6	Basement	BH-131	Miscellaneous	12" x 12" Lt. Purple mottle floor tile	Throughout	70	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	8	6	Basement	BH-131	Miscellaneous	Yellow floor tile mastic	Throughout	70	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	8	6	Basement	BH-131	Miscellaneous	Tan baseboard mastic	Throughout	34	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	9	6	Basement	BH-132	Miscellaneous	Gray duct seam sealant on metal	Throughout above drop ceiling	64	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	9	6	Basement	BH-132	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	92	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	9	6	Basement	BH-132	Miscellaneous	Drywall and joint compound	Throughout	888	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	9	6	Basement	BH-132	Miscellaneous	Tan pin mastic	Throughout	92	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	9	6	Basement	BH-132	Miscellaneous	Tan baseboard mastic	Throughout	74	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	9	6	Basement	BH-132	Miscellaneous	Yellow carpet mastic	Throughout	352	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	9	6	Basement	BH-132	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	352	SF	Good		NAD	Medium	n/a	H6-2	n/a	
DC	10	6	Basement	BH-133	Miscellaneous	Tan pin mastic	Throughout	300	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	10	6	Basement	BH-133	Miscellaneous	Gray duct seam sealant on metal	Throughout	140	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	10	6	Basement	BH-133	Miscellaneous	Drywall and joint compound	Throughout	720	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	10	6	Basement	BH-133	Miscellaneous	Tan baseboard mastic	Throughout	60	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	10	6	Basement	BH-133	Miscellaneous	Red fire stop	Throughout	4	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	10	6	Basement	BH-133	Surfacing	Gray spray-on fire proofing	Throughout	160	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	10	6	Basement	BH-133	Miscellaneous	White pipe seam sealant on paper	Throughout	40	LF	Good		NAD	High	n/a	H6-2	n/a	
DC	10	6	Basement	BH-133	Miscellaneous	Fire door	West wall	2 @ 3' x 7'	Doors	Good	Labeled/Wood	Assumed ACM	High	O & M	H6-2	N/A	
DC	11	6	Basement	BH-135, 135A,B,C,D,E	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	350	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	11	6	Basement	BH-135, 135A,B,C,D,E	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	600	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	11	6	Basement	BH-135, 135A,B,C,D,E	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	2340	SF	Good		NAD	Medium	n/a	H6-2	n/a	
DC	11	6	Basement	BH-135, 135A,B,C,D,E	Miscellaneous	Drywall and joint compound	Throughout	3000	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	11	6	Basement	BH-135, 135A,B,C,D,E	Miscellaneous	Tan baseboard mastic	Throughout	230	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	11	6	Basement	BH-135, 135A,B,C,D,E	Miscellaneous	Gray duct seam sealant on metal	Throughout above drop ceiling	240	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	11	6	Basement	BH-135, 135A,B,C,D,E	Miscellaneous	Fire door	Throughout	7 @ 3' x 7'	Doors	Good	Labeled/Wood	Assumed ACM	High	O & M	H6-2	N/A	
DC	12	6	Basement	BH-222	Miscellaneous	Gray duct seam sealant on metal	Throughout above drop ceiling	10	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	12	6	Basement	BH-222	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	30	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	12	6	Basement	BH-222	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	96	SF	Good		NAD	Medium	n/a	H6-2	n/a	
DC	12	6	Basement	BH-222	Miscellaneous	Drywall and joint compound	Throughout	480	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	12	6	Basement	BH-222	Miscellaneous	Tan baseboard mastic	Throughout	40	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	12	6	Basement	BH-222	Miscellaneous	12" x 12" Lt. Pink with Dk. pink specks floor tile	Throughout	96	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	12	6	Basement	BH-222	Miscellaneous	Yellow floor tile mastic	Throughout	96	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	13	6	Basement	BH-223	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	160	SF	Good		NAD	Medium	n/a	H6-2	n/a	

**Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6**

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	13	6	Basement	BH-223	Miscellaneous	Drywall and joint compound	Throughout	560	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	13	6	Basement	BH-223	Miscellaneous	12" x 12" Lt. Blue mottle floor tile	Throughout	160	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	13	6	Basement	BH-223	Miscellaneous	Yellow floor tile mastic	Throughout	160	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	13	6	Basement	BH-223	Miscellaneous	Tan baseboard mastic	Throughout	56	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	13	6	Basement	BH-223	Miscellaneous	Gray duct seam sealant on metal	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	13	6	Basement	BH-223	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	35	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	13	6	Basement	BH-223	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	50	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	14	6	Basement	BH-225	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	176	SF	Good		NAD	Medium	n/a	H6-2	n/a	
DC	14	6	Basement	BH-225	Miscellaneous	Drywall and joint compound	Throughout	720	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	14	6	Basement	BH-225	Miscellaneous	12" x 12" Lt. Green mottle floor tile	Throughout	176	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	14	6	Basement	BH-225	Miscellaneous	Yellow floor tile mastic	Throughout	176	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	14	6	Basement	BH-225	Miscellaneous	Tan baseboard mastic	Throughout	60	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	14	6	Basement	BH-225	Miscellaneous	Gray duct seam sealant on metal	Throughout above drop ceiling	80	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	14	6	Basement	BH-225	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	80	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	14	6	Basement	BH-225	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	176	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	15	6	Basement	BH-256	Miscellaneous	12" x 12" Pink with Dk. Pink specks floor tile	Throughout	72	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	15	6	Basement	BH-256	Miscellaneous	Yellow floor tile mastic	Throughout	72	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	15	6	Basement	BH-256	Miscellaneous	Tan baseboard mastic	Throughout	36	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	15	6	Basement	BH-256	Miscellaneous	Drywall and joint compound	Throughout	430	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	15	6	Basement	BH-256	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	72	SF	Good		NAD	Medium	n/a	H6-2	n/a	
DC	15	6	Basement	BH-256	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	150	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	16	6	Basement	BH-255	Miscellaneous	Red fire stop	Throughout	1	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	16	6	Basement	BH-255	Miscellaneous	Drywall and joint compound	Throughout	430	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	16	6	Basement	BH-255	Surfacing	Gray spray-on fire proofing	Throughout	150	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	16	6	Basement	BH-255	Miscellaneous	White duct seam sealant on foil	Throughout	150	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	16	6	Basement	BH-255	Miscellaneous	Tan baseboard mastic	Throughout	36	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	17	6	Basement	BH-254	Miscellaneous	Tan pin mastic	Throughout	550	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	17	6	Basement	BH-254	Miscellaneous	White pipe seam sealant on paper	Throughout	40	LF	Good		NAD	High	n/a	H6-2	n/a	
DC	17	6	Basement	BH-254	Miscellaneous	Drywall and joint compound	Throughout	1500	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	17	6	Basement	BH-254	Surfacing	Gray spray-on fire proofing	Throughout	260	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	17	6	Basement	BH-254	Miscellaneous	Red fire stop	Throughout	4	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	17	6	Basement	BH-254	Miscellaneous	Fire door	North wall	1 @ 4' x 7'	Doors	Good	Labeled/Metal	Assumed ACM	High	O & M	H6-2	N/A	
DC	17	6	Basement	BH-254	Miscellaneous	Flange gaskets	Throughout	5	Flange Gaskets	Good		Assumed ACM	Low	O & M	H6-2	N/A	
DC	18	6	Basement	BH-253	Miscellaneous	12" x 12" Peach mottle floor tile	Throughout	140	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	18	6	Basement	BH-253	Miscellaneous	Yellow floor tile mastic	Throughout	140	SF	Good		NAD	Low	n/a	H6-2	n/a	

Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	18	6	Basement	BH-253	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	140	SF	Good		NAD	Medium	n/a	H6-2	n/a	
DC	18	6	Basement	BH-253	Surfacing	Gray spray-on fire proofing	Throughout	40	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	18	6	Basement	BH-253	Miscellaneous	Drywall and joint compound	Throughout	580	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	18	6	Basement	BH-253	Miscellaneous	Tan baseboard mastic	Throughout	48	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	19	6	Basement	Stair #12	Miscellaneous	Drywall and joint compound	Throughout	1200	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	19	6	Basement	Stair #12	Miscellaneous	Fire door	West wall	1 @ 4' x 7'	Doors	Good	Labeled/Metal	Assumed ACM	High	O & M	H6-2	N/A	
DC	19	6	Basement	Stair #12	Miscellaneous	Tan baseboard mastic	Throughout	15	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	20	6	Basement	BH-226	Miscellaneous	12" x 12" Lt. Pink mottle floor tile	Throughout	16	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	20	6	Basement	BH-226	Miscellaneous	Yellow floor tile mastic	Throughout	16	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	20	6	Basement	BH-226	Miscellaneous	Tan baseboard mastic	Throughout	16	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	20	6	Basement	BH-226	Miscellaneous	Drywall and joint compound	Throughout	160	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	20	6	Basement	BH-226	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	16	SF	Good		NAD	Medium	n/a	H6-2	n/a	
DC	21	6	Basement	BH-233	Miscellaneous	Tan baseboard mastic	Throughout	20	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	21	6	Basement	BH-233	Miscellaneous	12" x 12" Lt. Pink mottle floor tile	Throughout	24	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	21	6	Basement	BH-233	Miscellaneous	Yellow floor tile mastic	Throughout	24	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	21	6	Basement	BH-233	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	24	SF	Good		NAD	Medium	n/a	H6-2	n/a	
DC	21	6	Basement	BH-233	Miscellaneous	Green duct seam sealant on metal	Throughout above drop ceiling	1	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	21	6	Basement	BH-233	Miscellaneous	Gray duct seam sealant on metal	Throughout above drop ceiling	2	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	21	6	Basement	BH-233	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	20	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	21	6	Basement	BH-233	Miscellaneous	Drywall and joint compound	Throughout	200	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	22	6	Basement	BH-238	Miscellaneous	12" x 12" Lt. Pink with Dk. pink specks floor tile	Throughout	80	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	22	6	Basement	BH-238	Miscellaneous	Yellow floor tile mastic	Throughout	80	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	22	6	Basement	BH-238	Miscellaneous	Tan baseboard mastic	Throughout	36	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	22	6	Basement	BH-238	Miscellaneous	Drywall and joint compound	Throughout	360	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	22	6	Basement	BH-238	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	80	SF	Good		NAD	Medium	n/a	H6-2	n/a	
DC	22	6	Basement	BH-238	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	110	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	23	6	Basement	BH-252	Miscellaneous	Drywall and joint compound	Throughout	2000	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	23	6	Basement	BH-252	Miscellaneous	Tan baseboard mastic	Throughout	200	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	23	6	Basement	BH-252	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	640	SF	Good		NAD	Medium	n/a	H6-2	n/a	
DC	23	6	Basement	BH-252	Miscellaneous	12" x 12" Lt. Pink with Dk. pink specks floor tile	Throughout	470	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	23	6	Basement	BH-252	Miscellaneous	12" x 12" Lt. Green with Dk. Green specks floor tile	Throughout	80	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	23	6	Basement	BH-252	Miscellaneous	Yellow floor tile mastic	Throughout	640	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	23	6	Basement	BH-252	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	275	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	23	6	Basement	BH-252	Miscellaneous	White duct seam sealant on metal	Throughout above drop ceiling	275	SF	Good		NAD	Low	n/a	H6-2	n/a	

Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	23	6	Basement	BH-252	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	300	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	23	6	Basement	BH-252	Miscellaneous	Gray duct seam sealant on metal	Throughout above drop ceiling	160	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	23	6	Basement	BH-252	Miscellaneous	12" x 12" Tan with Pink specks floor tile	Throughout	90	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	24	6	Basement	BH-200	Miscellaneous	12" x 12" Lt. Green with Dk. Green specks floor tile	Throughout	112	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	24	6	Basement	BH-200	Miscellaneous	12" x 12" Lt. Pink with Dk. pink specks floor tile	Throughout	578	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	24	6	Basement	BH-200	Miscellaneous	Yellow floor tile mastic	Throughout	720	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	24	6	Basement	BH-200	Miscellaneous	Drywall and joint compound	Throughout	1100	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	24	6	Basement	BH-200	Miscellaneous	Tan baseboard mastic	Throughout	92	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	24	6	Basement	BH-200	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	720	SF	Good		NAD	Medium	n/a	H6-2	n/a	
DC	24	6	Basement	BH-200	Miscellaneous	Yellow carpet mastic	Throughout	150	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	24	6	Basement	BH-200	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	550	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	24	6	Basement	BH-200	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	650	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	24	6	Basement	BH-200	Miscellaneous	Fire door	Throughout	2 @ 3' x 7'	Doors	Good	Labeled/Metal	Assumed ACM	High	O & M	H6-2	N/A	
DC	24	6	Basement	BH-200	Miscellaneous	12" x 12" Tan with Pink specks floor tile	Throughout	30	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	25	6	Basement	BH-240	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	1100	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	25	6	Basement	BH-240	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	110	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	25	6	Basement	BH-240	Miscellaneous	12" x 12" Lt. Pink mottle floor tile	Throughout	34	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	25	6	Basement	BH-240	Miscellaneous	Yellow floor tile mastic	Throughout	1168	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	25	6	Basement	BH-240	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	1168	SF	Good		NAD	Medium	n/a	H6-2	n/a	
DC	25	6	Basement	BH-240	Miscellaneous	12" x 12" Tan with Pink specks floor tile	Throughout	558	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	25	6	Basement	BH-240	Miscellaneous	12" x 12" Lt. Green with Dk. Green specks floor tile	Throughout	300	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	25	6	Basement	BH-240	Miscellaneous	12" x 12" Lt. Pink with Dk. pink specks floor tile	Throughout	276	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	25	6	Basement	BH-240	Miscellaneous	Drywall and joint compound	Throughout	3160	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	25	6	Basement	BH-240	Miscellaneous	Tan baseboard mastic	Throughout	316	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	25	6	Basement	BH-240	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	650	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	25	6	Basement	BH-240	Miscellaneous	Green duct seam sealant on metal	Throughout above drop ceiling	50	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	26	6	Basement	BH-251	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	250	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	26	6	Basement	BH-251	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	25	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	26	6	Basement	BH-251	Miscellaneous	Drywall and joint compound	Throughout	740	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	26	6	Basement	BH-251	Miscellaneous	Tan baseboard mastic	Throughout	74	LF	Good		NAD	Low	n/a	H6-2	n/a	

Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	26	6	Basement	BH-251	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	420	SF	Good		NAD	Medium	n/a	H6-2	n/a	
DC	26	6	Basement	BH-251	Miscellaneous	12" x 12" Gold mottle floor tile	Throughout	420	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	26	6	Basement	BH-251	Miscellaneous	Yellow floor tile mastic	Throughout	420	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	26	6	Basement	BH-251	Miscellaneous	Gray sink mastic	South wall	1 @ 2' x 2'	Sinks	Good		NAD	Medium	n/a	H6-2	n/a	
DC	27	6	Basement	BH-249	Miscellaneous	12" x 12" Gold mottle floor tile	Throughout	420	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	27	6	Basement	BH-249	Miscellaneous	Yellow floor tile mastic	Throughout	420	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	27	6	Basement	BH-249	Miscellaneous	Tan baseboard mastic	Throughout	82	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	27	6	Basement	BH-249	Miscellaneous	Drywall and joint compound	Throughout	820	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	27	6	Basement	BH-249	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	420	SF	Good		NAD	Medium	n/a	H6-2	n/a	
DC	27	6	Basement	BH-249	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	27	6	Basement	BH-249	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	50	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	27	6	Basement	BH-249	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	450	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	28	6	Basement	BH-248	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	364	SF	Good		NAD	Medium	n/a	H6-2	n/a	
DC	28	6	Basement	BH-248	Miscellaneous	12" x 12" White with Gray specks floor tile	Throughout	182	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	28	6	Basement	BH-248	Miscellaneous	12" x 12" Lt. Pink with Dk. pink specks floor tile	Throughout	182	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	28	6	Basement	BH-248	Miscellaneous	Yellow floor tile mastic	Throughout	364	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	28	6	Basement	BH-248	Miscellaneous	Gray sink mastic	North wall	1 @ 2' x 2'	Sinks	Good		NAD	Medium	n/a	H6-2	n/a	
DC	28	6	Basement	BH-248	Miscellaneous	Tan baseboard mastic	Throughout	80	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	28	6	Basement	BH-248	Miscellaneous	Drywall and joint compound	Throughout	800	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	28	6	Basement	BH-248	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	150	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	28	6	Basement	BH-248	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	350	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	29	6	Basement	BH-247	Miscellaneous	Yellow carpet mastic	Throughout	168	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	29	6	Basement	BH-247	Miscellaneous	Yellow floor tile mastic	Throughout under carpet	168	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	29	6	Basement	BH-247	Miscellaneous	12" x 12" Lt. Pink with Dk. pink specks floor tile	Throughout under carpet	168	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	29	6	Basement	BH-247	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	168	SF	Good		NAD	Medium	n/a	H6-2	n/a	
DC	29	6	Basement	BH-247	Miscellaneous	Tan baseboard mastic	Throughout	52	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	29	6	Basement	BH-247	Miscellaneous	Drywall and joint compound	Throughout	520	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	29	6	Basement	BH-247	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	29A	6	Basement	BH-245/BH-245A	Miscellaneous	12" x 12" Lt. Green with Dk. Green specks floor tile	Throughout	230	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	29A	6	Basement	BH-245/BH-245A	Miscellaneous	12" x 12" Lt. Pink with Dk. pink specks floor tile	Throughout	230	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	29A	6	Basement	BH-245/BH-245A	Miscellaneous	Yellow floor tile mastic	Throughout	460	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	29A	6	Basement	BH-245/BH-245A	Miscellaneous	Tan baseboard mastic	Throughout	82	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	29A	6	Basement	BH-245/BH-245A	Miscellaneous	Drywall and joint compound	Throughout	820	SF	Good		NAD	High	n/a	H6-2	n/a	

**Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6**

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	29A	6	Basement	BH-245/BH-245A	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	460	SF	Good		NAD	Medium	n/a	H6-2	n/a	
DC	29A	6	Basement	BH-245/BH-245A	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	29A	6	Basement	BH-245/BH-245A	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	50	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	29A	6	Basement	BH-245/BH-245A	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	460	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	29B	6	Basement	BH-246/BH-231/BH-243	Miscellaneous	12" x 12" Lt. Green with Dk. Green specks floor tile	Throughout	230	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	29B	6	Basement	BH-246/BH-231/BH-243	Miscellaneous	12" x 12" Lt. Pink with Dk. pink specks floor tile	Throughout	230	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	29B	6	Basement	BH-246/BH-231/BH-243	Miscellaneous	Yellow floor tile mastic	Throughout	460	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	29B	6	Basement	BH-246/BH-231/BH-243	Miscellaneous	Tan baseboard mastic	Throughout	82	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	29B	6	Basement	BH-246/BH-231/BH-243	Miscellaneous	Drywall and joint compound	Throughout	820	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	29B	6	Basement	BH-246/BH-231/BH-243	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	460	SF	Good		NAD	Medium	n/a	H6-2	n/a	
DC	29B	6	Basement	BH-246/BH-231/BH-243	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	29B	6	Basement	BH-246/BH-231/BH-243	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	50	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	29B	6	Basement	BH-246/BH-231/BH-243	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	460	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	29C	6	Basement	BH-232	Miscellaneous	12" x 12" Lt. Green with Dk. Green specks floor tile	Throughout	230	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	29C	6	Basement	BH-232	Miscellaneous	12" x 12" Lt. Pink with Dk. pink specks floor tile	Throughout	230	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	29C	6	Basement	BH-232	Miscellaneous	Yellow floor tile mastic	Throughout	460	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	29C	6	Basement	BH-232	Miscellaneous	Tan baseboard mastic	Throughout	82	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	29C	6	Basement	BH-232	Miscellaneous	Drywall and joint compound	Throughout	820	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	29C	6	Basement	BH-232	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	460	SF	Good		NAD	Medium	n/a	H6-2	n/a	
DC	29C	6	Basement	BH-232	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	29C	6	Basement	BH-232	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	50	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	29C	6	Basement	BH-232	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	460	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	29	6	Basement	BH-247	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	200	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	30	6	Basement	BH-244	Miscellaneous	Yellow ceramic tile mastic	Throughout	96	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	30	6	Basement	BH-244	Miscellaneous	Drywall and joint compound	Throughout	320	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	30	6	Basement	BH-244	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	60	SF	Good		NAD	Medium	n/a	H6-2	n/a	
DC	30	6	Basement	BH-244	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	200	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	30	6	Basement	BH-244	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	4	SF	Good		NAD	Low	n/a	H6-2	n/a	

**Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6**

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	31	6	Basement	BH-207	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	20	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	31	6	Basement	BH-207	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	31	6	Basement	BH-207	Miscellaneous	12" x 12" White with Lt. Green specks floor tile	Throughout	56	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	31	6	Basement	BH-207	Miscellaneous	Yellow floor tile mastic	Throughout	56	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	31	6	Basement	BH-207	Miscellaneous	Tan baseboard mastic	Throughout	30	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	31	6	Basement	BH-207	Miscellaneous	Drywall and joint compound	Throughout	300	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	31	6	Basement	BH-207	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	56	SF	Good		NAD	Medium	n/a	H6-2	n/a	
DC	32	6	Basement	BH-209	Miscellaneous	White sink mastic	North wall	1 @ 2' x 2'	Sinks	Good		NAD	Medium	n/a	H6-2	n/a	
DC	32	6	Basement	BH-209	Miscellaneous	12" x 12" Lt. Pink with Dk. pink specks floor tile	Throughout	32	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	32	6	Basement	BH-209	Miscellaneous	Yellow floor tile mastic	Throughout	32	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	32	6	Basement	BH-209	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	32	SF	Good		NAD	Medium	n/a	H6-2	n/a	
DC	32	6	Basement	BH-209	Miscellaneous	Tan baseboard mastic	Throughout	24	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	32	6	Basement	BH-209	Miscellaneous	Drywall and joint compound	Throughout	240	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	32	6	Basement	BH-209	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	12	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	32	6	Basement	BH-209	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	50	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	33	6	Basement	BH-210	Miscellaneous	Gray sink mastic	South wall	1 @ 2' x 2'	Sinks	Good		NAD	Medium	n/a	H6-2	n/a	
DC	33	6	Basement	BH-210	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	156	SF	Good		NAD	Medium	n/a	H6-2	n/a	
DC	33	6	Basement	BH-210	Miscellaneous	Yellow floor tile mastic	Throughout	156	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	33	6	Basement	BH-210	Miscellaneous	12" x 12" White with Gray specks floor tile	Throughout	34	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	33	6	Basement	BH-210	Miscellaneous	12" x 12" Lt. Pink with Dk. pink specks floor tile	Throughout	122	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	33	6	Basement	BH-210	Miscellaneous	Tan baseboard mastic	Throughout	50	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	33	6	Basement	BH-210	Miscellaneous	Drywall and joint compound	Throughout	500	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	33	6	Basement	BH-210	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	30	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	33	6	Basement	BH-210	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	250	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	34	6	Basement	BH-211	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	50	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	34	6	Basement	BH-211	Miscellaneous	Green duct seam sealant on metal	Throughout above drop ceiling	3	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	34	6	Basement	BH-211	Miscellaneous	12" x 12" Lt. Pink with Dk. pink specks floor tile	Throughout	36	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	34	6	Basement	BH-211	Miscellaneous	Yellow floor tile mastic	Throughout	36	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	34A	6	Basement	BL-104	Miscellaneous	2' x 2' White Ceiling Tile	Throughout ceiling	96	SF	Good		NAD	Medium	n/a	H6-2	n/a	
DC	34A	6	Basement	BL-104	Miscellaneous	Drywall and joint compound	Throughout walls	400	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	34A	6	Basement	BL-104	Miscellaneous	Tan baseboard mastic	Throughout walls	40	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	34A	6	Basement	BL-104	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	34A	6	Basement	BL-104	Miscellaneous	Gray duct seam sealant on metal	Throughout above drop ceiling	48	SF	Good		NAD	Low	n/a	H6-2	n/a	

Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	34A	6	Basement	BL-104	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	34A	6	Basement	BL-104	Miscellaneous	Fire door	North Wall	1 @ 3' x 7'	Door	Good	Labeled/Metal	Assumed ACM	High	O & M	H6-2	N/A	
DC	34B	6	Basement	BL-103	Miscellaneous	2' x 2' White Ceiling Tile	Throughout ceiling	96	SF	Good		NAD	Medium	n/a	H6-2	n/a	
DC	34B	6	Basement	BL-103	Miscellaneous	Drywall and joint compound	Throughout walls	400	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	34B	6	Basement	BL-103	Miscellaneous	Tan baseboard mastic	Throughout walls	40	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	34B	6	Basement	BL-103	Miscellaneous	Gray duct seam sealant on metal	Throughout above drop ceiling	48	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	34B	6	Basement	BL-103	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	34B	6	Basement	BL-103	Miscellaneous	Fire door	North Wall	1 @ 3' x 7'	Door	Good	Labeled/Metal	Assumed ACM	High	O & M	H6-2	N/A	
DC	34C	6	Basement	BL-102	Miscellaneous	2' x 2' White Ceiling Tile	Throughout ceiling	96	SF	Good		NAD	Medium	n/a	H6-2	n/a	
DC	34C	6	Basement	BL-102	Miscellaneous	Drywall and joint compound	Throughout walls	400	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	34C	6	Basement	BL-102	Miscellaneous	Tan baseboard mastic	Throughout walls	40	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	34C	6	Basement	BL-102	Miscellaneous	Gray duct seam sealant on metal	Throughout above drop ceiling	48	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	34C	6	Basement	BL-102	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	34C	6	Basement	BL-102	Miscellaneous	Fire door	North Wall	1 @ 3' x 7'	Door	Good	Labeled/Metal	Assumed ACM	High	O & M	H6-2	N/A	
DC	34	6	Basement	BH-211	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	36	SF	Good		NAD	Medium	n/a	H6-2	n/a	
DC	35	6	Basement	Coat Room	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	10	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	35	6	Basement	Coat Room	Miscellaneous	12" x 12" White with Lt. Green specks floor tile	Throughout	25	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	35	6	Basement	Coat Room	Miscellaneous	Yellow floor tile mastic	Throughout	25	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	35	6	Basement	Coat Room	Miscellaneous	Tan baseboard mastic	Throughout	20	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	35	6	Basement	Coat Room	Miscellaneous	Drywall and joint compound	Throughout	200	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	35	6	Basement	Coat Room	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	25	SF	Good		NAD	Medium	n/a	H6-2	n/a	
DC	36	6	Basement	BH-212; BH-213	Miscellaneous	12" x 12" White with Gray specks floor tile	Throughout	35	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	36	6	Basement	BH-212; BH-213	Miscellaneous	12" x 12" Lt. Pink with Dk. pink specks floor tile	Throughout	165	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	36	6	Basement	BH-212; BH-213	Miscellaneous	Yellow floor tile mastic	Throughout	200	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	36	6	Basement	BH-212; BH-213	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	160	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	36	6	Basement	BH-212; BH-213	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	40	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	36	6	Basement	BH-212; BH-213	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	200	SF	Good		NAD	Medium	n/a	H6-2	n/a	
DC	36	6	Basement	BH-212; BH-213	Miscellaneous	Gray sink mastic	North wall	1 @ 1' x 1'	Sinks	Good		NAD	Medium	n/a	H6-2	n/a	
DC	36	6	Basement	BH-212; BH-213	Miscellaneous	Drywall and joint compound	Throughout	960	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	36	6	Basement	BH-212; BH-213	Miscellaneous	Tan baseboard mastic	Throughout	80	LF	Good		NAD	Low	n/a	H6-2	n/a	

**Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6**

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	37	6	Basement	BH-214; BH-215	Miscellaneous	12" x 12" White with Lt. Green specks floor tile	Throughout	270	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	37	6	Basement	BH-214; BH-215	Miscellaneous	Yellow floor tile mastic	Throughout	270	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	37	6	Basement	BH-214; BH-215	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	270	SF	Good		NAD	Medium	n/a	H6-2	n/a	
DC	37	6	Basement	BH-214; BH-215	Miscellaneous	Drywall and joint compound	Throughout	920	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	37	6	Basement	BH-214; BH-215	Miscellaneous	Tan baseboard mastic	Throughout	92	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	37	6	Basement	BH-214; BH-215	Miscellaneous	Gray sink mastic	South wall	1 @ 1' x 1'	Sinks	Good		NAD	Medium	n/a	H6-2	n/a	
DC	37	6	Basement	BH-214; BH-215	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	260	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	37	6	Basement	BH-214; BH-215	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	80	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	37	6	Basement	BH-214; BH-215	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	10	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	38	6	Basement	BH-206	Miscellaneous	12" x 12" Lt. Purple with Dk. Purple specks floor tile	Throughout	216	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	38	6	Basement	BH-206	Miscellaneous	Yellow floor tile mastic	Throughout	216	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	38	6	Basement	BH-206	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	216	SF	Good		NAD	Medium	n/a	H6-2	n/a	
DC	38	6	Basement	BH-206	Miscellaneous	Drywall and joint compound	Throughout	840	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	38	6	Basement	BH-206	Miscellaneous	Tan baseboard mastic	Throughout	84	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	38	6	Basement	BH-206	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	38	6	Basement	BH-206	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	38	6	Basement	BH-206	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	10	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	39	6	Basement	BH-205	Miscellaneous	12" x 12" Lt. Purple with Dk. Purple specks floor tile	Throughout	40	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	39	6	Basement	BH-205	Miscellaneous	Yellow floor tile mastic	Throughout	40	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	39	6	Basement	BH-205	Miscellaneous	Drywall and joint compound	Throughout walls and ceiling	300	SF	Good	No Access above fixed ceiling	NAD	High	n/a	H6-2	n/a	
DC	39	6	Basement	BH-205	Miscellaneous	Gray duct seam sealant on metal	Throughout	1	SF	Good		NAD	Medium	n/a	H6-2	n/a	
DC	39	6	Basement	BH-205	Miscellaneous	Red duct seam sealant on metal	Throughout	1	SF	Good		NAD	Medium	n/a	H6-2	n/a	
DC	39	6	Basement	BH-205	Miscellaneous	Tan baseboard mastic	Throughout	26	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	40	6	Basement	BH-204	Miscellaneous	12" x 12" Peach mottle floor tile	Throughout	48	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	40	6	Basement	BH-204	Miscellaneous	12" x 12" Tan with Pink specks floor tile	Throughout	48	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	40	6	Basement	BH-204	Miscellaneous	Yellow floor tile mastic	Throughout	96	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	40	6	Basement	BH-204	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	48	SF	Good		NAD	Medium	n/a	H6-2	n/a	
DC	40	6	Basement	BH-204	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	40	6	Basement	BH-204	Miscellaneous	Drywall and joint compound	Throughout	280	SF	Good		NAD	High	n/a	H6-2	n/a	

**Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6**

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	40	6	Basement	BH-204	Miscellaneous	Tan baseboard mastic	Throughout	28	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	41	6	Basement	BH-220	Miscellaneous	12" x 12" Lt. Pink with Dk. pink specks floor tile	Throughout	48	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	41	6	Basement	BH-220	Miscellaneous	Yellow floor tile mastic	Throughout	48	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	41	6	Basement	BH-220	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	48	SF	Good		NAD	Medium	n/a	H6-2	n/a	
DC	41	6	Basement	BH-220	Miscellaneous	Drywall and joint compound	Throughout	280	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	41	6	Basement	BH-220	Miscellaneous	Tan baseboard mastic	Throughout	28	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	41	6	Basement	BH-220	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	64	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	42	6	Basement	BL-100	Miscellaneous	Fire door	North wall	2 @ 3' x 7'	Doors	Good	Labeled/Metal	Assumed ACM	Low	O & M	H6-2	N/A	
DC	42	6	Basement	BL-100	Miscellaneous	Flange gaskets	Throughout	20	Flange Gaskets	Good		Assumed ACM	Low	O & M	H6-2	N/A	
DC	42	6	Basement	BL-100	Miscellaneous	2' x 2' Solid white ceiling tile	Throughout	320	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	42	6	Basement	BL-100	Miscellaneous	Tan stair tread mastic	Throughout	60	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	42	6	Basement	BL-100	Miscellaneous	Tan baseboard mastic	Throughout	72	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	42	6	Basement	BL-100	Miscellaneous	Red fire stop	Throughout above drop ceiling	6	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	42	6	Basement	BL-100	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	450	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	42	6	Basement	BL-100	Miscellaneous	Black vapor barrier	Throughout	160	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	43	6	Basement	BL-101	Miscellaneous	Fire door	North wall	1 @ 4' x 7'	SF	Good	Labeled/Metal	Assumed ACM	High	O & M	H6-2	N/A	
DC	43	6	Basement	BL-101	Miscellaneous	Flange gaskets	Throughout	50	Flange Gaskets	Good		Assumed ACM	Low	O & M	H6-2	N/A	
DC	43	6	Basement	BL-101	Miscellaneous	White pipe seam sealant on paper	Throughout	480	LF	Good		NAD	High	n/a	H6-2	n/a	
DC	43	6	Basement	BL-101	Surfacing	Gray spray-on fire proofing	Throughout	960	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	43	6	Basement	BL-101	Miscellaneous	White duct seam sealant on paper	Throughout	1750	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	43	6	Basement	BL-101	Miscellaneous	Black vapor barrier	West wall	375	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	43	6	Basement	BL-101	Miscellaneous	Tan pin mastic	Throughout	1750	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	43	6	Basement	BL-101	Miscellaneous	Gray duct seam sealant on metal	Throughout	20	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	43	6	Basement	BL-101	Miscellaneous	Red fire stop	Throughout	15	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	44	6	Basement	BL-105A	Miscellaneous	2' x 2' Rough ceiling tile	Throughout	96	SF	Good		NAD	Medium	n/a	H6-2	n/a	
DC	44	6	Basement	BL-105A	Miscellaneous	Fire door	South wall	1 @ 3' x 7'	Doors	Good	Labeled/Wood	Assumed ACM	High	O & M	H6-2	N/A	
DC	44	6	Basement	BL-105A	Miscellaneous	Drywall and joint compound	Throughout	400	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	44	6	Basement	BL-105A	Miscellaneous	Tan baseboard mastic	Throughout	40	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	44	6	Basement	BL-105A	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	120	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	44	6	Basement	BL-105A	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	160	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	45	6	Basement	BL-105B	Miscellaneous	2' x 2' Rough ceiling tile	Throughout	96	SF	Good		NAD	Medium	n/a	H6-2	n/a	
DC	45	6	Basement	BL-105B	Miscellaneous	Fire door	South wall	1 @ 3' x 7'	Doors	Good	Labeled/Wood	Assumed ACM	High	O & M	H6-2	N/A	
DC	45	6	Basement	BL-105B	Miscellaneous	Drywall and joint compound	Throughout	400	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	45	6	Basement	BL-105B	Miscellaneous	Tan baseboard mastic	Throughout	40	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	45	6	Basement	BL-105B	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	120	SF	Good		NAD	Low	n/a	H6-2	n/a	

Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	45	6	Basement	BL-105B	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	160	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	46	6	Basement	BL-105C	Miscellaneous	2' x 2' Rough ceiling tile	Throughout	96	SF	Good		NAD	Medium	n/a	H6-2	n/a	
DC	46	6	Basement	BL-105C	Miscellaneous	Fire door	South wall	1 @ 3' x 7'	Doors	Good	Labeled/Wood	Assumed ACM	High	O & M	H6-2	N/A	
DC	46	6	Basement	BL-105C	Miscellaneous	Drywall and joint compound	Throughout	400	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	46	6	Basement	BL-105C	Miscellaneous	Tan baseboard mastic	Throughout	40	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	46	6	Basement	BL-105C	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	120	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	46	6	Basement	BL-105C	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	160	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	46	6	Basement	BL-105C	Miscellaneous	Gray duct seam sealant on metal	Throughout above drop ceiling	80	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	46	6	Basement	BL-105C	Miscellaneous	Red fire stop	Throughout above drop ceiling	5	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	47	6	Basement	BL-105D	Miscellaneous	Fire door	East wall	2 @ 3' x 7'	Doors	Good	Labeled/Wood	Assumed ACM	High	O & M	H6-2	N/A	
DC	47	6	Basement	BL-105D	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	50	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	47	6	Basement	BL-105D	Miscellaneous	Drywall and joint compound	Throughout	160	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	47	6	Basement	BL-105D	Miscellaneous	Tan baseboard mastic	Throughout	16	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	47	6	Basement	BL-105D	Miscellaneous	2' x 2' Rough ceiling tile	Throughout	12	SF	Good		NAD	Medium	n/a	H6-2	n/a	
DC	48	6	Basement	BL-105E	Miscellaneous	2' x 2' Rough ceiling tile	Throughout	96	SF	Good		NAD	Medium	n/a	H6-2	n/a	
DC	48	6	Basement	BL-105E	Miscellaneous	Fire door	North wall	1 @ 3' x 7'	Doors	Good	Labeled/Wood	Assumed ACM	High	O & M	H6-2	N/A	
DC	48	6	Basement	BL-105E	Miscellaneous	Drywall and joint compound	Throughout	400	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	48	6	Basement	BL-105E	Miscellaneous	Tan baseboard mastic	Throughout	40	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	48	6	Basement	BL-105E	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	120	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	48	6	Basement	BL-105E	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	160	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	49	6	Basement	BL-105F	Miscellaneous	2' x 2' Rough ceiling tile	Throughout	96	SF	Good		NAD	Medium	n/a	H6-2	n/a	
DC	49	6	Basement	BL-105F	Miscellaneous	Fire door	North wall	1 @ 3' x 7'	Doors	Good	Labeled/Wood	Assumed ACM	High	O & M	H6-2	N/A	
DC	49	6	Basement	BL-105F	Miscellaneous	Drywall and joint compound	Throughout	400	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	49	6	Basement	BL-105F	Miscellaneous	Tan baseboard mastic	Throughout	40	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	49	6	Basement	BL-105F	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	120	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	49	6	Basement	BL-105F	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	160	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	50	6	Basement	BL-105G	Miscellaneous	2' x 2' Rough ceiling tile	Throughout	96	SF	Good		NAD	Medium	n/a	H6-2	n/a	
DC	50	6	Basement	BL-105G	Miscellaneous	Fire door	North wall	1 @ 3' x 7'	Doors	Good	Labeled/Wood	Assumed ACM	High	O & M	H6-2	N/A	
DC	50	6	Basement	BL-105G	Miscellaneous	Drywall and joint compound	Throughout	400	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	50	6	Basement	BL-105G	Miscellaneous	Tan baseboard mastic	Throughout	40	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	50	6	Basement	BL-105G	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	120	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	50	6	Basement	BL-105G	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	160	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	51	6	Basement	BL-105H	Miscellaneous	2' x 2' Rough ceiling tile	Throughout	96	SF	Good		NAD	Medium	n/a	H6-2	n/a	
DC	51	6	Basement	BL-105H	Miscellaneous	Fire door	South wall	1 @ 3' x 7'	Doors	Good	Labeled/Wood	Assumed ACM	High	O & M	H6-2	N/A	

Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	51	6	Basement	BL-105H	Miscellaneous	Drywall and joint compound	Throughout	400	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	51	6	Basement	BL-105H	Miscellaneous	Tan baseboard mastic	Throughout	40	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	51	6	Basement	BL-105H	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	120	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	51	6	Basement	BL-105H	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	160	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	52	6	Basement	BL-105I	Miscellaneous	2' x 2' Rough ceiling tile	Throughout	192	SF	Good		NAD	Medium	n/a	H6-2	n/a	
DC	52	6	Basement	BL-105I	Miscellaneous	Fire door	South wall	1 @ 3' x 7'	Doors	Good	Labeled/Wood	Assumed ACM	High	O & M	H6-2	N/A	
DC	52	6	Basement	BL-105I	Miscellaneous	Drywall and joint compound	Throughout	800	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	52	6	Basement	BL-105I	Miscellaneous	Tan baseboard mastic	Throughout	80	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	52	6	Basement	BL-105I	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	240	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	52	6	Basement	BL-105I	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	320	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	52	6	Basement	BL-105I	Miscellaneous	Red fire stop	Throughout above drop ceiling	3	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	53	6	Basement	BL-105J	Miscellaneous	2' x 2' Rough ceiling tile	Throughout	64	SF	Good		NAD	Medium	n/a	H6-2	n/a	
DC	53	6	Basement	BL-105J	Miscellaneous	Drywall and joint compound	Throughout	320	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	53	6	Basement	BL-105J	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	70	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	53	6	Basement	BL-105J	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	20	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	53	6	Basement	BL-105J	Miscellaneous	Fire door	South wall	1 @ 3' x 7'	Doors	Good	Labeled/Wood	Assumed ACM	High	O & M	H6-2	N/A	
DC	54	6	Basement	BL-105K	Miscellaneous	2' x 2' Rough ceiling tile	Throughout	480	SF	Good		NAD	Medium	n/a	H6-2	n/a	
DC	54	6	Basement	BL-105K	Miscellaneous	Drywall and joint compound	Throughout	880	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	54	6	Basement	BL-105K	Miscellaneous	Tan baseboard mastic	Throughout	88	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	54	6	Basement	BL-105K	Miscellaneous	Fire door	East wall	1 @ 3' x 7'	Doors	Good	Labeled/Metal	Assumed ACM	High	O & M	H6-2	N/A	
DC	54	6	Basement	BL-105K	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	450	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	54	6	Basement	BL-105K	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	120	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	54	6	Basement	BL-105K	Miscellaneous	Gray duct seam sealant on metal	Throughout above drop ceiling	80	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	55	6	Basement	BL105KK	Miscellaneous	Fire door	North wall	1 @ 4' x 7'	Doors	Good	Labeled/Metal	Assumed ACM	High	O & M	H6-2	N/A	
DC	55	6	Basement	BL105KK	Miscellaneous	Flange gaskets	Throughout	10	Flange Gaskets	Good		Assumed ACM	Low	O & M	H6-2	N/A	
DC	55	6	Basement	BL105KK	Miscellaneous	White pipe seam sealant on paper	Throughout	250	LF	Good		NAD	High	n/a	H6-2	n/a	
DC	55	6	Basement	BL105KK	Miscellaneous	White duct seam sealant on paper	Throughout	720	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	55	6	Basement	BL105KK	Miscellaneous	Tan pin mastic	Throughout	720	SF	Good	Under FG Duct Ins	NAD	Low	n/a	H6-2	n/a	
DC	55	6	Basement	BL105KK	Miscellaneous	Black vapor barrier	West and South walls	950	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	55	6	Basement	BL105KK	Miscellaneous	Drywall and joint compound	Throughout columns	120	SF	Good	No Joint Compound	NAD	High	n/a	H6-2	n/a	
DC	55	6	Basement	BL105KK	Surfacing	Gray spray-on fire proofing	Throughout	600	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	55	6	Basement	BL105KK	Miscellaneous	Red fire stop	Throughout	8	SF	Good		NAD	Low	n/a	H6-2	n/a	

**Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6**

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	56	6	Basement	BL105L	Miscellaneous	12" x 12" Yellow with Gold specks floor tile	Throughout	100	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	56	6	Basement	BL105L	Miscellaneous	Yellow floor tile mastic	Throughout	100	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	56	6	Basement	BL105L	Miscellaneous	2' x 2' Rough ceiling tile	Throughout	100	SF	Good		NAD	Medium	n/a	H6-2	n/a	
DC	56	6	Basement	BL105L	Miscellaneous	Drywall and joint compound	Throughout	400	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	56	6	Basement	BL105L	Miscellaneous	Tan baseboard mastic	Throughout	40	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	56	6	Basement	BL105L	Miscellaneous	Fire door	North wall	1 @ 4' x 7'	Doors	Good	Labeled/Wood	Assumed ACM	High	O & M	H6-2	N/A	
DC	56	6	Basement	BL105L	Miscellaneous	White sink mastic	East wall	1 @ 2' x 2'	Sinks	Good		NAD	Medium	n/a	H6-2	n/a	
DC	56	6	Basement	BL105L	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	120	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	56	6	Basement	BL105L	Miscellaneous	Tan pin mastic	Throughout above drop ceiling	120	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	56	6	Basement	BL105L	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	120	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	57	6	Basement	BL-105M	Miscellaneous	2' x 2' Rough ceiling tile	Throughout	96	SF	Good		NAD	Medium	n/a	H6-2	n/a	
DC	57	6	Basement	BL-105M	Miscellaneous	Fire door	North wall	1 @ 3' x 7'	Doors	Good	Labeled/Wood	Assumed ACM	High	O & M	H6-2	N/A	
DC	57	6	Basement	BL-105M	Miscellaneous	Drywall and joint compound	Throughout	400	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	57	6	Basement	BL-105M	Miscellaneous	Tan baseboard mastic	Throughout	40	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	57	6	Basement	BL-105M	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	120	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	57	6	Basement	BL-105M	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	160	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	58	6	Basement	BL-105N	Miscellaneous	2' x 2' Rough ceiling tile	Throughout	96	SF	Good		NAD	Medium	n/a	H6-2	n/a	
DC	58	6	Basement	BL-105N	Miscellaneous	Fire door	North wall	1 @ 3' x 7'	Doors	Good	Labeled/Wood	Assumed ACM	High	O & M	H6-2	N/A	
DC	58	6	Basement	BL-105N	Miscellaneous	Drywall and joint compound	Throughout	400	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	58	6	Basement	BL-105N	Miscellaneous	Tan baseboard mastic	Throughout	40	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	58	6	Basement	BL-105N	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	120	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	58	6	Basement	BL-105N	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	160	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	59	6	Basement	BL-105O	Miscellaneous	2' x 2' Rough ceiling tile	Throughout	96	SF	Good		NAD	Medium	n/a	H6-2	n/a	
DC	59	6	Basement	BL-105O	Miscellaneous	Fire door	North wall	1 @ 3' x 7'	Doors	Good	Labeled/Wood	Assumed ACM	High	O & M	H6-2	N/A	
DC	59	6	Basement	BL-105O	Miscellaneous	Drywall and joint compound	Throughout	400	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	59	6	Basement	BL-105O	Miscellaneous	Tan baseboard mastic	Throughout	40	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	59	6	Basement	BL-105O	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	120	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	59	6	Basement	BL-105O	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	160	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	60	6	Basement	BL-105P	Miscellaneous	2' x 2' Rough ceiling tile	Throughout	96	SF	Good		NAD	Medium	n/a	H6-2	n/a	
DC	60	6	Basement	BL-105P	Miscellaneous	Fire door	South wall	1 @ 3' x 7'	Doors	Good	Labeled/Wood	Assumed ACM	High	O & M	H6-2	N/A	
DC	60	6	Basement	BL-105P	Miscellaneous	Drywall and joint compound	Throughout	400	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	60	6	Basement	BL-105P	Miscellaneous	Tan baseboard mastic	Throughout	40	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	60	6	Basement	BL-105P	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	120	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	60	6	Basement	BL-105P	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	160	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	61	6	Basement	BL-105Q	Miscellaneous	2' x 2' Rough ceiling tile	Throughout	96	SF	Good		NAD	Medium	n/a	H6-2	n/a	

**Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6**

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	61	6	Basement	BL-105Q	Miscellaneous	Fire door	South wall	1 @ 3' x 7'	Doors	Good	Labeled/Wood	Assumed ACM	High	O & M	H6-2	N/A	
DC	61	6	Basement	BL-105Q	Miscellaneous	Drywall and joint compound	Throughout	400	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	61	6	Basement	BL-105Q	Miscellaneous	Tan baseboard mastic	Throughout	40	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	61	6	Basement	BL-105Q	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	120	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	61	6	Basement	BL-105Q	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	160	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	62	6	Basement	BL105R	Miscellaneous	2' x 2' Rough ceiling tile	Throughout	192	SF	Good		NAD	Medium	n/a	H6-2	n/a	
DC	62	6	Basement	BL105R	Miscellaneous	Fire door	South wall	1 @ 3' x 7'	Doors	Good	Labeled/Wood	Assumed ACM	High	O & M	H6-2	N/A	
DC	62	6	Basement	BL105R	Miscellaneous	Drywall and joint compound	Throughout	800	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	62	6	Basement	BL105R	Miscellaneous	Tan baseboard mastic	Throughout	80	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	62	6	Basement	BL105R	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	240	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	62	6	Basement	BL105R	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	320	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	62	6	Basement	BL105R	Miscellaneous	Red fire stop	Throughout above drop ceiling	3	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	62	6	Basement	BL105R	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	20	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	63	6	Basement	BL-105S	Miscellaneous	12" x 12" Yellow with Gold specks floor tile	Throughout	140	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	63	6	Basement	BL-105S	Miscellaneous	Yellow floor tile mastic	Throughout	140	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	63	6	Basement	BL-105S	Miscellaneous	2' x 2' Rough ceiling tile	Throughout	140	SF	Good		NAD	Medium	n/a	H6-2	n/a	
DC	63	6	Basement	BL-105S	Miscellaneous	Drywall and joint compound	Throughout	480	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	63	6	Basement	BL-105S	Miscellaneous	Tan baseboard mastic	Throughout	48	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	63	6	Basement	BL-105S	Miscellaneous	Fire door	East wall	1 @ 3' x 7'	Doors	Good	Labeled/Wood	Assumed ACM	High	O & M	H6-2	N/A	
DC	63	6	Basement	BL-105S	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	120	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	63	6	Basement	BL-105S	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	80	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	63	6	Basement	BL-105S	Miscellaneous	Tan pin mastic	Throughout above drop ceiling	80	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	63	6	Basement	BL-105S	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	10	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	64	6	Basement	BL-105T; BL-105TT	Miscellaneous	Fire door	North, West and South walls	3 @ 3' x 7'	Doors	Good	Labeled/Wood	Assumed ACM	High	O & M	H6-1	N/A	
DC	64	6	Basement	BL-105T; BL-105TT	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	1600	SF	Good		NAD	Low	n/a	H6-1	n/a	
DC	64	6	Basement	BL-105T; BL-105TT	Miscellaneous	Tan pin mastic	Throughout above drop ceiling	1600	SF	Good		NAD	Low	n/a	H6-1	n/a	
DC	64	6	Basement	BL-105T; BL-105TT	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	800	SF	Good		NAD	Low	n/a	H6-1	n/a	
DC	64	6	Basement	BL-105T; BL-105TT	Miscellaneous	Drywall and joint compound	Throughout	1200	SF	Good		NAD	High	n/a	H6-1	n/a	
DC	64	6	Basement	BL-105T; BL-105TT	Miscellaneous	Tan baseboard mastic	Throughout	120	LF	Good		NAD	Low	n/a	H6-1	n/a	
DC	64	6	Basement	BL-105T; BL-105TT	Miscellaneous	2' x 2' Rough ceiling tile	Throughout	530	SF	Good		NAD	Medium	n/a	H6-1	n/a	

Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	64	6	Basement	BL-105T; BL-105TT	Miscellaneous	12" x 12" Yellow with Gold specks floor tile	Throughout	50	SF	Good		NAD	High	n/a	H6-1	n/a	
DC	64	6	Basement	BL-105T; BL-105TT	Miscellaneous	Yellow floor tile mastic	Throughout	50	SF	Good		NAD	Low	n/a	H6-1	n/a	
DC	65	6	Basement	BL-105 Hallway	Miscellaneous	2' x 2' Rough ceiling tile	Throughout	1500	SF	Good		NAD	Medium	n/a	H6-1	n/a	
DC	65	6	Basement	BL-105 Hallway	Miscellaneous	Drywall and joint compound	Throughout	5750	SF	Good		NAD	High	n/a	H6-1	n/a	
DC	65	6	Basement	BL-105 Hallway	Miscellaneous	Tan baseboard mastic	Throughout	500	LF	Good		NAD	Low	n/a	H6-1	n/a	
DC	65	6	Basement	BL-105 Hallway	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	1200	SF	Good		NAD	Low	n/a	H6-1	n/a	
DC	65	6	Basement	BL-105 Hallway	Miscellaneous	Tan pin mastic	Throughout above drop ceiling	1200	SF	Good		NAD	Low	n/a	H6-1	n/a	
DC	65	6	Basement	BL-105 Hallway	Miscellaneous	Gray duct seam sealant on metal	Throughout above drop ceiling	300	SF	Good		NAD	Low	n/a	H6-1	n/a	
DC	65	6	Basement	BL-105 Hallway	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	1600	SF	Good		NAD	Low	n/a	H6-1	n/a	
DC	65	6	Basement	BL-105 Hallway	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	30	LF	Good		NAD	Low	n/a	H6-1	n/a	
DC	66	6	Basement	BL-105U; BL-105UU	Miscellaneous	12" x 12" Yellow with Gold specks floor tile	Throughout	50	SF	Good		NAD	High	n/a	H6-1	n/a	
DC	66	6	Basement	BL-105U; BL-105UU	Miscellaneous	Yellow floor tile mastic	Throughout	50	SF	Good		NAD	Low	n/a	H6-1	n/a	
DC	66	6	Basement	BL-105U; BL-105UU	Miscellaneous	2' x 2' Rough ceiling tile	Throughout	850	SF	Good		NAD	Medium	n/a	H6-1	n/a	
DC	66	6	Basement	BL-105U; BL-105UU	Miscellaneous	Gray duct seam sealant on metal	Throughout above drop ceiling	80	SF	Good		NAD	Low	n/a	H6-1	n/a	
DC	66	6	Basement	BL-105U; BL-105UU	Miscellaneous	Drywall and joint compound	Throughout	2800	SF	Good		NAD	High	n/a	H6-1	n/a	
DC	67	6	Basement	BK-100	Miscellaneous	Red fire stop	Throughout	5	SF	Good		NAD	High	n/a	H6-1	n/a	
DC	67	6	Basement	BK-100	Surfacing	Gray spray-on fire proofing	Throughout	100	SF	Good		NAD	Medium	n/a	H6-1	n/a	
DC	67	6	Basement	BK-100	Miscellaneous	White expansion joint caulk	Throughout	60	LF	Good		2% Chrysotile	High	O & M	H6-1	05	
DC	68	6	Basement	Stair #19	Miscellaneous	12" x 12" Lt. Green mottle floor tile	Throughout	140	SF	Good		NAD	High	n/a	H6-1	n/a	
DC	68	6	Basement	Stair #19	Miscellaneous	Yellow floor tile mastic	Throughout	140	SF	Good		NAD	Low	n/a	H6-1	n/a	
DC	68	6	Basement	Stair #19	Miscellaneous	Tan stair tread mastic	Throughout	140	SF	Good		NAD	Low	n/a	H6-1	n/a	
DC	68	6	Basement	Stair #19	Miscellaneous	Black floor tile mastic	Throughout	140	SF	Good	Residual	4%-5% Chrysotile	Low	O & M	H6-1	02	
DC	68	6	Basement	Stair #19	Miscellaneous	Tan baseboard mastic	Throughout	50	SF	Good		NAD	Low	n/a	H6-1	n/a	

**Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6**

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	69	6	Basement	Garage North Storage	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout	60	SF	Good		NAD	Medium	n/a	H6-1	n/a	
DC	69	6	Basement	Garage North Storage	Miscellaneous	Drywall and joint compound	South wall	60	SF	Good	No Joint Compound	NAD	High	n/a	H6-1	n/a	
DC	70	6	Basement	Garage West Storage	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout	225	SF	Good		NAD	Medium	n/a	H6-1	n/a	
DC	70	6	Basement	Garage West Storage	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	160	SF	Good		NAD	Low	n/a	H6-1	n/a	
DC	70	6	Basement	Garage West Storage	Miscellaneous	Fire door	East and South walls	2 @ 4' x 7'	Doors	Good	Labeled/Wood	Assumed ACM	High	O & M	H6-1	N/A	
DC	71	6	Basement	BK-104	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout	200	SF	Good		NAD	Medium	n/a	H6-1	n/a	
DC	71	6	Basement	BK-104	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	200	SF	Damaged	<1 SF Damaged	5%-10% Chrysotile	High	Repair	H6-1	01	
DC	71	6	Basement	BK-104	Miscellaneous	Black floor tile mastic	Throughout	200	SF	Good		4%-5% Chrysotile	Low	O & M	H6-1	02	
DC	71	6	Basement	BK-104	Miscellaneous	Brown baseboard mastic	Throughout	22	LF	Good		NAD	Low	n/a	H6-1	n/a	
DC	71	6	Basement	BK-104	Miscellaneous	Drywall and joint compound	Center wall	120	SF	Good	No Joint Compound	NAD	High	n/a	H6-1	n/a	
DC	71	6	Basement	BK-104	Miscellaneous	Fire door	East, West and South walls	3 @ 3' x 7'	Doors	Good	Labeled/Metal	Assumed ACM	High	O & M	H6-1	N/A	
DC	71	6	Basement	BK-104	Miscellaneous	White expansion joint caulk	Northwest corner	20	LF	Good		2% Chrysotile	High	O & M	H6-1	05	
DC	71	6	Basement	BK-104	Miscellaneous	Flange gaskets	Throughout	8	Flange Gaskets	Good		Assumed ACM	Low	O & M	H6-1	N/A	
DC	71	6	Basement	BK-104	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	200	SF	Good		NAD	Low	n/a	H6-1	n/a	
DC	71	6	Basement	BK-104	Miscellaneous	Blue fire stop	East wall	2	SF	Good		NAD	High	n/a	H6-1	n/a	
DC	72	6	Basement	BK-103	Miscellaneous	12" x 12" Off-white with tan specks floor tile	Throughout	225	SF	Good		NAD	High	n/a	H6-1	n/a	
DC	72	6	Basement	BK-103	Miscellaneous	2' x 4' Gouged and dot ceiling tile	Throughout	200	SF	Good		NAD	Medium	n/a	H6-1	n/a	
DC	72	6	Basement	BK-103	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout	24	SF	Good		NAD	Medium	n/a	H6-1	n/a	
DC	72	6	Basement	BK-103	Miscellaneous	Yellow floor tile mastic	Throughout	225	SF	Good		NAD	Low	n/a	H6-1	n/a	
DC	72	6	Basement	BK-103	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	60	SF	Good		NAD	Low	n/a	H6-1	n/a	
DC	72	6	Basement	BK-103	Miscellaneous	Gray duct seam sealant on metal	Throughout above drop ceiling	40	SF	Good		NAD	Low	n/a	H6-1	n/a	
DC	72	6	Basement	BK-103	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	200	SF	Good		NAD	Low	n/a	H6-1	n/a	
DC	73	6	Basement	GG-100	Miscellaneous	Drywall and joint compound	Throughout	40	SF	Good		NAD	High	n/a	H6-1	n/a	
DC	73	6	Basement	GG-100	Miscellaneous	Red fire stop	Throughout	6	SF	Good		NAD	Medium	n/a	H6-1	n/a	
DC	73	6	Basement	GG-100	Miscellaneous	Tan duct seam sealant on metal	Throughout	30	SF	Good		2% Chrysotile	Medium	O & M	H6-1	04	
DC	73	6	Basement	GG-100	Miscellaneous	Blue fire stop	Throughout	1	SF	Good		NAD	Medium	n/a	H6-1	n/a	
DC	74	6	Basement	BK-110	Miscellaneous	2' x 2' Width-wise gouged ceiling tile	Throughout	1400	SF	Good		NAD	Medium	n/a	H6-1	n/a	
DC	74	6	Basement	BK-110	Miscellaneous	Fire door	North, South and West walls	3 @ 3' x 7'	Doors	Good	Labeled/Metal	Assumed ACM	High	O & M	H6-1	N/A	
DC	74	6	Basement	BK-110	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	800	SF	Good		NAD	Low	n/a	H6-1	n/a	
DC	74	6	Basement	BK-110	Miscellaneous	Tan pin mastic	Throughout above drop ceiling	800	SF	Good		NAD	Low	n/a	H6-1	n/a	

**Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6**

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	74	6	Basement	BK-110	Miscellaneous	Drywall and joint compound	Throughout	128	SF	Good		NAD	High	n/a	H6-1	n/a	
DC	74	6	Basement	BK-110	Miscellaneous	12" x 12" Lt. Pink mottle floor tile	Throughout	80	SF	Good		NAD	High	n/a	H6-1	n/a	
DC	74	6	Basement	BK-110	Miscellaneous	Yellow floor tile mastic	Throughout	80	SF	Good		NAD	Low	n/a	H6-1	n/a	
DC	74	6	Basement	BK-110	Miscellaneous	Tan baseboard mastic	Throughout	36	LF	Good		NAD	Low	n/a	H6-1	n/a	
DC	75	6	Basement	BK-110A	Miscellaneous	Black vapor barrier	South and West walls	275	SF	Good		NAD	High	n/a	H6-1	n/a	
DC	75	6	Basement	BK-110A	Miscellaneous	Fire door	East wall	1 @ 3' x 7'	Doors	Good	Labeled/Metal	Assumed ACM	High	O & M	H6-1	N/A	
DC	75	6	Basement	BK-110A	Surfacing	Gray spray-on fire proofing	Throughout	275	SF	Good		NAD	Low	n/a	H6-1	n/a	
DC	75	6	Basement	BK-110A	Miscellaneous	White pipe seam sealant on paper	Throughout	5	LF	Good		NAD	Medium	n/a	H6-1	n/a	
DC	76	6	Basement	BK-110B	Miscellaneous	Fire door	West wall	2 @ 4' x 7'	Doors	Good	Labeled/Metal	Assumed ACM	High	O & M	H6-1	N/A	
DC	76	6	Basement	BK-110B	Miscellaneous	White duct seam sealant on paper	Throughout	360	SF	Good		NAD	High	n/a	H6-1	n/a	
DC	76	6	Basement	BK-110B	Miscellaneous	Tan pin mastic	Throughout	360	SF	Good		NAD	Low	n/a	H6-1	n/a	
DC	76	6	Basement	BK-110B	Miscellaneous	White pipe seam sealant on paper	Throughout	30	LF	Good		NAD	High	n/a	H6-1	n/a	
DC	76	6	Basement	BK-110B	Miscellaneous	Gray duct seam sealant on metal	Throughout	25	SF	Good		NAD	High	n/a	H6-1	n/a	
DC	76	6	Basement	BK-110B	Miscellaneous	Red fire stop	Throughout	6	SF	Good		NAD	High	n/a	H6-1	n/a	
DC	76	6	Basement	BK-110B	Surfacing	Gray spray-on fire proofing	Throughout	100	SF	Good		NAD	Medium	n/a	H6-1	n/a	
DC	77	6	Basement	BK-109B	Miscellaneous	Yellow carpet mastic	Throughout under carpet	120	SF	Good		NAD	Low	n/a	H6-1	n/a	
DC	77	6	Basement	BK-109B	Miscellaneous	12" x 12" Lt. Pink mottle floor tile	Throughout under carpet	120	SF	Good		NAD	Low	n/a	H6-1	n/a	
DC	77	6	Basement	BK-109B	Miscellaneous	Yellow floor tile mastic	Throughout under carpet	120	SF	Good		NAD	Low	n/a	H6-1	n/a	
DC	77	6	Basement	BK-109B	Miscellaneous	2' x 2' Width-wise gouged ceiling tile	Throughout	120	SF	Good		NAD	Medium	n/a	H6-1	n/a	
DC	77	6	Basement	BK-109B	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	30	SF	Good		NAD	Low	n/a	H6-1	n/a	
DC	77	6	Basement	BK-109B	Miscellaneous	Drywall and joint compound	West and South walls	230	SF	Good		NAD	High	n/a	H6-1	n/a	
DC	77	6	Basement	BK-109B	Miscellaneous	Tan baseboard mastic	Throughout	46	LF	Good		NAD	Low	n/a	H6-1	n/a	
DC	78	6	Basement	BK-109	Miscellaneous	12" x 12" Lt. Pink mottle floor tile	Throughout North entrance	80	SF	Good		NAD	High	n/a	H6-1	n/a	
DC	78	6	Basement	BK-109	Miscellaneous	Yellow floor tile mastic	Throughout North entrance	80	SF	Good		NAD	Low	n/a	H6-1	n/a	
DC	78	6	Basement	BK-109	Miscellaneous	2' x 2' Width-wise gouged ceiling tile	Throughout	1300	SF	Good		NAD	Medium	n/a	H6-1	n/a	
DC	78	6	Basement	BK-109	Miscellaneous	Tan baseboard mastic	Throughout North entrance	30	LF	Good		NAD	Low	n/a	H6-1	n/a	
DC	78	6	Basement	BK-109	Miscellaneous	Drywall and joint compound	Throughout	380	SF	Good		NAD	High	n/a	H6-1	n/a	
DC	78	6	Basement	BK-109	Miscellaneous	Fire door	North and South walls	2 @ 3' x 7'	Doors	Good	Labeled/metal	Assumed ACM	High	O & M	H6-1	N/A	
DC	78	6	Basement	BK-109	Miscellaneous	Gray duct seam sealant on metal	Throughout above drop ceiling	270	SF	Good		NAD	Low	n/a	H6-1	n/a	
DC	78	6	Basement	BK-109	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	1300	SF	Good		NAD	Low	n/a	H6-1	n/a	
DC	79	6	Basement	BK109A	Miscellaneous	2' x 2' Width-wise gouged ceiling tile	Throughout	580	SF	Good		NAD	Medium	n/a	H6-1	n/a	

Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	79	6	Basement	BK109A	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	811	SF	Good		NAD	Low	n/a	H6-1	n/a	
DC	79	6	Basement	BK109A	Miscellaneous	Fire door	South wall	1 @ 3' x 7'	Doors	Good	Labeled/Metal	Assumed ACM	High	O & M	H6-1	N/A	
DC	79	6	Basement	BK109A	Miscellaneous	Drywall and joint compound	Throughout Bulkhead	35	SF	Good		NAD	High	n/a	H6-1	n/a	
DC	80	6	Basement	BK-108	Miscellaneous	12" x 12" Off-white mottle floor tile	Throughout	90	SF	Good		NAD	High	n/a	H6-1	n/a	
DC	80	6	Basement	BK-108	Miscellaneous	Yellow floor tile mastic	Throughout	90	SF	Good		NAD	Low	n/a	H6-1	n/a	
DC	80	6	Basement	BK-108	Miscellaneous	2' x 2' Width-wise gouged ceiling tile	Throughout	950	SF	Good		NAD	Medium	n/a	H6-1	n/a	
DC	80	6	Basement	BK-108	Miscellaneous	Drywall and joint compound	Throughout	360	SF	Good		NAD	High	n/a	H6-1	n/a	
DC	80	6	Basement	BK-108	Miscellaneous	Fire door	North, South and East walls	5 @ 3' x 7'	Doors	Good	Labeled/Metal	Assumed ACM	High	O & M	H6-1	N/A	
DC	80	6	Basement	BK-108	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	1600	SF	Good		NAD	Low	n/a	H6-1	n/a	
DC	81	6	Basement	BK-107	Miscellaneous	2' x 2' Width-wise gouged ceiling tile	Throughout	200	SF	Good		NAD	Medium	n/a	H6-1	n/a	
DC	81	6	Basement	BK-107	Miscellaneous	Fire door	North wall	1 @ 3' x 7'	Doors	Good	Labeled/Metal	Assumed ACM	High	O & M	H6-1	N/A	
DC	81	6	Basement	BK-107	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	300	SF	Good		NAD	Low	n/a	H6-1	n/a	
DC	82	6	Basement	BK-106	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout	280	SF	Good		NAD	Medium	n/a	H6-1	n/a	
DC	82	6	Basement	BK-106	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	280	SF	Good		5%-10% Chrysotile	High	O & M	H6-1	01	
DC	82	6	Basement	BK-106	Miscellaneous	Black floor tile mastic	Throughout	280	SF	Good		4%-5% Chrysotile	Low	O & M	H6-1	02	
DC	82	6	Basement	BK-106	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-1	n/a	
DC	82	6	Basement	BK-106	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	80	SF	Good		NAD	Low	n/a	H6-1	n/a	
DC	82	6	Basement	BK-106	Miscellaneous	Yellow ceramic tile mastic	Throughout	12	SF	Good		NAD	Low	n/a	H6-1	n/a	
DC	82	6	Basement	BK-106	Miscellaneous	Tan baseboard mastic	Throughout	68	LF	Good		NAD	Low	n/a	H6-1	n/a	
DC	82	6	Basement	BK-106	Miscellaneous	Drywall and joint compound	Throughout	680	SF	Good		NAD	High	n/a	H6-1	n/a	
DC	83	6	Basement	BH-112	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	120	SF	Good		NAD	Medium	n/a	H6-2	n/a	
DC	83	6	Basement	BH-112	Miscellaneous	Yellow carpet mastic	Throughout	120	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	83	6	Basement	BH-112	Miscellaneous	Drywall and joint compound	Throughout	440	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	83	6	Basement	BH-112	Miscellaneous	Tan baseboard mastic	Throughout	44	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	83	6	Basement	BH-112	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	84	6	Basement	BH-111	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	120	SF	Good		NAD	Medium	n/a	H6-2	n/a	
DC	84	6	Basement	BH-111	Miscellaneous	Yellow carpet mastic	Throughout	120	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	84	6	Basement	BH-111	Miscellaneous	Drywall and joint compound	Throughout	440	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	84	6	Basement	BH-111	Miscellaneous	Tan baseboard mastic	Throughout	44	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	84	6	Basement	BH-111	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	85	6	Basement	BH-114	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	120	SF	Good		NAD	Medium	n/a	H6-2	n/a	
DC	85	6	Basement	BH-114	Miscellaneous	Yellow carpet mastic	Throughout	120	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	85	6	Basement	BH-114	Miscellaneous	Drywall and joint compound	Throughout	440	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	85	6	Basement	BH-114	Miscellaneous	Tan baseboard mastic	Throughout	44	LF	Good		NAD	Low	n/a	H6-2	n/a	

**Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6**

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	85	6	Basement	BH-114	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	85	6	Basement	BH-114	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	120	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	86	6	Basement	BH-113	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	120	SF	Good		NAD	Medium	n/a	H6-2	n/a	
DC	86	6	Basement	BH-113	Miscellaneous	Yellow carpet mastic	Throughout	120	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	86	6	Basement	BH-113	Miscellaneous	Drywall and joint compound	Throughout	440	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	86	6	Basement	BH-113	Miscellaneous	Tan baseboard mastic	Throughout	44	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	86	6	Basement	BH-113	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	87	6	Basement	BH-110	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	200	SF	Good		NAD	Medium	n/a	H6-2	n/a	
DC	87	6	Basement	BH-110	Miscellaneous	Yellow carpet mastic	Throughout	200	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	87	6	Basement	BH-110	Miscellaneous	Drywall and joint compound	Throughout	560	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	87	6	Basement	BH-110	Miscellaneous	Tan baseboard mastic	Throughout	56	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	87	6	Basement	BH-110	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	88	6	Basement	BH-109	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	144	SF	Good		NAD	Medium	n/a	H6-2	n/a	
DC	88	6	Basement	BH-109	Miscellaneous	Yellow carpet mastic	Throughout	144	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	88	6	Basement	BH-109	Miscellaneous	Drywall and joint compound	Throughout	480	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	88	6	Basement	BH-109	Miscellaneous	Tan baseboard mastic	Throughout	48	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	88	6	Basement	BH-109	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	89	6	Basement	BH-115	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	89	6	Basement	BH-115	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	230	SF	Good		NAD	Medium	n/a	H6-2	n/a	
DC	89	6	Basement	BH-115	Miscellaneous	Yellow carpet mastic	Throughout	230	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	89	6	Basement	BH-115	Miscellaneous	Drywall and joint compound	Throughout	620	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	89	6	Basement	BH-115	Miscellaneous	Tan baseboard mastic	Throughout	62	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	89	6	Basement	BH-115	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	160	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	89	6	Basement	BH-115	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	240	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	89	6	Basement	BH-115	Miscellaneous	Tan pin mastic	Throughout above drop ceiling	240	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	90	6	Basement	BH-108	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	144	SF	Good		NAD	Medium	n/a	H6-2	n/a	
DC	90	6	Basement	BH-108	Miscellaneous	Yellow carpet mastic	Throughout	144	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	90	6	Basement	BH-108	Miscellaneous	Drywall and joint compound	Throughout	480	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	90	6	Basement	BH-108	Miscellaneous	Tan baseboard mastic	Throughout	48	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	90	6	Basement	BH-108	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	91	6	Basement	BH-107	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	144	SF	Good		NAD	Medium	n/a	H6-2	n/a	
DC	91	6	Basement	BH-107	Miscellaneous	Yellow carpet mastic	Throughout	144	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	91	6	Basement	BH-107	Miscellaneous	Drywall and joint compound	Throughout	480	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	91	6	Basement	BH-107	Miscellaneous	Tan baseboard mastic	Throughout	48	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	91	6	Basement	BH-107	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-2	n/a	

Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	92	6	Basement	BH-118	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	280	SF	Good		NAD	Medium	n/a	H6-2	n/a	
DC	92	6	Basement	BH-118	Miscellaneous	Yellow carpet mastic	Throughout	280	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	92	6	Basement	BH-118	Miscellaneous	Drywall and joint compound	Throughout	680	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	92	6	Basement	BH-118	Miscellaneous	Tan baseboard mastic	Throughout	68	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	92	6	Basement	BH-118	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	240	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	92	6	Basement	BH-118	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	280	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	93	6	Basement	BH-119	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	120	SF	Good		NAD	Medium	n/a	H6-2	n/a	
DC	93	6	Basement	BH-119	Miscellaneous	Yellow carpet mastic	Throughout	120	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	93	6	Basement	BH-119	Miscellaneous	Drywall and joint compound	Throughout	440	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	93	6	Basement	BH-119	Miscellaneous	Tan baseboard mastic	Throughout	44	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	93	6	Basement	BH-119	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	93	6	Basement	BH-119	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	120	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	94	6	Basement	BH-106	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	144	SF	Good		NAD	Medium	n/a	H6-2	n/a	
DC	94	6	Basement	BH-106	Miscellaneous	Yellow carpet mastic	Throughout	144	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	94	6	Basement	BH-106	Miscellaneous	Drywall and joint compound	Throughout	480	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	94	6	Basement	BH-106	Miscellaneous	Tan baseboard mastic	Throughout	48	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	94	6	Basement	BH-106	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	95	6	Basement	BH-105	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	120	SF	Good		NAD	Medium	n/a	H6-2	n/a	
DC	95	6	Basement	BH-105	Miscellaneous	Yellow carpet mastic	Throughout	120	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	95	6	Basement	BH-105	Miscellaneous	Drywall and joint compound	Throughout	440	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	95	6	Basement	BH-105	Miscellaneous	Tan baseboard mastic	Throughout	44	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	95	6	Basement	BH-105	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	96	6	Basement	BH-104	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	120	SF	Good		NAD	Medium	n/a	H6-2	n/a	
DC	96	6	Basement	BH-104	Miscellaneous	Yellow carpet mastic	Throughout	120	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	96	6	Basement	BH-104	Miscellaneous	Drywall and joint compound	Throughout	440	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	96	6	Basement	BH-104	Miscellaneous	Tan baseboard mastic	Throughout	44	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	96	6	Basement	BH-104	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	97	6	Basement	BH-103	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	120	SF	Good		NAD	Medium	n/a	H6-1	n/a	
DC	97	6	Basement	BH-103	Miscellaneous	Yellow carpet mastic	Throughout	120	SF	Good		NAD	Low	n/a	H6-1	n/a	
DC	97	6	Basement	BH-103	Miscellaneous	Drywall and joint compound	Throughout	440	SF	Good		NAD	High	n/a	H6-1	n/a	
DC	97	6	Basement	BH-103	Miscellaneous	Tan baseboard mastic	Throughout	44	LF	Good		NAD	Low	n/a	H6-1	n/a	
DC	97	6	Basement	BH-103	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-1	n/a	
DC	98	6	Basement	BH-102	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	120	SF	Good		NAD	Medium	n/a	H6-1	n/a	
DC	98	6	Basement	BH-102	Miscellaneous	Yellow carpet mastic	Throughout	120	SF	Good		NAD	Low	n/a	H6-1	n/a	
DC	98	6	Basement	BH-102	Miscellaneous	Drywall and joint compound	Throughout	440	SF	Good		NAD	High	n/a	H6-1	n/a	
DC	98	6	Basement	BH-102	Miscellaneous	Tan baseboard mastic	Throughout	44	LF	Good		NAD	Low	n/a	H6-1	n/a	

**Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6**

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	98	6	Basement	BH-102	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-1	n/a	
DC	99	6	Basement	BH-101	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	120	SF	Good		NAD	Medium	n/a	H6-1	n/a	
DC	99	6	Basement	BH-101	Miscellaneous	Yellow carpet mastic	Throughout	120	SF	Good		NAD	Low	n/a	H6-1	n/a	
DC	99	6	Basement	BH-101	Miscellaneous	Drywall and joint compound	Throughout	440	SF	Good		NAD	High	n/a	H6-1	n/a	
DC	99	6	Basement	BH-101	Miscellaneous	Tan baseboard mastic	Throughout	44	LF	Good		NAD	Low	n/a	H6-1	n/a	
DC	99	6	Basement	BH-101	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-1	n/a	
DC	100	6	Basement	BH-123	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-1	n/a	
DC	100	6	Basement	BH-123	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	120	SF	Good		NAD	Low	n/a	H6-1	n/a	
DC	100	6	Basement	BH-123	Miscellaneous	Tan pin mastic	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-1	n/a	
DC	100	6	Basement	BH-123	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	120	SF	Good		NAD	Medium	n/a	H6-1	n/a	
DC	100	6	Basement	BH-123	Miscellaneous	Yellow carpet mastic	Throughout	120	SF	Good		NAD	Low	n/a	H6-1	n/a	
DC	100	6	Basement	BH-123	Miscellaneous	Drywall and joint compound	Throughout	440	SF	Good		NAD	High	n/a	H6-1	n/a	
DC	100	6	Basement	BH-123	Miscellaneous	Tan baseboard mastic	Throughout	44	LF	Good		NAD	Low	n/a	H6-1	n/a	
DC	101	6	Basement	BH-124	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-1	n/a	
DC	101	6	Basement	BH-124	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	120	SF	Good		NAD	Low	n/a	H6-1	n/a	
DC	101	6	Basement	BH-124	Miscellaneous	Tan pin mastic	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-1	n/a	
DC	101	6	Basement	BH-124	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	120	SF	Good		NAD	Medium	n/a	H6-1	n/a	
DC	101	6	Basement	BH-124	Miscellaneous	Yellow carpet mastic	Throughout	120	SF	Good		NAD	Low	n/a	H6-1	n/a	
DC	101	6	Basement	BH-124	Miscellaneous	Drywall and joint compound	Throughout	440	SF	Good		NAD	High	n/a	H6-1	n/a	
DC	101	6	Basement	BH-124	Miscellaneous	Tan baseboard mastic	Throughout	44	LF	Good		NAD	Low	n/a	H6-1	n/a	
DC	102	6	Basement	BH-125	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-1	n/a	
DC	102	6	Basement	BH-125	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	120	SF	Good		NAD	Low	n/a	H6-1	n/a	
DC	102	6	Basement	BH-125	Miscellaneous	Tan pin mastic	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-1	n/a	
DC	102	6	Basement	BH-125	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	120	SF	Good		NAD	Medium	n/a	H6-1	n/a	
DC	102	6	Basement	BH-125	Miscellaneous	Yellow carpet mastic	Throughout	120	SF	Good		NAD	Low	n/a	H6-1	n/a	
DC	102	6	Basement	BH-125	Miscellaneous	Drywall and joint compound	Throughout	440	SF	Good		NAD	High	n/a	H6-1	n/a	
DC	102	6	Basement	BH-125	Miscellaneous	Tan baseboard mastic	Throughout	44	LF	Good		NAD	Low	n/a	H6-1	n/a	
DC	102	6	Basement	BH-125	Miscellaneous	Blue fire stop	Throughout above drop ceiling	2	SF	Good		NAD	Low	n/a	H6-1	n/a	
DC	103	6	Basement	BH-126	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-1	n/a	
DC	103	6	Basement	BH-126	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	120	SF	Good		NAD	Low	n/a	H6-1	n/a	
DC	103	6	Basement	BH-126	Miscellaneous	Tan pin mastic	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-1	n/a	
DC	103	6	Basement	BH-126	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	120	SF	Good		NAD	Medium	n/a	H6-1	n/a	

**Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6**

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	103	6	Basement	BH-126	Miscellaneous	Yellow carpet mastic	Throughout	120	SF	Good		NAD	Low	n/a	H6-1	n/a	
DC	103	6	Basement	BH-126	Miscellaneous	Drywall and joint compound	Throughout	440	SF	Good		NAD	High	n/a	H6-1	n/a	
DC	103	6	Basement	BH-126	Miscellaneous	Tan baseboard mastic	Throughout	44	LF	Good		NAD	Low	n/a	H6-1	n/a	
DC	104	6	Basement	Corridor	Miscellaneous	Yellow carpet mastic	Throughout	1100	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	104	6	Basement	Corridor	Miscellaneous	Drywall and joint compound	Throughout	3000	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	104	6	Basement	Corridor	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	1100	SF	Good		NAD	Medium	n/a	H6-2	n/a	
DC	104	6	Basement	Corridor	Miscellaneous	Tan baseboard mastic	Throughout	300	LF	Good		NAD	Low	n/a	H6-2	n/a	
DC	104	6	Basement	Corridor	Miscellaneous	12" x 12" Lt. Purple mottle floor tile	Throughout	30	SF	Good		NAD	High	n/a	H6-2	n/a	
DC	104	6	Basement	Corridor	Miscellaneous	Yellow floor tile mastic	Throughout	30	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	104	6	Basement	Corridor	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	300	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	104	6	Basement	Corridor	Miscellaneous	Tan pin mastic	Throughout above drop ceiling	300	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	104	6	Basement	Corridor	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	750	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	104	6	Basement	Corridor	Miscellaneous	Gray duct seam sealant on metal	Throughout above drop ceiling	5	SF	Good		NAD	Low	n/a	H6-2	n/a	
DC	105	6	Basement	BK-105	Miscellaneous	12" x 12" Lt. Pink mottle floor tile	Throughout	1888	SF	Good		NAD	High	n/a	H6-1	n/a	
DC	105	6	Basement	BK-105	Miscellaneous	Drywall and joint compound	Throughout	4640	SF	Good		NAD	High	n/a	H6-1	n/a	
DC	105	6	Basement	BK-105	Miscellaneous	Tan baseboard mastic	Throughout	464	LF	Good		NAD	Low	n/a	H6-1	n/a	
DC	105	6	Basement	BK-105	Miscellaneous	Yellow floor tile mastic	Throughout	1888	SF	Good		NAD	Low	n/a	H6-1	n/a	
DC	105	6	Basement	BK-105	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	1888	SF	Good		NAD	Medium	n/a	H6-1	n/a	
DC	105	6	Basement	BK-105	Miscellaneous	12" x 12" Lt. Green mottle floor tile	Throughout	24	SF	Good		NAD	High	n/a	H6-1	n/a	
DC	105	6	Basement	BK-105	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout under non-ACM 12" x 12"	1888	SF	Good		5%-10% Chrysotile	Low	O & M	H6-1	01	
DC	105	6	Basement	BK-105	Miscellaneous	Black floor tile mastic	Throughout	1888	SF	Good		4%-5% Chrysotile	Low	O & M	H6-1	02	
DC	105	6	Basement	BK-105	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	1200	SF	Good		NAD	Low	n/a	H6-1	n/a	
DC	105	6	Basement	BK-105	Miscellaneous	Tan duct seam sealant on metal	Throughout above drop ceiling	200	SF	Good		2% Chrysotile	Low	O & M	H6-1	04	
DC	105	6	Basement	BK-105	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	1500	SF	Good		NAD	Low	n/a	H6-1	n/a	
DC	105	6	Basement	BK-105	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	100	LF	Good		NAD	Low	n/a	H6-1	n/a	
DC	106	6	Basement	BH-137	Miscellaneous	12" x 12" Lt. Pink with Dk. pink specks floor tile	Throughout	700	SF	Good		NAD	High	n/a	H6-1	n/a	
DC	106	6	Basement	BH-137	Miscellaneous	Yellow floor tile mastic	Throughout	768	SF	Good		NAD	Low	n/a	H6-1	n/a	
DC	106	6	Basement	BH-137	Miscellaneous	12" x 12" Pink with Dk. Pink specks floor tile	Throughout	68	SF	Good		NAD	High	n/a	H6-1	n/a	
DC	106	6	Basement	BH-137	Miscellaneous	Drywall and joint compound	Throughout walls and ceiling	2688	SF	Good	Limited access above fixed ceiling	NAD	High	n/a	H6-1	n/a	
DC	106	6	Basement	BH-137	Miscellaneous	Tan baseboard mastic	Throughout	192	LF	Good		NAD	Low	n/a	H6-1	n/a	
DC	106	6	Basement	BH-137	Miscellaneous	Fire door	North and South walls	4 @ 4' x 7'	Doors	Good	Labeled/Wood	Assumed ACM	High	O & M	H6-1	N/A	

Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	106	6	Basement	BH-137	Miscellaneous	White duct seam sealant on foil	Throughout above fixed ceiling	960	SF	Good		NAD	Low	n/a	H6-1	n/a	
DC	106	6	Basement	BH-137	Miscellaneous	Tan duct seam sealant on metal	Throughout above fixed ceiling	125	SF	Good		2% Chrysotile	Low	O & M	H6-1	04	
DC	106	6	Basement	BH-137	Surfacing	Gray spray-on fire proofing	Throughout above fixed ceiling	800	SF	Good		NAD	Low	n/a	H6-1	n/a	
DC	107	6	First	1H-217	Miscellaneous	Gray duct seam sealant on metal	Throughout	65	SF	Good		NAD	Medium	n/a	H6-4	n/a	
DC	107	6	First	1H-217	Miscellaneous	Drywall and joint compound	Throughout	920	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	107	6	First	1H-217	Miscellaneous	Brown baseboard mastic	Throughout	92	LF	Good		NAD	Low	n/a	H6-4	n/a	
DC	107	6	First	1H-217	Miscellaneous	2' x 4' Gouged and dot ceiling tile	Throughout	524	SF	Good		NAD	Medium	n/a	H6-4	n/a	
DC	107	6	First	1H-217	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	524	SF	Good		5%-10% Chrysotile	High	O & M	H6-4	01	
DC	107	6	First	1H-217	Miscellaneous	Black floor tile mastic	Throughout	524	SF	Good		4%-5% Chrysotile	Low	O & M	H6-4	02	
DC	107	6	First	1H-217	Miscellaneous	Fire door	South wall	1 @ 3' x 7'	Doors	Good	Labeled/Metal	Assumed ACM	High	O & M	H6-4	N/A	
DC	107	6	First	1H-217	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	150	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	107	6	First	1H-217	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	450	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	107	6	First	1H-217	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	70	LF	Good		NAD	Low	n/a	H6-4	n/a	
DC	107	6	First	1H-217	Miscellaneous	Tan duct seam sealant on metal	Throughout above drop ceiling	50	SF	Good		2% Chrysotile	Low	O & M	H6-4	04	
DC	108	6	First	1H-218	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	240	SF	Good		5%-10% Chrysotile	High	O & M	H6-4	01	
DC	108	6	First	1H-218	Miscellaneous	Black floor tile mastic	Throughout	240	SF	Good		4%-5% Chrysotile	Low	O & M	H6-4	02	
DC	108	6	First	1H-218	Miscellaneous	2' x 4' Gouged and dot ceiling tile	Throughout	240	SF	Good		NAD	Medium	n/a	H6-4	n/a	
DC	108	6	First	1H-218	Miscellaneous	Brown baseboard mastic	Throughout	64	LF	Good		NAD	Low	n/a	H6-4	n/a	
DC	108	6	First	1H-218	Miscellaneous	Drywall and joint compound	Throughout	640	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	108	6	First	1H-218	Miscellaneous	Fire door	West wall	1 @ 4' x 7'	Doors	Good	Labeled/Metal	Assumed ACM	High	O & M	H6-4	N/A	
DC	108	6	First	1H-218	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	30	LF	Good		NAD	Low	n/a	H6-4	n/a	
DC	108	6	First	1H-218	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	75	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	108	6	First	1H-218	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	160	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	108	6	First	1H-218	Miscellaneous	Gray duct seam sealant on metal	Throughout above drop ceiling	10	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	108	6	First	1H-218	Miscellaneous	Tan duct seam sealant on metal	Throughout above drop ceiling	30	SF	Good		2% Chrysotile	Low	O & M	H6-4	04	
DC	109	6	First	1H-220	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	816	SF	Good		5%-10% Chrysotile	High	O & M	H6-4	01	
DC	109	6	First	1H-220	Miscellaneous	Black floor tile mastic	Throughout	816	SF	Good		4%-5% Chrysotile	Low	O & M	H6-4	02	
DC	109	6	First	1H-220	Miscellaneous	2' x 4' Gouged and dot ceiling tile	Throughout	816	SF	Good		NAD	Medium	n/a	H6-4	n/a	

Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	109	6	First	1H-220	Miscellaneous	Brown baseboard mastic	Throughout	116	LF	Good		NAD	Low	n/a	H6-4	n/a	
DC	109	6	First	1H-220	Miscellaneous	Drywall and joint compound	Throughout	1160	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	109	6	First	1H-220	Miscellaneous	Fire door	South wall	1 @ 4' x 7'	Doors	Good	Labeled/Metal	Assumed ACM	High	O & M	H6-4	N/A	
DC	109	6	First	1H-220	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	50	LF	Good		NAD	Low	n/a	H6-4	n/a	
DC	109	6	First	1H-220	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	160	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	109	6	First	1H-220	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	700	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	109	6	First	1H-220	Miscellaneous	Tan duct seam sealant on metal	Throughout above drop ceiling	160	SF	Good		2% Chrysotile	Low	O & M	H6-4	04	
DC	110	6	First	1H-222	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout closet	48	SF	Good		5%-10% Chrysotile	High	O & M	H6-4	01	
DC	110	6	First	1H-222	Miscellaneous	Black floor tile mastic	Throughout closet	48	SF	Good		4%-5% Chrysotile	Low	O & M	H6-4	02	
DC	110	6	First	1H-222	Miscellaneous	Yellow carpet mastic	Throughout	120	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	110	6	First	1H-222	Miscellaneous	2' x 4' Gouged and dot ceiling tile	Throughout	120	SF	Good		NAD	Medium	n/a	H6-4	n/a	
DC	110	6	First	1H-222	Miscellaneous	Brown baseboard mastic	Throughout	72	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	110	6	First	1H-222	Miscellaneous	Drywall and joint compound	Throughout	760	LF	Good		NAD	High	n/a	H6-4	n/a	
DC	110	6	First	1H-222	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	75	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	110	6	First	1H-222	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	240	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	110	6	First	1H-222	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	10	LF	Good		NAD	Low	n/a	H6-4	n/a	
DC	111	6	First	1H-220A	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	400	SF	Good		5%-10% Chrysotile	High	O & M	H6-4	01	
DC	111	6	First	1H-220A	Miscellaneous	Black floor tile mastic	Throughout	400	SF	Good		4%-5% Chrysotile	Low	O & M	H6-4	02	
DC	111	6	First	1H-220A	Miscellaneous	2' x 4' Gouged and dot ceiling tile	Throughout	400	SF	Good		NAD	Medium	n/a	H6-4	n/a	
DC	111	6	First	1H-220A	Miscellaneous	Brown baseboard mastic	Throughout	80	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	111	6	First	1H-220A	Miscellaneous	Drywall and joint compound	Throughout	800	LF	Good		NAD	High	n/a	H6-4	n/a	
DC	111	6	First	1H-220A	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	70	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	111	6	First	1H-220A	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	360	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	111	6	First	1H-220A	Miscellaneous	Gray duct seam sealant on metal	Throughout above drop ceiling	10	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	112	6	First	1H-224	Miscellaneous	Yellow carpet mastic	Throughout	168	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	112	6	First	1H-224	Miscellaneous	Brown baseboard mastic	Throughout	168	LF	Good		NAD	Low	n/a	H6-4	n/a	
DC	112	6	First	1H-224	Miscellaneous	Drywall and joint compound	Throughout	52	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	112	6	First	1H-224	Miscellaneous	2' x 4' Gouged and dot ceiling tile	Throughout	720	SF	Good		NAD	Medium	n/a	H6-4	n/a	
DC	112	6	First	1H-224	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	330	SF	Good		NAD	Low	n/a	H6-4	n/a	
	112	6	First	1H-224	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	40	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	112	6	First	1H-224	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout closet	48	SF	Good		5%-10% Chrysotile	High	O & M	H6-4	01	

Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	112	6	First	1H-224	Miscellaneous	Black floor tile mastic	Throughout closet	48	SF	Good		4%-5% Chrysotile	Low	O & M	H6-4	02	
DC	113	6	First	1H-220	Miscellaneous	Fire door	South wall	1 @ 4' x 7'	SF	Good	Labeled/Metal	Assumed ACM	High	O & M	H6-4	N/A	
DC	113	6	First	1H-220	Miscellaneous	12" x 12" Off-white mottle floor tile	Throughout	13	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	113	6	First	1H-220	Miscellaneous	12" x 12" Lt. Blue mottle floor tile	Throughout	40	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	113	6	First	1H-220	Miscellaneous	Yellow floor tile mastic	Throughout	53	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	113	6	First	1H-220	Miscellaneous	Yellow carpet mastic	Throughout	130	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	113	6	First	1H-220	Miscellaneous	Tan baseboard mastic	Throughout	50	LF	Good		NAD	Low	n/a	H6-4	n/a	
DC	113	6	First	1H-220	Miscellaneous	Drywall and joint compound	Throughout	500	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	113	6	First	1H-220	Miscellaneous	Tan duct seam sealant on metal	Throughout above drop ceiling	10	SF	Good		2% Chrysotile	Low	O & M	H6-4	04	
DC	113	6	First	1H-220	Miscellaneous	White duct seam sealant on metal	Throughout above drop ceiling	10	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	113	6	First	1H-220	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout	182	SF	Good		NAD	Medium	n/a	H6-4	n/a	
DC	113	6	First	1H-220	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	200	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	114	6	First	1H-201	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	420	SF	Good		5%-10% Chrysotile	High	O & M	H6-4	01	
DC	114	6	First	1H-201	Miscellaneous	Black floor tile mastic	Throughout	420	SF	Good		4%-5% Chrysotile	Low	O & M	H6-4	02	
DC	114	6	First	1H-201	Miscellaneous	Brown baseboard mastic	Throughout	94	LF	Good		NAD	Low	n/a	H6-4	n/a	
DC	114	6	First	1H-201	Miscellaneous	Drywall and joint compound	Throughout	940	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	114	6	First	1H-201	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout	420	SF	Good		NAD	Medium	n/a	H6-4	n/a	
DC	114	6	First	1H-201	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	400	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	114	6	First	1H-201	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	140	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	114	6	First	1H-201	Miscellaneous	Fire door	West wall	1 @ 4' x 7'	Doors	Good	Labeled/Metal	Assumed ACM	High	O & M	H6-4	N/A	
DC	115	6	First	1H-202	Miscellaneous	Lab Countertop	South and West walls	75	SF	Good		Assumed ACM	High	O & M	H6-4	03	
DC	115	6	First	1H-202	Miscellaneous	Drywall and joint compound	Throughout	960	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	115	6	First	1H-202	Miscellaneous	Yellow ceramic tile mastic	Throughout	480	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	115	6	First	1H-202	Miscellaneous	White duct seam sealant on foil	Throughout above fixed ceiling	40	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	115	6	First	1H-202	Surfacing	Gray spray-on fire proofing	Throughout above fixed ceiling	280	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	116	6	First	1H-203	Miscellaneous	Brown baseboard mastic	Throughout	38	LF	Good		NAD	Low	n/a	H6-4	n/a	
DC	116	6	First	1H-203	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	64	SF	Good		5%-10% Chrysotile	High	O & M	H6-4	01	
DC	116	6	First	1H-203	Miscellaneous	Black floor tile mastic	Throughout	64	SF	Good		4%-5% Chrysotile	Low	O & M	H6-4	02	
DC	116	6	First	1H-203	Miscellaneous	Drywall and joint compound	Throughout	380	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	116	6	First	1H-203	Miscellaneous	Tan duct seam sealant on metal	Throughout	10	SF	Good		2% Chrysotile	Medium	O & M	H6-4	04	
DC	116	6	First	1H-203	Miscellaneous	Red fire stop	Throughout	10	SF	Good		NAD	Medium	n/a	H6-4	n/a	
DC	116	6	First	1H-203	Miscellaneous	Blue fire stop	Throughout	3	SF	Good		NAD	Medium	n/a	H6-4	n/a	
DC	116	6	First	1H-203	Surfacing	Gray spray-on fire proofing	Throughout	50	SF	Good		NAD	Medium	n/a	H6-4	n/a	

Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	117	6	First	1H-204	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	18	SF	Good		5%-10% Chrysotile	High	O & M	H6-4	01	
DC	117	6	First	1H-204	Miscellaneous	Brown baseboard mastic	Throughout	18	LF	Good		NAD	Low	n/a	H6-4	n/a	
DC	117	6	First	1H-204	Miscellaneous	Drywall and joint compound	Throughout	180	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	117	6	First	1H-204	Miscellaneous	Red fire stop	Throughout	5	SF	Good		NAD	Medium	n/a	H6-4	n/a	
DC	117	6	First	1H-204	Surfacing	Gray spray-on fire proofing	Throughout	50	SF	Good		NAD	Medium	n/a	H6-4	n/a	
DC	117	6	First	1H-204	Miscellaneous	Gray duct seam sealant on metal	Throughout	5	SF	Good		NAD	Medium	n/a	H6-4	n/a	
DC	117	6	First	1H-204	Miscellaneous	Black floor tile mastic	Throughout	18	SF	Good		4%-5% Chrysotile	Low	O & M	H6-4	02	
DC	118	6	First	1H-205	Miscellaneous	Yellow ceramic tile mastic	Throughout	840	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	118	6	First	1H-205	Miscellaneous	Drywall and joint compound	Throughout	1140	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	118	6	First	1H-205	Miscellaneous	Tan baseboard mastic	West wall	10	LF	Good		NAD	Low	n/a	H6-4	n/a	
DC	118	6	First	1H-205	Miscellaneous	White pipe seam sealant on paper	Throughout above fixed ceiling	70	LF	Good		NAD	Low	n/a	H6-4	n/a	
DC	118	6	First	1H-205	Surfacing	Gray spray-on fire proofing	Throughout above fixed ceiling	300	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	118	6	First	1H-205	Miscellaneous	White duct seam sealant on foil	Throughout above fixed ceiling	60	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	118	6	First	1H-205	Miscellaneous	Fire door	North wall	1 @ 4' x 7'	Doors	Good	Labeled/Metal	Assumed ACM	High	O & M	H6-4	N/A	
DC	119	6	First	1H-206	Miscellaneous	12" x 12" Lt. Blue mottle floor tile	Throughout	400	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	119	6	First	1H-206	Miscellaneous	Yellow floor tile mastic	Throughout	400	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	119	6	First	1H-206	Miscellaneous	Black floor tile mastic	Throughout	400	SF	Good	Residual	4%-5% Chrysotile	Low	O & M	H6-4	02	
DC	119	6	First	1H-206	Miscellaneous	Tan baseboard mastic	Throughout	80	LF	Good		NAD	Low	n/a	H6-4	n/a	
DC	119	6	First	1H-206	Miscellaneous	Drywall and joint compound	Throughout	800	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	119	6	First	1H-206	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout	400	SF	Good		NAD	Medium	n/a	H6-4	n/a	
DC	119	6	First	1H-206	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	110	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	119	6	First	1H-206	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	25	LF	Good		NAD	Low	n/a	H6-4	n/a	
DC	119	6	First	1H-206	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	350	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	119	6	First	1H-206	Miscellaneous	Tan duct seam sealant on metal	Throughout above drop ceiling	110	SF	Good		2% Chrysotile	Low	O & M	H6-4	04	
DC	119	6	First	1H-206	Miscellaneous	Fire door	East wall	1 @ 4' x 7'	Doors	Good	Labeled/Metal	Assumed ACM	Low	O & M	H6-4	N/A	
DC	120	6	First	1H-207	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	45	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	120	6	First	1H-207	Miscellaneous	Gray duct seam sealant on metal	Throughout above drop ceiling	75	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	120	6	First	1H-207	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	260	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	120	6	First	1H-207	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	380	SF	Good		5%-10% Chrysotile	High	O & M	H6-4	01	
DC	120	6	First	1H-207	Miscellaneous	Black floor tile mastic	Throughout	380	SF	Good		4%-5% Chrysotile	Low	O & M	H6-4	02	
DC	120	6	First	1H-207	Miscellaneous	Tan baseboard mastic	Throughout	76	LF	Good		NAD	Low	n/a	H6-4	n/a	
DC	120	6	First	1H-207	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	380	SF	Good		NAD	Medium	n/a	H6-4	n/a	

Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	120	6	First	1H-207	Miscellaneous	Drywall and joint compound	Throughout	760	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	120	6	First	1H-207	Miscellaneous	Fire door	East wall	1 @ 3' x 7'	Doors	Good	Labeled/Metal	Assumed ACM	High	O & M	H6-4	N/A	
DC	121	6	First	1H-208	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	250	SF	Good		5%-10% Chrysotile	High	O & M	H6-4	01	
DC	121	6	First	1H-208	Miscellaneous	Black floor tile mastic	Throughout	250	SF	Good		4%-5% Chrysotile	Low	O & M	H6-4	02	
DC	121	6	First	1H-208	Miscellaneous	Tan baseboard mastic	Throughout	64	LF	Good		NAD	Low	n/a	H6-4	n/a	
DC	121	6	First	1H-208	Miscellaneous	Drywall and joint compound	Throughout	640	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	121	6	First	1H-208	Miscellaneous	2' x 4' Gouged and dot ceiling tile	Throughout	250	SF	Good		NAD	Medium	n/a	H6-4	n/a	
DC	121	6	First	1H-208	Miscellaneous	Tan duct seam sealant on metal	Throughout above drop ceiling	50	SF	Good		2% Chrysotile	Low	O & M	H6-4	04	
DC	121	6	First	1H-208	Miscellaneous	Gray duct seam sealant on metal	Throughout above drop ceiling	50	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	121	6	First	1H-208	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	180	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	121	6	First	1H-208	Miscellaneous	Fire door	East wall	1 @ 3' x 7'	Doors	Good	Labeled/Metal	Assumed ACM	High	O & M	H6-4	N/A	
DC	122	6	First	1H-209	Miscellaneous	12" x 12" Lt. Blue mottle floor tile	Throughout	370	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	122	6	First	1H-209	Miscellaneous	Yellow floor tile mastic	Throughout	370	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	122	6	First	1H-209	Miscellaneous	Black floor tile mastic	Throughout	370	SF	Good	Residual	4%-5% Chrysotile	Low	O & M	H6-4	02	
DC	122	6	First	1H-209	Miscellaneous	Tan baseboard mastic	Throughout	66	LF	Good		NAD	Low	n/a	H6-4	n/a	
DC	122	6	First	1H-209	Miscellaneous	Drywall and joint compound	Throughout	660	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	122	6	First	1H-209	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout	370	SF	Good		NAD	Medium	n/a	H6-4	n/a	
DC	122	6	First	1H-209	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	300	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	122	6	First	1H-209	Miscellaneous	Gray duct seam sealant on metal	Throughout above drop ceiling	90	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	122	6	First	1H-209	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	10	LF	Good		NAD	Low	n/a	H6-4	n/a	
DC	123	6	First	1H-210	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	123	6	First	1H-210	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	10	LF	Good		NAD	Low	n/a	H6-4	n/a	
DC	123	6	First	1H-210	Miscellaneous	Gray duct seam sealant on metal	Throughout above drop ceiling	30	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	123	6	First	1H-210	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	350	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	123	6	First	1H-210	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	440	SF	Good		5%-10% Chrysotile	High	O & M	H6-4	01	
DC	123	6	First	1H-210	Miscellaneous	Black floor tile mastic	Throughout	440	SF	Good		4%-5% Chrysotile	Low	O & M	H6-4	02	
DC	123	6	First	1H-210	Miscellaneous	Tan baseboard mastic	Throughout	84	LF	Good		NAD	Low	n/a	H6-4	n/a	
DC	123	6	First	1H-210	Miscellaneous	Drywall and joint compound	Throughout	840	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	123	6	First	1H-210	Miscellaneous	2' x 4' Gouged and dot ceiling tile	Throughout	440	SF	Good		NAD	Medium	n/a	H6-4	n/a	
DC	123	6	First	1H-210	Miscellaneous	Fire door	East wall	1 @ 3' x 7'	Doors	Good	Labeled/Metal	Assumed ACM	High	O & M	H6-4	N/A	

Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	124	6	First	1H-211	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	180	SF	Good		5%-10% Chrysotile	High	O & M	H6-4	01	
DC	124	6	First	1H-211	Miscellaneous	Black floor tile mastic	Throughout	180	SF	Good		4%-5% Chrysotile	Low	O & M	H6-4	02	
DC	124	6	First	1H-211	Miscellaneous	Drywall and joint compound	Throughout	1120	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	124	6	First	1H-211	Miscellaneous	Brown baseboard mastic	Throughout	56	LF	Good		NAD	Low	n/a	H6-4	n/a	
DC	124	6	First	1H-211	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout	180	SF	Good		NAD	Medium	n/a	H6-4	n/a	
DC	124	6	First	1H-211	Miscellaneous	Fire door	East wall	1 @ 3' x 7'	Doors	Good	Labeled/Metal	Assumed ACM	High	O & M	H6-4	N/A	
DC	124	6	First	1H-211	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	200	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	124	6	First	1H-211	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	30	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	124	6	First	1H-211	Miscellaneous	Yellow ceramic tile mastic	Throughout bathroom	160	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	124	6	First	1H-211	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	25	LF	Good		NAD	Low	n/a	H6-4	n/a	
DC	125	6	First	1H-213; 1H-214	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	180	SF	Good		5%-10% Chrysotile	High	O & M	H6-4	01	
DC	125	6	First	1H-213; 1H-214	Miscellaneous	Black floor tile mastic	Throughout	180	SF	Good		4%-5% Chrysotile	Low	O & M	H6-4	02	
DC	125	6	First	1H-213; 1H-214	Miscellaneous	Drywall and joint compound	Throughout	1120	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	125	6	First	1H-213; 1H-214	Miscellaneous	Brown baseboard mastic	Throughout	56	LF	Good		NAD	Low	n/a	H6-4	n/a	
DC	125	6	First	1H-213; 1H-214	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout	180	SF	Good		NAD	Medium	n/a	H6-4	n/a	
DC	125	6	First	1H-213; 1H-214	Miscellaneous	Fire door	East wall	1 @ 3' x 7'	Doors	Good	Labeled/Metal	Assumed ACM	High	O & M	H6-4	N/A	
DC	125	6	First	1H-213; 1H-214	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	200	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	125	6	First	1H-213; 1H-214	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	30	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	125	6	First	1H-213; 1H-214	Miscellaneous	Yellow ceramic tile mastic	Throughout bathroom	160	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	125	6	First	1H-213; 1H-214	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	25	LF	Good		NAD	Low	n/a	H6-4	n/a	
DC	126	6	First	1H-215	Miscellaneous	Drywall and joint compound	Throughout	320	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	126	6	First	1H-215	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	48	SF	Good		5%-10% Chrysotile	High	O & M	H6-4	01	
DC	126	6	First	1H-215	Miscellaneous	Black floor tile mastic	Throughout	48	SF	Good		4%-5% Chrysotile	Low	O & M	H6-4	02	
DC	126	6	First	1H-215	Miscellaneous	Brown baseboard mastic	Throughout	28	LF	Good		NAD	Low	n/a	H6-4	n/a	
DC	126	6	First	1H-215	Miscellaneous	Fire door	South wall	1 @ 3' x 7'	Doors	Good	Labeled/Metal	Assumed ACM	High	O & M	H6-4	N/A	
DC	127	6	First	1H-216	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	18	LF	Good		NAD	Low	n/a	H6-4	n/a	
DC	127	6	First	1H-216	Miscellaneous	Drywall and joint compound	Throughout	320	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	127	6	First	1H-216	Miscellaneous	Brown baseboard mastic	Throughout	28	LF	Good		NAD	Low	n/a	H6-4	n/a	
DC	127	6	First	1H-216	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout	48	SF	Good		NAD	Medium	n/a	H6-4	n/a	
DC	127	6	First	1H-216	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	48	SF	Good		5%-10% Chrysotile	High	O & M	H6-4	01	

Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	127	6	First	1H-216	Miscellaneous	Black floor tile mastic	Throughout	48	SF	Good		4%-5% Chrysotile	Low	O & M	H6-4	02	
DC	127	6	First	1H-216	Miscellaneous	Fire door	East wall	1 @ 3' x 7'	Doors	Good	Labeled/Metal	Assumed ACM	High	O & M	H6-4	N/A	
DC	127	6	First	1H-216	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	50	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	128	6	First	Vestibule	Miscellaneous	Brown baseboard mastic	Throughout	44	LF	Good		NAD	Low	n/a	H6-4	n/a	
DC	128	6	First	Vestibule	Miscellaneous	Drywall and joint compound	Throughout	440	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	128	6	First	Vestibule	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	96	SF	Good		5%-10% Chrysotile	High	O & M	H6-4	01	
DC	128	6	First	Vestibule	Miscellaneous	Black floor tile mastic	Throughout	96	SF	Good		4%-5% Chrysotile	Low	O & M	H6-4	02	
DC	128	6	First	Vestibule	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout	96	SF	Good		NAD	Medium	n/a	H6-4	n/a	
DC	128	6	First	Vestibule	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	128	6	First	Vestibule	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	18	LF	Good		NAD	Low	n/a	H6-4	n/a	
DC	129	6	First	1H-200	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	3296	SF	Good		5%-10% Chrysotile	High	O & M	H6-4	01	
DC	129	6	First	1H-200	Miscellaneous	Black floor tile mastic	Throughout	3296	SF	Good		4%-5% Chrysotile	Low	O & M	H6-4	02	
DC	129	6	First	1H-200	Miscellaneous	Brown baseboard mastic	Throughout	425	LF	Good		NAD	Low	n/a	H6-4	n/a	
DC	129	6	First	1H-200	Miscellaneous	Drywall and joint compound	Throughout	4250	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	129	6	First	1H-200	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout	3296	SF	Good		NAD	Medium	n/a	H6-4	n/a	
DC	129	6	First	1H-200	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	3000	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	129	6	First	1H-200	Miscellaneous	Fire door	Hallway West wall	1 @ 4' x 7'	Doors	Good	Labeled/Wood	Assumed ACM	High	O & M	H6-4	N/A	
DC	129	6	First	1H-200	Miscellaneous	Yellow ceramic tile mastic	West wall	80	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	129	6	First	1H-200	Miscellaneous	Tan duct seam sealant on metal	Throughout above drop ceiling	450	SF	Good		2% Chrysotile	Low	O & M	H6-4	04	
DC	129	6	First	1H-200	Miscellaneous	Gray duct seam sealant on metal	Throughout above drop ceiling	300	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	129	6	First	1H-200	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	2100	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	129	6	First	1H-200	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	340	LF	Good		NAD	Low	n/a	H6-4	n/a	
DC	129	6	First	1H-200	Miscellaneous	Red fire stop	Throughout above drop ceiling	30	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	130	6	First	Library	Miscellaneous	12" x 12" Lt. Green marble floor tile	Throughout	1242	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	130	6	First	Library	Miscellaneous	12" x 12" Dk. Green marble floor tile	Throughout	90	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	130	6	First	Library	Miscellaneous	Yellow floor tile mastic	Throughout	1332	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	130	6	First	Library	Miscellaneous	Tan baseboard mastic	Throughout	94	LF	Good		NAD	Low	n/a	H6-4	n/a	
DC	130	6	First	Library	Miscellaneous	Drywall and joint compound	Throughout	940	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	130	6	First	Library	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	1332	SF	Good		NAD	Medium	n/a	H6-4	n/a	
DC	130	6	First	Library	Miscellaneous	Black mastic on metal window frame	East and South walls	8 @ 6' x 3' 8 @ 8' x 9'	Windows	Good		NAD	High	n/a	H6-4	n/a	
DC	130	6	First	Library	Miscellaneous	White duct seam sealant on metal	Throughout above drop ceiling	320	SF	Good		NAD	Low	n/a	H6-4	n/a	

Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	130	6	First	Library	Miscellaneous	Red fire stop	Throughout above drop ceiling	15	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	130	6	First	Library	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	1200	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	130	6	First	Library	Miscellaneous	Black window caulk	East and South walls	416	LF	Good		NAD	High	n/a	H6-4	n/a	
DC	131	6	First	1L-131	Miscellaneous	Fire door	East wall	1 @ 3' x 7'	Doors	Good	Labeled/Wood	Assumed ACM	High	O & M	H6-4	N/A	
DC	131	6	First	1L-131	Miscellaneous	Drywall and joint compound	Throughout	360	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	131	6	First	1L-131	Miscellaneous	Red fire stop	Throughout	5	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	131	6	First	1L-131	Miscellaneous	Gray duct seam sealant on metal	Throughout	5	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	131	6	First	1L-131	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	80	SF	Good		NAD	Medium	n/a	H6-4	n/a	
DC	131	6	First	1L-131	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	25	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	132	6	First	1L-132	Miscellaneous	Fire door	East wall	1 @ 4' x 7'	Doors	Good	Labeled/Wood	Assumed ACM	High	O & M	H6-4	N/A	
DC	132	6	First	1L-132	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	280	SF	Good		NAD	Medium	n/a	H6-4	n/a	
DC	132	6	First	1L-132	Miscellaneous	Drywall and joint compound	Throughout	860	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	132	6	First	1L-132	Miscellaneous	Red fire stop	Throughout above drop ceiling	2	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	132	6	First	1L-132	Miscellaneous	Off-white with Blue specks floor sheeting	Throughout	280	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	132	6	First	1L-132	Miscellaneous	Tan floor sheeting mastic	Throughout	280	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	133	6	First	1L-133	Miscellaneous	Drywall and joint compound	Throughout	550	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	133	6	First	1L-133	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	240	SF	Good		NAD	Medium	n/a	H6-4	n/a	
DC	133	6	First	1L-133	Miscellaneous	12" x 12" Lt. Purple mottle floor tile	Throughout	240	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	133	6	First	1L-133	Miscellaneous	Yellow floor tile mastic	Throughout	240	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	133	6	First	1L-133	Miscellaneous	Tan baseboard mastic	Throughout	62	LF	Good		NAD	Low	n/a	H6-4	n/a	
DC	134	6	First	1L-134	Miscellaneous	12" x 12" Lt. Purple mottle floor tile	Throughout	388	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	134	6	First	1L-134	Miscellaneous	Yellow floor tile mastic	Throughout	388	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	134	6	First	1L-134	Miscellaneous	Drywall and joint compound	Throughout	1140	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	134	6	First	1L-134	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	388	SF	Good		NAD	Medium	n/a	H6-4	n/a	
DC	134	6	First	1L-134	Miscellaneous	Red fire stop	Throughout	8	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	134	6	First	1L-134	Miscellaneous	Gray duct seam sealant on metal	Throughout	8	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	134	6	First	1L-134	Miscellaneous	Tan baseboard mastic	Throughout	110	LF	Good		NAD	Low	n/a	H6-4	n/a	
DC	134	6	First	1L-134	Miscellaneous	Fire door	South wall	2 @ 3' x 7'	Doors	Good	Labeled/Metal	Assumed ACM	High	O & M	H6-4	N/A	
DC	135	6	First	1L-117	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	88	SF	Good		NAD	Medium	n/a	H6-4	n/a	
DC	135	6	First	1L-117	Miscellaneous	Fire door	West wall	1 @ 3' x 7'	Doors	Good	Labeled/Metal	Assumed ACM	High	O & M	H6-4	N/A	
DC	135	6	First	1L-117	Miscellaneous	12" x 12" Lt. Blue mottle floor tile	Throughout	88	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	135	6	First	1L-117	Miscellaneous	Yellow floor tile mastic	Throughout	88	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	135	6	First	1L-117	Miscellaneous	Tan baseboard mastic	Throughout	40	LF	Good		NAD	Low	n/a	H6-4	n/a	

Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	135	6	First	1L-117	Miscellaneous	Drywall and joint compound	Throughout walls and ceiling	468	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	135	6	First	1L-117	Miscellaneous	White duct seam sealant on foil	Throughout above fixed ceiling	50	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	136	6	First	1L-118	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	120	SF	Good		NAD	Medium	n/a	H6-4	n/a	
DC	136	6	First	1L-118	Miscellaneous	Drywall and joint compound	Throughout	560	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	136	6	First	1L-118	Miscellaneous	Yellow carpet mastic	Throughout	120	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	136	6	First	1L-118	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	20	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	136	6	First	1L-118	Miscellaneous	Tan baseboard mastic	Throughout	44	LF	Good		NAD	Low	n/a	H6-4	n/a	
DC	137	6	First	1L-120	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	120	SF	Good		NAD	Medium	n/a	H6-4	n/a	
DC	137	6	First	1L-120	Miscellaneous	Drywall and joint compound	Throughout	560	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	137	6	First	1L-120	Miscellaneous	Yellow carpet mastic	Throughout	120	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	137	6	First	1L-120	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	20	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	137	6	First	1L-120	Miscellaneous	Tan baseboard mastic	Throughout	44	LF	Good		NAD	Low	n/a	H6-4	n/a	
DC	138	6	First	1L-122	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	120	SF	Good		NAD	Medium	n/a	H6-4	n/a	
DC	138	6	First	1L-122	Miscellaneous	Drywall and joint compound	Throughout	560	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	138	6	First	1L-122	Miscellaneous	Yellow carpet mastic	Throughout	120	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	138	6	First	1L-122	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	20	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	138	6	First	1L-122	Miscellaneous	Tan baseboard mastic	Throughout	44	LF	Good		NAD	Low	n/a	H6-4	n/a	
DC	139	6	First	1L-124	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	120	SF	Good		NAD	Medium	n/a	H6-4	n/a	
DC	139	6	First	1L-124	Miscellaneous	Drywall and joint compound	Throughout	560	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	139	6	First	1L-124	Miscellaneous	Yellow carpet mastic	Throughout	120	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	139	6	First	1L-124	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	20	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	139	6	First	1L-124	Miscellaneous	Tan baseboard mastic	Throughout	44	LF	Good		NAD	Low	n/a	H6-4	n/a	
DC	140	6	First	1L-126	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	120	SF	Good		NAD	Medium	n/a	H6-4	n/a	
DC	140	6	First	1L-126	Miscellaneous	Drywall and joint compound	Throughout	560	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	140	6	First	1L-126	Miscellaneous	Yellow carpet mastic	Throughout	120	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	140	6	First	1L-126	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	20	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	140	6	First	1L-126	Miscellaneous	Tan baseboard mastic	Throughout	44	LF	Good		NAD	Low	n/a	H6-4	n/a	
DC	141	6	First	1L-130	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	144	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	141	6	First	1L-130	Miscellaneous	Yellow carpet mastic	Throughout	144	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	141	6	First	1L-130	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	30	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	141	6	First	1L-130	Miscellaneous	Tan baseboard mastic	Throughout	48	LF	Good		NAD	Low	n/a	H6-4	n/a	
DC	141	6	First	1L-130	Miscellaneous	Drywall and joint compound	Throughout	624	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	141	6	First	1L-130	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	2	LF	Good		NAD	Low	n/a	H6-4	n/a	
DC	142	6	First	1L-129	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	144	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	142	6	First	1L-129	Miscellaneous	Yellow carpet mastic	Throughout	144	SF	Good		NAD	Low	n/a	H6-4	n/a	

**Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6**

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	142	6	First	1L-129	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	30	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	142	6	First	1L-129	Miscellaneous	Tan baseboard mastic	Throughout	48	LF	Good		NAD	Low	n/a	H6-4	n/a	
DC	142	6	First	1L-129	Miscellaneous	Drywall and joint compound	Throughout	624	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	142	6	First	1L-129	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	2	LF	Good		NAD	Low	n/a	H6-4	n/a	
DC	143	6	First	1L-128	Miscellaneous	Drywall and joint compound	Throughout	684	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	143	6	First	1L-128	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	168	SF	Good		NAD	Medium	n/a	H6-4	n/a	
DC	143	6	First	1L-128	Miscellaneous	Yellow carpet mastic	Throughout	168	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	143	6	First	1L-128	Miscellaneous	Tan baseboard mastic	Throughout	52	LF	Good		NAD	Low	n/a	H6-4	n/a	
DC	143	6	First	1L-128	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	30	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	143	6	First	1L-128	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	2	LF	Good		NAD	Low	n/a	H6-4	n/a	
DC	144	6	First	1L-127	Miscellaneous	Drywall and joint compound	Throughout	682	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	144	6	First	1L-127	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	160	SF	Good		NAD	Medium	n/a	H6-4	n/a	
DC	144	6	First	1L-127	Miscellaneous	Yellow carpet mastic	Throughout	160	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	144	6	First	1L-127	Miscellaneous	Tan baseboard mastic	Throughout	52	LF	Good		NAD	Low	n/a	H6-4	n/a	
DC	144	6	First	1L-127	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	60	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	144	6	First	1L-127	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	8	LF	Good		NAD	Low	n/a	H6-4	n/a	
DC	144	6	First	1L-127	Miscellaneous	Gray duct seam sealant on metal	Throughout above drop ceiling	20	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	145	6	First	1L-125	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	120	SF	Good		NAD	Medium	n/a	H6-4	n/a	
DC	145	6	First	1L-125	Miscellaneous	Drywall and joint compound	Throughout	560	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	145	6	First	1L-125	Miscellaneous	Yellow carpet mastic	Throughout	120	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	145	6	First	1L-125	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	20	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	145	6	First	1L-125	Miscellaneous	Tan baseboard mastic	Throughout	44	LF	Good		NAD	Low	n/a	H6-4	n/a	
DC	146	6	First	1L-123	Miscellaneous	12" x 12" Lt. Blue mottle floor tile	Throughout	280	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	146	6	First	1L-123	Miscellaneous	Yellow floor tile mastic	Throughout	280	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	146	6	First	1L-123	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	280	SF	Good		NAD	Medium	n/a	H6-4	n/a	
DC	146	6	First	1L-123	Miscellaneous	White duct seam sealant on foil	Throughout	140	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	146	6	First	1L-123	Miscellaneous	Drywall and joint compound	Throughout	860	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	146	6	First	1L-123	Miscellaneous	Tan baseboard mastic	Throughout	64	LF	Good		NAD	Low	n/a	H6-4	n/a	
DC	147	6	First	1L-121	Miscellaneous	12" x 12" Lt. Blue mottle floor tile	Throughout	240	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	147	6	First	1L-121	Miscellaneous	Yellow floor tile mastic	Throughout	240	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	147	6	First	1L-121	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	240	SF	Good		NAD	Medium	n/a	H6-4	n/a	
DC	147	6	First	1L-121	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	80	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	147	6	First	1L-121	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	2	LF	Good		NAD	Low	n/a	H6-4	n/a	
DC	147	6	First	1L-121	Miscellaneous	Drywall and joint compound	Throughout	880	SF	Good		NAD	High	n/a	H6-4	n/a	

**Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6**

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	147	6	First	1L-121	Miscellaneous	Tan baseboard mastic	Throughout	64	LF	Good		NAD	Low	n/a	H6-4	n/a	
DC	147	6	First	1L-121	Miscellaneous	Gray sink mastic	West wall	1 @ 2' x 2'	Sinks	Good		NAD	Medium	n/a	H6-4	n/a	
DC	148	6	First	1L-116	Miscellaneous	12" x 12" Lt. Blue mottle floor tile	Throughout	130	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	148	6	First	1L-116	Miscellaneous	Yellow floor tile mastic	Throughout	130	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	148	6	First	1L-116	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	160	SF	Good		NAD	Medium	n/a	H6-4	n/a	
DC	148	6	First	1L-116	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	5	LF	Good		NAD	Low	n/a	H6-4	n/a	
DC	148	6	First	1L-116	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	40	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	148	6	First	1L-116	Miscellaneous	Gray duct seam sealant on metal	Throughout above drop ceiling	20	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	148	6	First	1L-116	Miscellaneous	Yellow ceramic tile mastic	Throughout restroom	120	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	149	6	First	1L-114	Miscellaneous	12" x 12" Lt. Blue mottle floor tile	Throughout	130	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	149	6	First	1L-114	Miscellaneous	Yellow floor tile mastic	Throughout	130	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	149	6	First	1L-114	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	160	SF	Good		NAD	Medium	n/a	H6-4	n/a	
DC	149	6	First	1L-114	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	5	LF	Good		NAD	Low	n/a	H6-4	n/a	
DC	149	6	First	1L-114	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	40	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	149	6	First	1L-114	Miscellaneous	Gray duct seam sealant on metal	Throughout above drop ceiling	20	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	149	6	First	1L-114	Miscellaneous	Yellow ceramic tile mastic	Throughout restroom	120	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	150	6	First	1L-115	Miscellaneous	Drywall and joint compound	Throughout	880	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	150	6	First	1L-115	Miscellaneous	2' x 2' Solid white ceiling tile	Throughout	224	SF	Good		NAD	Medium	n/a	H6-4	n/a	
DC	150	6	First	1L-115	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	80	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	150	6	First	1L-115	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	10	LF	Good		NAD	Low	n/a	H6-4	n/a	
DC	150	6	First	1L-115	Miscellaneous	Off-white with Blue specks floor sheeting	Throughout	200	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	150	6	First	1L-115	Miscellaneous	Blue floor sheeting	Throughout	30	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	150	6	First	1L-115	Miscellaneous	Tan floor sheeting mastic	Throughout	230	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	151	6	First	Corridor 103	Miscellaneous	12" x 12" Lt. Blue mottle floor tile	Throughout	886	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	151	6	First	Corridor 103	Miscellaneous	12" x 12" Lt. Pink mottle floor tile	Throughout	60	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	151	6	First	Corridor 103	Miscellaneous	12" x 12" Red mottle floor tile	Throughout	14	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	151	6	First	Corridor 103	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	960	SF	Good		NAD	Medium	n/a	H6-4	n/a	
DC	151	6	First	Corridor 103	Miscellaneous	Tan baseboard mastic	Throughout	332	LF	Good		NAD	Low	n/a	H6-4	n/a	
DC	151	6	First	Corridor 103	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	1600	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	151	6	First	Corridor 103	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	40	LF	Good		NAD	Low	n/a	H6-4	n/a	
DC	151	6	First	Corridor 103	Miscellaneous	Drywall and joint compound	Throughout	1292	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	151	6	First	Corridor 103	Miscellaneous	Yellow floor tile mastic	Throughout	960	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	151	6	First	Corridor 103	Miscellaneous	Tan pin mastic	Throughout above drop ceiling	1600	SF	Good	Under FG Duct insulation	NAD	Low	n/a	H6-4	n/a	

**Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6**

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	152	6	First	1L-113	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	80	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	152	6	First	1L-113	Miscellaneous	Drywall and joint compound	Throughout	560	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	152	6	First	1L-113	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	120	SF	Good		NAD	Medium	n/a	H6-4	n/a	
DC	152	6	First	1L-113	Miscellaneous	Off-white with Blue specks floor sheeting	Throughout	120	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	152	6	First	1L-113	Miscellaneous	Tan floor sheeting mastic	Throughout	120	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	153	6	First	1L-111	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	80	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	153	6	First	1L-111	Miscellaneous	Drywall and joint compound	Throughout	560	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	153	6	First	1L-111	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	120	SF	Good		NAD	Medium	n/a	H6-4	n/a	
DC	153	6	First	1L-111	Miscellaneous	Off-white with Blue specks floor sheeting	Throughout	120	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	153	6	First	1L-111	Miscellaneous	Tan floor sheeting mastic	Throughout	120	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	154	6	First	1L-109	Miscellaneous	12" x 12" Lt. Blue mottle floor tile	Throughout	216	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	154	6	First	1L-109	Miscellaneous	Yellow floor tile mastic	Throughout	216	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	154	6	First	1L-109	Miscellaneous	Drywall and joint compound	Throughout walls and ceiling	816	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	154	6	First	1L-109	Miscellaneous	White duct seam sealant on foil	Throughout above fixed ceiling	80	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	154	6	First	1L-109	Miscellaneous	White pipe seam sealant on paper	Throughout above fixed ceiling	4	LF	Good		NAD	Low	n/a	H6-4	n/a	
DC	154	6	First	1L-109	Miscellaneous	Gray duct seam sealant on metal	Throughout above fixed ceiling	60	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	154	6	First	1L-109	Miscellaneous	Tan baseboard mastic	Throughout	40	LF	Good		NAD	Low	n/a	H6-4	n/a	
DC	155	6	First	1L-108	Miscellaneous	Off-white with Blue specks floor sheeting	Throughout	144	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	155	6	First	1L-108	Miscellaneous	Tan floor sheeting mastic	Throughout	144	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	155	6	First	1L-108	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	6	LF	Good		NAD	Low	n/a	H6-4	n/a	
DC	155	6	First	1L-108	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	80	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	155	6	First	1L-108	Miscellaneous	Gray duct seam sealant on metal	Throughout above drop ceiling	860	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	155	6	First	1L-108	Miscellaneous	2' x 2' Solid white ceiling tile	Throughout	144	SF	Good		NAD	Medium	n/a	H6-4	n/a	
DC	155	6	First	1L-108	Miscellaneous	Drywall and joint compound	Throughout walls and ceiling	624	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	156	6	First	1L-110	Miscellaneous	Off-white with Blue specks floor sheeting	Throughout	144	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	156	6	First	1L-110	Miscellaneous	Tan floor sheeting mastic	Throughout	144	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	156	6	First	1L-110	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	6	LF	Good		NAD	Low	n/a	H6-4	n/a	
DC	156	6	First	1L-110	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	80	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	156	6	First	1L-110	Miscellaneous	Gray duct seam sealant on metal	Throughout above drop ceiling	860	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	156	6	First	1L-110	Miscellaneous	2' x 2' Solid white ceiling tile	Throughout	144	SF	Good		NAD	Medium	n/a	H6-4	n/a	
DC	156	6	First	1L-110	Miscellaneous	Drywall and joint compound	Throughout walls and ceiling	624	SF	Good		NAD	High	n/a	H6-4	n/a	

**Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6**

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	157	6	First	1L-112	Miscellaneous	Off-white with Blue specks floor sheeting	Throughout	144	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	157	6	First	1L-112	Miscellaneous	Tan floor sheeting mastic	Throughout	144	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	157	6	First	1L-112	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	6	LF	Good		NAD	Low	n/a	H6-4	n/a	
DC	157	6	First	1L-112	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	80	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	157	6	First	1L-112	Miscellaneous	Gray duct seam sealant on metal	Throughout above drop ceiling	860	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	157	6	First	1L-112	Miscellaneous	2' x 2' Solid white ceiling tile	Throughout	144	SF	Good		NAD	Medium	n/a	H6-4	n/a	
DC	157	6	First	1L-112	Miscellaneous	Drywall and joint compound	Throughout walls and ceiling	624	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	158	6	First	1L-106	Miscellaneous	2' x 2' Solid white ceiling tile	Throughout	324	SF	Good		NAD	Medium	n/a	H6-4	n/a	
DC	158	6	First	1L-106	Miscellaneous	Off-white with Blue specks floor sheeting	Throughout	324	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	158	6	First	1L-106	Miscellaneous	Tan floor sheeting mastic	Throughout	324	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	158	6	First	1L-106	Miscellaneous	Drywall and joint compound	Throughout	1400	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	158	6	First	1L-106	Miscellaneous	Gray duct seam sealant on metal	Throughout above drop ceiling	80	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	158	6	First	1L-106	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	158	6	First	1L-106	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	10	LF	Good		NAD	Low	n/a	H6-4	n/a	
DC	159	6	First	1L-105	Miscellaneous	Drywall and joint compound	Throughout walls and ceiling	500	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	159	6	First	1L-105	Miscellaneous	Off-white with Blue specks floor sheeting	Throughout	112	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	159	6	First	1L-105	Miscellaneous	Tan floor sheeting mastic	Throughout	112	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	159	6	First	1L-105	Miscellaneous	White duct seam sealant on foil	Throughout	20	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	159	6	First	1L-105	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	112	SF	Good		NAD	Medium	n/a	H6-4	n/a	
DC	159	6	First	1L-105	Miscellaneous	Gray sink mastic	East wall	1 @ 2' x 2'	Sinks	Good		NAD	Medium	n/a	H6-4	n/a	
DC	160	6	First	1L-101, 102, 103, 104	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	3100	SF	Good		NAD	Medium	n/a	H6-4	n/a	
DC	160	6	First	1L-101, 102, 103, 104	Miscellaneous	Off-white with Blue specks floor sheeting	Throughout	3100	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	160	6	First	1L-101, 102, 103, 104	Miscellaneous	Tan floor sheeting mastic	Throughout	3100	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	160	6	First	1L-101, 102, 103, 104	Miscellaneous	Drywall and joint compound	Throughout walls and ceiling	5500	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	160	6	First	1L-101, 102, 103, 104	Miscellaneous	White duct seam sealant on foil	Throughout above ceiling	2600	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	160	6	First	1L-101, 102, 103, 104	Miscellaneous	White pipe seam sealant on paper	Throughout above ceiling	100	LF	Good		NAD	Low	n/a	H6-4	n/a	
DC	160	6	First	1L-101, 102, 103, 104	Miscellaneous	Gray duct seam sealant on metal	Throughout above ceiling	300	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	160	6	First	1L-101, 102, 103, 104	Miscellaneous	Yellow ceramic tile mastic	Throughout restroom	150	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	160	6	First	1L-101, 102, 103, 104	Miscellaneous	Blue floor sheeting	Throughout	80	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	161	6	First	1L-100	Miscellaneous	Drywall and joint compound	Throughout	1480	SF	Good		NAD	High	n/a	H6-4	n/a	

**Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6**

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	161	6	First	1L-100	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	720	SF	Good		NAD	Medium	n/a	H6-4	n/a	
DC	161	6	First	1L-100	Miscellaneous	12" x 12" Lt. Pink mottle floor tile	Throughout	116	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	161	6	First	1L-100	Miscellaneous	12" x 12" Red mottle floor tile	Throughout	16	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	161	6	First	1L-100	Miscellaneous	12" x 12" Lt. Blue mottle floor tile	Throughout	588	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	161	6	First	1L-100	Miscellaneous	Yellow floor tile mastic	Throughout	720	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	161	6	First	1L-100	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	600	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	161	6	First	1L-100	Miscellaneous	Tan pin mastic	Throughout above drop ceiling	600	SF	Good	Under FG Duct insulation	NAD	Low	n/a	H6-4	n/a	
DC	162	6	First	1L-100A	Miscellaneous	Drywall and joint compound	Throughout	348	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	162	6	First	1L-100A	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	48	SF	Good		NAD	Medium	n/a	H6-4	n/a	
DC	162	6	First	1L-100A	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	10	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	163	6	First	Corridor	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	1200	SF	Good		NAD	Medium	n/a	H6-4	n/a	
DC	163	6	First	Corridor	Miscellaneous	Black mastic on metal window frame	East wall	22 @ 6' x 3'	Windows	Good		NAD	High	n/a	H6-4	n/a	
DC	163	6	First	Corridor	Miscellaneous	12" x 12" Lt. Green marble floor tile	Throughout	1100	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	163	6	First	Corridor	Miscellaneous	12" x 12" Dk. Green marble floor tile	Throughout	100	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	163	6	First	Corridor	Miscellaneous	Yellow floor tile mastic	Throughout	1200	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	163	6	First	Corridor	Miscellaneous	Drywall and joint compound	Throughout West wall and ceiling	3000	SF	Good		NAD	High	n/a	H6-4	n/a	
DC	163	6	First	Corridor	Miscellaneous	Black window caulk	East wall	300	LF	Good		NAD	High	n/a	H6-4	n/a	
DC	163	6	First	Corridor	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	600	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	163	6	First	Corridor	Miscellaneous	Drywall and joint compound textured coating	Throughout above drop ceiling	1500	SF	Good		NAD	Low	n/a	H6-4	n/a	
DC	164	6	First	1J-108	Miscellaneous	Drywall and joint compound	Throughout	432	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	164	6	First	1J-108	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout	72	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	164	6	First	1J-108	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	72	SF	Good		5%-10% Chrysotile	High	O & M	H6-3	01	
DC	164	6	First	1J-108	Miscellaneous	Black floor tile mastic	Throughout	72	SF	Good		4%-5% Chrysotile	Low	O & M	H6-3	02	
DC	164	6	First	1J-108	Miscellaneous	Brown baseboard mastic	Throughout	36	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	164	6	First	1J-108	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	30	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	164	6	First	1J-108	Miscellaneous	Fire door	North wall	1 @ 3' x 7'	Doors	Good	Labeled/Metal	Assumed ACM	High	O & M	H6-3	N/A	
DC	165	6	First	1J-110	Miscellaneous	Drywall and joint compound	Throughout	540	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	165	6	First	1J-110	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout	180	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	165	6	First	1J-110	Miscellaneous	Yellow carpet mastic	Throughout	180	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	165	6	First	1J-110	Miscellaneous	Tan baseboard mastic	Throughout	54	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	165	6	First	1J-110	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	200	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	165	6	First	1J-110	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	60	SF	Good		NAD	Low	n/a	H6-3	n/a	

Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	165	6	First	1J-110	Miscellaneous	2' x 4' Gouged and dot ceiling tile	Throughout walls	300	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	165	6	First	1J-110	Miscellaneous	Brown mastic dots	Throughout walls	300	SF	Good	Throughout under 2' x 4' gouged and dot ceiling tiles on walls	NAD	Low	n/a	H6-3	n/a	
DC	166	6	First	Booth 7	Surfacing	Gray spray-on fire proofing	Throughout above metal ceiling	120	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	166	6	First	Booth 7	Miscellaneous	White duct seam sealant on foil	Throughout above metal ceiling	40	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	166	6	First	Booth 7	Miscellaneous	Yellow carpet mastic	Throughout	100	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	167	6	First	Booth 7A	Surfacing	Gray spray-on fire proofing	Throughout above metal ceiling	120	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	167	6	First	Booth 7A	Miscellaneous	White duct seam sealant on foil	Throughout above metal ceiling	40	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	167	6	First	Booth 7A	Miscellaneous	Yellow carpet mastic	Throughout	100	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	168	6	First	Booth 6	Surfacing	Gray spray-on fire proofing	Throughout above metal ceiling	120	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	168	6	First	Booth 6	Miscellaneous	White duct seam sealant on foil	Throughout above metal ceiling	40	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	168	6	First	Booth 6	Miscellaneous	Yellow carpet mastic	Throughout	100	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	169	6	First	Booth 6A	Surfacing	Gray spray-on fire proofing	Throughout above metal ceiling	120	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	169	6	First	Booth 6A	Miscellaneous	White duct seam sealant on foil	Throughout above metal ceiling	40	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	169	6	First	Booth 6A	Miscellaneous	Yellow carpet mastic	Throughout	100	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	170	6	First	1H-132	Miscellaneous	Black mastic on metal window frame	South wall	5 @ 6' x 3'	Windows	Good		NAD	High	n/a	H6-3	n/a	
DC	170	6	First	1H-132	Miscellaneous	Black window caulk	South wall	70	LF	Good		NAD	High	n/a	H6-3	n/a	
DC	170	6	First	1H-132	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout	648	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	170	6	First	1H-132	Miscellaneous	Yellow carpet mastic	Throughout	648	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	170	6	First	1H-132	Miscellaneous	Tan baseboard mastic	Throughout	108	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	170	6	First	1H-132	Miscellaneous	White pipe seam sealant on paper	Throughout	20	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	170	6	First	1H-132	Miscellaneous	White duct seam sealant on foil	Throughout	160	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	170	6	First	1H-132	Surfacing	Gray spray-on fire proofing	Throughout	450	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	170	6	First	1H-132	Miscellaneous	2' x 4' Gouged and dot ceiling tile	Throughout walls	540	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	170	6	First	1H-132	Miscellaneous	Brown mastic dots	Throughout walls	540	SF	Good	Throughout under 2' x 4' gouged and dot ceiling tiles on walls	NAD	Low	n/a	H6-3	n/a	
DC	170	6	First	1H-132	Miscellaneous	Drywall and joint compound	Throughout	1080	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	171	6	First	1H-133	Miscellaneous	12" x 12" Off-white mottle floor tile	Throughout	216	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	171	6	First	1H-133	Miscellaneous	Yellow floor tile mastic	Throughout	216	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	171	6	First	1H-133	Miscellaneous	Drywall and joint compound	Throughout	600	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	171	6	First	1H-133	Miscellaneous	2' x 4' Gouged and dot ceiling tile	Throughout walls	300	SF	Good		NAD	High	n/a	H6-3	n/a	

**Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6**

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	171	6	First	1H-133	Miscellaneous	Brown mastic dots	Throughout walls	300	SF	Good	Throughout under 2' x 4' gouged and dot ceiling tiles on walls	NAD	Low	n/a	H6-3	n/a	
DC	171	6	First	1H-133	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	216	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	171	6	First	1H-133	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	10	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	171	6	First	1H-133	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	30	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	171	6	First	1H-133	Miscellaneous	Black mastic on metal window frame	South wall	1 @ 4' x 6'	Windows	Good		NAD	High	n/a	H6-3	n/a	
DC	171	6	First	1H-133	Miscellaneous	Black window caulk	South wall	15	LF	Good		NAD	High	n/a	H6-3	n/a	
DC	172	6	First	Stair #13	Miscellaneous	Fire door	West wall	1 @ 4' x 7'	Doors	Good	Labeled/Wood	Assumed ACM	High	O & M	H6-3	N/A	
DC	172	6	First	Stair #13	Miscellaneous	Drywall and joint compound	Throughout	500	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	172	6	First	Stair #13	Miscellaneous	Red fire stop	West wall	1	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	173	6	First	1H-130	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout	140	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	173	6	First	1H-130	Miscellaneous	Yellow carpet mastic	Throughout	140	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	173	6	First	1H-130	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	6	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	173	6	First	1H-130	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	80	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	173	6	First	1H-130	Miscellaneous	Yellow ceramic tile mastic	Throughout	10	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	173	6	First	1H-130	Miscellaneous	Drywall and joint compound	Throughout	480	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	173	6	First	1H-130	Miscellaneous	Tan baseboard mastic	Throughout	48	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	173	6	First	1H-130	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	173	6	First	1H-130	Miscellaneous	2' x 4' Gouged and dot ceiling tile	Throughout walls	240	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	173	6	First	1H-130	Miscellaneous	Brown mastic dots	Throughout walls	240	SF	Good	Throughout under 2' x 4' gouged and dot ceiling tiles on walls	NAD	Low	n/a	H6-3	n/a	
DC	173	6	First	1H-130	Miscellaneous	Black mastic on metal window frame	East wall	2 @ 6' x 3'	Windows	Good		NAD	High	n/a	H6-3	n/a	
DC	173	6	First	1H-130	Miscellaneous	Black window caulk	East wall	40	LF	Good		NAD	High	n/a	H6-3	n/a	
DC	174	6	First	1H-128	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout	140	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	174	6	First	1H-128	Miscellaneous	Yellow carpet mastic	Throughout	140	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	174	6	First	1H-128	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	6	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	174	6	First	1H-128	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	80	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	174	6	First	1H-128	Miscellaneous	Yellow ceramic tile mastic	Throughout	10	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	174	6	First	1H-128	Miscellaneous	Drywall and joint compound	Throughout	480	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	174	6	First	1H-128	Miscellaneous	Tan baseboard mastic	Throughout	48	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	174	6	First	1H-128	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	174	6	First	1H-128	Miscellaneous	2' x 4' Gouged and dot ceiling tile	Throughout walls	240	SF	Good		NAD	High	n/a	H6-3	n/a	

Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	174	6	First	1H-128	Miscellaneous	Brown mastic dots	Throughout walls	240	SF	Good	Throughout under 2' x 4' gouged and dot ceiling tiles on walls	NAD	Low	n/a	H6-3	n/a	
DC	174	6	First	1H-128	Miscellaneous	Black mastic on metal window frame	East wall	2 @ 6' x 3'	Windows	Good		NAD	High	n/a	H6-3	n/a	
DC	174	6	First	1H-128	Miscellaneous	Black window caulk	East wall	40	LF	Good		NAD	High	n/a	H6-3	n/a	
DC	175	6	First	1H-126	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout	140	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	175	6	First	1H-126	Miscellaneous	Yellow carpet mastic	Throughout	140	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	175	6	First	1H-126	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	6	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	175	6	First	1H-126	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	80	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	175	6	First	1H-126	Miscellaneous	Yellow ceramic tile mastic	Throughout	10	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	175	6	First	1H-126	Miscellaneous	Drywall and joint compound	Throughout	480	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	175	6	First	1H-126	Miscellaneous	Tan baseboard mastic	Throughout	48	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	175	6	First	1H-126	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	175	6	First	1H-126	Miscellaneous	2' x 4' Gouged and dot ceiling tile	Throughout walls	240	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	175	6	First	1H-126	Miscellaneous	Brown mastic dots	Throughout walls	240	SF	Good	Throughout under 2' x 4' gouged and dot ceiling tiles on walls	NAD	Low	n/a	H6-3	n/a	
DC	175	6	First	1H-126	Miscellaneous	Black mastic on metal window frame	East wall	2 @ 6' x 3'	Windows	Good		NAD	High	n/a	H6-3	n/a	
DC	175	6	First	1H-126	Miscellaneous	Black window caulk	East wall	40	LF	Good		NAD	High	n/a	H6-3	n/a	
DC	175	6	First	1H-126	Miscellaneous	Gray duct seam sealant on metal	Throughout above drop ceiling	30	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	176	6	First	1H-123	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout	140	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	176	6	First	1H-123	Miscellaneous	Yellow carpet mastic	Throughout	140	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	176	6	First	1H-123	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	6	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	176	6	First	1H-123	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	80	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	176	6	First	1H-123	Miscellaneous	Drywall and joint compound	Throughout	480	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	176	6	First	1H-123	Miscellaneous	Tan baseboard mastic	Throughout	48	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	176	6	First	1H-123	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	176	6	First	1H-123	Miscellaneous	2' x 4' Gouged and dot ceiling tile	Throughout walls	240	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	176	6	First	1H-123	Miscellaneous	Brown mastic dots	Throughout walls	240	SF	Good	Throughout under 2' x 4' gouged and dot ceiling tiles on walls	NAD	Low	n/a	H6-3	n/a	
DC	176	6	First	1H-123	Miscellaneous	Black mastic on metal window frame	East wall	1 @ 6' x 3'	Windows	Good		NAD	High	n/a	H6-3	n/a	
DC	176	6	First	1H-123	Miscellaneous	Black window caulk	East wall	20	LF	Good		NAD	High	n/a	H6-3	n/a	
DC	177	6	First	1H-122	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout	140	SF	Good		NAD	Medium	n/a	H6-3	n/a	

**Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6**

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	177	6	First	1H-122	Miscellaneous	Yellow carpet mastic	Throughout	140	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	177	6	First	1H-122	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	6	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	177	6	First	1H-122	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	80	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	177	6	First	1H-122	Miscellaneous	Yellow ceramic tile mastic	Throughout	10	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	177	6	First	1H-122	Miscellaneous	Drywall and joint compound	Throughout	480	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	177	6	First	1H-122	Miscellaneous	Tan baseboard mastic	Throughout	48	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	177	6	First	1H-122	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	177	6	First	1H-122	Miscellaneous	2' x 4' Gouged and dot ceiling tile	Throughout walls	240	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	177	6	First	1H-122	Miscellaneous	Brown mastic dots	Throughout walls	240	SF	Good	Throughout under 2' x 4' gouged and dot ceiling tiles on walls	NAD	Low	n/a	H6-3	n/a	
DC	177	6	First	1H-122	Miscellaneous	Black mastic on metal window frame	East wall	1 @ 6' x 3'	Windows	Good		NAD	High	n/a	H6-3	n/a	
DC	177	6	First	1H-122	Miscellaneous	Black window caulk	East wall	20	LF	Good		NAD	High	n/a	H6-3	n/a	
DC	177	6	First	1H-122	Miscellaneous	Gray duct seam sealant on metal	Throughout above drop ceiling	30	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	178	6	First	1H-120	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout	140	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	178	6	First	1H-120	Miscellaneous	Yellow carpet mastic	Throughout	140	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	178	6	First	1H-120	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	80	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	178	6	First	1H-120	Miscellaneous	Yellow ceramic tile mastic	Throughout	10	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	178	6	First	1H-120	Miscellaneous	Drywall and joint compound	Throughout	480	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	178	6	First	1H-120	Miscellaneous	Tan baseboard mastic	Throughout	48	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	178	6	First	1H-120	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	178	6	First	1H-120	Miscellaneous	2' x 4' Gouged and dot ceiling tile	Throughout walls	240	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	178	6	First	1H-120	Miscellaneous	Brown mastic dots	Throughout walls	240	SF	Good	Throughout under 2' x 4' gouged and dot ceiling tiles on walls	NAD	Low	n/a	H6-3	n/a	
DC	178	6	First	1H-120	Miscellaneous	Black mastic on metal window frame	East wall	1 @ 6' x 3'	Windows	Good		NAD	High	n/a	H6-3	n/a	
DC	178	6	First	1H-120	Miscellaneous	Black window caulk	East wall	20	LF	Good		NAD	High	n/a	H6-3	n/a	
DC	179	6	First	1H-119	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout	140	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	179	6	First	1H-119	Miscellaneous	Yellow carpet mastic	Throughout	140	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	179	6	First	1H-119	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	6	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	179	6	First	1H-119	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	80	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	179	6	First	1H-119	Miscellaneous	Yellow ceramic tile mastic	Throughout	10	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	179	6	First	1H-119	Miscellaneous	Drywall and joint compound	Throughout	480	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	179	6	First	1H-119	Miscellaneous	Tan baseboard mastic	Throughout	48	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	179	6	First	1H-119	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-3	n/a	

**Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6**

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	179	6	First	1H-119	Miscellaneous	2' x 4' Gouged and dot ceiling tile	Throughout walls	240	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	179	6	First	1H-119	Miscellaneous	Brown mastic dots	Throughout walls	240	SF	Good	Throughout under 2' x 4' gouged and dot ceiling tiles on walls	NAD	Low	n/a	H6-3	n/a	
DC	179	6	First	1H-119	Miscellaneous	Black mastic on metal window frame	East wall	1 @ 6' x 3'	Windows	Good		NAD	High	n/a	H6-3	n/a	
DC	179	6	First	1H-119	Miscellaneous	Black window caulk	East wall	20	LF	Good		NAD	High	n/a	H6-3	n/a	
DC	180	6	First	1H-118	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout	140	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	180	6	First	1H-118	Miscellaneous	Yellow carpet mastic	Throughout	140	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	180	6	First	1H-118	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	6	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	180	6	First	1H-118	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	80	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	180	6	First	1H-118	Miscellaneous	Yellow ceramic tile mastic	West wall	10	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	180	6	First	1H-118	Miscellaneous	Drywall and joint compound	Throughout	480	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	180	6	First	1H-118	Miscellaneous	Tan baseboard mastic	Throughout	48	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	180	6	First	1H-118	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	180	6	First	1H-118	Miscellaneous	2' x 4' Gouged and dot ceiling tile	Throughout walls	240	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	180	6	First	1H-118	Miscellaneous	Brown mastic dots	Throughout walls	240	SF	Good	Throughout under 2' x 4' gouged and dot ceiling tiles on walls	NAD	Low	n/a	H6-3	n/a	
DC	180	6	First	1H-118	Miscellaneous	Black mastic on metal window frame	East wall	1 @ 6' x 3'	Windows	Good		NAD	High	n/a	H6-3	n/a	
DC	180	6	First	1H-118	Miscellaneous	Black window caulk	East wall	20	LF	Good		NAD	High	n/a	H6-3	n/a	
DC	181	6	First	1H-116	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout	140	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	181	6	First	1H-116	Miscellaneous	Yellow carpet mastic	Throughout	140	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	181	6	First	1H-116	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	6	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	181	6	First	1H-116	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	80	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	181	6	First	1H-116	Miscellaneous	Drywall and joint compound	Throughout	480	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	181	6	First	1H-116	Miscellaneous	Tan baseboard mastic	Throughout	48	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	181	6	First	1H-116	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	181	6	First	1H-116	Miscellaneous	2' x 4' Gouged and dot ceiling tile	Throughout walls	240	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	181	6	First	1H-116	Miscellaneous	Brown mastic dots	Throughout walls	240	SF	Good	Throughout under 2' x 4' gouged and dot ceiling tiles on walls	NAD	Low	n/a	H6-3	n/a	
DC	182	6	First	1H-115	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout	140	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	182	6	First	1H-115	Miscellaneous	Yellow carpet mastic	Throughout	140	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	182	6	First	1H-115	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	6	LF	Good		NAD	Low	n/a	H6-3	n/a	

Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	182	6	First	1H-115	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	80	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	182	6	First	1H-115	Miscellaneous	Drywall and joint compound	Throughout	480	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	182	6	First	1H-115	Miscellaneous	Tan baseboard mastic	Throughout	48	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	182	6	First	1H-115	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	182	6	First	1H-115	Miscellaneous	2' x 4' Gouged and dot ceiling tile	Throughout walls	240	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	182	6	First	1H-115	Miscellaneous	Brown mastic dots	Throughout walls	240	SF	Good	Throughout under 2' x 4' gouged and dot ceiling tiles on walls	NAD	Low	n/a	H6-3	n/a	
DC	183	6	First	1H-114	Miscellaneous	Drywall and joint compound	Throughout walls and ceiling	350	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	183	6	First	1H-114	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	50	SF	Good		5%-10% Chrysotile	High	O & M	H6-3	01	
DC	183	6	First	1H-114	Miscellaneous	Black floor tile mastic	Throughout	50	SF	Good		4%-5% Chrysotile	Low	O & M	H6-3	02	
DC	183	6	First	1H-114	Miscellaneous	Tan baseboard mastic	Throughout	30	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	183	6	First	1H-114	Miscellaneous	White duct seam sealant on foil	Throughout above fixed ceiling	40	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	183	6	First	1H-114	Surfacing	Gray spray-on fire proofing	Throughout above fixed ceiling	50	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	184	6	First	1H-113	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout	140	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	184	6	First	1H-113	Miscellaneous	Yellow carpet mastic	Throughout	140	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	184	6	First	1H-113	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	80	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	184	6	First	1H-113	Miscellaneous	Yellow ceramic tile mastic	Throughout	10	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	184	6	First	1H-113	Miscellaneous	Drywall and joint compound	Throughout	480	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	184	6	First	1H-113	Miscellaneous	Tan baseboard mastic	Throughout	48	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	184	6	First	1H-113	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	184	6	First	1H-113	Miscellaneous	2' x 4' Gouged and dot ceiling tile	Throughout walls	240	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	184	6	First	1H-113	Miscellaneous	Brown mastic dots	Throughout walls	240	SF	Good	Throughout under 2' x 4' gouged and dot ceiling tiles on walls	NAD	Low	n/a	H6-3	n/a	
DC	184	6	First	1H-113	Miscellaneous	12" x 12" White with Cream and Brown specks floor tile	Throughout	140	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	184	6	First	1H-113	Miscellaneous	Yellow floor tile mastic	Throughout	140	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	185	6	First	1H-117	Miscellaneous	12" x 12" White with Cream and Brown specks floor tile	Throughout	144	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	185	6	First	1H-117	Miscellaneous	Yellow floor tile mastic	Throughout	144	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	185	6	First	1H-117	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout	144	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	185	6	First	1H-117	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	40	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	185	6	First	1H-117	Miscellaneous	Tan baseboard mastic	Throughout	48	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	185	6	First	1H-117	Miscellaneous	Yellow ceramic tile mastic	North wall	20	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	185	6	First	1H-117	Miscellaneous	Drywall and joint compound	Throughout	480	SF	Good		NAD	High	n/a	H6-3	n/a	

Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	186	6	First	1H-121	Miscellaneous	Yellow carpet mastic	Throughout	216	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	186	6	First	1H-121	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout	216	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	186	6	First	1H-121	Miscellaneous	Drywall and joint compound	Throughout	600	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	186	6	First	1H-121	Miscellaneous	Tan baseboard mastic	Throughout	60	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	186	6	First	1H-121	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	200	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	186	6	First	1H-121	Miscellaneous	Yellow ceramic tile mastic	South wall	20	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	186	6	First	1H-121	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	186	6	First	1H-121	Miscellaneous	2' x 4' Gouged and dot ceiling tile	Throughout walls	300	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	186	6	First	1H-121	Miscellaneous	Brown mastic dots	Throughout walls	300	SF	Good	Throughout under 2' x 4' gouged and dot ceiling tiles on walls	NAD	Low	n/a	H6-3	n/a	
DC	187	6	First	1H-124	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	160	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	187	6	First	1H-124	Miscellaneous	Yellow ceramic tile mastic	West wall	20	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	187	6	First	1H-124	Miscellaneous	Yellow carpet mastic	Throughout	144	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	187	6	First	1H-124	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	144	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	187	6	First	1H-124	Miscellaneous	Drywall and joint compound	Throughout	580	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	187	6	First	1H-124	Miscellaneous	2' x 4' Gouged and dot ceiling tile	Throughout walls	290	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	187	6	First	1H-124	Miscellaneous	Brown mastic dots	Throughout walls	290	SF	Good	Throughout under 2' x 4' gouged and dot ceiling tiles on walls	NAD	Low	n/a	H6-3	n/a	
DC	187	6	First	1H-124	Miscellaneous	Tan baseboard mastic	Throughout	48	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	187	6	First	1H-124	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	40	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	188	6	First	1H-125	Miscellaneous	Drywall and joint compound	Throughout	400	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	188	6	First	1H-125	Miscellaneous	12" x 12" White with Cream and Brown specks floor tile	Throughout	48	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	188	6	First	1H-125	Miscellaneous	Yellow floor tile mastic	Throughout	48	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	188	6	First	1H-125	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	40	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	188	6	First	1H-125	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	10	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	188	6	First	1H-125	Miscellaneous	Brown baseboard mastic	Throughout	32	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	188	6	First	1H-125	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	48	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	189	6	First	1H-127	Miscellaneous	Drywall and joint compound	Throughout	480	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	189	6	First	1H-127	Miscellaneous	Yellow ceramic tile mastic	West wall	20	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	189	6	First	1H-127	Miscellaneous	Gray duct seam sealant on metal	Throughout above drop ceiling	10	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	189	6	First	1H-127	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	2	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	189	6	First	1H-127	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	20	SF	Good		NAD	Low	n/a	H6-3	n/a	

Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	189	6	First	1H-127	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	160	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	189	6	First	1H-127	Miscellaneous	Tan baseboard mastic	Throughout	48	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	189	6	First	1H-127	Miscellaneous	Yellow carpet mastic	Throughout	144	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	189	6	First	1H-127	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	144	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	189	6	First	1H-127	Miscellaneous	2' x 4' Gouged and dot ceiling tile	Throughout walls and ceiling	240	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	189	6	First	1H-127	Miscellaneous	Brown mastic dots	Throughout walls and ceiling	240	SF	Good	Throughout under 2' x 4' gouged and dot ceiling tiles on walls	NAD	Low	n/a	H6-3	n/a	
DC	190	6	First	1H-129	Miscellaneous	Drywall and joint compound	Throughout	480	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	190	6	First	1H-129	Miscellaneous	Yellow ceramic tile mastic	West wall	20	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	190	6	First	1H-129	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	160	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	190	6	First	1H-129	Miscellaneous	Tan baseboard mastic	Throughout	48	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	190	6	First	1H-129	Miscellaneous	Yellow carpet mastic	Throughout	144	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	190	6	First	1H-129	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	144	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	190	6	First	1H-129	Miscellaneous	2' x 4' Gouged and dot ceiling tile	Throughout walls and ceiling	240	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	190	6	First	1H-129	Miscellaneous	Brown mastic dots	Throughout walls and ceiling	240	SF	Good	Throughout under 2' x 4' gouged and dot ceiling tiles on walls	NAD	Low	n/a	H6-3	n/a	
DC	191	6	First	1H-131	Miscellaneous	Drywall and joint compound	Throughout	480	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	191	6	First	1H-131	Miscellaneous	Gray duct seam sealant on metal	Throughout above drop ceiling	10	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	191	6	First	1H-131	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	2	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	191	6	First	1H-131	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	160	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	191	6	First	1H-131	Miscellaneous	Tan baseboard mastic	Throughout	48	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	191	6	First	1H-131	Miscellaneous	Yellow carpet mastic	Throughout	144	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	191	6	First	1H-131	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	144	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	191	6	First	1H-131	Miscellaneous	2' x 4' Gouged and dot ceiling tile	Throughout walls and ceiling	240	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	191	6	First	1H-131	Miscellaneous	Brown mastic dots	Throughout walls and ceiling	240	SF	Good	Throughout under 2' x 4' gouged and dot ceiling tiles on walls	NAD	Low	n/a	H6-3	n/a	
DC	192	6	First	1H-100	Miscellaneous	12" x 12" Off-white mottle floor tile	Throughout	180	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	192	6	First	1H-100	Miscellaneous	Yellow floor tile mastic	Throughout	180	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	192	6	First	1H-100	Miscellaneous	Drywall and joint compound	Throughout	560	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	192	6	First	1H-100	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout	180	SF	Good		NAD	Medium	n/a	H6-3	n/a	

Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	192	6	First	1H-100	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	180	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	192	6	First	1H-100	Miscellaneous	2' x 4' Gouged and dot ceiling tile	Throughout walls	280	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	192	6	First	1H-100	Miscellaneous	Brown mastic dots	Throughout walls	280	SF	Good	Throughout under 2' x 4' gouged and dot ceiling tiles on walls	NAD	Low	n/a	H6-3	n/a	
DC	192	6	First	1H-100	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	30	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	192	6	First	1H-100	Miscellaneous	Tan baseboard mastic	Throughout	56	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	193	6	First	1J-116	Miscellaneous	Yellow carpet mastic	Throughout	252	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	193	6	First	1J-116	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	252	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	193	6	First	1J-116	Miscellaneous	2' x 4' Gouged and dot ceiling tile	Throughout walls	360	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	193	6	First	1J-116	Miscellaneous	Brown mastic dots	Throughout walls	360	SF	Good	Throughout under 2' x 4' gouged and dot ceiling tiles on walls	NAD	Low	n/a	H6-3	n/a	
DC	193	6	First	1J-116	Miscellaneous	Drywall and joint compound	Throughout	720	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	193	6	First	1J-116	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	300	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	193	6	First	1J-116	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	80	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	194	6	First	1J-113	Miscellaneous	Drywall and joint compound	Throughout	680	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	194	6	First	1J-113	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	300	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	194	6	First	1J-113	Miscellaneous	2' x 4' Gouged and dot ceiling tile	Throughout walls and ceiling	620	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	194	6	First	1J-113	Miscellaneous	Brown mastic dots	Throughout walls	340	SF	Good	Throughout under 2' x 4' gouged and dot ceiling tiles on walls	NAD	Low	n/a	H6-3	n/a	
DC	194	6	First	1J-113	Miscellaneous	Yellow carpet mastic	Throughout	288	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	194	6	First	1J-113	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	2	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	194	6	First	1J-113	Miscellaneous	Yellow ceramic tile mastic	West wall	10	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	194	6	First	1J-113	Miscellaneous	Tan baseboard mastic	Throughout	72	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	195	6	First	1J-111	Miscellaneous	Yellow carpet mastic	Throughout	360	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	195	6	First	1J-111	Miscellaneous	Drywall and joint compound	Throughout	760	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	195	6	First	1J-111	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	360	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	195	6	First	1J-111	Miscellaneous	2' x 4' Gouged and dot ceiling tile	South and West walls	280	SF	Good		NAD	High	n/a	H6-3	n/a	

**Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6**

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	195	6	First	1J-111	Miscellaneous	Brown mastic dots	South and West walls	280	SF	Good	Throughout under 2' x 4' gouged and dot ceiling tiles on walls	NAD	Low	n/a	H6-3	n/a	
DC	195	6	First	1J-111	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	5	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	195	6	First	1J-111	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	300	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	195	6	First	1J-111	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	80	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	195	6	First	1J-111	Miscellaneous	Tan baseboard mastic	Throughout	76	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	196	6	First	1J-109	Miscellaneous	Drywall and joint compound	Throughout	720	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	196	6	First	1J-109	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout	320	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	196	6	First	1J-109	Miscellaneous	Yellow carpet mastic	Throughout	320	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	196	6	First	1J-109	Miscellaneous	2' x 4' Gouged and dot ceiling tile	Throughout walls	360	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	196	6	First	1J-109	Miscellaneous	Brown mastic dots	Throughout walls	360	SF	Good	Throughout under 2' x 4' gouged and dot ceiling tiles on walls	NAD	Low	n/a	H6-3	n/a	
DC	196	6	First	1J-109	Miscellaneous	Tan baseboard mastic	Throughout	72	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	196	6	First	1J-109	Miscellaneous	Yellow ceramic tile mastic	North wall	10	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	196	6	First	1J-109	Miscellaneous	Green duct seam sealant on metal	Throughout above drop ceiling	10	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	196	6	First	1J-109	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	196	6	First	1J-109	Miscellaneous	Gray duct seam sealant on metal	Throughout above drop ceiling	10	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	196	6	First	1J-109	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	300	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	197	6	First	Booth 1	Miscellaneous	Yellow carpet mastic	Throughout	100	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	197	6	First	Booth 1	Surfacing	Gray spray-on fire proofing	Throughout above metal ceiling	40	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	197	6	First	Booth 1	Miscellaneous	White duct seam sealant on foil	Throughout above metal ceiling	40	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	197	6	First	Booth 1	Miscellaneous	Drywall and joint compound	East wall	100	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	198	6	First	Booth 1A	Miscellaneous	Yellow carpet mastic	Throughout	100	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	198	6	First	Booth 1A	Surfacing	Gray spray-on fire proofing	Throughout above metal ceiling	40	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	198	6	First	Booth 1A	Miscellaneous	White duct seam sealant on foil	Throughout above metal ceiling	40	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	198	6	First	Booth 1A	Miscellaneous	Drywall and joint compound	East wall	100	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	199	6	First	Booth 2	Miscellaneous	Yellow carpet mastic	Throughout	100	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	199	6	First	Booth 2	Surfacing	Gray spray-on fire proofing	Throughout above metal ceiling	40	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	199	6	First	Booth 2	Miscellaneous	White duct seam sealant on foil	Throughout above metal ceiling	40	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	199	6	First	Booth 2	Miscellaneous	Drywall and joint compound	East wall	100	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	200	6	First	Booth 2A	Miscellaneous	Yellow carpet mastic	Throughout	100	SF	Good		NAD	Low	n/a	H6-3	n/a	

Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	200	6	First	Booth 2A	Surfacing	Gray spray-on fire proofing	Throughout above metal ceiling	40	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	200	6	First	Booth 2A	Miscellaneous	White duct seam sealant on foil	Throughout above metal ceiling	40	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	200	6	First	Booth 2A	Miscellaneous	Drywall and joint compound	East wall	100	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	201	6	First	1H-107	Miscellaneous	Yellow carpet mastic	Throughout	144	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	201	6	First	1H-107	Miscellaneous	Drywall and joint compound	Throughout	144	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	201	6	First	1H-107	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout	48	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	201	6	First	1H-107	Miscellaneous	Tan baseboard mastic	Throughout	480	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	201	6	First	1H-107	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	150	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	201	6	First	1H-107	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	60	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	202	6	First	Booth 3	Miscellaneous	Yellow carpet mastic	Throughout	100	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	202	6	First	Booth 3	Surfacing	Gray spray-on fire proofing	Throughout above metal ceiling	40	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	202	6	First	Booth 3	Miscellaneous	White duct seam sealant on foil	Throughout above metal ceiling	40	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	202	6	First	Booth 3	Miscellaneous	Drywall and joint compound	East wall	100	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	203	6	First	Booth 3A	Miscellaneous	Yellow carpet mastic	Throughout	100	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	203	6	First	Booth 3A	Surfacing	Gray spray-on fire proofing	Throughout above metal ceiling	40	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	203	6	First	Booth 3A	Miscellaneous	White duct seam sealant on foil	Throughout above metal ceiling	40	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	203	6	First	Booth 3A	Miscellaneous	Drywall and joint compound	East wall	100	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	204	6	First	Booth 4A	Miscellaneous	Yellow carpet mastic	Throughout	100	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	204	6	First	Booth 4A	Surfacing	Gray spray-on fire proofing	Throughout above metal ceiling	40	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	204	6	First	Booth 4A	Miscellaneous	White duct seam sealant on foil	Throughout above metal ceiling	40	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	204	6	First	Booth 4A	Miscellaneous	Drywall and joint compound	West wall	100	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	205	6	First	Booth 4	Miscellaneous	Yellow carpet mastic	Throughout	100	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	205	6	First	Booth 4	Surfacing	Gray spray-on fire proofing	Throughout above metal ceiling	40	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	205	6	First	Booth 4	Miscellaneous	White duct seam sealant on foil	Throughout above metal ceiling	40	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	205	6	First	Booth 4	Miscellaneous	Drywall and joint compound	West wall	100	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	206	6	First	Booth 5	Miscellaneous	Yellow carpet mastic	Throughout	100	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	206	6	First	Booth 5	Surfacing	Gray spray-on fire proofing	Throughout above metal ceiling	40	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	206	6	First	Booth 5	Miscellaneous	White duct seam sealant on foil	Throughout above metal ceiling	40	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	206	6	First	Booth 5	Miscellaneous	Drywall and joint compound	West wall	100	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	207	6	First	Booth 5A	Miscellaneous	Yellow carpet mastic	Throughout	100	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	207	6	First	Booth 5A	Surfacing	Gray spray-on fire proofing	Throughout above metal ceiling	40	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	207	6	First	Booth 5A	Miscellaneous	White duct seam sealant on foil	Throughout above metal ceiling	40	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	207	6	First	Booth 5A	Miscellaneous	Drywall and joint compound	West wall	100	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	208	6	First	1H-108	Miscellaneous	Drywall and joint compound	Throughout	440	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	208	6	First	1H-108	Miscellaneous	Yellow carpet mastic	Throughout	120	SF	Good		NAD	Low	n/a	H6-3	n/a	

Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	208	6	First	1H-108	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	120	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	208	6	First	1H-108	Miscellaneous	2' x 4' Gouged and dot ceiling tile	Throughout walls	220	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	208	6	First	1H-108	Miscellaneous	Brown mastic dots	Throughout walls	220	SF	Good	Throughout under 2' x 4' gouged and dot ceiling tiles on walls	NAD	Low	n/a	H6-3	n/a	
DC	208	6	First	1H-108	Miscellaneous	Tan baseboard mastic	Throughout	441	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	208	6	First	1H-108	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	40	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	208	6	First	1H-108	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	209	6	First	Corridor	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	1500	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	209	6	First	Corridor	Miscellaneous	Yellow carpet mastic	Throughout	3000	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	209	6	First	Corridor	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout	3000	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	209	6	First	Corridor	Miscellaneous	2' x 4' Gouged and dot ceiling tile	Throughout walls	3500	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	209	6	First	Corridor	Miscellaneous	Brown mastic dots	Throughout walls	3500	SF	Good	Throughout under 2' x 4' gouged and dot ceiling tiles on walls	NAD	Low	n/a	H6-3	n/a	
DC	209	6	First	Corridor	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	3000	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	209	6	First	Corridor	Miscellaneous	Drywall and joint compound	Throughout	7500	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	209	6	First	Corridor	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	100	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	210	6	First	1J-101	Miscellaneous	Drywall and joint compound	Throughout	820	SF	Good	Area currently under renovation	NAD	High	n/a	H6-3	n/a	
DC	210	6	First	1J-101	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	120	SF	Good	Area currently under renovation	NAD	Low	n/a	H6-3	n/a	
DC	210	6	First	1J-101	Miscellaneous	12" x 12" White mottle floor tile	Throughout	70	SF	Good	Area currently under renovation	NAD	High	n/a	H6-3	n/a	
DC	210	6	First	1J-101	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	330	SF	Good	Area currently under renovation	5%-10% Chrysotile	High	O & M	H6-3	01	
DC	210	6	First	1J-101	Miscellaneous	Black floor tile mastic	Throughout	400	SF	Good	Area currently under renovation	4%-5% Chrysotile	Low	O & M	H6-3	02	
DC	210	6	First	1J-101	Miscellaneous	Brown baseboard mastic	Throughout	82	LF	Good	Area currently under renovation	NAD	Low	n/a	H6-3	n/a	
DC	210	6	First	1J-101	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	400	SF	Good	Area currently under renovation	NAD	Medium	n/a	H6-3	n/a	
DC	210	6	First	1J-101	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	10	SF	Good	Area currently under renovation	NAD	Low	n/a	H6-3	n/a	
DC	210	6	First	1J-101	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	10	LF	Good	Area currently under renovation	NAD	Low	n/a	H6-3	n/a	

Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	210	6	First	1J-101	Miscellaneous	Tan duct seam sealant on metal	Throughout above drop ceiling	5	SF	Good	Area currently under renovation	2% Chrysotile	Low	O & M	H6-3	04	
DC	211	6	First	1J-107	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout	144	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	211	6	First	1J-107	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	60	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	211	6	First	1J-107	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	211	6	First	1J-107	Miscellaneous	Drywall and joint compound	Throughout	580	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	211	6	First	1J-107	Miscellaneous	Tan baseboard mastic	Throughout	48	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	211	6	First	1J-107	Miscellaneous	Tan duct seam sealant on metal	Throughout above drop ceiling	15	SF	Good		2% Chrysotile	Low	O & M	H6-3	04	
DC	211	6	First	1J-107	Miscellaneous	Yellow carpet mastic	Throughout	144	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	212	6	First	1J-106	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout	144	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	212	6	First	1J-106	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	60	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	212	6	First	1J-106	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	212	6	First	1J-106	Miscellaneous	Drywall and joint compound	Throughout	580	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	212	6	First	1J-106	Miscellaneous	Tan baseboard mastic	Throughout	48	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	212	6	First	1J-106	Miscellaneous	Yellow carpet mastic	Throughout	144	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	213	6	First	1J-105	Miscellaneous	Yellow carpet mastic	Throughout	136	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	213	6	First	1J-105	Miscellaneous	Tan baseboard mastic	Throughout	46	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	213	6	First	1J-105	Miscellaneous	Drywall and joint compound	Throughout	460	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	213	6	First	1J-105	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout	136	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	213	6	First	1J-105	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	213	6	First	1J-105	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	60	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	213	6	First	1J-105	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	136	SF	Good		5%-10% Chrysotile	High	O & M	H6-3	01	
DC	213	6	First	1J-105	Miscellaneous	Black floor tile mastic	Throughout	136	SF	Good		4%-5% Chrysotile	Low	O & M	H6-3	02	
DC	214	6	First	1J-104	Miscellaneous	Yellow carpet mastic	Throughout	136	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	214	6	First	1J-104	Miscellaneous	Tan baseboard mastic	Throughout	46	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	214	6	First	1J-104	Miscellaneous	Drywall and joint compound	Throughout	460	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	214	6	First	1J-104	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout	136	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	214	6	First	1J-104	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	214	6	First	1J-104	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	60	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	214	6	First	1J-104	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	136	SF	Good		5%-10% Chrysotile	High	O & M	H6-3	01	
DC	214	6	First	1J-104	Miscellaneous	Black floor tile mastic	Throughout	136	SF	Good		4%-5% Chrysotile	Low	O & M	H6-3	02	
DC	215	6	First	Corridor	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	128	SF	Good		5%-10% Chrysotile	High	O & M	H6-3	01	
DC	215	6	First	Corridor	Miscellaneous	Yellow carpet mastic	Throughout	216	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	215	6	First	Corridor	Miscellaneous	Black floor tile mastic	Throughout	128	SF	Good		4%-5% Chrysotile	Low	O & M	H6-3	02	
DC	215	6	First	Corridor	Miscellaneous	Drywall and joint compound	Throughout	1040	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	215	6	First	Corridor	Miscellaneous	Tan baseboard mastic	Throughout	104	SF	Good		NAD	Low	n/a	H6-3	n/a	

Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	215	6	First	Corridor	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout	344	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	215	6	First	Corridor	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	60	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	215	6	First	Corridor	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	220	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	215	6	First	Corridor	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	10	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	215	6	First	Corridor	Miscellaneous	Fire door	North wall	2 @ 4' x 7'	Doors	Good	Labeled/Metal	Assumed ACM	High	O & M	H6-3	N/A	
DC	216	6	First	1J-102	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	50	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	216	6	First	1J-102	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout	48	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	216	6	First	1J-102	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	48	SF	Good		5%-10% Chrysotile	High	O & M	H6-3	01	
DC	216	6	First	1J-102	Miscellaneous	Black floor tile mastic	Throughout	48	SF	Good		4%-5% Chrysotile	Low	O & M	H6-3	02	
DC	216	6	First	1J-102	Miscellaneous	Tan baseboard mastic	Throughout	28	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	216	6	First	1J-102	Miscellaneous	Brown baseboard mastic	Throughout	28	LF	Good	Residual	NAD	Low	n/a	H6-3	n/a	
DC	216	6	First	1J-102	Miscellaneous	Drywall and joint compound	Throughout	80	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	216	6	First	1J-102	Miscellaneous	Fire door	West wall	1 @ 3' x 7'	Doors	Good	Labeled/Metal	Assumed ACM	High	O & M	H6-3	N/A	
DC	217	6	First	1J-103	Miscellaneous	Fire door	West wall	1 @ 3' x 7'	Doors	Good	Labeled/Metal	Assumed ACM	High	O & M	H6-3	N/A	
DC	217	6	First	1J-103	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	70	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	217	6	First	1J-103	Miscellaneous	12" x 12" Lt. Pink mottle floor tile	Throughout	32	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	217	6	First	1J-103	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout	96	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	217	6	First	1J-103	Miscellaneous	Tan baseboard mastic	Throughout	40	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	217	6	First	1J-103	Miscellaneous	Brown baseboard mastic	Throughout	40	LF	Good	Residual	NAD	Low	n/a	H6-3	n/a	
DC	217	6	First	1J-103	Miscellaneous	Drywall and joint compound	North wall	120	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	217	6	First	1J-103	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	64	SF	Good		5%-10% Chrysotile	High	O & M	H6-3	01	
DC	217	6	First	1J-103	Miscellaneous	Black floor tile mastic	Throughout	64	SF	Good		4%-5% Chrysotile	Low	O & M	H6-3	02	
DC	217	6	First	1J-103	Miscellaneous	Yellow floor tile mastic	Throughout	32	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	218	6	First	1J-154	Miscellaneous	Yellow carpet mastic	Throughout	280	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	218	6	First	1J-154	Miscellaneous	Drywall and joint compound	Throughout	680	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	218	6	First	1J-154	Miscellaneous	Tan baseboard mastic	Throughout	68	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	218	6	First	1J-154	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	280	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	218	6	First	1J-154	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	220	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	218	6	First	1J-154	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	30	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	218	6	First	1J-154	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	110	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	219	6	First	1J-155; 1J-156	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	2200	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	219	6	First	1J-155; 1J-156	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	5000	SF	Good		NAD	Low	n/a	H6-3	n/a	

Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	219	6	First	1J-155; 1J-156	Miscellaneous	Red fire stop	Throughout above drop ceiling	12	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	219	6	First	1J-155; 1J-156	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	250	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	219	6	First	1J-155; 1J-156	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	7284	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	219	6	First	1J-155; 1J-156	Miscellaneous	Drywall and joint compound	Throughout	3800	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	219	6	First	1J-155; 1J-156	Miscellaneous	Tan baseboard mastic	Throughout	380	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	219	6	First	1J-155; 1J-156	Miscellaneous	Yellow carpet mastic	Throughout	7284	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	219	6	First	1J-155; 1J-156	Miscellaneous	Fire door	South wall	1 @ 3' x 7'	SF	Good	Labeled/Metal	Assumed ACM	High	O & M	H6-3	N/A	
DC	220	6	First	1J-156A	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	220	6	First	1J-156A	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	90	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	220	6	First	1J-156A	Miscellaneous	Drywall and joint compound	Throughout	740	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	220	6	First	1J-156A	Miscellaneous	Tan baseboard mastic	Throughout	74	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	220	6	First	1J-156A	Miscellaneous	Yellow carpet mastic	Throughout	330	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	220	6	First	1J-156A	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	330	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	221	6	First	1J-157	Miscellaneous	Drywall and joint compound	Throughout	440	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	221	6	First	1J-157	Miscellaneous	Tan baseboard mastic	Throughout	44	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	221	6	First	1J-157	Miscellaneous	Yellow carpet mastic	Throughout	120	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	221	6	First	1J-157	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	120	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	221	6	First	1J-157	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	50	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	221	6	First	1J-157	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	20	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	222	6	First	1J-145	Miscellaneous	Drywall and joint compound	Throughout	1240	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	222	6	First	1J-145	Miscellaneous	Tan baseboard mastic	Throughout	124	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	222	6	First	1J-145	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	410	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	222	6	First	1J-145	Miscellaneous	Yellow carpet mastic	Throughout	820	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	222	6	First	1J-145	Miscellaneous	2' x 2' Rough and dot ceiling tile	Throughout	410	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	222	6	First	1J-145	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	600	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	222 A	6	First	1J-137	Miscellaneous	Yellow carpet mastic	Throughout	336	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	222 A	6	First	1J-137	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	336	SF	Good		5%-10% Chrysotile	Low	O & M	H6-3	01	
DC	222 A	6	First	1J-137	Miscellaneous	Black floor tile mastic	Throughout	336	SF	Good		4%-5% Chrysotile	Low	O & M	H6-3	02	
DC	222 A	6	First	1J-137	Miscellaneous	Drywall and joint compound	Throughout walls	336	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	222 A	6	First	1J-137	Miscellaneous	Tan baseboard mastic	All walls	80	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	222 A	6	First	1J-137	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	120	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	222 A	6	First	1J-137	Miscellaneous	Fire door	North Wall	1 @ 3' x 7'	Door	Good	Labeled/Wood	Assumed ACM	High	O & M	H6-3	N/A	

Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	222	6	First	1J-145	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	600	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	223	6	First	1J-142	Miscellaneous	Drywall and joint compound	Throughout walls and ceiling	624	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	223	6	First	1J-142	Miscellaneous	Yellow ceramic tile mastic	Throughout	200	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	223	6	First	1J-142	Surfacing	Gray spray-on fire proofing	Throughout above fixed ceiling	150	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	224	6	First	1J-143	Miscellaneous	Drywall and joint compound	Throughout walls and ceiling	624	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	224	6	First	1J-143	Miscellaneous	Yellow ceramic tile mastic	Throughout	200	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	224	6	First	1J-143	Surfacing	Gray spray-on fire proofing	Throughout above fixed ceiling	150	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	225	6	First	1J-140	Miscellaneous	Drywall and joint compound	Throughout	480	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	225	6	First	1J-140	Miscellaneous	Tan baseboard mastic	Throughout	48	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	225	6	First	1J-140	Miscellaneous	Yellow carpet mastic	Throughout	144	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	225	6	First	1J-140	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout	144	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	225	6	First	1J-140	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	150	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	225	6	First	1J-140	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	60	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	225	6	First	1J-140	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	144	SF	Good		5%-10% Chrysotile	High	O & M	H6-3	01	
DC	225	6	First	1J-140	Miscellaneous	Black floor tile mastic	Throughout	144	SF	Good		4%-5% Chrysotile	Low	O & M	H6-3	02	
DC	226	6	First	1J-134	Miscellaneous	Drywall and joint compound	Throughout	440	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	226	6	First	1J-134	Miscellaneous	Tan baseboard mastic	Throughout	44	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	226	6	First	1J-134	Miscellaneous	Yellow carpet mastic	Throughout	120	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	226	6	First	1J-134	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout	120	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	226	6	First	1J-134	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	150	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	226	6	First	1J-134	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	20	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	227	6	First	1J-134A	Miscellaneous	Drywall and joint compound	Throughout	440	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	227	6	First	1J-134A	Miscellaneous	Tan baseboard mastic	Throughout	44	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	227	6	First	1J-134A	Miscellaneous	Yellow carpet mastic	Throughout	120	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	227	6	First	1J-134A	Miscellaneous	2' x 2' Width-wise fissured and dot ceiling tile	Throughout	120	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	227	6	First	1J-134A	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	200	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	227	6	First	1J-134A	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	20	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	228	6	First	1J-138	Miscellaneous	Drywall and joint compound	Throughout	440	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	228	6	First	1J-138	Miscellaneous	Tan baseboard mastic	Throughout	44	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	228	6	First	1J-138	Miscellaneous	Yellow carpet mastic	Throughout	120	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	228	6	First	1J-138	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout	120	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	228	6	First	1J-138	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	75	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	228	6	First	1J-138	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	20	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	229	6	First	1J-139	Miscellaneous	Drywall and joint compound	Throughout	440	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	229	6	First	1J-139	Miscellaneous	Tan baseboard mastic	Throughout	44	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	229	6	First	1J-139	Miscellaneous	Yellow carpet mastic	Throughout	120	SF	Good		NAD	Low	n/a	H6-3	n/a	

Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	229	6	First	1J-139	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout	120	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	229	6	First	1J-139	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	75	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	230	6	First	1K-116A	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	10	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	230	6	First	1K-116A	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	230	6	First	1K-116A	Miscellaneous	2' x 2' Rough and dot ceiling tile	Throughout	144	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	230	6	First	1K-116A	Miscellaneous	Yellow carpet mastic	Throughout	144	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	230	6	First	1K-116A	Miscellaneous	Tan baseboard mastic	Throughout	48	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	230	6	First	1K-116A	Miscellaneous	Drywall and joint compound	Throughout	480	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	230	6	First	1K-116A	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	144	SF	Good		5%-10% Chrysotile	High	O & M	H6-3	01	
DC	230	6	First	1K-116A	Miscellaneous	Black floor tile mastic	Throughout	144	SF	Good		4%-5% Chrysotile	Low	O & M	H6-3	02	
DC	231	6	First	1K-117	Miscellaneous	Tan baseboard mastic	Throughout	40	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	231	6	First	1K-117	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	231	6	First	1K-117	Miscellaneous	Drywall and joint compound	Throughout	400	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	231	6	First	1K-117	Miscellaneous	Yellow carpet mastic	Throughout	96	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	231	6	First	1K-117	Miscellaneous	2' x 2' Rough and dot ceiling tile	Throughout	96	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	231	6	First	1K-117	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	96	SF	Good		5%-10% Chrysotile	High	O & M	H6-3	01	
DC	231	6	First	1K-117	Miscellaneous	Black floor tile mastic	Throughout	96	SF	Good		4%-5% Chrysotile	Low	O & M	H6-3	02	
DC	232	6	First	1K-118	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	200	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	232	6	First	1K-118	Miscellaneous	Tan duct seam sealant on metal	Throughout above drop ceiling	40	SF	Good		2% Chrysotile	Low	O & M	H6-3	04	
DC	232	6	First	1K-118	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	220	SF	Good		5%-10% Chrysotile	High	O & M	H6-3	01	
DC	232	6	First	1K-118	Miscellaneous	Black floor tile mastic	Throughout	220	SF	Good		4%-5% Chrysotile	Low	O & M	H6-3	02	
DC	232	6	First	1K-118	Miscellaneous	Drywall and joint compound	Throughout	768	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	232	6	First	1K-118	Miscellaneous	Tan baseboard mastic	Throughout	64	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	232	6	First	1K-118	Miscellaneous	Yellow carpet mastic	Throughout	220	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	232	6	First	1K-118	Miscellaneous	2' x 2' Rough and dot ceiling tile	Throughout	220	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	233	6	First	1K-119	Miscellaneous	Tan duct seam sealant on metal	Throughout above drop ceiling	15	SF	Good		2% Chrysotile	Low	O & M	H6-3	04	
DC	233	6	First	1K-119	Miscellaneous	Tan baseboard mastic	Throughout	56	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	233	6	First	1K-119	Miscellaneous	Drywall and joint compound	Throughout	560	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	233	6	First	1K-119	Miscellaneous	Yellow carpet mastic	Throughout	192	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	233	6	First	1K-119	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout under carpet	192	SF	Good		5%-10% Chrysotile	Low	O & M	H6-3	01	
DC	233	6	First	1K-119	Miscellaneous	Black floor tile mastic	Throughout under carpet	192	SF	Good		4%-5% Chrysotile	Low	O & M	H6-3	02	
DC	233	6	First	1K-119	Miscellaneous	2' x 2' Rough and dot ceiling tile	Throughout	192	SF	Good		NAD	Medium	n/a	H6-3	n/a	

Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	234	6	First	1K-120	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	40	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	234	6	First	1K-120	Miscellaneous	Tan baseboard mastic	Throughout	56	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	234	6	First	1K-120	Miscellaneous	Drywall and joint compound	Throughout	560	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	234	6	First	1K-120	Miscellaneous	Yellow carpet mastic	Throughout	192	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	234	6	First	1K-120	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout under carpet	192	SF	Good		5%-10% Chrysotile	Low	O & M	H6-3	01	
DC	234	6	First	1K-120	Miscellaneous	Black floor tile mastic	Throughout under carpet	192	SF	Good		4%-5% Chrysotile	Low	O & M	H6-3	02	
DC	234	6	First	1K-120	Miscellaneous	2' x 2' Rough and dot ceiling tile	Throughout	192	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	235	6	First	1K-121	Miscellaneous	Yellow ceramic tile mastic	Throughout	120	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	235	6	First	1K-121	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout under carpet	120	SF	Good		5%-10% Chrysotile	High	O & M	H6-3	01	
DC	235	6	First	1K-121	Miscellaneous	Black floor tile mastic	Throughout under carpet	120	SF	Good		4%-5% Chrysotile	Low	O & M	H6-3	02	
DC	235	6	First	1K-121	Miscellaneous	Tan baseboard mastic	Throughout	44	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	235	6	First	1K-121	Miscellaneous	Drywall and joint compound	Throughout	440	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	235	6	First	1K-121	Miscellaneous	2' x 2' Rough and dot ceiling tile	Throughout	120	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	235	6	First	1K-121	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	60	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	235	6	First	1K-121	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	40	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	235	6	First	1K-121	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	236	6	First	1K-122	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	236	6	First	1K-122	Miscellaneous	2' x 2' Rough and dot ceiling tile	Throughout	144	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	236	6	First	1K-122	Miscellaneous	Yellow carpet mastic	Throughout	144	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	236	6	First	1K-122	Miscellaneous	Tan baseboard mastic	Throughout	48	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	236	6	First	1K-122	Miscellaneous	Drywall and joint compound	Throughout	480	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	236	6	First	1K-122	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	144	SF	Good		5%-10% Chrysotile	High	O & M	H6-3	01	
DC	236	6	First	1K-122	Miscellaneous	Black floor tile mastic	Throughout	144	SF	Good		4%-5% Chrysotile	Low	O & M	H6-3	02	
DC	237	6	First	Corridor	Miscellaneous	Yellow carpet mastic	Throughout	220	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	237	6	First	Corridor	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	220	SF	Good		5%-10% Chrysotile	High	O & M	H6-3	01	
DC	237	6	First	Corridor	Miscellaneous	Black floor tile mastic	Throughout	220	SF	Good		4%-5% Chrysotile	Low	O & M	H6-3	02	
DC	237	6	First	Corridor	Miscellaneous	2' x 2' Rough and dot ceiling tile	Throughout	220	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	237	6	First	Corridor	Miscellaneous	Tan duct seam sealant on metal	Throughout above drop ceiling	130	SF	Good		2% Chrysotile	Low	O & M	H6-3	04	
DC	237	6	First	Corridor	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	80	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	237	6	First	Corridor	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	20	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	237	6	First	Corridor	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	250	SF	Good		NAD	Low	n/a	H6-3	n/a	

Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	237	6	First	Corridor	Miscellaneous	Tan baseboard mastic	Throughout	64	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	237	6	First	Corridor	Miscellaneous	Drywall and joint compound	Throughout	640	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	238	6	First	1K-115	Miscellaneous	Red fire stop	Throughout	5	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	238	6	First	1K-115	Miscellaneous	Drywall and joint compound	Throughout	500	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	238	6	First	1K-115	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	120	SF	Good		5%-10% Chrysotile	High	O & M	H6-3	01	
DC	238	6	First	1K-115	Miscellaneous	Black floor tile mastic	Throughout	120	SF	Good		4%-5% Chrysotile	Low	O & M	H6-3	02	
DC	238	6	First	1K-115	Miscellaneous	Tan baseboard mastic	Throughout	50	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	238	6	First	1K-115	Surfacing	Gray spray-on fire proofing	Throughout	30	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	239	6	First	1K-114	Miscellaneous	12" x 12" Tan mottle floor tile	Throughout	18	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	239	6	First	1K-114	Miscellaneous	Yellow floor tile mastic	Throughout	18	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	239	6	First	1K-114	Miscellaneous	Red fire stop	Throughout	15	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	239	6	First	1K-114	Miscellaneous	Drywall and joint compound	Throughout	180	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	239	6	First	1K-114	Surfacing	Gray spray-on fire proofing	Throughout	12	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	240	6	First	1K-125A	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout	120	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	240	6	First	1K-125A	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	40	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	240	6	First	1K-125A	Miscellaneous	Yellow carpet mastic	Throughout	120	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	240	6	First	1K-125A	Miscellaneous	Tan baseboard mastic	Throughout	44	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	240	6	First	1K-125A	Miscellaneous	Drywall and joint compound	Throughout	440	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	240	6	First	1K-125A	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	75	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	241	6	First	1K-125	Miscellaneous	Tan duct seam sealant on metal	Throughout above drop ceiling	20	SF	Good		2% Chrysotile	Low	O & M	H6-3	04	
DC	241	6	First	1K-125	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	75	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	241	6	First	1K-125	Miscellaneous	Yellow stone pattern linoleum	Throughout	120	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	241	6	First	1K-125	Miscellaneous	Yellow linoleum mastic	Throughout	120	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	241	6	First	1K-125	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout	120	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	241	6	First	1K-125	Miscellaneous	Drywall and joint compound	Throughout	440	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	241	6	First	1K-125	Miscellaneous	Tan baseboard mastic	Throughout	44	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	242	6	First	1K-126	Miscellaneous	Tan duct seam sealant on metal	Throughout above drop ceiling	20	SF	Good		2% Chrysotile	Low	O & M	H6-3	04	
DC	242	6	First	1K-126	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	75	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	242	6	First	1K-126	Miscellaneous	Yellow stone pattern linoleum	Throughout	120	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	242	6	First	1K-126	Miscellaneous	Yellow linoleum mastic	Throughout	120	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	242	6	First	1K-126	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout	120	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	242	6	First	1K-126	Miscellaneous	Drywall and joint compound	Throughout	440	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	242	6	First	1K-126	Miscellaneous	Tan baseboard mastic	Throughout	44	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	243	6	First	1K-127 through 1K168	Miscellaneous	Yellow carpet mastic	Throughout	600	SF	Good	Dental Clinic area currently under renovation	NAD	Low	n/a	H6-3	n/a	
DC	243	6	First	1K-127 through 1K168	Miscellaneous	White duct seam sealant on foil	Throughout	3600	SF	Good	Dental Clinic area currently under renovation	NAD	Low	n/a	H6-3	n/a	
DC	243	6	First	1K-127 through 1K168	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout	360	SF	Good	Dental Clinic area currently under renovation	NAD	Medium	n/a	H6-3	n/a	

Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	243	6	First	1K-127 through 1K168	Miscellaneous	White pipe seam sealant on paper	Throughout	200	LF	Good	Dental Clinic area currently under renovation	NAD	Low	n/a	H6-3	n/a	
DC	243	6	First	1K-127 through 1K168	Miscellaneous	Yellow stone pattern linoleum	Throughout	260	SF	Good	Dental Clinic area currently under renovation	NAD	High	n/a	H6-3	n/a	
DC	243	6	First	1K-127 through 1K168	Miscellaneous	Yellow linoleum mastic	Throughout	260	SF	Good	Dental Clinic area currently under renovation	NAD	Low	n/a	H6-3	n/a	
DC	243	6	First	1K-127 through 1K168	Miscellaneous	2' x 2' White Ceiling tile	Throughout	4800	SF	Good	Dental Clinic area currently under renovation	NAD	Medium	n/a	H6-3	n/a	
DC	243	6	First	1K-127 through 1K168	Miscellaneous	Gray floor sheeting	Throughout	1440	SF	Good	Dental Clinic area currently under renovation	NAD	High	n/a	H6-3	n/a	
DC	243	6	First	1K-127 through 1K168	Miscellaneous	Tan floor sheeting	Throughout	1080	SF	Good	Dental Clinic area currently under renovation	NAD	High	n/a	H6-3	n/a	
DC	243	6	First	1K-127 through 1K168	Miscellaneous	Yellow floor tile mastic	Throughout	4024	SF	Good	Dental Clinic area currently under renovation	NAD	Low	n/a	H6-3	n/a	
DC	243	6	First	1K-127 through 1K168	Miscellaneous	Tan floor sheeting mastic	Throughout	2520	SF	Good	Dental Clinic area currently under renovation	NAD	Low	n/a	H6-3	n/a	
DC	243	6	First	1K-127 through 1K168	Miscellaneous	12" x 12" Lt. Green mottle floor tile	Throughout	4004	SF	Good	Dental Clinic area currently under renovation	NAD	High	n/a	H6-3	n/a	
DC	243	6	First	1K-127 through 1K168	Miscellaneous	12" x 12" Dk. Blue mottle floor tile	Throughout	8	SF	Good	Dental Clinic area currently under renovation	NAD	High	n/a	H6-3	n/a	
DC	243	6	First	1K-127 through 1K168	Miscellaneous	12" x 12" Dk. Green mottle floor tile	Throughout	8	SF	Good	Dental Clinic area currently under renovation	NAD	High	n/a	H6-3	n/a	
DC	243	6	First	1K-127 through 1K168	Miscellaneous	Tan baseboard mastic	Throughout	1080	LF	Good	Dental Clinic area currently under renovation	NAD	Low	n/a	H6-3	n/a	
DC	243	6	First	1K-127 through 1K168	Miscellaneous	Drywall and joint compound	Throughout	10800	SF	Good	Dental Clinic area currently under renovation	NAD	High	n/a	H6-3	n/a	
DC	243	6	First	1K-127 through 1K168	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	60	SF	Good	Dental Clinic area currently under renovation	5%-10% Chrysotile	High	O & M	H6-3	01	
DC	243	6	First	1K-127 through 1K168	Miscellaneous	Black floor tile mastic	Throughout	60	SF	Good	Dental Clinic area currently under renovation	4%-5% Chrysotile	Low	O & M	H6-3	02	
DC	243	6	First	1K-127 through 1K168	Miscellaneous	Yellow ceramic tile mastic	Throughout	40	SF	Good	Dental Clinic area currently under renovation	NAD	Low	n/a	H6-3	n/a	

Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	243	6	First	1K-127 through 1K168	Miscellaneous	Fire door	Throughout	2 @ 3' x 7'	Doors	Good	Dental Clinic area currently under renovation (Labeled/Metal)	Assumed ACM	High	O & M	H6-3	N/A	
DC	243	6	First	1K-127 through 1K168	Surfacing	Gray spray-on fire proofing	Throughout	3000	SF	Good	Dental Clinic area currently under renovation	NAD	Low	n/a	H6-3	n/a	
DC	244	6	First	1K-123	Miscellaneous	Yellow carpet mastic	Throughout	120	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	244	6	First	1K-123	Miscellaneous	12" x 12" Tan mottle floor tile	Throughout under carpet	120	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	244	6	First	1K-123	Miscellaneous	Yellow floor tile mastic	Throughout under carpet	120	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	244	6	First	1K-123	Miscellaneous	Drywall and joint compound	Throughout walls and ceiling	560	SF	Good	No access above fixed ceiling	NAD	High	n/a	H6-3	n/a	
DC	244	6	First	1K-123	Miscellaneous	Tan baseboard mastic	Throughout	44	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	245	6	First	1K-124	Miscellaneous	Yellow stone pattern linoleum	Throughout	120	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	245	6	First	1K-124	Miscellaneous	Yellow linoleum mastic	Throughout	120	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	245	6	First	1K-124	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	10	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	245	6	First	1K-124	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	170	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	245	6	First	1K-124	Miscellaneous	Drywall and joint compound	Throughout	440	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	245	6	First	1K-124	Miscellaneous	Tan baseboard mastic	Throughout	44	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	245	6	First	1K-124	Miscellaneous	Fire door	South wall	1 @ 3' x 7'	Doors	Good	Labeled/Metal	Assumed ACM	High	O & M	H6-3	N/A	
DC	245	6	First	1K-124	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout	120	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	246	6	First	1K-137	Miscellaneous	Yellow carpet mastic	Throughout	120	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	246	6	First	1K-137	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout	120	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	246	6	First	1K-137	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	30	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	246	6	First	1K-137	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	170	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	246	6	First	1K-137	Miscellaneous	Drywall and joint compound	Throughout	440	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	246	6	First	1K-137	Miscellaneous	Tan baseboard mastic	Throughout	44	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	247	6	First	1K-113	Miscellaneous	Yellow stone pattern linoleum	Throughout	120	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	247	6	First	1K-113	Miscellaneous	Yellow linoleum mastic	Throughout	120	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	247	6	First	1K-113	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	180	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	247	6	First	1K-113	Miscellaneous	Tan duct seam sealant on metal	Throughout above drop ceiling	2	SF	Good		2% Chrysotile	Low	O & M	H6-3	04	
DC	247	6	First	1K-113	Miscellaneous	Tan baseboard mastic	Throughout	120	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	247	6	First	1K-113	Miscellaneous	Drywall and joint compound	Throughout	120	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	247	6	First	1K-113	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout	120	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	248	6	First	1K-112	Miscellaneous	Yellow stone pattern linoleum	Throughout	120	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	248	6	First	1K-112	Miscellaneous	Yellow linoleum mastic	Throughout	120	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	248	6	First	1K-112	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	180	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	248	6	First	1K-112	Miscellaneous	Tan duct seam sealant on metal	Throughout above drop ceiling	2	SF	Good		2% Chrysotile	Low	O & M	H6-3	04	
DC	248	6	First	1K-112	Miscellaneous	Tan baseboard mastic	Throughout	120	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	248	6	First	1K-112	Miscellaneous	Drywall and joint compound	Throughout	120	SF	Good		NAD	High	n/a	H6-3	n/a	

Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	248	6	First	1K-112	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout	120	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	249	6	First	1K-111	Miscellaneous	Yellow stone pattern linoleum	Throughout	120	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	249	6	First	1K-111	Miscellaneous	Yellow linoleum mastic	Throughout	120	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	249	6	First	1K-111	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	180	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	249	6	First	1K-111	Miscellaneous	Tan duct seam sealant on metal	Throughout above drop ceiling	2	SF	Good		2% Chrysotile	Low	O & M	H6-3	04	
DC	249	6	First	1K-111	Miscellaneous	Tan baseboard mastic	Throughout	120	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	249	6	First	1K-111	Miscellaneous	Drywall and joint compound	Throughout	120	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	249	6	First	1K-111	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout	120	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	250	6	First	1K-110	Miscellaneous	Yellow stone pattern linoleum	Throughout	120	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	250	6	First	1K-110	Miscellaneous	Yellow linoleum mastic	Throughout	120	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	250	6	First	1K-110	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	180	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	250	6	First	1K-110	Miscellaneous	Tan duct seam sealant on metal	Throughout above drop ceiling	2	SF	Good		2% Chrysotile	Low	O & M	H6-3	04	
DC	250	6	First	1K-110	Miscellaneous	Tan baseboard mastic	Throughout	120	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	250	6	First	1K-110	Miscellaneous	Drywall and joint compound	Throughout	120	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	250	6	First	1K-110	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout	120	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	251	6	First	1K-109	Miscellaneous	Yellow stone pattern linoleum	Throughout	120	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	251	6	First	1K-109	Miscellaneous	Yellow linoleum mastic	Throughout	120	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	251	6	First	1K-109	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	180	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	251	6	First	1K-109	Miscellaneous	Tan duct seam sealant on metal	Throughout above drop ceiling	2	SF	Good		2% Chrysotile	Low	O & M	H6-3	04	
DC	251	6	First	1K-109	Miscellaneous	Tan baseboard mastic	Throughout	120	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	251	6	First	1K-109	Miscellaneous	Drywall and joint compound	Throughout	120	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	251	6	First	1K-109	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout	120	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	252	6	First	1K-108	Miscellaneous	Yellow stone pattern linoleum	Throughout	72	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	252	6	First	1K-108	Miscellaneous	Yellow linoleum mastic	Throughout	72	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	252	6	First	1K-108	Miscellaneous	Drywall and joint compound	Throughout	360	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	252	6	First	1K-108	Miscellaneous	Tan baseboard mastic	Throughout	36	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	252	6	First	1K-108	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout	72	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	252	6	First	1K-108	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	30	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	253	6	First	1K-108A	Miscellaneous	Yellow stone pattern linoleum	Throughout	72	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	253	6	First	1K-108A	Miscellaneous	Yellow linoleum mastic	Throughout	72	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	253	6	First	1K-108A	Miscellaneous	Drywall and joint compound	Throughout	360	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	253	6	First	1K-108A	Miscellaneous	Tan baseboard mastic	Throughout	36	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	253	6	First	1K-108A	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout	72	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	253	6	First	1K-108A	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	70	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	253	6	First	1K-108A	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	10	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	254	6	First	1K-107	Miscellaneous	Yellow stone pattern linoleum	Throughout	120	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	254	6	First	1K-107	Miscellaneous	Yellow linoleum mastic	Throughout	120	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	254	6	First	1K-107	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	180	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	254	6	First	1K-107	Miscellaneous	Tan duct seam sealant on metal	Throughout above drop ceiling	2	SF	Good		2% Chrysotile	Low	O & M	H6-3	04	
DC	254	6	First	1K-107	Miscellaneous	Tan baseboard mastic	Throughout	120	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	254	6	First	1K-107	Miscellaneous	Drywall and joint compound	Throughout	120	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	254	6	First	1K-107	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout	120	SF	Good		NAD	Medium	n/a	H6-3	n/a	

Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	255	6	First	1K-105	Miscellaneous	Yellow stone pattern linoleum	Throughout	120	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	255	6	First	1K-105	Miscellaneous	Yellow linoleum mastic	Throughout	120	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	255	6	First	1K-105	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	180	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	255	6	First	1K-105	Miscellaneous	Tan duct seam sealant on metal	Throughout above drop ceiling	2	SF	Good		2% Chrysotile	Low	O & M	H6-3	04	
DC	255	6	First	1K-105	Miscellaneous	Tan baseboard mastic	Throughout	120	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	255	6	First	1K-105	Miscellaneous	Drywall and joint compound	Throughout	120	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	255	6	First	1K-105	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout	120	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	256	6	First	1K-106	Miscellaneous	Yellow stone pattern linoleum	Throughout	140	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	256	6	First	1K-106	Miscellaneous	Yellow linoleum mastic	Throughout	140	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	256	6	First	1K-106	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout	140	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	256	6	First	1K-106	Miscellaneous	Drywall and joint compound	Throughout	480	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	256	6	First	1K-106	Miscellaneous	Tan baseboard mastic	Throughout	48	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	256	6	First	1K-106	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	40	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	256	6	First	1K-106	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	125	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	256	6	First	1K-106	Miscellaneous	Yellow stone pattern linoleum	Throughout	140	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	256	6	First	1K-106	Miscellaneous	Yellow linoleum mastic	Throughout	140	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	256	6	First	1K-106	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout	140	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	256	6	First	1K-106	Miscellaneous	Drywall and joint compound	Throughout walls	480	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	256	6	First	1K-106	Miscellaneous	Tan baseboard mastic	Throughout walls	48	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	256	6	First	1K-106	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	40	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	256	6	First	1K-106	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	125	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	257	6	First	1K-135; 1K-136	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout	420	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	257	6	First	1K-135; 1K-136	Miscellaneous	Yellow carpet mastic	Throughout	420	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	257	6	First	1K-135; 1K-136	Miscellaneous	Tan baseboard mastic	Throughout	84	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	257	6	First	1K-135; 1K-136	Miscellaneous	Drywall and joint compound	Throughout	840	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	257	6	First	1K-135; 1K-136	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	700	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	257	6	First	1K-135; 1K-136	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	170	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	257	6	First	1K-135; 1K-136	Miscellaneous	Yellow linoleum mastic	Throughout	70	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	257	6	First	1K-135; 1K-136	Miscellaneous	Yellow stone pattern linoleum	Throughout	70	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	258	6	First	1K-138	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	180	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	258	6	First	1K-138	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	40	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	258	6	First	1K-138	Miscellaneous	Tan baseboard mastic	Throughout	48	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	258	6	First	1K-138	Miscellaneous	Drywall and joint compound	Throughout	480	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	258	6	First	1K-138	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout	144	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	258	6	First	1K-138	Miscellaneous	Yellow carpet mastic	Throughout	144	SF	Good		NAD	Low	n/a	H6-3	n/a	

**Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6**

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	259	6	First	1K-140	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	750	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	259	6	First	1K-140	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	190	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	259	6	First	1K-140	Miscellaneous	Tan baseboard mastic	Throughout	112	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	259	6	First	1K-140	Miscellaneous	Drywall and joint compound	Throughout	1120	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	259	6	First	1K-140	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout	748	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	259	6	First	1K-140	Miscellaneous	Yellow carpet mastic	Throughout	748	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	259	6	First	1K-140	Miscellaneous	Yellow ceramic tile mastic	Throughout	80	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	259	6	First	1K-140	Miscellaneous	Yellow carpet mastic	Throughout	748	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	259	6	First	1K-140	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout ceiling	748	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	259	6	First	1K-140	Miscellaneous	Tan baseboard mastic	Throughout walls	112	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	259	6	First	1K-140	Miscellaneous	Drywall and joint compound	Throughout walls	1120	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	259	6	First	1K-140	Miscellaneous	Yellow ceramic tile mastic	South wall	80	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	259	6	First	1K-140	Surfacing	Gray spray-on fire proofing	Througghout above drop ceiling	75	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	259	6	First	1K-140	Miscellaneous	White duct seam sealant on foil	Througghout above drop ceiling	190	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	260	6	First	1K-134	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	220	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	260	6	First	1K-134	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	65	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	260	6	First	1K-134	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout ceiling	240	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	260	6	First	1K-134	Miscellaneous	Yellow stone pattern linoleum	Throughout	180	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	260	6	First	1K-134	Miscellaneous	Yellow linoleum mastic	Throughout	76	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	260	6	First	1K-134	Miscellaneous	Tan baseboard mastic	Throughout	760	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	260	6	First	1K-134	Miscellaneous	Drywall and joint compound	Throughout	60	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	260	6	First	1K-134	Miscellaneous	Tan floor sheeting	Throughout	60	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	260	6	First	1K-134	Miscellaneous	Tan floor sheeting mastic	Throughout	60	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	261	6	First	1K-133	Miscellaneous	White sink mastic	South wall	1 @ 2' x 2'	Sinks	Good		NAD	Medium	n/a	H6-3	n/a	
DC	261	6	First	1K-133	Miscellaneous	Yellow stone pattern linoleum	Throughout	96	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	261	6	First	1K-133	Miscellaneous	Yellow linoleum mastic	Throughout	96	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	261	6	First	1K-133	Miscellaneous	Green duct seam sealant on metal	Throughout above drop ceiling	10	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	261	6	First	1K-133	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	20	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	261	6	First	1K-133	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	70	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	261	6	First	1K-133	Miscellaneous	Tan baseboard mastic	Throughout walls	40	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	261	6	First	1K-133	Miscellaneous	Drywall and joint compound	Throughout walls	400	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	261	6	First	1K-133	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout ceiling	96	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	262	6	First	1K-143	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	75	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	262	6	First	1K-143	Miscellaneous	Tan duct seam sealant on metal	Throughout above drop ceiling	10	SF	Good		2% Chrysotile	Low	O & M	H6-3	04	
DC	262	6	First	1K-143	Miscellaneous	Tan floor sheeting	Throughout Floor	144	SF	Good		5%-10% Chrysotile	High	O & M	H6-3		
DC	262	6	First	1K-143	Miscellaneous	Tan floor sheeting mastic	Throughout Floor	144	SF	Good		5%-10% Chrysotile	Low	O & M	H6-3		
DC	262	6	First	1K-143	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout ceiling	144	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	262	6	First	1K-143	Miscellaneous	Drywall and joint compound	Throughout walls	480	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	263	6	First	1K-145	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	75	SF	Good		NAD	Low	n/a	H6-3	n/a	

Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	263	6	First	1K-145	Miscellaneous	Tan duct seam sealant on metal	Throughout above drop ceiling	10	SF	Good		2% Chrysotile	Low	O & M	H6-3	04	
DC	263	6	First	1K-145	Miscellaneous	Tan floor sheeting	Throughout Floor	144	SF	Good		5%-10% Chrysotile	High	O & M	H6-3		
DC	263	6	First	1K-145	Miscellaneous	Tan floor sheeting mastic	Throughout Floor	144	SF	Good		5%-10% Chrysotile	Low	O & M	H6-3		
DC	263	6	First	1K-145	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout ceiling	144	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	263	6	First	1K-145	Miscellaneous	Drywall and joint compound	Throughout walls	480	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	263	6	First	1K-145	Miscellaneous	White pipe seam sealant on paper	Throughout	6	LF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	264	6	First	1K-144	Miscellaneous	12" x 12" Tan mottle floor tile	Throughout Floor	144	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	264	6	First	1K-144	Miscellaneous	12" x 12" Brown mottle floor tile	Throughout Floor	144	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	264	6	First	1K-144	Miscellaneous	Yellow floor tile mastic	Throughout Floor	188	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	264	6	First	1K-144	Miscellaneous	Tan baseboard mastic	Throughout walls	48	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	264	6	First	1K-144	Miscellaneous	Drywall and joint compound	Throughout walls	480	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	264	6	First	1K-144	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout ceiling	144	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	264	6	First	1K-144	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	135	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	264	6	First	1K-144	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	10	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	265	6	First	1K-153	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	80	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	265	6	First	1K-153	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	140	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	265	6	First	1K-153	Miscellaneous	12" x 12" Lt. Blue mottle floor tile	Throughout	36	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	265	6	First	1K-153	Miscellaneous	12" x 12" Tan mottle floor tile	Throughout	44	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	265	6	First	1K-153	Miscellaneous	Yellow floor tile mastic	Throughout	80	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	265	6	First	1K-153	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout	80	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	265	6	First	1K-153	Miscellaneous	Tan baseboard mastic	Throughout walls	36	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	265	6	First	1K-153	Miscellaneous	Drywall and joint compound	Throughout walls	360	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	266	6	First	1K-152	Miscellaneous	Yellow stone pattern linoleum	Throughout	160	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	266	6	First	1K-152	Miscellaneous	Yellow stone pattern linoleum	Throughout	160	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	266	6	First	1K-152	Miscellaneous	Drywall and joint compound	Throughout walls	400	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	266	6	First	1K-152	Miscellaneous	Tan baseboard mastic	Throughout walls	40	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	266	6	First	1K-152	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout ceiling	100	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	266	6	First	1K-152	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	20	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	266	6	First	1K-152	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	170	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	267	6	First	1K-151	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	267	6	First	1K-151	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	25	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	267	6	First	1K-151	Miscellaneous	Drywall and joint compound	Throughout walls	440	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	267	6	First	1K-151	Miscellaneous	Tan baseboard mastic	Throughout walls	44	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	267	6	First	1K-151	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout ceiling	120	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	267	6	First	1K-151	Miscellaneous	Yellow linoleum mastic	Throughout Floor	120	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	268	6	First	1K-150	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-3	n/a	

Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	268	6	First	1K-150	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	25	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	268	6	First	1K-150	Miscellaneous	Drywall and joint compound	Throughout walls	440	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	268	6	First	1K-150	Miscellaneous	Tan baseboard mastic	Throughout walls	44	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	268	6	First	1K-150	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout ceiling	120	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	268	6	First	1K-150	Miscellaneous	Yellow linoleum mastic	Throughout Floor	120	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	269	6	First	1K-147	Miscellaneous	Tan with brown specks floor sheeting	Throughout	144	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	269	6	First	1K-147	Miscellaneous	Tan floor sheeting mastic	Throughout	144	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	269	6	First	1K-147	Miscellaneous	Drywall and joint compound	Throughout walls	480	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	269	6	First	1K-147	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	6	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	269	6	First	1K-147	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	10	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	269	6	First	1K-147	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	80	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	269	6	First	1K-147	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout above drop ceiling	144	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	270	6	First	1K-148	Miscellaneous	Tan with brown specks floor sheeting	Throughout	144	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	270	6	First	1K-148	Miscellaneous	Tan floor sheeting mastic	Throughout	144	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	270	6	First	1K-148	Miscellaneous	Drywall and joint compound	Throughout walls	480	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	270	6	First	1K-148	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	6	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	270	6	First	1K-148	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	10	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	270	6	First	1K-148	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	80	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	270	6	First	1K-148	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout above drop ceiling	144	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	271	6	First	1K-149	Miscellaneous	Tan with brown specks floor sheeting	Throughout	144	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	271	6	First	1K-149	Miscellaneous	Tan floor sheeting mastic	Throughout	144	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	271	6	First	1K-149	Miscellaneous	Drywall and joint compound	Throughout walls	480	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	271	6	First	1K-149	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	6	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	271	6	First	1K-149	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	10	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	271	6	First	1K-149	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	80	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	271	6	First	1K-149	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout above drop ceiling	144	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	272	6	First	1K-146	Miscellaneous	Tan with brown specks floor sheeting	Throughout	144	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	272	6	First	1K-146	Miscellaneous	Tan floor sheeting mastic	Throughout	144	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	272	6	First	1K-146	Miscellaneous	Drywall and joint compound	Throughout walls	480	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	272	6	First	1K-146	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	6	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	272	6	First	1K-146	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	10	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	272	6	First	1K-146	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	80	SF	Good		NAD	Low	n/a	H6-3	n/a	

**Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6**

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	272	6	First	1K-146	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout above drop ceiling	144	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	273	6	First	Corridor	Miscellaneous	Red fire stop	Throughout above drop ceiling	20	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	273	6	First	Corridor	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	250	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	273	6	First	Corridor	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	450	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	273	6	First	Corridor	Miscellaneous	12" x 12" Green mottle floor tile	Throughout Floor	368	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	273	6	First	Corridor	Miscellaneous	Yellow floor tile mastic	Throughout Floor	368	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	273	6	First	Corridor	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout ceiling	368	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	273	6	First	Corridor	Miscellaneous	Tan baseboard mastic	Throughout walls	108	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	273	6	First	Corridor	Miscellaneous	Drywall and joint compound	Throughout walls	1080	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	274	6	First	1K-141	Miscellaneous	Drywall and joint compound	Throughout walls and ceiling	620	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	274	6	First	1K-141	Miscellaneous	Yellow ceramic tile mastic	Throughout walls	180	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	275	6	First	1K-142	Miscellaneous	Drywall and joint compound	Throughout walls and ceiling	620	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	275	6	First	1K-142	Miscellaneous	Yellow ceramic tile mastic	Throughout walls	180	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	276	6	First	Corridor	Miscellaneous	Yellow carpet mastic	Throughout	200	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	276	6	First	Corridor	Miscellaneous	12" x 12" Lt. Green mottle floor tile	Throughout	600	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	276	6	First	Corridor	Miscellaneous	Yellow floor tile mastic	Throughout	1200	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	276	6	First	Corridor	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout	800	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	276	6	First	Corridor	Miscellaneous	12" x 12" Tan mottle floor tile	Throughout	600	SF	Good	under 12"x12" Lt. Green	NAD	Low	n/a	H6-3	n/a	
DC	276	6	First	Corridor	Miscellaneous	Drywall and joint compound	Throughout walls	2180	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	276	6	First	Corridor	Miscellaneous	Tan baseboard mastic	Throughout walls	218	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	276	6	First	Corridor	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	550	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	276	6	First	Corridor	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	110	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	276	6	First	Corridor	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	1200	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	277	6	First	Corridor	Miscellaneous	Drywall and joint compound	Throughout walls	2800	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	277	6	First	Corridor	Miscellaneous	Tan baseboard mastic	Throughout walls	280	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	277	6	First	Corridor	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout ceiling	1056	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	277	6	First	Corridor	Miscellaneous	Yellow carpet mastic	Throughout	1056	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	277	6	First	Corridor	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	450	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	277	6	First	Corridor	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	350	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	277	6	First	Corridor	Miscellaneous	Fire door	North Wall	2 @ 4' x 7'	Door	Good	Labeled/Wood	Assumed ACM	High	O & M	H6-3	N/A	
DC	278	6	First	1K-104	Miscellaneous	Yellow stone pattern linoleum	Throughout	120	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	278	6	First	1K-104	Miscellaneous	Yellow linoleum mastic	Throughout	120	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	278	6	First	1K-104	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	180	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	278	6	First	1K-104	Miscellaneous	Tan duct seam sealant on metal	Throughout above drop ceiling	2	SF	Good		2% Chrysotile	Low	O & M	H6-3	04	
DC	278	6	First	1K-104	Miscellaneous	Tan baseboard mastic	Throughout	120	LF	Good		NAD	Low	n/a	H6-3	n/a	

Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	278	6	First	1K-104	Miscellaneous	Drywall and joint compound	Throughout	120	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	278	6	First	1K-104	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout	120	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	279	6	First	1K-100	Miscellaneous	Yellow stone pattern linoleum	Throughout	120	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	279	6	First	1K-100	Miscellaneous	Yellow linoleum mastic	Throughout	120	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	279	6	First	1K-100	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	180	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	279	6	First	1K-100	Miscellaneous	Tan duct seam sealant on metal	Throughout above drop ceiling	2	SF	Good		2% Chrysotile	Low	O & M	H6-3	04	
DC	279	6	First	1K-100	Miscellaneous	Tan baseboard mastic	Throughout	120	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	279	6	First	1K-100	Miscellaneous	Drywall and joint compound	Throughout	120	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	279	6	First	1K-100	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout	120	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	280	6	First	1K-101,102,103	Miscellaneous	Tan duct seam sealant on metal	Throughout above drop ceiling	50	SF	Good		2% Chrysotile	Low	O & M	H6-3	04	
DC	280	6	First	1K-101,102,103	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	360	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	280	6	First	1K-101,102,103	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	700	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	280	6	First	1K-101,102,103	Miscellaneous	Yellow stone pattern linoleum	Throughout	704	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	280	6	First	1K-101,102,103	Miscellaneous	Yellow linoleum mastic	Throughout	704	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	280	6	First	1K-101,102,103	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout	960	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	280	6	First	1K-101,102,103	Miscellaneous	Yellow carpet mastic	Throughout	256	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	280	6	First	1K-101,102,103	Miscellaneous	Tan baseboard mastic	Throughout walls	240	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	280	6	First	1K-101,102,103	Miscellaneous	Drywall and joint compound	Throughout walls	2400	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	280	6	First	1K-101,102,103	Miscellaneous	Fire door	North Wall	2 @ 4' x 7'	Door	Good	Labeled/Wood	Assumed ACM	High	O & M	H6-3	N/A	
DC	281	6	First	Hall	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout	3630	SF	Good		NAD	Medium	n/a	H6-3	n/a	
DC	281	6	First	Hall	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	3630	SF	Good		5%-10% Chrysotile	High	O & M	H6-3	01	
DC	281	6	First	Hall	Miscellaneous	Black floor tile mastic	Throughout	3630	SF	Good		4%-5% Chrysotile	Low	O & M	H6-3	02	
DC	281	6	First	Hall	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	2950	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	281	6	First	Hall	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	2110	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	281	6	First	Hall	Miscellaneous	Red fire stop	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	281	6	First	Hall	Miscellaneous	Drywall and joint compound	Throughout walls	9300	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	281	6	First	Hall	Miscellaneous	Tan baseboard mastic	All walls	700	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	281	6	First	Hall	Miscellaneous	Tan duct seam sealant on metal	Throughout above drop ceiling	145	SF	Good		2% Chrysotile	Low	O & M	H6-3	04	
DC	281	6	First	Hall	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	90	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	281	6	First	Hall	Miscellaneous	12" x 12" Green mottle floor tile	Entrance to Bldg 1	55	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	281	6	First	Hall	Miscellaneous	12" x 12" White with Green Specks floor tile	Ent. To Bldg 1	25	SF	Good		NAD	High	n/a	H6-3	n/a	

Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	281	6	First	Hall	Miscellaneous	Yellow floor tile mastic	Ent. To Bldg 1	80	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	281	6	First	Hall	Miscellaneous	Fire door	Throughout	10 @ 4' x 7'	Door	Good	Labeled/Wood	Assumed ACM	High	O & M	H6-3	N/A	
DC	281A	6	First	Stair 19	Miscellaneous	12" x 12" Lt. Green mottle floor tile	Throughout	100	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	281A	6	First	Stair 19	Miscellaneous	Yellow floor tile mastic	Throughout	100	SF	Good		NAD	Low	n/a	H6-3	n/a	
DC	281A	6	First	Stair 19	Miscellaneous	Fire door	West Wall	1 @ 4' x 7'	Door	Good	Labeled/Wood	Assumed ACM	High	O & M	H6-3	N/A	
DC	281A	6	First	Stair 19	Miscellaneous	Tan baseboard mastic	Throughout walls	40	LF	Good		NAD	Low	n/a	H6-3	n/a	
DC	281A	6	First	Stair 19	Miscellaneous	Drywall and joint compound	Throughout walls	400	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	282	6	Second	2J-125A	Miscellaneous	Yellow ceramic tile mastic	All walls	450	SF	Good		NAD	High	n/a	H6-3	n/a	
DC	282	6	Second	2J-125A	Miscellaneous	Drywall and joint compound	Throughout walls and ceiling	1250	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	283	6	Second	2J-125B	Miscellaneous	Yellow ceramic tile mastic	All walls	550	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	283	6	Second	2J-125B	Miscellaneous	Drywall and joint compound	Throughout walls and ceiling	1500	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	284	6	Second	2J-127	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	10	LF	Good		NAD	Low	n/a	H6-5	n/a	
DC	284	6	Second	2J-127	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	250	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	284	6	Second	2J-127	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	120	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	284	6	Second	2J-127	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout	365	SF	Good		NAD	Medium	n/a	H6-5	n/a	
DC	284	6	Second	2J-127	Miscellaneous	Yellow carpet mastic	Throughout	365	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	284	6	Second	2J-127	Miscellaneous	Tan baseboard mastic	All walls	82	LF	Good		NAD	Low	n/a	H6-5	n/a	
DC	284	6	Second	2J-127	Miscellaneous	Drywall and joint compound	Throughout walls	900	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	284	6	Second	2J-127	Miscellaneous	Black mastic on metal window frame	North Wall	1 @ 6' x 8'	Window	Good		NAD	Low	n/a	H6-5	n/a	
DC	285	6	Second	2J-128	Miscellaneous	Yellow carpet mastic	Throughout	280	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	285	6	Second	2J-128	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout	280	SF	Good		NAD	Medium	n/a	H6-5	n/a	
DC	285	6	Second	2J-128	Miscellaneous	Tan baseboard mastic	All walls	76	LF	Good		NAD	Low	n/a	H6-5	n/a	
DC	285	6	Second	2J-128	Miscellaneous	Drywall and joint compound	Throughout walls	950	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	285	6	Second	2J-128	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	300	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	285	6	Second	2J-128	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	200	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	285	6	Second	2J-128	Miscellaneous	Black mastic on metal window frame	North Wall	1 @ 6' x 8'	Window	Good		NAD	Low	n/a	H6-5	n/a	
DC	285	6	Second	2J-128	Miscellaneous	Black floor tile mastic	Throughout	280	SF	Good	Residual	4%-5% Chrysotile	Low	O & M	H6-5	02	
DC	286	6	Second	Employee Lounge	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	40	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	286	6	Second	Employee Lounge	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	300	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	286	6	Second	Employee Lounge	Miscellaneous	12" x 12" Tan mottle floor tile	Throughout	280	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	286	6	Second	Employee Lounge	Miscellaneous	Yellow floor tile mastic	Throughout	280	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	286	6	Second	Employee Lounge	Miscellaneous	Tan baseboard mastic	All walls	72	LF	Good		NAD	Low	n/a	H6-5	n/a	
DC	286	6	Second	Employee Lounge	Miscellaneous	Drywall and joint compound	Throughout walls	720	SF	Good		NAD	High	n/a	H6-5	n/a	

Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	286	6	Second	Employee Lounge	Miscellaneous	Black mastic on metal window frame	North Wall	1 @ 6' x 8'	Window	Good		NAD	Low	n/a	H6-5	n/a	
DC	286	6	Second	Employee Lounge	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout	280	SF	Good		NAD	Medium	n/a	H6-5	n/a	
DC	287	6	Second	Male Locker Room	Miscellaneous	Drywall and joint compound	Throughout walls and ceiling	1650	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	287	6	Second	Male Locker Room	Miscellaneous	Yellow ceramic tile mastic	All walls	450	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	287	6	Second	Male Locker Room	Miscellaneous	Brown baseboard mastic	Locker	20	LF	Good		NAD	Low	n/a	H6-5	n/a	
DC	288	6	Second	Womens Locker Room	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	420	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	288	6	Second	Womens Locker Room	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	120	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	288	6	Second	Womens Locker Room	Miscellaneous	Red fire stop	Throughout above drop ceiling	20	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	288	6	Second	Womens Locker Room	Miscellaneous	12" x 12" Blue mottle floor tile	Throughout	336	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	288	6	Second	Womens Locker Room	Miscellaneous	Yellow floor tile mastic	Throughout	336	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	288	6	Second	Womens Locker Room	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout	336	SF	Good		NAD	Medium	n/a	H6-5	n/a	
DC	288	6	Second	Womens Locker Room	Miscellaneous	Drywall and joint compound	Throughout walls	2000	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	288	6	Second	Womens Locker Room	Miscellaneous	Brown baseboard mastic	All walls	80	LF	Good		NAD	Low	n/a	H6-5	n/a	
DC	288	6	Second	Womens Locker Room	Miscellaneous	Yellow ceramic tile mastic	Bathroom walls	400	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	288	6	Second	Womens Locker Room	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	336	SF	Good		5%-10% Chrysotile	Low	O & M	H6-5	01	
DC	288	6	Second	Womens Locker Room	Miscellaneous	Black floor tile mastic	Throughout	336	SF	Good		4%-5% Chrysotile	Low	O & M	H6-5	02	
DC	289	6	Second	2H-100	Miscellaneous	12" x 12" Dk. Blue mottle floor tile	Throughout	15	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	289	6	Second	2H-100	Miscellaneous	Yellow floor tile mastic	Throughout	30	SF	Good	both layers under 12x12 Dark Blue	NAD	Low	n/a	H6-5	n/a	
DC	289	6	Second	2H-100	Miscellaneous	12" x 12" Blue mottle floor tile	Throughout	15	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	289	6	Second	2H-100	Miscellaneous	Tan baseboard mastic	All walls	15	LF	Good		NAD	Low	n/a	H6-5	n/a	
DC	289	6	Second	2H-100	Miscellaneous	Drywall and joint compound	Throughout walls	150	SF	Damaged		NAD	Medium	n/a	H6-5	n/a	
DC	289	6	Second	2H-100	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	15	SF	Good		NAD	Medium	n/a	H6-5	n/a	
DC	289	6	Second	2H-100	Miscellaneous	Fire door	East Wall	1 @ 3' x 7'	Door	Good	Labeled/Wood	Assumed ACM	High	O & M	H6-5	N/A	
DC	290	6	Second	2H-101	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	650	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	290	6	Second	2H-101	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	120	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	290	6	Second	2H-101	Miscellaneous	Tan duct seam sealant on metal	Throughout above drop ceiling	15	SF	Good		2% Chrysotile	Low	O & M	H6-5	04	
DC	290	6	Second	2H-101	Miscellaneous	12" x 12" Lt. Blue mottle floor tile	Throughout	415	SF	Good		NAD	Medium	n/a	H6-5	n/a	

**Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6**

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	290	6	Second	2H-101	Miscellaneous	Yellow floor tile mastic	Throughout	415	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	290	6	Second	2H-101	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	415	SF	Good		NAD	Medium	n/a	H6-5	n/a	
DC	290	6	Second	2H-101	Miscellaneous	Black mastic on metal window frame	West Wall	1 @ 4' x 6'	Window	Good		NAD	Low	n/a	H6-5	n/a	
DC	290	6	Second	2H-101	Miscellaneous	Tan baseboard mastic	All walls	85	LF	Good		NAD	Low	n/a	H6-5	n/a	
DC	290	6	Second	2H-101	Miscellaneous	Drywall and joint compound	Throughout walls	1100	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	290	6	Second	2H-101	Miscellaneous	Yellow ceramic tile mastic	Bathroom walls	360	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	291	6	Second	2H-102	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	325	SF	Good		NAD	Medium	n/a	H6-5	n/a	
DC	291	6	Second	2H-102	Miscellaneous	12" x 12" Lt. Blue mottle floor tile	Throughout	325	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	291	6	Second	2H-102	Miscellaneous	Yellow floor tile mastic	Throughout	325	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	291	6	Second	2H-102	Miscellaneous	Tan baseboard mastic	All walls	75	LF	Good		NAD	Low	n/a	H6-5	n/a	
DC	291	6	Second	2H-102	Miscellaneous	Drywall and joint compound	Throughout walls	1000	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	291	6	Second	2H-102	Miscellaneous	Black mastic on metal window frame	West Wall	1 @ 4' x 6'	Window	Good		NAD	High	n/a	H6-5	n/a	
DC	291	6	Second	2H-102	Miscellaneous	Yellow ceramic tile mastic	Bathroom walls	440	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	291	6	Second	2H-102	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	440	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	291	6	Second	2H-102	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	120	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	292	6	Second	2H-104	Miscellaneous	12" x 12" Tan mottle floor tile	Throughout	400	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	292	6	Second	2H-104	Miscellaneous	Yellow floor tile mastic	Throughout	400	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	292	6	Second	2H-104	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	400	SF	Good		NAD	Medium	n/a	H6-5	n/a	
DC	292	6	Second	2H-104	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	1000	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	292	6	Second	2H-104	Miscellaneous	Tan baseboard mastic	All walls	82	LF	Good		NAD	Low	n/a	H6-5	n/a	
DC	292	6	Second	2H-104	Miscellaneous	Drywall and joint compound	Throughout walls	1000	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	292	6	Second	2H-104	Miscellaneous	Yellow ceramic tile mastic	Bathroom	520	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	292	6	Second	2H-104	Miscellaneous	Black mastic on metal window frame	West Wall	2 @ 6' x 6'	Window	Good		NAD	Low	n/a	H6-5	n/a	
DC	293	6	Second	2H-106	Miscellaneous	12" x 12" Tan mottle floor tile	Throughout	325	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	293	6	Second	2H-106	Miscellaneous	Yellow floor tile mastic	Throughout	325	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	293	6	Second	2H-106	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	800	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	293	6	Second	2H-106	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	325	SF	Good		NAD	Medium	n/a	H6-5	n/a	
DC	293	6	Second	2H-106	Miscellaneous	Tan baseboard mastic	All walls	75	LF	Good		NAD	Low	n/a	H6-5	n/a	
DC	293	6	Second	2H-106	Miscellaneous	Drywall and joint compound	Throughout walls	1000	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	293	6	Second	2H-106	Miscellaneous	Yellow ceramic tile mastic	Bathroom	440	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	293	6	Second	2H-106	Miscellaneous	Black mastic on metal window frame	West Wall	1 @ 6' x 6'	Window	Good		NAD	High	n/a	H6-5	n/a	
DC	294	6	Second	2H-108	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	325	SF	Good		NAD	Medium	n/a	H6-5	n/a	
DC	294	6	Second	2H-108	Miscellaneous	12" x 12" Lt. Blue mottle floor tile	Throughout	325	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	294	6	Second	2H-108	Miscellaneous	Yellow floor tile mastic	Throughout	325	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	294	6	Second	2H-108	Miscellaneous	Tan baseboard mastic	All walls	75	LF	Good		NAD	Low	n/a	H6-5	n/a	
DC	294	6	Second	2H-108	Miscellaneous	Drywall and joint compound	Throughout walls	1000	SF	Good		NAD	High	n/a	H6-5	n/a	

Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	294	6	Second	2H-108	Miscellaneous	Black mastic on metal window frame	West Wall	1 @ 4' x 6'	Window	Good		NAD	High	n/a	H6-5	n/a	
DC	294	6	Second	2H-108	Miscellaneous	Yellow ceramic tile mastic	Bathroom walls	440	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	294	6	Second	2H-108	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	440	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	294	6	Second	2H-108	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	120	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	295	6	Second	2H-110	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	325	SF	Good		NAD	Medium	n/a	H6-5	n/a	
DC	295	6	Second	2H-110	Miscellaneous	12" x 12" Lt. Blue mottle floor tile	Throughout	325	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	295	6	Second	2H-110	Miscellaneous	Yellow floor tile mastic	Throughout	325	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	295	6	Second	2H-110	Miscellaneous	Tan baseboard mastic	All walls	75	LF	Good		NAD	Low	n/a	H6-5	n/a	
DC	295	6	Second	2H-110	Miscellaneous	Drywall and joint compound	Throughout walls	1000	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	295	6	Second	2H-110	Miscellaneous	Black mastic on metal window frame	West Wall	1 @ 4' x 6'	Window	Good		NAD	High	n/a	H6-5	n/a	
DC	295	6	Second	2H-110	Miscellaneous	Yellow ceramic tile mastic	Bathroom walls	440	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	295	6	Second	2H-110	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	440	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	295	6	Second	2H-110	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	120	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	296	6	Second	2H-112	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	325	SF	Good		NAD	Medium	n/a	H6-5	n/a	
DC	296	6	Second	2H-112	Miscellaneous	12" x 12" Lt. Blue mottle floor tile	Throughout	325	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	296	6	Second	2H-112	Miscellaneous	Yellow floor tile mastic	Throughout	325	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	296	6	Second	2H-112	Miscellaneous	Tan baseboard mastic	All walls	75	LF	Good		NAD	Low	n/a	H6-5	n/a	
DC	296	6	Second	2H-112	Miscellaneous	Drywall and joint compound	Throughout walls	1000	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	296	6	Second	2H-112	Miscellaneous	Black mastic on metal window frame	West Wall	1 @ 4' x 6'	Window	Good		NAD	High	n/a	H6-5	n/a	
DC	296	6	Second	2H-112	Miscellaneous	Yellow ceramic tile mastic	Bathroom walls	440	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	296	6	Second	2H-112	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	440	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	296	6	Second	2H-112	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	120	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	297	6	Second	2H-114	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	325	SF	Good		NAD	Medium	n/a	H6-5	n/a	
DC	297	6	Second	2H-114	Miscellaneous	12" x 12" Lt. Blue mottle floor tile	Throughout	325	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	297	6	Second	2H-114	Miscellaneous	Yellow floor tile mastic	Throughout	325	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	297	6	Second	2H-114	Miscellaneous	Tan baseboard mastic	All walls	75	LF	Good		NAD	Low	n/a	H6-5	n/a	
DC	297	6	Second	2H-114	Miscellaneous	Drywall and joint compound	Throughout walls	1000	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	297	6	Second	2H-114	Miscellaneous	Black mastic on metal window frame	West Wall	1 @ 4' x 6'	Window	Good		NAD	High	n/a	H6-5	n/a	
DC	297	6	Second	2H-114	Miscellaneous	Yellow ceramic tile mastic	Bathroom walls	440	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	297	6	Second	2H-114	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	440	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	297	6	Second	2H-114	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	120	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	298	6	Second	2H-116	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	325	SF	Good		NAD	Medium	n/a	H6-5	n/a	

Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	298	6	Second	2H-116	Miscellaneous	12" x 12" Lt. Blue mottle floor tile	Throughout	325	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	298	6	Second	2H-116	Miscellaneous	Yellow floor tile mastic	Throughout	325	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	298	6	Second	2H-116	Miscellaneous	Tan baseboard mastic	All walls	75	LF	Good		NAD	Low	n/a	H6-5	n/a	
DC	298	6	Second	2H-116	Miscellaneous	Drywall and joint compound	Throughout walls	1000	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	298	6	Second	2H-116	Miscellaneous	Black mastic on metal window frame	West Wall	1 @ 4' x 6'	Window	Good		NAD	High	n/a	H6-5	n/a	
DC	298	6	Second	2H-116	Miscellaneous	Yellow ceramic tile mastic	Bathroom walls	440	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	298	6	Second	2H-116	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	440	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	298	6	Second	2H-116	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	120	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	299	6	Second	2H-118	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	325	SF	Good		NAD	Medium	n/a	H6-5	n/a	
DC	299	6	Second	2H-118	Miscellaneous	12" x 12" Lt. Blue mottle floor tile	Throughout	325	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	299	6	Second	2H-118	Miscellaneous	Yellow floor tile mastic	Throughout	325	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	299	6	Second	2H-118	Miscellaneous	Tan baseboard mastic	All walls	75	LF	Good		NAD	Low	n/a	H6-5	n/a	
DC	299	6	Second	2H-118	Miscellaneous	Drywall and joint compound	Throughout walls	1000	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	299	6	Second	2H-118	Miscellaneous	Black mastic on metal window frame	West Wall	1 @ 4' x 6'	Window	Good		NAD	High	n/a	H6-5	n/a	
DC	299	6	Second	2H-118	Miscellaneous	Yellow ceramic tile mastic	Bathroom walls	440	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	299	6	Second	2H-118	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	440	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	299	6	Second	2H-118	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	120	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	300	6	Second	2H-120	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	325	SF	Good		NAD	Medium	n/a	H6-5	n/a	
DC	300	6	Second	2H-120	Miscellaneous	12" x 12" Lt. Blue mottle floor tile	Throughout	325	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	300	6	Second	2H-120	Miscellaneous	Yellow floor tile mastic	Throughout	325	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	300	6	Second	2H-120	Miscellaneous	Tan baseboard mastic	All walls	75	LF	Good		NAD	Low	n/a	H6-5	n/a	
DC	300	6	Second	2H-120	Miscellaneous	Drywall and joint compound	Throughout walls	1000	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	300	6	Second	2H-120	Miscellaneous	Black mastic on metal window frame	West Wall	1 @ 4' x 6'	Window	Good		NAD	High	n/a	H6-5	n/a	
DC	300	6	Second	2H-120	Miscellaneous	Yellow ceramic tile mastic	Bathroom walls	440	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	300	6	Second	2H-120	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	440	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	300	6	Second	2H-120	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	120	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	301	6	Second	2H-122	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	240	SF	Good		NAD	Medium	n/a	H6-5	n/a	
DC	301	6	Second	2H-122	Miscellaneous	12" x 12" Tan mottle floor tile	Throughout	240	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	301	6	Second	2H-122	Miscellaneous	Yellow floor tile mastic	Throughout	240	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	301	6	Second	2H-122	Miscellaneous	Tan baseboard mastic	All walls	62	LF	Good		NAD	Low	n/a	H6-5	n/a	
DC	301	6	Second	2H-122	Miscellaneous	Drywall and joint compound	Throughout walls	820	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	301	6	Second	2H-122	Miscellaneous	Black mastic on metal window frame	North Wall	1 @ 6' x 6'	Window	Good		NAD	Low	n/a	H6-5	n/a	
DC	301	6	Second	2H-122	Miscellaneous	Yellow ceramic tile mastic	Bathroom	320	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	301	6	Second	2H-122	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	500	SF	Good		NAD	Low	n/a	H6-5	n/a	

Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	302	6	Second	2H-124	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	200	SF	Good		NAD	Medium	n/a	H6-5	n/a	
DC	302	6	Second	2H-124	Miscellaneous	12" x 12" Tan mottle floor tile	Throughout	200	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	302	6	Second	2H-124	Miscellaneous	Yellow floor tile mastic	Throughout	200	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	302	6	Second	2H-124	Miscellaneous	Tan baseboard mastic	All walls	56	LF	Good		NAD	Low	n/a	H6-5	n/a	
DC	302	6	Second	2H-124	Miscellaneous	Drywall and joint compound	throughout walls	700	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	302	6	Second	2H-124	Miscellaneous	Black mastic on metal window frame	North Wall	1 @ 6' x 6'	Window	Good		NAD	Low	n/a	H6-5	n/a	
DC	302	6	Second	2H-124	Miscellaneous	Yellow ceramic tile mastic	Bathroom	250	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	302	6	Second	2H-124	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	80	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	303	6	Second	2H-126	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	200	SF	Good		NAD	Medium	n/a	H6-5	n/a	
DC	303	6	Second	2H-126	Miscellaneous	12" x 12" Tan mottle floor tile	Throughout	200	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	303	6	Second	2H-126	Miscellaneous	Yellow floor tile mastic	Throughout	200	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	303	6	Second	2H-126	Miscellaneous	Tan baseboard mastic	All walls	56	LF	Good		NAD	Low	n/a	H6-5	n/a	
DC	303	6	Second	2H-126	Miscellaneous	Drywall and joint compound	throughout walls	700	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	303	6	Second	2H-126	Miscellaneous	Black mastic on metal window frame	North Wall	1 @ 6' x 6'	Window	Good		NAD	Low	n/a	H6-5	n/a	
DC	303	6	Second	2H-126	Miscellaneous	Yellow ceramic tile mastic	Bathroom	250	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	303	6	Second	2H-126	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	240	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	304	6	Second	2H-128	Miscellaneous	12" x 12" Tan mottle floor tile	Throughout	170	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	304	6	Second	2H-128	Miscellaneous	Yellow floor tile mastic	Throughout	170	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	304	6	Second	2H-128	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	170	SF	Good		NAD	Medium	n/a	H6-5	n/a	
DC	304	6	Second	2H-128	Miscellaneous	Tan baseboard mastic	All walls	52	LF	Good		NAD	Low	n/a	H6-5	n/a	
DC	304	6	Second	2H-128	Miscellaneous	Drywall and joint compound	Throughout walls	750	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	304	6	Second	2H-128	Miscellaneous	Black mastic on metal window frame	North Wall	1 @ 6' x 6'	Window	Good		NAD	Low	n/a	H6-5	n/a	
DC	304	6	Second	2H-128	Miscellaneous	Yellow ceramic tile mastic	Bathroom	350	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	304	6	Second	2H-128	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	305	6	Second	2H-130	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	200	SF	Good		NAD	Medium	n/a	H6-5	n/a	
DC	305	6	Second	2H-130	Miscellaneous	12" x 12" Tan mottle floor tile	Throughout	200	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	305	6	Second	2H-130	Miscellaneous	Yellow floor tile mastic	Throughout	200	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	305	6	Second	2H-130	Miscellaneous	Tan baseboard mastic	All walls	56	LF	Good		NAD	Low	n/a	H6-5	n/a	
DC	305	6	Second	2H-130	Miscellaneous	Drywall and joint compound	throughout walls	700	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	305	6	Second	2H-130	Miscellaneous	Black mastic on metal window frame	North Wall	1 @ 6' x 6'	Window	Good		NAD	Low	n/a	H6-5	n/a	
DC	305	6	Second	2H-130	Miscellaneous	Yellow ceramic tile mastic	Bathroom	250	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	305	6	Second	2H-130	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	306	6	Second	2H-132	Miscellaneous	12" x 12" Tan mottle floor tile	Throughout	170	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	306	6	Second	2H-132	Miscellaneous	Yellow floor tile mastic	Throughout	170	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	306	6	Second	2H-132	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	170	SF	Good		NAD	Medium	n/a	H6-5	n/a	
DC	306	6	Second	2H-132	Miscellaneous	Tan baseboard mastic	All walls	52	LF	Good		NAD	Low	n/a	H6-5	n/a	
DC	306	6	Second	2H-132	Miscellaneous	Drywall and joint compound	Throughout walls	750	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	306	6	Second	2H-132	Miscellaneous	Black mastic on metal window frame	North Wall	1 @ 6' x 6'	Window	Good		NAD	Low	n/a	H6-5	n/a	
DC	306	6	Second	2H-132	Miscellaneous	Yellow ceramic tile mastic	Bathroom	350	SF	Good		NAD	Low	n/a	H6-5	n/a	

Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	306	6	Second	2H-132	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	307	6	Second	Stairs 12	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout	200	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	307	6	Second	Stairs 12	Miscellaneous	Drywall and joint compound	Throughout walls	750	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	307	6	Second	Stairs 12	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	250	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	307	6	Second	Stairs 12	Miscellaneous	Fire door	West Wall	1 @ 4' x 7'	Door	Good	Labeled/Wood	Assumed ACM	High	O & M	H6-5	N/A	
DC	308	6	Second	2H-134	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout	340	SF	Good		NAD	Medium	n/a	H6-5	n/a	
DC	308	6	Second	2H-134	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	340	SF	Good		5%-10% Chrysotile	High	O & M	H6-5	01	
DC	308	6	Second	2H-134	Miscellaneous	Black floor tile mastic	Throughout	340	SF	Good		4%-5% Chrysotile	Low	O & M	H6-5	02	
DC	308	6	Second	2H-134	Miscellaneous	Brown baseboard mastic	All walls	76	LF	Good		NAD	Low	n/a	H6-5	n/a	
DC	308	6	Second	2H-134	Miscellaneous	Drywall and joint compound	Throughout walls	1000	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	308	6	Second	2H-134	Miscellaneous	Black mastic on metal window frame	East Wall	1 @ 6' x 6'	Window	Good		NAD	Low	n/a	H6-5	n/a	
DC	308	6	Second	2H-134	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	20	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	308	6	Second	2H-134	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	500	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	308	6	Second	2H-134	Miscellaneous	Yellow ceramic tile mastic	Bathroom walls	350	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	309	6	Second	2H-136	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout	340	SF	Good		NAD	Medium	n/a	H6-5	n/a	
DC	309	6	Second	2H-136	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	340	SF	Good		5%-10% Chrysotile	High	O & M	H6-5	01	
DC	309	6	Second	2H-136	Miscellaneous	Black floor tile mastic	Throughout	340	SF	Good		4%-5% Chrysotile	Low	O & M	H6-5	02	
DC	309	6	Second	2H-136	Miscellaneous	Brown baseboard mastic	All walls	76	LF	Good		NAD	Low	n/a	H6-5	n/a	
DC	309	6	Second	2H-136	Miscellaneous	Drywall and joint compound	Throughout walls	1000	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	309	6	Second	2H-136	Miscellaneous	Black mastic on metal window frame	East Wall	1 @ 6' x 6'	Window	Good		NAD	Low	n/a	H6-5	n/a	
DC	309	6	Second	2H-136	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	20	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	309	6	Second	2H-136	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	500	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	310	6	Second	2H-138	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout	340	SF	Good		NAD	Medium	n/a	H6-5	n/a	
DC	310	6	Second	2H-138	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	340	SF	Good		5%-10% Chrysotile	High	O & M	H6-5	01	
DC	310	6	Second	2H-138	Miscellaneous	Black floor tile mastic	Throughout	340	SF	Good		4%-5% Chrysotile	Low	O & M	H6-5	02	
DC	310	6	Second	2H-138	Miscellaneous	Brown baseboard mastic	All walls	76	LF	Good		NAD	Low	n/a	H6-5	n/a	
DC	310	6	Second	2H-138	Miscellaneous	Drywall and joint compound	Throughout walls	1000	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	310	6	Second	2H-138	Miscellaneous	Black mastic on metal window frame	East Wall	1 @ 6' x 6'	Window	Good		NAD	Low	n/a	H6-5	n/a	
DC	310	6	Second	2H-138	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	20	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	310	6	Second	2H-138	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	500	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	310	6	Second	2H-138	Miscellaneous	Yellow ceramic tile mastic	Bathroom walls	350	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	311	6	Second	2H-140	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout	340	SF	Good		NAD	Medium	n/a	H6-5	n/a	
DC	311	6	Second	2H-140	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	340	SF	Good		5%-10% Chrysotile	High	O & M	H6-5	01	

Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	311	6	Second	2H-140	Miscellaneous	Black floor tile mastic	Throughout	340	SF	Good		4%-5% Chrysotile	Low	O & M	H6-5	02	
DC	311	6	Second	2H-140	Miscellaneous	Brown baseboard mastic	All walls	76	LF	Good		NAD	Low	n/a	H6-5	n/a	
DC	311	6	Second	2H-140	Miscellaneous	Drywall and joint compound	Throughout walls	1000	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	311	6	Second	2H-140	Miscellaneous	Black mastic on metal window frame	East Wall	1 @ 6' x 6'	Window	Good		NAD	Low	n/a	H6-5	n/a	
DC	311	6	Second	2H-140	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	20	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	311	6	Second	2H-140	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	500	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	312	6	Second	2H-142	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout	340	SF	Good		NAD	Medium	n/a	H6-5	n/a	
DC	312	6	Second	2H-142	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	340	SF	Good		5%-10% Chrysotile	High	O & M	H6-5	01	
DC	312	6	Second	2H-142	Miscellaneous	Black floor tile mastic	Throughout	340	SF	Good		4%-5% Chrysotile	Low	O & M	H6-5	02	
DC	312	6	Second	2H-142	Miscellaneous	Brown baseboard mastic	All walls	76	LF	Good		NAD	Low	n/a	H6-5	n/a	
DC	312	6	Second	2H-142	Miscellaneous	Drywall and joint compound	Throughout walls	1000	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	312	6	Second	2H-142	Miscellaneous	Black mastic on metal window frame	East Wall	1 @ 6' x 6'	Window	Good		NAD	Low	n/a	H6-5	n/a	
DC	312	6	Second	2H-142	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	20	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	312	6	Second	2H-142	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	500	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	312	6	Second	2H-142	Miscellaneous	Yellow ceramic tile mastic	Bathroom walls	350	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	313	6	Second	2H-144	Miscellaneous	12" x 12" Tan mottle floor tile	Throughout	672	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	313	6	Second	2H-144	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout	672	SF	Good		NAD	Medium	n/a	H6-5	n/a	
DC	313	6	Second	2H-144	Miscellaneous	Black floor tile mastic	Throughout	672	SF	Good		4%-5% Chrysotile	Low	O & M	H6-5	02	
DC	313	6	Second	2H-144	Miscellaneous	Tan baseboard mastic	All walls	105	LF	Good		NAD	Low	n/a	H6-5	n/a	
DC	313	6	Second	2H-144	Miscellaneous	Drywall and joint compound	Throughout walls	1250	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	313	6	Second	2H-144	Miscellaneous	Black mastic on metal window frame	East Wall	2 @ 6' x 6'	Window	Good		NAD	Low	n/a	H6-5	n/a	
DC	313	6	Second	2H-144	Miscellaneous	Yellow ceramic tile mastic	Bathroom walls	400	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	313	6	Second	2H-144	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	240	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	313	6	Second	2H-144	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	1000	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	314	6	Second	2H-146	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout	340	SF	Good		NAD	Medium	n/a	H6-5	n/a	
DC	314	6	Second	2H-146	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	340	SF	Good		5%-10% Chrysotile	High	O & M	H6-5	01	
DC	314	6	Second	2H-146	Miscellaneous	Black floor tile mastic	Throughout	340	SF	Good		4%-5% Chrysotile	Low	O & M	H6-5	02	
DC	314	6	Second	2H-146	Miscellaneous	Brown baseboard mastic	All walls	76	LF	Good		NAD	Low	n/a	H6-5	n/a	
DC	314	6	Second	2H-146	Miscellaneous	Drywall and joint compound	Throughout walls	1000	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	314	6	Second	2H-146	Miscellaneous	Black mastic on metal window frame	East Wall	1 @ 6' x 6'	Window	Good		NAD	Low	n/a	H6-5	n/a	
DC	314	6	Second	2H-146	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	20	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	314	6	Second	2H-146	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	500	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	314	6	Second	2H-146	Miscellaneous	Yellow ceramic tile mastic	Bathroom walls	400	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	315	6	Second	2H-148	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout	340	SF	Good		NAD	Medium	n/a	H6-5	n/a	

Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	315	6	Second	2H-148	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	340	SF	Good		5%-10% Chrysotile	High	O & M	H6-5	01	
DC	315	6	Second	2H-148	Miscellaneous	Black floor tile mastic	Throughout	340	SF	Good		4%-5% Chrysotile	Low	O & M	H6-5	02	
DC	315	6	Second	2H-148	Miscellaneous	Brown baseboard mastic	All walls	76	LF	Good		NAD	Low	n/a	H6-5	n/a	
DC	315	6	Second	2H-148	Miscellaneous	Drywall and joint compound	Throughout walls	1000	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	315	6	Second	2H-148	Miscellaneous	Black mastic on metal window frame	East Wall	1 @ 6' x 6'	Window	Good		NAD	Low	n/a	H6-5	n/a	
DC	315	6	Second	2H-148	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	20	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	315	6	Second	2H-148	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	500	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	315	6	Second	2H-148	Miscellaneous	Yellow ceramic tile mastic	Bathroom walls	350	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	316	6	Second	2H-150	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout	340	SF	Good		NAD	Medium	n/a	H6-5	n/a	
DC	316	6	Second	2H-150	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	340	SF	Good		5%-10% Chrysotile	High	O & M	H6-5	01	
DC	316	6	Second	2H-150	Miscellaneous	Black floor tile mastic	Throughout	340	SF	Good		4%-5% Chrysotile	Low	O & M	H6-5	02	
DC	316	6	Second	2H-150	Miscellaneous	Brown baseboard mastic	All walls	76	LF	Good		NAD	Low	n/a	H6-5	n/a	
DC	316	6	Second	2H-150	Miscellaneous	Drywall and joint compound	Throughout walls	1000	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	316	6	Second	2H-150	Miscellaneous	Black mastic on metal window frame	East Wall	1 @ 6' x 6'	Window	Good		NAD	Low	n/a	H6-5	n/a	
DC	316	6	Second	2H-150	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	20	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	316	6	Second	2H-150	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	500	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	316	6	Second	2H-150	Miscellaneous	Yellow ceramic tile mastic	Bathroom walls	170	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	317	6	Second	2H-152	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout	340	SF	Good		NAD	Medium	n/a	H6-5	n/a	
DC	317	6	Second	2H-152	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	340	SF	Good		5%-10% Chrysotile	High	O & M	H6-5	01	
DC	317	6	Second	2H-152	Miscellaneous	Black floor tile mastic	Throughout	340	SF	Good		4%-5% Chrysotile	Low	O & M	H6-5	02	
DC	317	6	Second	2H-152	Miscellaneous	Brown baseboard mastic	All walls	76	LF	Good		NAD	Low	n/a	H6-5	n/a	
DC	317	6	Second	2H-152	Miscellaneous	Drywall and joint compound	Throughout walls	1000	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	317	6	Second	2H-152	Miscellaneous	Black mastic on metal window frame	East Wall	1 @ 6' x 6'	Window	Good		NAD	Low	n/a	H6-5	n/a	
DC	317	6	Second	2H-152	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	20	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	317	6	Second	2H-152	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	500	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	317	6	Second	2H-152	Miscellaneous	Yellow ceramic tile mastic	Bathroom walls	350	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	318	6	Second	2H-154	Miscellaneous	12" x 12" Tan mottle floor tile	Throughout	672	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	318	6	Second	2H-154	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout	672	SF	Good		NAD	Medium	n/a	H6-5	n/a	
DC	318	6	Second	2H-154	Miscellaneous	Black floor tile mastic	Throughout	672	SF	Good		4%-5% Chrysotile	Low	O & M	H6-5	02	
DC	318	6	Second	2H-154	Miscellaneous	Tan baseboard mastic	All walls	105	LF	Good		NAD	Low	n/a	H6-5	n/a	
DC	318	6	Second	2H-154	Miscellaneous	Drywall and joint compound	Throughout walls	1250	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	318	6	Second	2H-154	Miscellaneous	Black mastic on metal window frame	East Wall	2 @ 6' x 6'	Window	Good		NAD	Low	n/a	H6-5	n/a	
DC	318	6	Second	2H-154	Miscellaneous	Yellow ceramic tile mastic	Bathroom walls	200	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	318	6	Second	2H-154	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	244	SF	Good		NAD	Low	n/a	H6-5	n/a	

Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	318	6	Second	2H-154	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	1000	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	319	6	Second	2H-156	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout	340	SF	Good		NAD	Medium	n/a	H6-5	n/a	
DC	319	6	Second	2H-156	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	340	SF	Good		5%-10% Chrysotile	High	O & M	H6-5	01	
DC	319	6	Second	2H-156	Miscellaneous	Black floor tile mastic	Throughout	340	SF	Good		4%-5% Chrysotile	Low	O & M	H6-5	02	
DC	319	6	Second	2H-156	Miscellaneous	Brown baseboard mastic	All walls	76	LF	Good		NAD	Low	n/a	H6-5	n/a	
DC	319	6	Second	2H-156	Miscellaneous	Drywall and joint compound	Throughout walls	1000	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	319	6	Second	2H-156	Miscellaneous	Black mastic on metal window frame	East Wall	1 @ 6' x 6'	Window	Good		NAD	Low	n/a	H6-5	n/a	
DC	319	6	Second	2H-156	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	500	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	319	6	Second	2H-156	Miscellaneous	Yellow ceramic tile mastic	Bathroom walls	170	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	320	6	Second	2H-158	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout	340	SF	Good		NAD	Medium	n/a	H6-5	n/a	
DC	320	6	Second	2H-158	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	340	SF	Good		5%-10% Chrysotile	High	O & M	H6-5	01	
DC	320	6	Second	2H-158	Miscellaneous	Black floor tile mastic	Throughout	340	SF	Good		4%-5% Chrysotile	Low	O & M	H6-5	02	
DC	320	6	Second	2H-158	Miscellaneous	Brown baseboard mastic	All walls	76	LF	Good		NAD	Low	n/a	H6-5	n/a	
DC	320	6	Second	2H-158	Miscellaneous	Drywall and joint compound	Throughout walls	1000	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	320	6	Second	2H-158	Miscellaneous	Black mastic on metal window frame	East Wall	1 @ 6' x 6'	Window	Good		NAD	Low	n/a	H6-5	n/a	
DC	320	6	Second	2H-158	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	20	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	320	6	Second	2H-158	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	500	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	320	6	Second	2H-158	Miscellaneous	Yellow ceramic tile mastic	Bathroom walls	470	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	321	6	Second	2H-160	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout	340	SF	Good		NAD	Medium	n/a	H6-5	n/a	
DC	321	6	Second	2H-160	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	340	SF	Good		5%-10% Chrysotile	High	O & M	H6-5	01	
DC	321	6	Second	2H-160	Miscellaneous	Black floor tile mastic	Throughout	340	SF	Good		4%-5% Chrysotile	Low	O & M	H6-5	02	
DC	321	6	Second	2H-160	Miscellaneous	Brown baseboard mastic	All walls	76	LF	Good		NAD	Low	n/a	H6-5	n/a	
DC	321	6	Second	2H-160	Miscellaneous	Drywall and joint compound	Throughout walls	1000	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	321	6	Second	2H-160	Miscellaneous	Black mastic on metal window frame	East Wall	1 @ 6' x 6'	Window	Good		NAD	Low	n/a	H6-5	n/a	
DC	321	6	Second	2H-160	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	20	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	321	6	Second	2H-160	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	500	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	322	6	Second	2H-213	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	160	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	322	6	Second	2H-213	Miscellaneous	Gray duct seam sealant on metal	Throughout above drop ceiling	20	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	322	6	Second	2H-213	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	120	SF	Good		NAD	Medium	n/a	H6-5	n/a	
DC	322	6	Second	2H-213	Miscellaneous	12" x 12" Green mottle floor tile	Throughout	120	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	322	6	Second	2H-213	Miscellaneous	Yellow floor tile mastic	throughout	120	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	322	6	Second	2H-213	Miscellaneous	Tan baseboard mastic	All walls	44	LF	Good		NAD	Low	n/a	H6-5	n/a	
DC	322	6	Second	2H-213	Miscellaneous	Drywall and joint compound	Throughout walls	440	SF	Good		NAD	High	n/a	H6-5	n/a	

Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	323	6	Second	2H-212	Miscellaneous	12" x 12" Green mottle floor tile	Throughout	96	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	323	6	Second	2H-212	Miscellaneous	Yellow floor tile mastic	Throughout	96	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	323	6	Second	2H-212	Miscellaneous	Tan baseboard mastic	All walls	40	LF	Good		NAD	Low	n/a	H6-5	n/a	
DC	323	6	Second	2H-212	Miscellaneous	Drywall and joint compound	Throughout walls and ceiling	496	SF	Good		NAD	Medium	n/a	H6-5	n/a	
DC	323	6	Second	2H-212	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	324	6	Second	2H-211	Miscellaneous	Drywall and joint compound	Throughout walls and ceiling	1100	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	324	6	Second	2H-211	Miscellaneous	Yellow ceramic tile mastic	Throughout walls	800	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	324	6	Second	2H-211	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	80	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	324	6	Second	2H-211	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	240	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	325	6	Second	2H-209A	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	80	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	325	6	Second	2H-209A	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	40	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	325	6	Second	2H-209A	Miscellaneous	12" x 12" Tan mottle floor tile	Throughout	100	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	325	6	Second	2H-209A	Miscellaneous	Yellow floor tile mastic	Throughout	100	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	325	6	Second	2H-209A	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	100	SF	Good		NAD	Medium	n/a	H6-5	n/a	
DC	325	6	Second	2H-209A	Miscellaneous	Tan baseboard mastic	All walls	40	LF	Good		NAD	Low	n/a	H6-5	n/a	
DC	325	6	Second	2H-209A	Miscellaneous	Drywall and joint compound	Throughout walls	400	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	326	6	Second	2H-209B	Miscellaneous	Yellow ceramic tile mastic	Throughout walls	200	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	326	6	Second	2H-209B	Miscellaneous	Drywall and joint compound	Throughout walls	200	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	326	6	Second	2H-209B	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	24	SF	Good		NAD	Medium	n/a	H6-5	n/a	
DC	327	6	Second	2H-209	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	375	SF	Good		NAD	Medium	n/a	H6-5	n/a	
DC	327	6	Second	2H-209	Miscellaneous	12" x 12" Tan mottle floor tile	Throughout	375	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	327	6	Second	2H-209	Miscellaneous	Yellow floor tile mastic	Throughout	375	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	327	6	Second	2H-209	Miscellaneous	Tan baseboard mastic	All walls	75	LF	Good		NAD	Low	n/a	H6-5	n/a	
DC	327	6	Second	2H-209	Miscellaneous	Drywall and joint compound	Throughout walls	500	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	327	6	Second	2H-209	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	400	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	328	6	Second	2H-207	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	54	SF	Good		5%-10% Chrysotile	High	O & M	H6-5	01	
DC	328	6	Second	2H-207	Miscellaneous	Black floor tile mastic	Throughout	54	SF	Good		4%-5% Chrysotile	Low	O & M	H6-5	02	
DC	328	6	Second	2H-207	Miscellaneous	Red fire stop	Throughout	10	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	328	6	Second	2H-207	Miscellaneous	Drywall and joint compound	Throughout walls	300	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	328	6	Second	2H-207	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	64	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	328	6	Second	2H-207	Miscellaneous	Brown baseboard mastic	All walls	30	LF	Good		NAD	Low	n/a	H6-5	n/a	
DC	329	6	Second	2H-206	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	15	LF	Good		NAD	Low	n/a	H6-5	n/a	
DC	329	6	Second	2H-206	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	80	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	329	6	Second	2H-206	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout	132	SF	Good		NAD	Medium	n/a	H6-5	n/a	

**Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6**

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	329	6	Second	2H-206	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	40	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	329	6	Second	2H-206	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	throughout	132	SF	Good		5%-10% Chrysotile	High	O & M	H6-5	01	
DC	329	6	Second	2H-206	Miscellaneous	Black floor tile mastic	Throughout	132	SF	Good		4%-5% Chrysotile	Low	O & M	H6-5	02	
DC	329	6	Second	2H-206	Miscellaneous	Brown baseboard mastic	All walls	46	LF	Good		NAD	Low	n/a	H6-5	n/a	
DC	329	6	Second	2H-206	Miscellaneous	Drywall and joint compound	Throughout walls	460	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	330	6	Second	2H-205	Miscellaneous	2' x 4' Textured Ceiling tile	throughout	110	SF	Good		NAD	Medium	n/a	H6-5	n/a	
DC	330	6	Second	2H-205	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	110	SF	Good		5%-10% Chrysotile	High	O & M	H6-5	01	
DC	330	6	Second	2H-205	Miscellaneous	Black floor tile mastic	Throughout	110	SF	Good		4%-5% Chrysotile	Low	O & M	H6-5	02	
DC	330	6	Second	2H-205	Miscellaneous	Brown baseboard mastic	All walls	42	LF	Good		NAD	Low	n/a	H6-5	n/a	
DC	330	6	Second	2H-205	Miscellaneous	Drywall and joint compound	Throughout walls	420	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	330	6	Second	2H-205	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	20	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	330	6	Second	2H-205	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	160	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	331	6	Second	2H-204	Miscellaneous	2' x 4' Textured Ceiling tile	throughout	110	SF	Good		NAD	Medium	n/a	H6-5	n/a	
DC	331	6	Second	2H-204	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	110	SF	Good		5%-10% Chrysotile	High	O & M	H6-5	01	
DC	331	6	Second	2H-204	Miscellaneous	Black floor tile mastic	Throughout	110	SF	Good		4%-5% Chrysotile	Low	O & M	H6-5	02	
DC	331	6	Second	2H-204	Miscellaneous	Brown baseboard mastic	All walls	42	LF	Good		NAD	Low	n/a	H6-5	n/a	
DC	331	6	Second	2H-204	Miscellaneous	Drywall and joint compound	Throughout walls	420	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	331	6	Second	2H-204	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	20	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	331	6	Second	2H-204	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	160	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	331	6	Second	2H-204	Miscellaneous	Yellow ceramic tile mastic	North and South walls	50	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	332	6	Second	2H-203	Miscellaneous	Yellow carpet mastic	Throughout	144	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	332	6	Second	2H-203	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout	144	SF	Good		NAD	Medium	n/a	H6-5	n/a	
DC	332	6	Second	2H-203	Miscellaneous	Drywall and joint compound	Throughout	480	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	332	6	Second	2H-203	Miscellaneous	Tan baseboard mastic	Throughout	48	LF	Good		NAD	Low	n/a	H6-5	n/a	
DC	332	6	Second	2H-203	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	80	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	332	6	Second	2H-203	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	50	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	332	6	Second	2H-203	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	144	SF	Good		5%-10% Chrysotile	Low	O & M	H6-5	01	
DC	332	6	Second	2H-203	Miscellaneous	Black floor tile mastic	Throughout	144	SF	Good		4%-5% Chrysotile	Low	O & M	H6-5	02	
DC	334	6	Second	2H-201	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	260	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	334	6	Second	2H-201	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	50	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	334	6	Second	2H-201	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	10	LF	Good		NAD	Low	n/a	H6-5	n/a	
DC	334	6	Second	2H-201	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	200	SF	Good		5%-10% Chrysotile	High	O & M	H6-5	01	

**Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6**

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	334	6	Second	2H-201	Miscellaneous	Black floor tile mastic	Throughout	200	SF	Good		4%-5% Chrysotile	Low	O & M	H6-5	02	
DC	334	6	Second	2H-201	Miscellaneous	2' x 4' Textured Ceiling tile	throughout	200	SF	Good		NAD	Medium	n/a	H6-5	n/a	
DC	334	6	Second	2H-201	Miscellaneous	Tan baseboard mastic	All walls	58	LF	Good		NAD	Low	n/a	H6-5	n/a	
DC	334	6	Second	2H-201	Miscellaneous	Drywall and joint compound	Throughout walls	580	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	334	6	Second	2H-201	Miscellaneous	Fire door	South Wall	1 @ 3' x 7'	Door	Good	Labeled/Wood	Assumed ACM	High	O & M	H6-5	N/A	
DC	335	6	Second	Stairs 13	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	15	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	335	6	Second	Stairs 13	Miscellaneous	Red fire stop	Throughout above drop ceiling	2	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	335	6	Second	Stairs 13	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	200	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	335	6	Second	Stairs 13	Miscellaneous	Fire door	East Wall	1 @ 3' x 7'	Door	Good	Labeled/Wood	Assumed ACM	High	O & M	H6-6	N/A	
DC	335	6	Second	Stairs 13	Miscellaneous	Drywall and joint compound	Throughout walls	600	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	336	6	Second	2H-200	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	throughout	120	SF	Good		5%-10% Chrysotile	High	O & M	H6-6	01	
DC	336	6	Second	2H-200	Miscellaneous	Black floor tile mastic	Throughout	120	SF	Good		4%-5% Chrysotile	Low	O & M	H6-6	02	
DC	336	6	Second	2H-200	Miscellaneous	Drywall and joint compound	Throughout	440	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	336	6	Second	2H-200	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	120	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	336	6	Second	2H-200	Miscellaneous	Red fire stop	Throughout above drop ceiling	20	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	336	6	Second	2H-200	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	250	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	336	6	Second	2H-200	Miscellaneous	Tan pin mastic	Throughout above drop ceiling	250	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	336	6	Second	2H-200	Miscellaneous	Tan baseboard mastic	Throughout	44	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	337	6	Second	2J-100	Miscellaneous	1' x 1' Textured ceiling tile	Throughout	2000	SF	Good		NAD	Medium	n/a	H6-6	n/a	
DC	337	6	Second	2J-100	Miscellaneous	12" x 12" Tan mottle floor tile	Throughout	2000	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	337	6	Second	2J-100	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	180	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	337	6	Second	2J-100	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	2000	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	337	6	Second	2J-100	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	2500	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	337	6	Second	2J-100	Miscellaneous	Black mastic on metal window frame	Throughout	20 @ 6' x 8'	Window	Good		NAD	Low	n/a	H6-6	n/a	
DC	337	6	Second	2J-100	Miscellaneous	Drywall and joint compound	Throughout	3500	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	337	6	Second	2J-100	Miscellaneous	Yellow ceramic tile mastic	North Wall	40	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	337	6	Second	2J-100	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	1125	SF	Good		5%-10% Chrysotile	Low	O & M	H6-6	01	
DC	337	6	Second	2J-100	Miscellaneous	Black floor tile mastic	Throughout	1,125	SF	Good		4%-5% Chrysotile	Low	O & M	H6-6	02	
DC	337	6	Second	2J-100	Miscellaneous	Fire door	North Wall	1 @ 4' x 7'	Door	Good	Labeled/Wood	Assumed ACM	High	O & M	H6-6	N/A	
DC	338	6	Second	2J-105	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout	540	SF	Good		NAD	Medium	n/a	H6-6	n/a	
DC	338	6	Second	2J-105	Miscellaneous	12" x 12" Tan mottle floor tile	Throughout	720	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	338	6	Second	2J-105	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	450	SF	Good		NAD	Low	n/a	H6-6	n/a	

**Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6**

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	338	6	Second	2J-105	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	800	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	338	6	Second	2J-105	Miscellaneous	Drywall and joint compound	Throughout	1220	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	338	6	Second	2J-105	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	45	LF	Good		NAD	High	n/a	H6-6	n/a	
DC	339	6	Second	2J-106	Miscellaneous	Drywall and joint compound	Throughout	340	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	339	6	Second	2J-106	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout	60	SF	Good		NAD	Medium	n/a	H6-6	n/a	
DC	339	6	Second	2J-106	Miscellaneous	12" x 12" Tan mottle floor tile	Throughout	60	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	339	6	Second	2J-106	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	339	6	Second	2J-106	Miscellaneous	Brown baseboard mastic	Throughout	34	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	340	6	Second	2J-104	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout	240	SF	Good		NAD	Medium	n/a	H6-6	n/a	
DC	340	6	Second	2J-104	Miscellaneous	Drywall and joint compound	Throughout	640	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	340	6	Second	2J-104	Miscellaneous	Yellow ceramic tile mastic	East Wall	140	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	340	6	Second	2J-104	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	125	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	340	6	Second	2J-104	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	40	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	340	6	Second	2J-104	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	10	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	340	6	Second	2J-104	Miscellaneous	12" x 12" Tan mottle floor tile	throughout	240	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	341	6	Second	2J-103	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout	144	SF	Good		NAD	Medium	n/a	H6-6	n/a	
DC	341	6	Second	2J-103	Miscellaneous	12" x 12" Lt. Blue mottle floor tile	Throughout	45	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	341	6	Second	2J-103	Miscellaneous	12" x 12" Tan mottle floor tile	Throughout	100	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	341	6	Second	2J-103	Miscellaneous	Yellow floor tile mastic	Throughout	100	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	341	6	Second	2J-103	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	145	SF	Good		5%-10% Chrysotile	High	O & M	H6-6	01	
DC	341	6	Second	2J-103	Miscellaneous	Black floor tile mastic	Throughout	96	SF	Good		4%-5% Chrysotile	Low	O & M	H6-6	02	
DC	341	6	Second	2J-103	Miscellaneous	Drywall and joint compound	Throughout	480	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	341	6	Second	2J-103	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	32	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	341	6	Second	2J-103	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	60	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	341	6	Second	2J-103	Miscellaneous	Tan baseboard mastic	Throughout	48	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	342	6	Second	2J-102	Miscellaneous	12" x 12" Dk. Blue mottle floor tile	Throughout	224	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	342	6	Second	2J-102	Miscellaneous	Yellow floor tile mastic	Throughout	224	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	342	6	Second	2J-102	Miscellaneous	Red fire stop	Throughout above drop ceiling	5	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	342	6	Second	2J-102	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	342	6	Second	2J-102	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	342	6	Second	2J-102	Miscellaneous	Tan baseboard mastic	Throughout	60	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	342	6	Second	2J-102	Miscellaneous	Drywall and joint compound	Throughout	600	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	343	6	Second	2J-114	Miscellaneous	Fire door	North Wall	1 @ 3' x 7'	Door	Good	Labeled/Wood	Assumed ACM	High	O & M	H6-6	N/A	
DC	343	6	Second	2J-114	Miscellaneous	12" x 12" Tan mottle floor tile	Throughout	10	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	343	6	Second	2J-114	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	86	SF	Good		5%-10% Chrysotile	High	O & M	H6-6	01	

**Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6**

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	343	6	Second	2J-114	Miscellaneous	Black floor tile mastic	Throughout	96	SF	Good		4%-5% Chrysotile	Low	O & M	H6-6	02	
DC	343	6	Second	2J-114	Miscellaneous	Brown baseboard mastic	Throughout	40	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	343	6	Second	2J-114	Miscellaneous	Drywall and joint compound	throughout	400	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	343	6	Second	2J-114	Miscellaneous	Red fire stop	Throughout above drop ceiling	15	SF	Good		NAD	Medium	n/a	H6-6	n/a	
DC	343	6	Second	2J-114	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	20	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	343	6	Second	2J-114	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout	96	SF	Good		NAD	Medium	n/a	H6-6	n/a	
DC	344	6	Second	2nd Floor Lobby	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout under carpet	1350	SF	Good		5%-10% Chrysotile	Low	O & M	H6-6	01	
DC	344	6	Second	2nd Floor Lobby	Miscellaneous	Drywall and joint compound	Throughout	2000	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	344	6	Second	2nd Floor Lobby	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	250	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	344	6	Second	2nd Floor Lobby	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	700	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	344	6	Second	2nd Floor Lobby	Miscellaneous	12" x 12" Blue mottle floor tile	South entrance	20	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	344	6	Second	2nd Floor Lobby	Miscellaneous	12" x 12" Lt. Green mottle floor tile	south entrance	80	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	344	6	Second	2nd Floor Lobby	Miscellaneous	Black floor tile mastic	south entrance	100	SF	Good		4%-5% Chrysotile	Low	O & M	H6-6	02	
DC	344	6	Second	2nd Floor Lobby	Miscellaneous	Tan baseboard mastic	south entrance	10	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	344	6	Second	2nd Floor Lobby	Miscellaneous	Black mastic on metal window frame	South Wall	5 @ 6' x 8'	Window	Good		NAD	High	n/a	H6-6	n/a	
DC	345	6	Second	2J-112	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout	780	SF	Good		NAD	Medium	n/a	H6-6	n/a	
DC	345	6	Second	2J-112	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	320	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	345	6	Second	2J-112	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	550	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	345	6	Second	2J-112	Miscellaneous	Drywall and joint compound	throughout	1120	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	345	6	Second	2J-112	Miscellaneous	12" x 12" Off-white with tan specks floor tile	Throughout	780	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	345	6	Second	2J-112	Miscellaneous	Yellow floor tile mastic	Throughout	780	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	345	6	Second	2J-112	Miscellaneous	Fire door	West Wall	1 @ 4' x 7'	Door	Good	Labeled/Wood	Assumed ACM	High	O & M	H6-6	N/A	
DC	345	6	Second	2J-112	Miscellaneous	White pipe seam sealant on paper	Throughout	601	LF	Good		NAD	High	n/a	H6-6	n/a	
DC	346	6	Second	2J-111	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	20	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	346	6	Second	2J-111	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	12	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	346	6	Second	2J-111	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	170	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	346	6	Second	2J-111	Miscellaneous	12" x 12" Off-white with tan specks floor tile	Throughout	120	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	346	6	Second	2J-111	Miscellaneous	Yellow floor tile mastic	Throughout	120	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	346	6	Second	2J-111	Miscellaneous	Tan baseboard mastic	Throughout	44	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	346	6	Second	2J-111	Miscellaneous	Drywall and joint compound	Throughout	440	SF	Good		NAD	High	n/a	H6-6	n/a	

**Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6**

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	347	6	Second	2J-113	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	250	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	347	6	Second	2J-113	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	160	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	347	6	Second	2J-113	Miscellaneous	12" x 12" Lt. Purple mottle floor tile	throughout	144	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	347	6	Second	2J-113	Miscellaneous	Yellow floor tile mastic	Throughout	144	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	347	6	Second	2J-113	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout under carpet	144	SF	Good		5%-10% Chrysotile	Low	O & M	H6-6	01	
DC	347	6	Second	2J-113	Miscellaneous	Black floor tile mastic	Throughout under carpet	144	SF	Good		4%-5% Chrysotile	Low	O & M	H6-6	02	
DC	347	6	Second	2J-113	Miscellaneous	Tan baseboard mastic	Throughout	34	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	347	6	Second	2J-113	Miscellaneous	Drywall and joint compound	Throughout	340	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	348	6	Second	2J-120	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	96	SF	Good		5%-10% Chrysotile	High	O & M	H6-5	01	
DC	348	6	Second	2J-120	Miscellaneous	Black floor tile mastic	Throughout	96	SF	Good		4%-5% Chrysotile	High	O & M	H6-5	02	
DC	348	6	Second	2J-120	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	160	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	348	6	Second	2J-120	Miscellaneous	Red fire stop	Throughout above drop ceiling	5	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	348	6	Second	2J-120	Miscellaneous	Brown baseboard mastic	Throughout	40	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	348	6	Second	2J-120	Miscellaneous	Drywall and joint compound	Throughout	440	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	349	6	Second	2J-121	Miscellaneous	12" x 12" Peach mottle floor tile	Throughout	1050	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	349	6	Second	2J-121	Miscellaneous	Yellow floor tile mastic	Throughout	1050	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	349	6	Second	2J-121	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout	1050	SF	Good		NAD	Medium	n/a	H6-5	n/a	
DC	349	6	Second	2J-121	Miscellaneous	Yellow ceramic tile mastic	South Wall	150	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	349	6	Second	2J-121	Miscellaneous	Drywall and joint compound	throughout	1300	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	349	6	Second	2J-121	Miscellaneous	Brown baseboard mastic	Throughout	130	LF	Good		NAD	Low	n/a	H6-5	n/a	
DC	349	6	Second	2J-121	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	280	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	349	6	Second	2J-121	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	60	LF	Good		NAD	Low	n/a	H6-5	n/a	
DC	349	6	Second	2J-121	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	60	LF	Good		NAD	Low	n/a	H6-5	n/a	
DC	349	6	Second	2J-121	Miscellaneous	Black mastic on metal window frame	North and East walls	1 @ 4' x 6' & 4 @ 6' x 8'	Window	Good		NAD	High	n/a	H6-5	n/a	
DC	349	6	Second	2J-121	Miscellaneous	Fire door	North Wall	1 @ 4' x 7'	Door	Good	Labeled/Wood	Assumed ACM	High	O & M	H6-5	N/A	
DC	350	6	Second	2J-123	Miscellaneous	Black mastic on metal window frame	North and East walls	1 @ 4' x 6'	Window	Good		NAD	Low	n/a	H6-5	n/a	
DC	350	6	Second	2J-123	Miscellaneous	12" x 12" Peach mottle floor tile	throughout	120	SF	Good		NAD	High	n/a	H6-5	n/a	
DC	350	6	Second	2J-123	Miscellaneous	Yellow floor tile mastic	Throughout	120	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	350	6	Second	2J-123	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	120	SF	Good		NAD	Low	n/a	H6-5	n/a	
DC	350	6	Second	2J-123	Miscellaneous	Tan baseboard mastic	Throughout	44	LF	Good		NAD	Low	n/a	H6-5	n/a	
DC	350	6	Second	2J-123	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout	120	SF	Good		NAD	Medium	n/a	H6-5	n/a	
DC	351	6	Second	2J-122	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	throughout	96	SF	Good		5%-10% Chrysotile	High	O & M	H6-6	01	

Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	351	6	Second	2J-122	Miscellaneous	Black floor tile mastic	Throughout	96	SF	Good		4%-5% Chrysotile	High	O & M	H6-6	02	
DC	351	6	Second	2J-122	Miscellaneous	Drywall and joint compound	Throughout	400	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	351	6	Second	2J-122	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	96	SF	Good		NAD	Medium	n/a	H6-6	n/a	
DC	351	6	Second	2J-122	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	55	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	351	6	Second	2J-122	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	55	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	351	6	Second	2J-122	Miscellaneous	Fire door	South Wall	1 @ 4' x 7'	Door	Good	Labeled/Wood	Assumed ACM	High	O & M	H6-6	N/A	
DC	352	6	Second	Patio	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	140	SF	Good		NAD	Medium	n/a	H6-6	n/a	
DC	352	6	Second	Patio	Miscellaneous	White duct seam sealant on metal	Throughout above drop ceiling	20	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	352	6	Second	Patio	Miscellaneous	Black mastic on metal window frame	West Wall	1 @ 6' x 8'	Window	Good		NAD	High	n/a	H6-6	n/a	
DC	352	6	Second	Patio	Miscellaneous	Black window caulk	West Wall	20	LF	Good		NAD	High	n/a	H6-6	n/a	
DC	353	6	Second	Smoking Room	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	800	SF	Good		NAD	Medium	n/a	H6-6	n/a	
DC	353	6	Second	Smoking Room	Miscellaneous	White duct seam sealant on metal	Throughout above drop ceiling	120	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	353	6	Second	Smoking Room	Miscellaneous	Gray duct seam sealant on metal	Throughout above drop ceiling	20	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	354	6	Second	2J-115	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	100	SF	Good		5%-10% Chrysotile	High	O & M	H6-6	01	
DC	354	6	Second	2J-115	Miscellaneous	12" x 12" Pink Floor Tile	Throughout	25	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	354	6	Second	2J-115	Miscellaneous	Black floor tile mastic	Throughout	125	SF	Good		4%-5% Chrysotile	High	O & M	H6-6	02	
DC	354	6	Second	2J-115	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout	100	SF	Good		NAD	Medium	n/a	H6-6	n/a	
DC	354	6	Second	2J-115	Miscellaneous	Fire door	West Wall	2 @ 4' x 7'	Door	Good	Labeled/Wood	Assumed ACM	High	O & M	H6-6	N/A	
DC	354	6	Second	2J-115	Miscellaneous	Red fire stop	Throughout above drop ceiling	20	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	354	6	Second	2J-115	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	354	6	Second	2J-115	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	32	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	354	6	Second	2J-115	Miscellaneous	Drywall and joint compound	throughout	300	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	355	6	Second	2K-100	Miscellaneous	12" x 12" Green mottle floor tile	throughout	375	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	355	6	Second	2K-100	Miscellaneous	Yellow floor tile mastic	throughout	375	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	355	6	Second	2K-100	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	175	SF	Good		NAD	Medium	n/a	H6-6	n/a	
DC	355	6	Second	2K-100	Miscellaneous	2' x 2' Width-wise fissured and dot ceiling tile	Throughout	175	SF	Good		NAD	Medium	n/a	H6-6	n/a	
DC	355	6	Second	2K-100	Miscellaneous	Black mastic on metal window frame	East Wall	1 @ 6' x 6'	Window	Good		NAD	Medium	n/a	H6-6	n/a	
DC	355	6	Second	2K-100	Miscellaneous	Black window caulk	East Wall	30	LF	Good		NAD	High	n/a	H6-6	n/a	
DC	355	6	Second	2K-100	Miscellaneous	Red fire stop	Throughout above drop ceiling	20	SF	Good		NAD	Low	n/a	H6-6	n/a	

Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	355	6	Second	2K-100	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	220	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	355	6	Second	2K-100	Miscellaneous	Tan baseboard mastic	Throughout	80	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	355A	6	Second	2K-101	Miscellaneous	Drywall and joint compound	Throughout	280	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	355A	6	Second	2K-101	Miscellaneous	Yellow ceramic tile mastic	South Wall	20	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	355A	6	Second	2K-101	Miscellaneous	2' x 2' Textured Ceiling tile	throughout	48	SF	Good		NAD	Medium	n/a	H6-6	n/a	
DC	355A	6	Second	2K-101	Miscellaneous	12" x 12" Peach mottle floor tile	Throughout	48	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	355A	6	Second	2K-101	Miscellaneous	Yellow floor tile mastic	throughout	48	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	355A	6	Second	2K-101	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout under carpet	48	SF	Good		5%-10% Chrysotile	Low	O & M	H6-6	01	
DC	355A	6	Second	2K-101	Miscellaneous	Black floor tile mastic	Throughout	48	SF	Good		4%-5% Chrysotile	Low	O & M	H6-6	02	
DC	355A	6	Second	2K-101	Miscellaneous	Tan baseboard mastic	Throughout	30	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	355A	6	Second	2K-101	Miscellaneous	Brown baseboard mastic	Throughout	30	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	355A	6	Second	2K-101	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	20	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	355A	6	Second	2K-101	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	25	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	355	6	Second	2K-100	Miscellaneous	Drywall and joint compound	Throughout	800	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	356	6	Second	2K-102	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	375	SF	Good		5%-10% Chrysotile	High	O & M	H6-6	01	
DC	356	6	Second	2K-102	Miscellaneous	Black floor tile mastic	Throughout	375	SF	Good		4%-5% Chrysotile	High	O & M	H6-6	02	
DC	356	6	Second	2K-102	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout	375	SF	Good		NAD	Medium	n/a	H6-6	n/a	
DC	356	6	Second	2K-102	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	50	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	356	6	Second	2K-102	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	50	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	356	6	Second	2K-102	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	10	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	356	6	Second	2K-102	Miscellaneous	2' x 2' Solid white ceiling tile	Bathroom	48	SF	Good		NAD	Medium	n/a	H6-6	n/a	
DC	356	6	Second	2K-102	Miscellaneous	Yellow ceramic tile mastic	Bathroom walls	280	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	356	6	Second	2K-102	Miscellaneous	Drywall and joint compound	Throughout	950	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	356	6	Second	2K-102	Miscellaneous	Brown baseboard mastic	Throughout	80	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	356	6	Second	2K-102	Miscellaneous	Black mastic on metal window frame	East Wall	1 @ 6' x 6'	Window	Good		NAD	Low	n/a	H6-6	n/a	
DC	357	6	Second	2K-104	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	375	SF	Good		5%-10% Chrysotile	High	O & M	H6-6	01	
DC	357	6	Second	2K-104	Miscellaneous	Black floor tile mastic	Throughout	375	SF	Good		4%-5% Chrysotile	High	O & M	H6-6	02	
DC	357	6	Second	2K-104	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout	423	SF	Good		NAD	Medium	n/a	H6-6	n/a	
DC	357	6	Second	2K-104	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	50	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	357	6	Second	2K-104	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	50	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	357	6	Second	2K-104	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	10	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	357	6	Second	2K-104	Miscellaneous	Yellow ceramic tile mastic	Bathroom walls	140	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	357	6	Second	2K-104	Miscellaneous	Drywall and joint compound	Throughout	950	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	357	6	Second	2K-104	Miscellaneous	Brown baseboard mastic	Throughout	80	LF	Good		NAD	Low	n/a	H6-6	n/a	

Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	357	6	Second	2K-104	Miscellaneous	Black mastic on metal window frame	East Wall	1 @ 6' x 6'	Window	Good		NAD	Low	n/a	H6-6	n/a	
DC	358	6	Second	2K-106	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout	750	SF	Good		NAD	Medium	n/a	H6-6	n/a	
DC	358	6	Second	2K-106	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	throughout	750	SF	Good		5%-10% Chrysotile	High	O & M	H6-6	01	
DC	358	6	Second	2K-106	Miscellaneous	Black floor tile mastic	Throughout	750	SF	Good		4%-5% Chrysotile	Low	O & M	H6-6	02	
DC	358	6	Second	2K-106	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	125	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	358	6	Second	2K-106	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	450	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	358	6	Second	2K-106	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	10	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	358	6	Second	2K-106	Miscellaneous	Yellow ceramic tile mastic	Throughout Bathroom	140	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	358	6	Second	2K-106	Miscellaneous	Black mastic on metal window frame	East Wall	2 @ 6' x 6'	Window	Good		NAD	Low	n/a	H6-6	n/a	
DC	358	6	Second	2K-106	Miscellaneous	Drywall and joint compound	Throughout	1200	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	359	6	Second	2K-108	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout	750	SF	Good		NAD	Medium	n/a	H6-6	n/a	
DC	359	6	Second	2K-108	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	throughout	750	SF	Good		5%-10% Chrysotile	High	O & M	H6-6	01	
DC	359	6	Second	2K-108	Miscellaneous	Black floor tile mastic	Throughout	750	SF	Good		4%-5% Chrysotile	Low	O & M	H6-6	02	
DC	359	6	Second	2K-108	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	125	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	359	6	Second	2K-108	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	650	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	359	6	Second	2K-108	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	10	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	359	6	Second	2K-108	Miscellaneous	Yellow ceramic tile mastic	Throughout Bathroom	140	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	359	6	Second	2K-108	Miscellaneous	Black mastic on metal window frame	East Wall	2 @ 6' x 6'	Window	Good		NAD	Low	n/a	H6-6	n/a	
DC	360	6	Second	2K-110	Miscellaneous	Drywall and joint compound	Throughout	1200	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	360	6	Second	2K-110	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	375	SF	Good		5%-10% Chrysotile	High	O & M	H6-6	01	
DC	360	6	Second	2K-110	Miscellaneous	Black floor tile mastic	Throughout	375	SF	Good		4%-5% Chrysotile	High	O & M	H6-6	02	
DC	360	6	Second	2K-110	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout	423	SF	Good		NAD	Medium	n/a	H6-6	n/a	
DC	360	6	Second	2K-110	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	50	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	360	6	Second	2K-110	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	50	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	360	6	Second	2K-110	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	70	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	360	6	Second	2K-110	Miscellaneous	Yellow ceramic tile mastic	Bathroom walls	140	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	360	6	Second	2K-110	Miscellaneous	Drywall and joint compound	Throughout	950	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	360	6	Second	2K-110	Miscellaneous	Brown baseboard mastic	Throughout	80	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	360	6	Second	2K-110	Miscellaneous	Black mastic on metal window frame	East Wall	1 @ 6' x 6'	Window	Good		NAD	Low	n/a	H6-6	n/a	
DC	361	6	Second	2K-112	Miscellaneous	Drywall and joint compound	Throughout	1400	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	361	6	Second	2K-112	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	375	SF	Good		5%-10% Chrysotile	High	O & M	H6-6	01	

**Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6**

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	361	6	Second	2K-112	Miscellaneous	Black floor tile mastic	Throughout	375	SF	Good		4%-5% Chrysotile	High	O & M	H6-6	02	
DC	361	6	Second	2K-112	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout	423	SF	Good		NAD	Medium	n/a	H6-6	n/a	
DC	361	6	Second	2K-112	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	50	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	361	6	Second	2K-112	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	50	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	361	6	Second	2K-112	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	70	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	361	6	Second	2K-112	Miscellaneous	Yellow ceramic tile mastic	Bathroom walls	340	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	361	6	Second	2K-112	Miscellaneous	Drywall and joint compound	Throughout	950	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	361	6	Second	2K-112	Miscellaneous	Brown baseboard mastic	Throughout	80	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	361	6	Second	2K-112	Miscellaneous	Black mastic on metal window frame	East Wall	1 @ 6' x 6'	Window	Good		NAD	Low	n/a	H6-6	n/a	
DC	362	6	Second	2K-114	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout	750	SF	Good		NAD	Medium	n/a	H6-6	n/a	
DC	362	6	Second	2K-114	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	throughout	750	SF	Good		5%-10% Chrysotile	High	O & M	H6-6	01	
DC	362	6	Second	2K-114	Miscellaneous	Black floor tile mastic	Throughout	750	SF	Good		4%-5% Chrysotile	Low	O & M	H6-6	02	
DC	362	6	Second	2K-114	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	125	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	362	6	Second	2K-114	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	450	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	362	6	Second	2K-114	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	10	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	362	6	Second	2K-114	Miscellaneous	Black mastic on metal window frame	East Wall	2 @ 6' x 6'	Window	Good		NAD	Low	n/a	H6-6	n/a	
DC	362	6	Second	2K-114	Miscellaneous	Drywall and joint compound	Throughout	1200	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	363	6	Second	2K-116	Miscellaneous	Drywall and joint compound	Throughout	1500	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	363	6	Second	2K-116	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	375	SF	Good		5%-10% Chrysotile	High	O & M	H6-6	01	
DC	363	6	Second	2K-116	Miscellaneous	Black floor tile mastic	Throughout	375	SF	Good		4%-5% Chrysotile	High	O & M	H6-6	02	
DC	363	6	Second	2K-116	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout	523	SF	Good		NAD	Medium	n/a	H6-6	n/a	
DC	363	6	Second	2K-116	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	50	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	363	6	Second	2K-116	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	150	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	363	6	Second	2K-116	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	30	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	363	6	Second	2K-116	Miscellaneous	Yellow ceramic tile mastic	Bathroom walls	340	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	363	6	Second	2K-116	Miscellaneous	Drywall and joint compound	Throughout	950	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	363	6	Second	2K-116	Miscellaneous	Brown baseboard mastic	Throughout	80	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	363	6	Second	2K-116	Miscellaneous	Black mastic on metal window frame	East Wall	1 @ 6' x 6'	Window	Good		NAD	Low	n/a	H6-6	n/a	
DC	364	6	Second	2K-118	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout	750	SF	Good		NAD	Medium	n/a	H6-6	n/a	
DC	364	6	Second	2K-118	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	throughout	750	SF	Good		5%-10% Chrysotile	High	O & M	H6-6	01	
DC	364	6	Second	2K-118	Miscellaneous	Black floor tile mastic	Throughout	750	SF	Good		4%-5% Chrysotile	Low	O & M	H6-6	02	
DC	364	6	Second	2K-118	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	125	SF	Good		NAD	Low	n/a	H6-6	n/a	

Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	364	6	Second	2K-118	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	450	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	364	6	Second	2K-118	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	10	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	364	6	Second	2K-118	Miscellaneous	Black mastic on metal window frame	East Wall	2 @ 6' x 6'	Window	Good		NAD	Low	n/a	H6-6	n/a	
DC	364	6	Second	2K-118	Miscellaneous	Drywall and joint compound	Throughout	1200	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	365	6	Second	Stairs 15	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout	200	SF	Good		NAD	Medium	n/a	H6-6	n/a	
DC	365	6	Second	Stairs 15	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	400	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	365	6	Second	Stairs 15	Miscellaneous	Red fire stop	Throughout above drop ceiling	3	SF	Good		NAD	Medium	n/a	H6-6	n/a	
DC	365	6	Second	Stairs 15	Miscellaneous	Drywall and joint compound	throughout	750	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	366	6	Second	2K-120	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout	196	SF	Good		NAD	Medium	n/a	H6-6	n/a	
DC	366	6	Second	2K-120	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	196	SF	Good		5%-10% Chrysotile	High	O & M	H6-6	01	
DC	366	6	Second	2K-120	Miscellaneous	Black floor tile mastic	Throughout	196	SF	Good		4%-5% Chrysotile	Low	O & M	H6-6	02	
DC	366	6	Second	2K-120	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	50	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	366	6	Second	2K-120	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	150	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	366	6	Second	2K-120	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	10	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	366	6	Second	2K-120	Miscellaneous	Yellow ceramic tile mastic	Throughout Bathroom	90	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	366	6	Second	2K-120	Miscellaneous	Brown baseboard mastic	Throughout Bathroom	56	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	366	6	Second	2K-120	Miscellaneous	Drywall and joint compound	Throughout	600	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	366	6	Second	2K-120	Miscellaneous	Black mastic on metal window frame	South Wall	1 @ 6' x 6'	Window	Good		NAD	Low	n/a	H6-6	n/a	
DC	367	6	Second	2K-122	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout	196	SF	Good		NAD	Medium	n/a	H6-6	n/a	
DC	367	6	Second	2K-122	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	196	SF	Good		5%-10% Chrysotile	High	O & M	H6-6	01	
DC	367	6	Second	2K-122	Miscellaneous	Black floor tile mastic	Throughout	196	SF	Good		4%-5% Chrysotile	Low	O & M	H6-6	02	
DC	367	6	Second	2K-122	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	50	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	367	6	Second	2K-122	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	150	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	367	6	Second	2K-122	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	10	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	367	6	Second	2K-122	Miscellaneous	Yellow ceramic tile mastic	Throughout Bathroom	90	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	367	6	Second	2K-122	Miscellaneous	Brown baseboard mastic	Throughout Bathroom	56	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	367	6	Second	2K-122	Miscellaneous	Drywall and joint compound	Throughout	600	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	367	6	Second	2K-122	Miscellaneous	Black mastic on metal window frame	South Wall	1 @ 6' x 6'	Window	Good		NAD	Low	n/a	H6-6	n/a	
DC	368	6	Second	2K-124	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout	196	SF	Good		NAD	Medium	n/a	H6-6	n/a	
DC	368	6	Second	2K-124	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	196	SF	Good		5%-10% Chrysotile	High	O & M	H6-6	01	
DC	368	6	Second	2K-124	Miscellaneous	Black floor tile mastic	Throughout	196	SF	Good		4%-5% Chrysotile	Low	O & M	H6-6	02	

Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	368	6	Second	2K-124	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	50	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	368	6	Second	2K-124	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	150	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	368	6	Second	2K-124	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	10	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	368	6	Second	2K-124	Miscellaneous	Yellow ceramic tile mastic	Throughout Bathroom	90	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	368	6	Second	2K-124	Miscellaneous	Brown baseboard mastic	Throughout Bathroom	56	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	368	6	Second	2K-124	Miscellaneous	Drywall and joint compound	Throughout	600	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	368	6	Second	2K-124	Miscellaneous	Black mastic on metal window frame	South Wall	1 @ 6' x 6'	Window	Good		NAD	Low	n/a	H6-6	n/a	
DC	369	6	Second	2K-126	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout	196	SF	Good		NAD	Medium	n/a	H6-6	n/a	
DC	369	6	Second	2K-126	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	196	SF	Good		5%-10% Chrysotile	High	O & M	H6-6	01	
DC	369	6	Second	2K-126	Miscellaneous	Black floor tile mastic	Throughout	196	SF	Good		4%-5% Chrysotile	Low	O & M	H6-6	02	
DC	369	6	Second	2K-126	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	50	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	369	6	Second	2K-126	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	150	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	369	6	Second	2K-126	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	10	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	369	6	Second	2K-126	Miscellaneous	Yellow ceramic tile mastic	Throughout Bathroom	90	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	369	6	Second	2K-126	Miscellaneous	Brown baseboard mastic	Throughout Bathroom	56	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	369	6	Second	2K-126	Miscellaneous	Drywall and joint compound	Throughout	600	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	369	6	Second	2K-126	Miscellaneous	Black mastic on metal window frame	South Wall	1 @ 6' x 6'	Window	Good		NAD	Low	n/a	H6-6	n/a	
DC	370	6	Second	2K-128	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout	196	SF	Good		NAD	Medium	n/a	H6-6	n/a	
DC	370	6	Second	2K-128	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	196	SF	Good		5%-10% Chrysotile	High	O & M	H6-6	01	
DC	370	6	Second	2K-128	Miscellaneous	Black floor tile mastic	Throughout	196	SF	Good		4%-5% Chrysotile	Low	O & M	H6-6	02	
DC	370	6	Second	2K-128	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	50	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	370	6	Second	2K-128	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	150	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	370	6	Second	2K-128	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	10	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	370	6	Second	2K-128	Miscellaneous	Yellow ceramic tile mastic	Throughout Bathroom	90	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	370	6	Second	2K-128	Miscellaneous	Brown baseboard mastic	Throughout Bathroom	56	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	370	6	Second	2K-128	Miscellaneous	Drywall and joint compound	Throughout	600	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	370	6	Second	2K-128	Miscellaneous	Black mastic on metal window frame	South Wall	1 @ 6' x 6'	Window	Good		NAD	Low	n/a	H6-6	n/a	
DC	371	6	Second	2K-130	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout	196	SF	Good		NAD	Medium	n/a	H6-6	n/a	
DC	371	6	Second	2K-130	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	196	SF	Good		5%-10% Chrysotile	High	O & M	H6-6	01	
DC	371	6	Second	2K-130	Miscellaneous	Black floor tile mastic	Throughout	196	SF	Good		4%-5% Chrysotile	Low	O & M	H6-6	02	
DC	371	6	Second	2K-130	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	50	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	371	6	Second	2K-130	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	150	SF	Good		NAD	Low	n/a	H6-6	n/a	

Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	371	6	Second	2K-130	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	10	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	371	6	Second	2K-130	Miscellaneous	Yellow ceramic tile mastic	Throughout Bathroom	90	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	371	6	Second	2K-130	Miscellaneous	Brown baseboard mastic	Throughout Bathroom	56	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	371	6	Second	2K-130	Miscellaneous	Drywall and joint compound	Throughout	600	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	371	6	Second	2K-130	Miscellaneous	Black mastic on metal window frame	South Wall	1 @ 6' x 6'	Window	Good		NAD	Low	n/a	H6-6	n/a	
DC	372	6	Second	2K-132	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	throughout	375	SF	Good		5%-10% Chrysotile	High	O & M	H6-6	01	
DC	372	6	Second	2K-132	Miscellaneous	Black floor tile mastic	Throughout	375	SF	Good		4%-5% Chrysotile	High	O & M	H6-6	02	
DC	372	6	Second	2K-132	Miscellaneous	Brown baseboard mastic	Throughout	80	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	372	6	Second	2K-132	Miscellaneous	Drywall and joint compound	Throughout	950	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	372	6	Second	2K-132	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	300	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	372	6	Second	2K-132	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	50	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	372	6	Second	2K-132	Miscellaneous	Black mastic on metal window frame	West Wall	1 @ 6' x 6'	Window	Good		NAD	Low	n/a	H6-6	n/a	
DC	372	6	Second	2K-132	Miscellaneous	Yellow floor tile mastic	Throughout	250	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	372	6	Second	2K-132	Miscellaneous	2' x 2' Solid white ceiling tile	Throughout Bathroom	72	SF	Good		NAD	Medium	n/a	H6-6	n/a	
DC	372	6	Second	2K-132	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	30	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	372	6	Second	2K-132	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout	375	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	373	6	Second	2K-134	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	throughout	375	SF	Good		5%-10% Chrysotile	High	O & M	H6-6	01	
DC	373	6	Second	2K-134	Miscellaneous	Black floor tile mastic	Throughout	375	SF	Good		4%-5% Chrysotile	High	O & M	H6-6	02	
DC	373	6	Second	2K-134	Miscellaneous	Brown baseboard mastic	Throughout	80	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	373	6	Second	2K-134	Miscellaneous	Drywall and joint compound	Throughout	750	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	373	6	Second	2K-134	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	300	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	373	6	Second	2K-134	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	50	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	373	6	Second	2K-134	Miscellaneous	Black mastic on metal window frame	West Wall	1 @ 6' x 6'	Window	Good		NAD	Low	n/a	H6-6	n/a	
DC	373	6	Second	2K-134	Miscellaneous	Yellow floor tile mastic	Throughout	250	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	373	6	Second	2K-134	Miscellaneous	2' x 2' Solid white ceiling tile	Throughout Bathroom	72	SF	Good		NAD	Medium	n/a	H6-6	n/a	
DC	373	6	Second	2K-134	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	30	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	373	6	Second	2K-134	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout	375	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	374	6	Second	2K-136	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	throughout	375	SF	Good		5%-10% Chrysotile	High	O & M	H6-6	01	
DC	374	6	Second	2K-136	Miscellaneous	Black floor tile mastic	Throughout	375	SF	Good		4%-5% Chrysotile	High	O & M	H6-6	02	
DC	374	6	Second	2K-136	Miscellaneous	Brown baseboard mastic	Throughout	80	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	374	6	Second	2K-136	Miscellaneous	Drywall and joint compound	Throughout	950	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	374	6	Second	2K-136	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	300	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	374	6	Second	2K-136	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	50	SF	Good		NAD	Low	n/a	H6-6	n/a	

**Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6**

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	374	6	Second	2K-136	Miscellaneous	Black mastic on metal window frame	West Wall	1 @ 6' x 6'	Window	Good		NAD	Low	n/a	H6-6	n/a	
DC	374	6	Second	2K-136	Miscellaneous	Yellow floor tile mastic	Throughout	250	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	374	6	Second	2K-136	Miscellaneous	2' x 2' Solid white ceiling tile	Throughout Bathroom	72	SF	Good		NAD	Medium	n/a	H6-6	n/a	
DC	374	6	Second	2K-136	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	30	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	374	6	Second	2K-136	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout	375	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	375	6	Second	2K-138	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	throughout	375	SF	Good		5%-10% Chrysotile	High	O & M	H6-6	01	
DC	375	6	Second	2K-138	Miscellaneous	Black floor tile mastic	Throughout	375	SF	Good		4%-5% Chrysotile	High	O & M	H6-6	02	
DC	375	6	Second	2K-138	Miscellaneous	Brown baseboard mastic	Throughout	80	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	375	6	Second	2K-138	Miscellaneous	Drywall and joint compound	Throughout	750	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	375	6	Second	2K-138	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	300	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	375	6	Second	2K-138	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	50	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	375	6	Second	2K-138	Miscellaneous	Black mastic on metal window frame	West Wall	1 @ 6' x 6'	Window	Good		NAD	Low	n/a	H6-6	n/a	
DC	375	6	Second	2K-138	Miscellaneous	Yellow floor tile mastic	Throughout	250	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	375	6	Second	2K-138	Miscellaneous	2' x 2' Solid white ceiling tile	Throughout Bathroom	72	SF	Good		NAD	Medium	n/a	H6-6	n/a	
DC	375	6	Second	2K-138	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	30	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	375	6	Second	2K-138	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout	375	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	376	6	Second	2K-140	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	throughout	375	SF	Good		5%-10% Chrysotile	High	O & M	H6-6	01	
DC	376	6	Second	2K-140	Miscellaneous	Black floor tile mastic	Throughout	375	SF	Good		4%-5% Chrysotile	High	O & M	H6-6	02	
DC	376	6	Second	2K-140	Miscellaneous	Brown baseboard mastic	Throughout	80	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	376	6	Second	2K-140	Miscellaneous	Drywall and joint compound	Throughout	950	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	376	6	Second	2K-140	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	300	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	376	6	Second	2K-140	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	50	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	376	6	Second	2K-140	Miscellaneous	Black mastic on metal window frame	West Wall	1 @ 6' x 6'	Window	Good		NAD	Low	n/a	H6-6	n/a	
DC	376	6	Second	2K-140	Miscellaneous	Yellow floor tile mastic	Throughout	250	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	376	6	Second	2K-140	Miscellaneous	2' x 2' Solid white ceiling tile	Throughout Bathroom	72	SF	Good		NAD	Medium	n/a	H6-6	n/a	
DC	376	6	Second	2K-140	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	30	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	376	6	Second	2K-140	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout	375	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	377	6	Second	2K-142	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout	750	SF	Good		NAD	Medium	n/a	H6-6	n/a	
DC	377	6	Second	2K-142	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	throughout	750	SF	Good		5%-10% Chrysotile	High	O & M	H6-6	01	
DC	377	6	Second	2K-142	Miscellaneous	Black floor tile mastic	Throughout	750	SF	Good		4%-5% Chrysotile	Low	O & M	H6-6	02	
DC	377	6	Second	2K-142	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	125	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	377	6	Second	2K-142	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	450	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	377	6	Second	2K-142	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	10	LF	Good		NAD	Low	n/a	H6-6	n/a	

Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	377	6	Second	2K-142	Miscellaneous	Yellow ceramic tile mastic	Throughout Bathroom	140	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	377	6	Second	2K-142	Miscellaneous	Black mastic on metal window frame	West Wall	2 @ 6' x 6'	Window	Good		NAD	Low	n/a	H6-6	n/a	
DC	377	6	Second	2K-142	Miscellaneous	Drywall and joint compound	Throughout	1200	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	378	6	Second	2K-144	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	throughout	375	SF	Good		5%-10% Chrysotile	High	O & M	H6-6	01	
DC	378	6	Second	2K-144	Miscellaneous	Black floor tile mastic	Throughout	375	SF	Good		4%-5% Chrysotile	High	O & M	H6-6	02	
DC	378	6	Second	2K-144	Miscellaneous	Brown baseboard mastic	Throughout	80	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	378	6	Second	2K-144	Miscellaneous	Drywall and joint compound	Throughout	950	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	378	6	Second	2K-144	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	300	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	378	6	Second	2K-144	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	378	6	Second	2K-144	Miscellaneous	Black mastic on metal window frame	West Wall	1 @ 6' x 6'	Window	Good		NAD	Low	n/a	H6-6	n/a	
DC	378	6	Second	2K-144	Miscellaneous	Yellow floor tile mastic	Throughout	250	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	378	6	Second	2K-144	Miscellaneous	2' x 2' Solid white ceiling tile	Throughout Bathroom	72	SF	Good		NAD	Medium	n/a	H6-6	n/a	
DC	378	6	Second	2K-144	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	30	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	378	6	Second	2K-144	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout	375	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	379	6	Second	2K-146	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	throughout	375	SF	Good		5%-10% Chrysotile	High	O & M	H6-6	01	
DC	379	6	Second	2K-146	Miscellaneous	Black floor tile mastic	Throughout	375	SF	Good		4%-5% Chrysotile	High	O & M	H6-6	02	
DC	379	6	Second	2K-146	Miscellaneous	Brown baseboard mastic	Throughout	80	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	379	6	Second	2K-146	Miscellaneous	Drywall and joint compound	Throughout	950	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	379	6	Second	2K-146	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	300	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	379	6	Second	2K-146	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	50	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	379	6	Second	2K-146	Miscellaneous	Black mastic on metal window frame	West Wall	1 @ 6' x 6'	Window	Good		NAD	Low	n/a	H6-6	n/a	
DC	379	6	Second	2K-146	Miscellaneous	Yellow floor tile mastic	Throughout	250	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	379	6	Second	2K-146	Miscellaneous	2' x 2' Solid white ceiling tile	Throughout Bathroom	72	SF	Good		NAD	Medium	n/a	H6-6	n/a	
DC	379	6	Second	2K-146	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	30	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	379	6	Second	2K-146	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout	375	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	380	6	Second	2K-148	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	throughout	375	SF	Good		5%-10% Chrysotile	High	O & M	H6-6	01	
DC	380	6	Second	2K-148	Miscellaneous	Black floor tile mastic	Throughout	375	SF	Good		4%-5% Chrysotile	High	O & M	H6-6	02	
DC	380	6	Second	2K-148	Miscellaneous	Brown baseboard mastic	Throughout	80	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	380	6	Second	2K-148	Miscellaneous	Drywall and joint compound	Throughout	750	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	380	6	Second	2K-148	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	300	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	380	6	Second	2K-148	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	50	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	380	6	Second	2K-148	Miscellaneous	Black mastic on metal window frame	West Wall	1 @ 6' x 6'	Window	Good		NAD	Low	n/a	H6-6	n/a	
DC	380	6	Second	2K-148	Miscellaneous	Yellow floor tile mastic	Throughout	250	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	380	6	Second	2K-148	Miscellaneous	2' x 2' Solid white ceiling tile	Throughout Bathroom	72	SF	Good		NAD	Medium	n/a	H6-6	n/a	

Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	380	6	Second	2K-148	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	30	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	380	6	Second	2K-148	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout	375	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	381	6	Second	2K-150	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	throughout	375	SF	Good		5%-10% Chrysotile	High	O & M	H6-6	01	
DC	381	6	Second	2K-150	Miscellaneous	Black floor tile mastic	Throughout	375	SF	Good		4%-5% Chrysotile	High	O & M	H6-6	02	
DC	381	6	Second	2K-150	Miscellaneous	Brown baseboard mastic	Throughout	80	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	381	6	Second	2K-150	Miscellaneous	Drywall and joint compound	Throughout	950	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	381	6	Second	2K-150	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	300	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	381	6	Second	2K-150	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	50	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	381	6	Second	2K-150	Miscellaneous	Black mastic on metal window frame	West Wall	1 @ 6' x 6'	Window	Good		NAD	Low	n/a	H6-6	n/a	
DC	381	6	Second	2K-150	Miscellaneous	Yellow floor tile mastic	Throughout	250	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	381	6	Second	2K-150	Miscellaneous	2' x 2' Solid white ceiling tile	Throughout Bathroom	72	SF	Good		NAD	Medium	n/a	H6-6	n/a	
DC	381	6	Second	2K-150	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	30	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	381	6	Second	2K-150	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout	375	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	382	6	Second	2K-152	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	throughout	375	SF	Good		5%-10% Chrysotile	High	O & M	H6-6	01	
DC	382	6	Second	2K-152	Miscellaneous	Black floor tile mastic	Throughout	375	SF	Good		4%-5% Chrysotile	High	O & M	H6-6	02	
DC	382	6	Second	2K-152	Miscellaneous	Brown baseboard mastic	Throughout	80	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	382	6	Second	2K-152	Miscellaneous	Drywall and joint compound	Throughout	750	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	382	6	Second	2K-152	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	300	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	382	6	Second	2K-152	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	50	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	382	6	Second	2K-152	Miscellaneous	Black mastic on metal window frame	West Wall	1 @ 6' x 6'	Window	Good		NAD	Low	n/a	H6-6	n/a	
DC	382	6	Second	2K-152	Miscellaneous	Yellow floor tile mastic	Throughout	250	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	382	6	Second	2K-152	Miscellaneous	2' x 2' Solid white ceiling tile	Throughout Bathroom	72	SF	Good		NAD	Medium	n/a	H6-6	n/a	
DC	382	6	Second	2K-152	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	30	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	382	6	Second	2K-152	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout	375	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	383	6	Second	2K-154	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	throughout	375	SF	Good		5%-10% Chrysotile	High	O & M	H6-6	01	
DC	383	6	Second	2K-154	Miscellaneous	Black floor tile mastic	Throughout	375	SF	Good		4%-5% Chrysotile	High	O & M	H6-6	02	
DC	383	6	Second	2K-154	Miscellaneous	Brown baseboard mastic	Throughout	80	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	383	6	Second	2K-154	Miscellaneous	Drywall and joint compound	Throughout	950	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	383	6	Second	2K-154	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	300	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	383	6	Second	2K-154	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	50	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	383	6	Second	2K-154	Miscellaneous	Black mastic on metal window frame	West Wall	1 @ 6' x 6'	Window	Good		NAD	Low	n/a	H6-6	n/a	
DC	383	6	Second	2K-154	Miscellaneous	Yellow floor tile mastic	Throughout	250	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	383	6	Second	2K-154	Miscellaneous	2' x 2' Solid white ceiling tile	Throughout Bathroom	72	SF	Good		NAD	Medium	n/a	H6-6	n/a	

Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	383	6	Second	2K-154	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	30	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	383	6	Second	2K-154	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout	375	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	384	6	Second	2K-156	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	throughout	375	SF	Good		5%-10% Chrysotile	High	O & M	H6-6	01	
DC	384	6	Second	2K-156	Miscellaneous	Black floor tile mastic	Throughout	375	SF	Good		4%-5% Chrysotile	High	O & M	H6-6	02	
DC	384	6	Second	2K-156	Miscellaneous	Brown baseboard mastic	Throughout	80	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	384	6	Second	2K-156	Miscellaneous	Drywall and joint compound	Throughout	750	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	384	6	Second	2K-156	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	300	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	384	6	Second	2K-156	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	50	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	384	6	Second	2K-156	Miscellaneous	Black mastic on metal window frame	West Wall	1 @ 6' x 6'	Window	Good		NAD	Low	n/a	H6-6	n/a	
DC	384	6	Second	2K-156	Miscellaneous	Yellow floor tile mastic	Throughout	250	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	384	6	Second	2K-156	Miscellaneous	2' x 2' Solid white ceiling tile	Throughout Bathroom	72	SF	Good		NAD	Medium	n/a	H6-6	n/a	
DC	384	6	Second	2K-156	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	30	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	384	6	Second	2K-156	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout	375	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	385	6	Second	2K-158	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	throughout	375	SF	Good		5%-10% Chrysotile	High	O & M	H6-6	01	
DC	385	6	Second	2K-158	Miscellaneous	Black floor tile mastic	Throughout	375	SF	Good		4%-5% Chrysotile	High	O & M	H6-6	02	
DC	385	6	Second	2K-158	Miscellaneous	Brown baseboard mastic	Throughout	80	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	385	6	Second	2K-158	Miscellaneous	Drywall and joint compound	Throughout	950	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	385	6	Second	2K-158	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	300	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	385	6	Second	2K-158	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	50	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	385	6	Second	2K-158	Miscellaneous	Black mastic on metal window frame	West Wall	1 @ 6' x 6'	Window	Good		NAD	Low	n/a	H6-6	n/a	
DC	385	6	Second	2K-158	Miscellaneous	Yellow floor tile mastic	Throughout	250	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	385	6	Second	2K-158	Miscellaneous	2' x 2' Solid white ceiling tile	Throughout Bathroom	72	SF	Good		NAD	Medium	n/a	H6-6	n/a	
DC	385	6	Second	2K-158	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	30	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	385	6	Second	2K-158	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout	375	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	386	6	Second	2K-160	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	throughout	375	SF	Good		5%-10% Chrysotile	High	O & M	H6-6	01	
DC	386	6	Second	2K-160	Miscellaneous	Black floor tile mastic	Throughout	375	SF	Good		4%-5% Chrysotile	High	O & M	H6-6	02	
DC	386	6	Second	2K-160	Miscellaneous	Brown baseboard mastic	Throughout	80	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	386	6	Second	2K-160	Miscellaneous	Drywall and joint compound	Throughout	750	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	386	6	Second	2K-160	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	300	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	386	6	Second	2K-160	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	50	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	386	6	Second	2K-160	Miscellaneous	Black mastic on metal window frame	West Wall	1 @ 6' x 6'	Window	Good		NAD	Low	n/a	H6-6	n/a	
DC	386	6	Second	2K-160	Miscellaneous	Yellow floor tile mastic	Throughout	250	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	386	6	Second	2K-160	Miscellaneous	2' x 2' Solid white ceiling tile	Throughout Bathroom	72	SF	Good		NAD	Medium	n/a	H6-6	n/a	

Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	386	6	Second	2K-160	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	30	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	386	6	Second	2K-160	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout	375	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	387	6	Second	2K-200	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	throughout	192	SF	Good		5%-10% Chrysotile	High	O & M	H6-6	01	
DC	387	6	Second	2K-200	Miscellaneous	Black floor tile mastic	Throughout	192	SF	Good		4%-5% Chrysotile	High	O & M	H6-6	02	
DC	387	6	Second	2K-200	Miscellaneous	2' x 4' Gouged and dot ceiling tile	Throughout	192	SF	Good		NAD	Medium	n/a	H6-6	n/a	
DC	387	6	Second	2K-200	Miscellaneous	Drywall and joint compound	Throughout	560	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	387	6	Second	2K-200	Miscellaneous	Brown baseboard mastic	Throughout	56	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	387	6	Second	2K-200	Miscellaneous	Fire door	south Wall	1 @ 3' x 7'	Door	Good	Labeled/Wood	Assumed ACM	High	O & M	H6-6	N/A	
DC	387	6	Second	2K-200	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	100	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	387	6	Second	2K-200	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	55	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	388	6	Second	2K-201	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	60	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	388	6	Second	2K-201	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	50	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	388	6	Second	2K-201	Miscellaneous	Drywall and joint compound	Throughout	480	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	388	6	Second	2K-201	Miscellaneous	Brown baseboard mastic	Throughout	48	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	388	6	Second	2K-201	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout	144	SF	Good		NAD	Medium	n/a	H6-6	n/a	
DC	388	6	Second	2K-201	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	144	SF	Good		5%-10% Chrysotile	Low	O & M	H6-6	01	
DC	388	6	Second	2K-201	Miscellaneous	Black floor tile mastic	Throughout	144	SF	Good		4%-5% Chrysotile	Low	O & M	H6-6	02	
DC	388	6	Second	2K-201	Miscellaneous	Fire door	West Wall	1 @ 3' x 7'	Door	Good	Labeled/Wood	Assumed ACM	High	O & M	H6-6	N/A	
DC	389	6	Second	2K-202	Miscellaneous	12" x 12" Off-white with brown specks floor tile	throughout	192	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	389	6	Second	2K-202	Miscellaneous	Yellow floor tile mastic	Throughout	192	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	389	6	Second	2K-202	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	192	SF	Good		5%-10% Chrysotile	Low	O & M	H6-6	01	
DC	389	6	Second	2K-202	Miscellaneous	Black floor tile mastic	Throughout	192	SF	Good		4%-5% Chrysotile	Low	O & M	H6-6	02	
DC	389	6	Second	2K-202	Miscellaneous	2' x 4' Textured Ceiling tile	throughout	192	SF	Good		NAD	Medium	n/a	H6-6	n/a	
DC	389	6	Second	2K-202	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	60	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	389	6	Second	2K-202	Miscellaneous	White duct seam sealant on foil	Throughout	50	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	389	6	Second	2K-202	Miscellaneous	Brown baseboard mastic	Throughout	56	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	389	6	Second	2K-202	Miscellaneous	Drywall and joint compound	Throughout	560	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	390	6	Second	2K-203	Miscellaneous	2' x 4' Textured Ceiling tile	throughout	180	SF	Good		NAD	Medium	n/a	H6-6	n/a	
DC	390	6	Second	2K-203	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	120	SF	Good		5%-10% Chrysotile	High	O & M	H6-6	01	
DC	390	6	Second	2K-203	Miscellaneous	Black floor tile mastic	Throughout	120	SF	Good		4%-5% Chrysotile	Low	O & M	H6-6	02	
DC	390	6	Second	2K-203	Miscellaneous	Brown baseboard mastic	Throughout	44	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	390	6	Second	2K-203	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	30	SF	Good		NAD	Low	n/a	H6-6	n/a	

Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	390	6	Second	2K-203	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	35	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	390	6	Second	2K-203	Miscellaneous	Drywall and joint compound	Throughout	440	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	390	6	Second	2K-203	Miscellaneous	Yellow ceramic tile mastic	Throughout	75	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	391	6	Second	2K-204	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	60	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	391	6	Second	2K-204	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	50	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	391	6	Second	2K-204	Miscellaneous	Drywall and joint compound	Throughout	480	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	391	6	Second	2K-204	Miscellaneous	Brown baseboard mastic	Throughout	48	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	391	6	Second	2K-204	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout	144	SF	Good		NAD	Medium	n/a	H6-6	n/a	
DC	391	6	Second	2K-204	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	144	SF	Good		5%-10% Chrysotile	Low	O & M	H6-6	01	
DC	391	6	Second	2K-204	Miscellaneous	Black floor tile mastic	Throughout	144	SF	Good		4%-5% Chrysotile	Low	O & M	H6-6	02	
DC	391	6	Second	2K-204	Miscellaneous	Fire door	East Wall	1 @ 3' x 7'	Door	Good	Labeled/Wood	Assumed ACM	High	O & M	H6-6	N/A	
DC	392	6	Second	2K-207	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	60	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	392	6	Second	2K-207	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	50	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	392	6	Second	2K-207	Miscellaneous	Drywall and joint compound	Throughout	480	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	392	6	Second	2K-207	Miscellaneous	Brown baseboard mastic	Throughout	48	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	392	6	Second	2K-207	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout	144	SF	Good		NAD	Medium	n/a	H6-6	n/a	
DC	392	6	Second	2K-207	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	144	SF	Good		5%-10% Chrysotile	Low	O & M	H6-6	01	
DC	392	6	Second	2K-207	Miscellaneous	Black floor tile mastic	Throughout	144	SF	Good		4%-5% Chrysotile	Low	O & M	H6-6	02	
DC	392	6	Second	2K-207	Miscellaneous	Fire door	East Wall	1 @ 3' x 7'	Door	Good	Labeled/Wood	Assumed ACM	High	O & M	H6-6	N/A	
DC	393	6	Second	2K-206	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	60	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	393	6	Second	2K-206	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	90	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	393	6	Second	2K-206	Miscellaneous	Drywall and joint compound	Throughout	480	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	393	6	Second	2K-206	Miscellaneous	Brown baseboard mastic	Throughout	48	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	393	6	Second	2K-206	Miscellaneous	2' x 4' Textured Ceiling tile	Throughout	144	SF	Good		NAD	Medium	n/a	H6-6	n/a	
DC	393	6	Second	2K-206	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	144	SF	Good		5%-10% Chrysotile	Low	O & M	H6-6	01	
DC	393	6	Second	2K-206	Miscellaneous	Black floor tile mastic	Throughout	144	SF	Good		4%-5% Chrysotile	Low	O & M	H6-6	02	
DC	393	6	Second	2K-206	Miscellaneous	12" x 12" Off-white mottled floor tile	Throughout	144	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	394	6	Second	2K-207	Miscellaneous	White duct seam sealant on foil	Throughout	120	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	394	6	Second	2K-207	Miscellaneous	White duct seam sealant on metal	Throughout	10	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	394	6	Second	2K-207	Miscellaneous	Drywall and joint compound	Throughout	480	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	394	6	Second	2K-207	Miscellaneous	White pipe seam sealant on paper	Throughout	25	LF	Good		NAD	High	n/a	H6-6	n/a	
DC	394	6	Second	2K-207	Miscellaneous	Red fire stop	Throughout	3	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	395	6	Second	2K-208	Surfacing	Gray spray-on fire proofing	Throughout	75	SF	Good		NAD	Low	n/a	H6-6	n/a	

Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	395	6	Second	2K-208	Miscellaneous	Drywall and joint compound	Throughout	300	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	395	6	Second	2K-208	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	throughout	56	SF	Good		5%-10% Chrysotile	High	O & M	H6-6	01	
DC	395	6	Second	2K-208	Miscellaneous	Black floor tile mastic	Throughout	56	SF	Good		4%-5% Chrysotile	Low	O & M	H6-6	02	
DC	395	6	Second	2K-208	Miscellaneous	Brown baseboard mastic	throughout	30	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	395	6	Second	2K-208	Miscellaneous	Red fire stop	Throughout	18	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	396	6	Second	Electric Closet	Miscellaneous	12" x 12" Off-white with Gray specks floor tile	Throughout	40	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	396	6	Second	Electric Closet	Miscellaneous	Yellow floor tile mastic	Throughout	40	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	396	6	Second	Electric Closet	Miscellaneous	Brown baseboard mastic	Throughout	18	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	396	6	Second	Electric Closet	Miscellaneous	Drywall and joint compound	Throughout	180	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	396	6	Second	Electric Closet	Miscellaneous	Red fire stop	Throughout	20	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	396	6	Second	Electric Closet	Surfacing	Gray spray-on fire proofing	Throughout	25	SF	Good		NAD	Medium	n/a	H6-6	n/a	
DC	396	6	Second	Electric Closet	Miscellaneous	Gray duct seam sealant on metal	Throughout	5	SF	Good		NAD	Medium	n/a	H6-6	n/a	
DC	397	6	Second	2K-212	Miscellaneous	2' x 4' Textured Ceiling tile	throughout	120	SF	Good		NAD	Medium	n/a	H6-6	n/a	
DC	397	6	Second	2K-212	Miscellaneous	Drywall and joint compound	Throughout	440	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	397	6	Second	2K-212	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	60	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	397	6	Second	2K-212	Miscellaneous	Tan baseboard mastic	Throughout	44	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	397	6	Second	2K-212	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	120	SF	Good		5%-10% Chrysotile	Low	O & M	H6-6	01	
DC	397	6	Second	2K-212	Miscellaneous	Black floor tile mastic	Throughout	120	SF	Good		4%-5% Chrysotile	Low	O & M	H6-6	02	
DC	398	6	Second	2K-213	Miscellaneous	Drywall and joint compound	Throughout	624	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	398	6	Second	2K-213	Miscellaneous	White duct seam sealant on foil	Throughout	35	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	398	6	Second	2K-213	Miscellaneous	Gray duct seam sealant on metal	Throughout	35	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	398	6	Second	2K-213	Surfacing	Gray spray-on fire proofing	Throughout	75	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	399	6	Second	2K-214	Miscellaneous	Drywall and joint compound	Throughout	670	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	399	6	Second	2K-214	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	240	SF	Good		NAD	Medium	n/a	H6-6	n/a	
DC	399	6	Second	2K-214	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	150	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	399	6	Second	2K-214	Miscellaneous	Gray duct seam sealant on metal	Throughout above drop ceiling	120	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	399	6	Second	2K-214	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	60	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	399	6	Second	2K-214	Miscellaneous	12" x 12" Green mottle floor tile	Throughout	240	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	399	6	Second	2K-214	Miscellaneous	Yellow floor tile mastic	Throughout	240	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	400	6	Second	2K-213A	Miscellaneous	Yellow ceramic tile mastic	Throughout	600	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	400	6	Second	2K-213A	Miscellaneous	Drywall and joint compound	Throughout	600	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	401	6	Second	2K-210A	Miscellaneous	2' x 2' Textured Ceiling tile	Throughout	72	SF	Good		NAD	Medium	n/a	H6-6	n/a	
DC	401	6	Second	2K-210A	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	throughout	72	SF	Good		5%-10% Chrysotile	High	O & M	H6-6	01	
DC	401	6	Second	2K-210A	Miscellaneous	Black floor tile mastic	Throughout	72	SF	Good		4%-5% Chrysotile	Low	O & M	H6-6	02	
DC	401	6	Second	2K-210A	Miscellaneous	Brown baseboard mastic	Throughout	36	LF	Good		NAD	Low	n/a	H6-6	n/a	

Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	401	6	Second	2K-210A	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	72	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	401	6	Second	2K-210A	Miscellaneous	Drywall and joint compound	Throughout	360	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	402	6	Second	Corridor	Miscellaneous	Drywall and joint compound	Throughout walls	1360	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	402	6	Second	Corridor	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	544	SF	Good		5%-10% Chrysotile	Low	O & M	H6-6	01	
DC	402	6	Second	Corridor	Miscellaneous	Black floor tile mastic	Throughout	544	SF	Good		4%-5% Chrysotile	Low	O & M	H6-6	02	
DC	402	6	Second	Corridor	Miscellaneous	2' x 2' Gouged and dot ceiling tile	throughout	544	SF	Good		NAD	Medium	n/a	H6-6	n/a	
DC	402	6	Second	Corridor	Miscellaneous	Fire door	East Wall	2 @ 4' x 7'	Door	Good	Labeled/Wood	Assumed ACM	High	O & M	H6-6	N/A	
DC	402	6	Second	Corridor	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	500	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	402	6	Second	Corridor	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	500	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	403	6	Second	FWE West Corridor	Miscellaneous	12" x 12" Blue mottle floor tile	Throughout	1900	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	403	6	Second	FWE West Corridor	Miscellaneous	Yellow floor tile mastic	Throughout	1900	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	403	6	Second	FWE West Corridor	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	1900	SF	Good		NAD	Medium	n/a	H6-6	n/a	
DC	403	6	Second	FWE West Corridor	Miscellaneous	Tan baseboard mastic	All walls	468	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	403	6	Second	FWE West Corridor	Miscellaneous	Drywall and joint compound	Throughout walls	4680	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	403	6	Second	FWE West Corridor	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	2400	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	403	6	Second	FWE West Corridor	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	950	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	403	6	Second	FWE West Corridor	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	40	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	404	6	Second	FWE East Corridor	Miscellaneous	12" x 12" Blue mottle floor tile	Throughout	2300	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	404	6	Second	FWE East Corridor	Miscellaneous	Yellow floor tile mastic	Throughout	2300	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	404	6	Second	FWE East Corridor	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	2300	SF	Good		NAD	Medium	n/a	H6-6	n/a	
DC	404	6	Second	FWE East Corridor	Miscellaneous	Tan baseboard mastic	All walls	588	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	404	6	Second	FWE East Corridor	Miscellaneous	Drywall and joint compound	Throughout walls	5850	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	404	6	Second	FWE East Corridor	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	2600	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	404	6	Second	FWE East Corridor	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	80	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	404	6	Second	FWE East Corridor	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	1100	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	405	6	Second	FWW East Corridor	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	throughout	1900	SF	Good		5%-10% Chrysotile	Low	O & M	H6-6	01	
DC	405	6	Second	FWW East Corridor	Miscellaneous	Black floor tile mastic	Throughout	1900	SF	Good		4%-5% Chrysotile	Low	O & M	H6-6	02	

**Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6**

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	405	6	Second	FWW East Corridor	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	1900	SF	Good		NAD	Medium	n/a	H6-6	n/a	
DC	405	6	Second	FWW East Corridor	Miscellaneous	Tan baseboard mastic	All walls	468	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	405	6	Second	FWW East Corridor	Miscellaneous	Drywall and joint compound	Throughout walls	4680	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	405	6	Second	FWW East Corridor	Miscellaneous	Fire door	East Wall and Center	4 @ 4' x 7'	Door	Good	Labeled/Wood	Assumed ACM	High	O & M	H6-6	N/A	
DC	405	6	Second	FWW East Corridor	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	3800	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	405	6	Second	FWW East Corridor	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	40	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	405	6	Second	FWW East Corridor	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	950	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	406	6	Second	FWW South Corridor	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	Throughout	675	SF	Good	under wood floor	5%-10% Chrysotile	Low	O & M	H6-6	01	
DC	406	6	Second	FWW South Corridor	Miscellaneous	Black floor tile mastic	Throughout	675	SF	Good		4%-5% Chrysotile	Low	O & M	H6-6	02	
DC	406	6	Second	FWW South Corridor	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	675	SF	Good		NAD	Medium	n/a	H6-6	n/a	
DC	406	6	Second	FWW South Corridor	Miscellaneous	Tan baseboard mastic	All walls	168	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	406	6	Second	FWW South Corridor	Miscellaneous	Drywall and joint compound	Throughout walls	1680	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	406	6	Second	FWW South Corridor	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	150	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	406	6	Second	FWW South Corridor	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	700	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	406	6	Second	FWW South Corridor	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	240	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	407	6	Second	FWW West Corridor	Miscellaneous	12" x 12" Tan with Brown and White specks floor tile	throughout	1900	SF	Good		5%-10% Chrysotile	Low	O & M	H6-6	01	
DC	407	6	Second	FWW West Corridor	Miscellaneous	Black floor tile mastic	Throughout	1900	SF	Good		4%-5% Chrysotile	Low	O & M	H6-6	02	
DC	407	6	Second	FWW West Corridor	Miscellaneous	2' x 2' Gouged and dot ceiling tile	Throughout	1900	SF	Good		NAD	Medium	n/a	H6-6	n/a	
DC	407	6	Second	FWW West Corridor	Miscellaneous	Tan baseboard mastic	All walls	468	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	407	6	Second	FWW West Corridor	Miscellaneous	Drywall and joint compound	Throughout walls	4680	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	407	6	Second	FWW West Corridor	Miscellaneous	Fire door	East Wall and Center	4 @ 4' x 7'	Door	Good	Labeled/Wood	Assumed ACM	High	O & M	H6-6	N/A	
DC	407	6	Second	FWW West Corridor	Miscellaneous	White duct seam sealant on foil	Throughout above drop ceiling	3800	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	407	6	Second	FWW West Corridor	Miscellaneous	White pipe seam sealant on paper	Throughout above drop ceiling	40	LF	Good		NAD	Low	n/a	H6-6	n/a	
DC	407	6	Second	FWW West Corridor	Surfacing	Gray spray-on fire proofing	Throughout above drop ceiling	950	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	408	6	Second	Stair 19 Roof	Miscellaneous	Drywall and joint compound	Throughout walls	800	SF	Good		NAD	High	n/a	H6-6	n/a	
DC	408	6	Second	Stair 19 Roof	Surfacing	Gray spray-on fire proofing	At ceiling Perimeter	100	SF	Good		NAD	Low	n/a	H6-6	n/a	
DC	408	6	Second	Stair 19 Roof	Miscellaneous	Fire door	West Wall	1 @ 3' x 7'	Door	Good	Labeled/Wood	Assumed ACM	High	O & M	H6-6	N/A	

Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	409	6	Exterior	Exterior	Miscellaneous	White exterior caulk	Throughout	6000	LF	Good		NAD	High	n/a	n/a	n/a	
DC	409	6	Exterior	Exterior	Miscellaneous	Black vapor barrier	Throughout	30000	SF	Good		NAD	Low	n/a	n/a	n/a	
DC	409	6	Exterior	Exterior	Miscellaneous	Drywall and joint compound textured coating	Throughout	12000	SF	Good		NAD	Low	n/a	n/a	n/a	
DC	409	6	Exterior	Exterior	Miscellaneous	Built-up roofing	Throughout	45,000	SF	Good		Assumed ACM	High	O & M	n/a	N/A	
DC	410	6	First	Garage	Miscellaneous	White pipe seam sealant on paper	Throughout	400	LF	Good		NAD	Low	n/a	H6-7	n/a	
DC	410	6	First	Garage	Surfacing	Gray spray-on fire proofing	Throughout	1400	SF	Good		NAD	Low	n/a	H6-7	n/a	
DC	410	6	First	Garage	Miscellaneous	Gray duct seam sealant on metal	Throughout	300	SF	Good		NAD	Low	n/a	H6-7	n/a	
DC	410	6	First	Garage	Miscellaneous	White exterior caulk	Throughout	1500	LF	Good		NAD	High	n/a	H6-7	n/a	
DC	411	6	First	Stair 18	Miscellaneous	Tan baseboard mastic	throughout	15	LF	Good		NAD	Low	n/a	H6-7	n/a	
DC	411	6	First	Stair 18	Miscellaneous	Fire door	East Wall	1 @ 4' x 7'	Door	Good	Labeled/Wood	Assumed ACM	High	O & M	H6-7	N/A	
DC	411A	6	First	Garage Storage							Inaccessible			n/a	H6-7	n/a	
DC	411	6	First	Stair 18	Miscellaneous	Drywall and joint compound	Throughout	150	SF	Good		NAD	High	n/a	H6-7	n/a	
DC	413	6	First	Stair 17	Miscellaneous	Tan baseboard mastic	throughout	15	LF	Good		NAD	Low	n/a	H6-7	n/a	
DC	413	6	First	Stair 17	Miscellaneous	Fire door	East Wall	1 @ 4' x 7'	Door	Good	Labeled/Wood	Assumed ACM	High	O & M	H6-7	N/A	
DC	413	6	First	Stair 17	Miscellaneous	Drywall and joint compound	Throughout	150	SF	Good		NAD	High	n/a	H6-7	n/a	
DC	416	6	First	Stair 16	Miscellaneous	Fire door	West Wall	1 @ 4' x 7'	Door	Good	Labeled/Wood	Assumed ACM	High	O & M	H6-7	N/A	
DC	417	6	First	Stair 15	Miscellaneous	Red fire stop	Throughout	4	SF	Good		NAD	Medium	n/a	H6-7	n/a	
DC	417	6	First	Stair 15	Miscellaneous	Tan baseboard mastic	Throughout	25	LF	Good		NAD	Low	n/a	H6-7	n/a	
DC	417	6	First	Stair 15	Miscellaneous	Drywall and joint compound	Throughout	500	SF	Good		NAD	High	n/a	H6-7	n/a	
DC	417	6	First	Stair 15	Miscellaneous	Fire door	West Wall	1 @ 4' x 7'	Door	Good	Labeled/Wood	Assumed ACM	High	O & M	H6-7	N/A	
DC	418	6	Second	Garage	Surfacing	Gray spray-on fire proofing	Throughout	5500	SF	Good		NAD	Low	n/a	H6-8	n/a	
DC	418	6	Second	Garage	Miscellaneous	Drywall and joint compound	Throughout	5500	SF	Good		NAD	High	n/a	H6-8	n/a	
DC	418	6	Second	Garage	Miscellaneous	Drywall and joint compound textured coating	Throughout	5500	SF	Good		NAD	Low	n/a	H6-8	n/a	
DC	418A	6	Second	Garage Storage							Inaccessible			n/a	H6-8	n/a	
DC	418	6	Second	Garage	Miscellaneous	White exterior caulk	Throughout	1500	LF	Good		NAD	High	n/a	H6-8	n/a	
DC	419	6	Second	Garage Storage	Miscellaneous	Red fire stop	Throughout	3	SF	Good		NAD	Medium	n/a	H6-8	n/a	
DC	419	6	Second	Garage Storage	Miscellaneous	Gray duct seam sealant on metal	Throughout	5	SF	Good		NAD	Medium	n/a	H6-8	n/a	
DC	420	6	Second	Stair 18	Miscellaneous	Tan baseboard mastic	throughout	15	LF	Good		NAD	Low	n/a	H6-8	n/a	
DC	420	6	Second	Stair 18	Miscellaneous	Fire door	East Wall	1 @ 4' x 7'	Door	Good	Labeled/Wood	Assumed ACM	High	O & M	H6-8	N/A	
DC	420	6	Second	Stair 18	Miscellaneous	Drywall and joint compound	Throughout	150	SF	Good		NAD	High	n/a	H6-8	n/a	
DC	422	6	Second	Stair 17	Miscellaneous	Drywall and joint compound	Throughout	300	SF	Good		NAD	High	n/a	H6-8	n/a	
DC	422	6	Second	Stair 17	Miscellaneous	Tan baseboard mastic	Throughout	15	LF	Good		NAD	Low	n/a	H6-8	n/a	
DC	422	6	Second	Stair 17	Miscellaneous	Fire door	East Wall	1 @ 4' x 7'	Door	Good	Labeled/Wood	Assumed ACM	High	O & M	H6-8	N/A	
DC	423	6	Second	Stair 16	Miscellaneous	Tan baseboard mastic	Throughout	15	LF	Good		NAD	Low	n/a	H6-8	n/a	
DC	423	6	Second	Stair 16	Miscellaneous	Drywall and joint compound	Throughout	300	SF	Good		NAD	High	n/a	H6-8	n/a	
DC	423	6	Second	Stair 16	Miscellaneous	Fire door	West Wall	1 @ 4' x 7'	Door	Good	Labeled/Wood	Assumed ACM	High	O & M	H6-8	N/A	

Asbestos Inventory Table
Veterans Administration Hospital
Washington, DC
Building 6

Campus/Site	Area Designation	Building Number	Floor	Room Number	Category (AHERA Class)	Material Type	Location	Quantity	Unit of Measure	Condition	Comments	Asbestos Content	Access	Response Action	Drawing Number	Photo Number	VA Comments
DC	424	6	Second	Stair 15	Miscellaneous	Fire door	North and West walls	2 @ 4' x 7'	Door	Good	Labeled/Wood	Assumed ACM	High	O & M	H6-8	N/A	
DC	424	6	Second	Stair 15	Miscellaneous	Drywall and joint compound	Throughout	500	SF	Good		NAD	High	n/a	H6-8	n/a	
DC	424	6	Second	Stair 15	Miscellaneous	Tan baseboard mastic	Throughout	30	LF	Good		NAD	Low	n/a	H6-8	n/a	
DC	425	6	Third	Garage	Miscellaneous	White exterior caulk	Throughout	1500	LF	Good		NAD	High	n/a	H6-9	n/a	
DC	425	6	Third	Garage	Surfacing	Gray spray-on fire proofing	Throughout	5500	SF	Good		NAD	Low	n/a	H6-9	n/a	
DC	425	6	Third	Garage	Miscellaneous	Drywall and joint compound	Throughout	5500	SF	Damaged		NAD	Medium	n/a	H6-9	n/a	
DC	425	6	Third	Garage	Miscellaneous	Drywall and joint compound textured coating	Throughout	5500	SF	Damaged		NAD	Medium	n/a	H6-9	n/a	
DC	426	6	Third	Stair 18	Miscellaneous	Tan baseboard mastic	throughout	15	LF	Good		NAD	Low	n/a	H6-9	n/a	
DC	426	6	Third	Stair 18	Miscellaneous	Fire door	East Wall	1 @ 4' x 7'	Door	Good	Labeled/Wood	Assumed ACM	High	O & M	H6-9	N/A	
DC	426	6	Third	Stair 18	Miscellaneous	Drywall and joint compound	Throughout	150	SF	Good		NAD	High	n/a	H6-9	n/a	
DC	428	6	Third	Stair 17	Miscellaneous	Drywall and joint compound	Throughout	300	SF	Good		NAD	High	n/a	H6-9	n/a	
DC	428	6	Third	Stair 17	Miscellaneous	Tan baseboard mastic	Throughout	15	LF	Good		NAD	Low	n/a	H6-9	n/a	
DC	428	6	Third	Stair 17	Miscellaneous	Fire door	East Wall	1 @ 4' x 7'	Door	Good	Labeled/Wood	Assumed ACM	High	O & M	H6-9	N/A	
DC	429	6	Third	Stair 16	Miscellaneous	Tan baseboard mastic	Throughout	15	LF	Good		NAD	Low	n/a	H6-9	n/a	
DC	429	6	Third	Stair 16	Miscellaneous	Drywall and joint compound	Throughout	300	SF	Good		NAD	High	n/a	H6-9	n/a	
DC	429	6	Third	Stair 16	Miscellaneous	Fire door	West Wall	1 @ 4' x 7'	Door	Good	Labeled/Wood	Assumed ACM	High	O & M	H6-9	N/A	
DC	430	6	Third	Stair 15	Miscellaneous	Red fire stop	Throughout	4	SF	Good		NAD	Medium	n/a	H6-9	n/a	
DC	430	6	Third	Stair 15	Miscellaneous	Tan baseboard mastic	Throughout	25	LF	Good		NAD	Low	n/a	H6-9	n/a	
DC	430	6	Third	Stair 15	Miscellaneous	Drywall and joint compound	Throughout	500	SF	Good		NAD	High	n/a	H6-9	n/a	
DC	430	6	Third	Stair 15	Miscellaneous	Fire door	West Wall	1 @ 4' x 7'	Door	Good	Labeled/Wood	Assumed ACM	High	O & M	H6-9	N/A	
DC	431	6	Third	Vestibule	Miscellaneous	Drywall and joint compound	Throughout	1300	SF	Good		NAD	High	n/a	H6-9	n/a	