

Veterans Affairs Medical Center

Milwaukee, Wisconsin

May 8-11, 2017

Location			New Panel ID	Panel ID	Inspections/Tests			
Building	Floor	Room			Infrared Scan	Tighten	Contact Resistance	Operate Breakers
111	10th Floor	10120-EC	EUL-CR-101-1	EUL-1-10A	✓	✓	✓	✓
111	10th Floor	10120-EC	EUL-CR-101-1A	-	✓	✓	✓	✓
111	10th Floor	10120-EC	LL-101-1	LL-1-10A	✓	✓	✓	✓
111	10th Floor	10120-EC	LL-101-1A	-	✓	✓	✓	✓
111	10th Floor	10120-EC	UL-101-1	UL-1-10A	✓	✓	✓	✓
111	10th Floor	10151-EC	UL-101-2	UL-2-10A	✓	✓	✓	✓
111	10th Floor	10151-EC	UL-101-2A	SUB PANEL	✓	✓	✓	✓
111	10th Floor	10220-EC	LL-102-1	LL-3-10A	✓	✓	✓	✓
111	10th Floor	10220-EC	UL-102-1	UL-3-10A	✓	✓	✓	✓
111	10th Floor	10226-EC	EUL-CR-102-1	EUL-3-10A	✓	✓	✓	✓
111	10th Floor	10255-EC	LH-101-1		✓	✓	✓	✓
111	10th Floor	10300-EC	EUL-Q-103-1	EUL-7-10B	✓	✓	✓	✓
111	10th Floor	10510-EC	UL-105-1	-	✓	✓	✓	✓
111	10th Floor	10515-EC	LL-105-1	LL-1-10C	✓	✓	✓	✓
111	10th Floor	10515-EC	UL-105-2	UL-1-10C Sect A	✓	✓	✓	✓
111	10th Floor	10515-EC	UL-105-3	UL-1-10C Sect B	✓	✓	✓	✓
111	10th Floor	10523-EC	ELH-CR-105-1	LH-2-10C	✓	✓	✓	✓
111	10th Floor	10523-EC	EUL-CR-105-1	UL-2-10C	✓	✓	✓	✓
111	10th Floor	10547-EC	UL-105-4	-	✓	✓	✓	✓
111	10th Floor	10620-EC	LL-106-1	LL-3-10C	✓	✓	✓	✓
111	10th Floor	10620-EC	UL-106-1	UL-3-10C	✓	✓	✓	✓
111	10th Floor	10627-EC	EUL-CR-106-2	EUL-3-10C	✓	✓	✓	✓
111	10th Floor	10655-EC	LH-105-1	-	✓	✓	✓	✓

Number of Panels 23

Location				New Panel ID	Panel ID		Inspections/Tests			
Building	Floor	Room					Infrared Scan	Tighten	Contact Resistance	Operate Breakers
111	9th Floor	9611-EC		UL-96-1	UL-96-1		✓	✓	✓	✓
111	9th Floor	9617-EC		EUL-CR-96-1	EUL-CR-96-1		✓	✓	✓	✓
111	9th Floor	9632-EC		EUL-CR-96-2	EUL-CR-96-2		✓	✓	✓	✓
111	9th Floor	9637-EC		LH-95-1			✓	✓	✓	✓

Number of Panels 30

Veterans Affairs Medical Center

Milwaukee, Wisconsin

May 8-11, 2017

Location			New Panel ID	Panel ID	Inspections/Tests			
Building	Floor	Room			Infrared Scan	Tighten	Contact Resistance	Operate Breakers
111	9th Floor	9118-EC	EUL-CR-91-1	EUL-1-9A	✓	✓	✓	✓
111	9th Floor	9118-EC	LL-91-1	LL-1L-9A	✓	✓	✓	✓
111	9th Floor	9118-EC	UL-91-1	UL-1-9A	✓	✓	✓	✓
111	9th Floor	9126-EC	ELH-LS-91-1	ELH-LS-91-1	✓	✓	✓	✓
111	9th Floor	9126-EC	ELL-LS-91-1	ELL-LS-91-1	✓	✓	✓	✓
111	9th Floor	9126-EC	EUL-CR-91-2	SUB PANEL	✓	✓	✓	✓
111	9th Floor	9151-EC	ELH-CR-91-1	ELH-2-9A	✓	✓	✓	✓
111	9th Floor	9153-EC	UL-91-2	UL-2-9A	✓	✓	✓	✓
111	9th Floor	9218-EC	LL-92-1	LL-3-9A	✓	✓	✓	✓
111	9th Floor	9218-EC	UL-92-1	UL-3-9A	✓	✓	✓	✓
111	9th Floor	9226-EC	EUL-CR-92-1	EUUL-3-9A	✓	✓	✓	✓
111	9th Floor	9226-EC	EUL-CR-92-2		✓	✓	✓	✓
111	9th Floor	9253-EC	LH-91-1	LH-2-9A	✓	✓	✓	✓
111	9th Floor	9303-EC	UL-93-1	UL-1-9B	✓	✓	✓	✓
111	9th Floor	9406-EC	ELH-CR-94-1	ELH-1-9B	✓	✓	✓	✓
111	9th Floor	9406-EC	LH-94-1	LJ-1-PB	✓	✓	✓	✓
111	9th Floor	9407-EC	UL-94-1	-	✓	✓	✓	✓
111	9th Floor	9407-EC	UL-94-2	-	✓	✓	✓	✓
111	9th Floor	9515-EC	EUL-CR-95-1		✓	✓	✓	✓
111	9th Floor	9515-EC	LL-95-1		✓	✓	✓	✓
111	9th Floor	9515-EC	UL-95-1		✓	✓	✓	✓
111	9th Floor	9531-AEC	ELH-LS-95-1		✓	✓	✓	✓
111	9th Floor	9531-AEC	ELL-LS-95-1		✓	✓	✓	✓
111	9th Floor	9531-AEC	EUL-CR-95-2		✓	✓	✓	✓
111	9th Floor	9545-EC	UL-95-2	UL-95--2	✓	✓	✓	✓
111	9th Floor	9611-EC	LL-96-1	LL-96-1	✓	✓	✓	✓