

Salient Characteristics

659-18-3-6049-0496

Repair water Leak:

Replace the in ground 4" inch water main behind building five. Re-route line around the existing loading dock and make a underground wall penetration into the mechanical room and connect withtheexisting water line. A hot tap is the perffered method of this repar due to the chiller plant being on the same line.

Description of Need: Four inch water line with inground valve.

Must meet the following specs:

Hot tap method of repair

New water line must be of same type currently in use

New line must meet all specfications and standards of potable water lines

A wall penetrations must be sealed to specs