





#	POINT TABLE	
	NORTHING	EASTING
1	1831552.6499	225000.6475
2	1831379.6839	222530.3969
3	1831334.7120	222553.7664
4	1831289.7401	222597.1360
5	1831256.3706	222552.1641
6	1831301.3425	222518.7945
7	1831346.3144	222485.4250

NOTE: ALL LAWSNS & IRRIGATION LINES WITHIN THE BURIAL SECTIONS SHALL BE INSTALLED AND ACCEPTED PRIOR TO MONUMENT-BASE PLACEMENT; ALL LAWSNS & IRRIGATION LINES DAMAGED DURING INSTALLATION SHALL BE REPAIRED AT CONTRACTOR'S EXPENSE

NOTE:
AT THE CONTRACTOR'S
OPTION, MONUMENT
MARKERS MAY BE
PROVIDED AS PRECAST
UNITS. PROVIDE SHOP
DRAWINGS AND METHOD
OF INSTALLATION FOR R.E.
APPROVAL.

[illegible]