

Client Name: HDH Technical, Inc.

PLM Bulk Asbestos Report

VAMC - Boiler #3 Burner Repl.; Clarksburg, WV

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
TI-6.2	112081104-12	No	NAD
Location: Tank Insulation - DA Tank			(by CVES) by William M. Dunstan on 08/02/12
Analyst Description: Lt. Gray, Heterogeneous, Fibrous, Bulk Material			
Asbestos Types:			
Other Material: Fibrous glass 40 %, Non-fibrous 60 %			
TI-6.3	112081104-13	No	NAD
Location: Tank Insulation - DA Tank			(by CVES) by William M. Dunstan on 08/02/12
Analyst Description: Lt. Gray, Heterogeneous, Fibrous, Bulk Material			
Asbestos Types:			
Other Material: Fibrous glass 40 %, Non-fibrous 60 %			
ES-7.1	112081104-14	No	NAD
Location: End Sealer On FG @ DA Tank			(by CVES) by William M. Dunstan on 08/02/12
Analyst Description: White, Heterogeneous, Non-Fibrous, Bulk Material			
Asbestos Types:			
Other Material: Non-fibrous 100 %			
ES-7.2	112081104-15	No	NAD
Location: End Sealer On FG @ DA Tank			(by CVES) by William M. Dunstan on 08/02/12
Analyst Description: White, Heterogeneous, Non-Fibrous, Bulk Material			
Asbestos Types:			
Other Material: Non-fibrous 100 %			

Reporting Notes:

Analyzed by: William M. Dunstan

Date

8/2/12

*NAD = no asbestos detected, Detection Limit <1%, Reporting Limits: CVES = 1%, 400 Pt Ct = 0.25%, 1000 Pt Ct = 0.1%; "Present" or NVA = "No Visible Asbestos" are observations made during a qualitative analysis; NA = not analyzed; NA/PS = not analyzed / positive stop; PLM Bulk Asbestos Analysis by EPA 600/M4-82-020 per 40 CFR 763 (NVLAP Lab Code 101904-0) and ELAP PLM Analysis Protocol 198.1 for New York friable samples (198.6 for NOB samples)(NYSDOH ELAP Lab # 10984); CA ELAP Lab # 2508; Note: PLM is not consistently reliable in detecting asbestos in floor coverings and similar NOB materials. NAD or Trace results by PLM are inconclusive, TEM is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos-containing in New York State (also see EPA Advisory for floor tile, FR 59, 146, 38970, 8/1/94). NIST Accreditation requirements mandate that this report must not be reproduced except in full without the approval of the laboratory. This PLM report relates ONLY to the items tested.

Reviewed By: _____