

**Louis A. Johnson VA Medical Center  
Clarksburg, West Virginia**



**NO SUSPECT ACM WAS IDENTIFIED PRESENT ON THE BURNER ITSELF OR ON THE EQUIPEMENT TO BE DISTURBED ASSOCIATED WITH BOILER #3. THE WINDOW GLAZING ON THE CONTROL ROOM DOORS WAS THE ONLY SUSPECT MATERIAL SAMPLED IDENTIFIED TO BE ASBESTOS CONTAINING BY THE LABORATORY. NO LEAD BASED PAINT WAS IDENTIFIED IN ANY OF THE AREAS OR ANY EQUIPMENT DETERMINED TO BE DISTURBED.**