




ALL DEVICE COVERS, SCREWS, AND CONNECTIONS SHALL BE TAMPER - RESISTANT



ALL	(2) OXYGEN (2) MEDICAL AIR (2) VACUUM (8) ELECTRICAL - NORMAL
-----	--



UMA)



CONCLUSION