

Reading No	Time	Duration	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Res	Escale 1	Escale CT	Results	Depth Index	PbC	PbC Error	PbL	PbL Error	PbK	PbK Error
1159	10/19/2007 8:17	41.93									427.6	4.56	2.32			10.93	0	1.45	0	0	0
1160	10/19/2007 8:18	1.03			CALIBRATE		WHITE							Negative	1 < LOD		0.03 < LOD		0.03 < LOD		3.2
1161	10/19/2007 8:19	1.03			CALIBRATE		GOLD							Negative	1 < LOD		0.6 < LOD		0.6 < LOD		4.5
1162	10/19/2007 8:19	1.54			CALIBRATE		GOLD							Negative	1.15	0.7	0.3	0.7	0.3 < LOD		2.4
1163	10/19/2007 8:19	16.54			CALIBRATE		RED							Positive	1.14	1.1	0.1	1.1	0.1	0.5	0.3
1164	10/19/2007 8:51	3.6	WALL	PLASTER	C	POOR	WHITE	BLDG 222 NE BLDG	1ST	NORTH ROOM				Negative	3.32 < LOD		1.23 < LOD		0.11 < LOD		1.23
1165	10/19/2007 8:52	2.57	WALL	PLASTER	C	POOR	GRAY	BLDG 222 NE BLDG	1ST	NORTH ROOM				Negative	1.95 < LOD		0.15 < LOD		0.15 < LOD		2.21
1166	10/19/2007 8:52	3.59	WALL	PLASTER	B	POOR	GRAY	BLDG 222 NE BLDG	1ST	NORTH ROOM				Negative	1.45	0.08	0.04	0.08	0.04 < LOD		1.25
1167	10/19/2007 8:52	4.61	WALL	PLASTER	B	POOR	WHITE	BLDG 222 NE BLDG	1ST	NORTH ROOM				Negative	4.44 < LOD		1.07 < LOD		0.14 < LOD		1.07
1168	10/19/2007 8:53	1.03	WINDOW CASING	WOOD	B	POOR	GRAY	BLDG 222 NE BLDG	1ST	NORTH ROOM				Positive	3.68 < LOD		4.2 < LOD		4.2 < LOD		6.6
1169	10/19/2007 8:53	2.05	WINDOW	WOOD	B	POOR	GRAY	BLDG 222 NE BLDG	1ST	NORTH ROOM				Positive	3.86	2	0.9	2	0.9	2.5	1.6
1170	10/19/2007 8:54	1.03	WINDOW	WOOD	D	POOR	WHITE	BLDG 222 NE BLDG	1ST	NORTH ROOM				Positive	1.92	2.8	1.5	2.8	1.5 < LOD		6.75
1171	10/19/2007 8:54	1.03	WALL	PLASTER	D	POOR	WHITE	BLDG 222 NE BLDG	1ST	NORTH ROOM				Negative	6.2 < LOD		0.88 < LOD		0.88 < LOD		4.67
1172	10/19/2007 8:55	3.58	WALL	PLASTER	D	POOR	GRAY	BLDG 222 NE BLDG	1ST	NORTH ROOM				Negative	1.41	0.08	0.04	0.08	0.04 < LOD		1.25
1173	10/19/2007 8:55	0.51	WALL	PLASTER	A	POOR	GRAY	BLDG 222 NE BLDG	1ST	NORTH ROOM				Null	1.08 < LOD		0.24 < LOD		0.24 < LOD		7.84
1174	10/19/2007 8:55	1.03	WALL	PLASTER	A	POOR	GRAY	BLDG 222 NE BLDG	1ST	NORTH ROOM				Null	1.65 < LOD		0.29 < LOD		0.29 < LOD		4.96
1175	10/19/2007 8:55	3.09	WALL	PLASTER	A	POOR	GRAY	BLDG 222 NE BLDG	1ST	NORTH ROOM				Negative	1.55 < LOD		0.11 < LOD		0.11 < LOD		1.99
1176	10/19/2007 8:56	3.58	WALL	PLASTER	A	POOR	WHITE	BLDG 222 NE BLDG	1ST	NORTH ROOM				Negative	5.07 < LOD		1.27 < LOD		0.19 < LOD		1.27
1177	10/19/2007 8:56	3.59	DOOR	WOOD	A	POOR	GRAY	BLDG 222 NE BLDG	1ST	NORTH ROOM				Positive	3.73	2.1	0.8	0.9	0.3	2.1	0.8
1178	10/19/2007 8:56	1.54	DOOR CASING	WOOD	A	POOR	GRAY	BLDG 222 NE BLDG	1ST	NORTH ROOM				Positive	5.58	4	2.3	1.9	1.2	4	2.3
1179	10/19/2007 8:58	3.59	WALL	WOOD	B	POOR	GRAY	BLDG 222 NE BLDG	1ST	NORTH OVEN ROOM				Negative	1.65	0.08	0.04	0.08	0.04 < LOD		1.25
1180	10/19/2007 8:58	1.03	WALL	WOOD	A	POOR	GRAY	BLDG 222 NE BLDG	1ST	NORTH OVEN ROOM				Negative	1.05 < LOD		0.16 < LOD		0.16 < LOD		5.08
1181	10/19/2007 8:58	3.6	WINDOW	WOOD	A	POOR	GRAY	BLDG 222 NE BLDG	1ST	NORTH OVEN ROOM				Negative	2.09 < LOD		0.17 < LOD		0.17 < LOD		0.6
1182	10/19/2007 8:59	1.03	DOOR	METAL	D	FAIR	GRAY	BLDG 222 NE BLDG	1ST	NORTH OVEN ROOM				Negative	1.05 < LOD		0.22 < LOD		0.22 < LOD		4.68
1183	10/19/2007 8:59	1.03	DOOR CASING	METAL	D	FAIR	GRAY	BLDG 222 NE BLDG	1ST	NORTH OVEN ROOM				Negative	1 < LOD		0.03 < LOD		0.03 < LOD		5.7
1184	10/19/2007 9:01	1.54	DOOR CASING	WOOD	D	POOR	GRAY	BLDG 222 NE BLDG	1ST	NORTH MIDDLE ROOM				Positive	10	4.4	2.4 < LOD		6.9	4.4	2.4
1185	10/19/2007 9:01	1.03	DOOR	WOOD	D	POOR	GRAY	BLDG 222 NE BLDG	1ST	NORTH MIDDLE ROOM				Positive	6.79 < LOD		7.5 < LOD		11.1 < LOD		7.5
1186	10/19/2007 9:03	1.03	WALL	PLASTER	D	POOR	GRAY	BLDG 222 NE BLDG	1ST	NORTH MIDDLE ROOM				Positive	10 < LOD		9 < LOD		13.35 < LOD		9
1187	10/19/2007 9:03	1.54	WALL	PLASTER	D	POOR	WHITE	BLDG 222 NE BLDG	1ST	NORTH MIDDLE ROOM				Positive	8.85	4.9	3.2	5.9	3.7	4.9	3.2
1188	10/19/2007 9:04	6.18	WALL	PLASTER	C	POOR	WHITE	BLDG 222 NE BLDG	1ST	NORTH MIDDLE ROOM				Negative	6.53 < LOD		0.99	0.6	0.2 < LOD		0.99
1189	10/19/2007 9:04	3.59	WALL	PLASTER	C	POOR	GRAY	BLDG 222 NE BLDG	1ST	NORTH MIDDLE ROOM				Negative	2.74 < LOD		1.33	0.25	0.11 < LOD		1.33
1190	10/19/2007 9:04	4.64	WALL	PLASTER	B	POOR	GRAY	BLDG 222 NE BLDG	1ST	NORTH MIDDLE ROOM				Negative	3.93 < LOD		1.11	0.4	0.1 < LOD		1.11
1191	10/19/2007 9:05	9.25	WALL	PLASTER	B	POOR	WHITE	BLDG 222 NE BLDG	1ST	NORTH MIDDLE ROOM				Null	5.81	0.3	0.12	0.3	0.12 < LOD		0.75
1192	10/19/2007 9:05	6.13	WALL	PLASTER	B	POOR	WHITE	BLDG 222 NE BLDG	1ST	NORTH MIDDLE ROOM				Negative	4.86 < LOD		0.96	0.28	0.12 < LOD		0.96
1193	10/19/2007 9:06	4.1	WALL	PLASTER	A	POOR	WHITE	BLDG 222 NE BLDG	1ST	NORTH MIDDLE ROOM				Negative	4.7 < LOD		1.25	0.19	0.12 < LOD		1.25
1194	10/19/2007 9:06	1.03	WALL	PLASTER	A	POOR	GRAY	BLDG 222 NE BLDG	1ST	NORTH MIDDLE ROOM				Negative	2.43 < LOD		0.53 < LOD		0.53 < LOD		4.95
1195	10/19/2007 9:07	3.09	FLOOR	CONCRETE	A	POOR	RED	BLDG 222 NE BLDG	1ST	NORTH MIDDLE ROOM				Negative	1 < LOD		0.05 < LOD		0.05 < LOD		2.09
1196	10/19/2007 9:08	3.59	WALL	PLASTER	A	POOR	WHITE	BLDG 222 NE BLDG	1ST	RESTROOM				Null	6.32	0.6	0.3	0.6	0.3 < LOD		1.35
1197	10/19/2007 9:08	1.03	WALL	PLASTER	A	POOR	WHITE	BLDG 222 NE BLDG	1ST	RESTROOM				Null	3.65 < LOD		0.74 < LOD		0.74 < LOD		5.55
1198	10/19/2007 9:08	3.59	WALL	PLASTER	A	POOR	WHITE	BLDG 222 NE BLDG	1ST	RESTROOM				Negative	7.97 < LOD		1.32	0.7	0.3 < LOD		1.32
1199	10/19/2007 9:09	1.54	WALL	PLASTER	B	POOR	WHITE	BLDG 222 NE BLDG	1ST	RESTROOM				Negative	2.05 < LOD		0.12 < LOD		0.12 < LOD		2.8
1200	10/19/2007 9:10	1.03	WALL	PLASTER	C	POOR	WHITE	BLDG 222 NE BLDG	1ST	RESTROOM				Negative	4.1 < LOD		0.78 < LOD		0.78 < LOD		5.1
1201	10/19/2007 9:10	4.63	WALL	PLASTER	B	POOR	WHITE	BLDG 222 NE BLDG	1ST	RESTROOM				Null	6.26	0.26	0.16	0.26	0.16 < LOD		1.05
1202	10/19/2007 9:11	4.1	WALL	PLASTER	B	POOR	WHITE	BLDG 222 NE BLDG	1ST	RESTROOM				Negative	5.04 < LOD		1.22	0.2	0.13 < LOD		1.22
1203	10/19/2007 9:11	10.8	DOOR	WOOD	B	FAIR	GRAY	BLDG 222 NE BLDG	1ST	RESTROOM				Negative	4.27	0.8	0.2	0.8	0.2	1.2	0.4
1204	10/19/2007 9:11	2.06	DOOR CASING	WOOD	B	FAIR	GRAY	BLDG 222 NE BLDG	1ST	RESTROOM				Positive	7.75	3	1.8	2	1.3	3	1.8
1205	10/19/2007 9:13	1.03	WALL	WOOD	D	POOR	GRAY	BLDG 222 NE BLDG	1ST	LARGE STORAGE AREA				Negative	4.12 < LOD		0.77 < LOD		0.77 < LOD		4.89
1206	10/19/2007 9:13	1.03	WALL	WOOD	C	POOR	GRAY	BLDG 222 NE BLDG	1ST	LARGE STORAGE AREA				Negative	4.96 < LOD		1.02 < LOD		1.02 < LOD		5.18
1207	10/19/2007 9:14	0.52	WALL	WOOD	B	POOR	GRAY	BLDG 222 NE BLDG	1ST	LARGE STORAGE AREA				Positive	3.43 < LOD		16.2 < LOD		7.5 < LOD		16.2
1208	10/19/2007 9:14	2.06	WALL	WOOD	A	POOR	GRAY	BLDG 222 NE BLDG	1ST	LARGE STORAGE AREA				Negative	3.49 < LOD		0.4 < LOD		0.4 < LOD		3.15
1209	10/19/2007 9:15	1.03	WINDOW	WOOD	B	POOR	GRAY	BLDG 222 NE BLDG	1ST	LARGE STORAGE AREA				Positive	7.16 < LOD		7.2 < LOD		6.9 < LOD		7.2
1210	10/19/2007 9:15	1.54	WINDOW CASING	WOOD	B	POOR	GRAY	BLDG 222 NE BLDG	1ST	LARGE STORAGE AREA				Positive	5.91	6.2	2.6	2.4	1.5	6.2	2.6
1211	10/19/2007 9:15	1.03	DOOR	METAL	A	POOR	SILVER	BLDG 222 NE BLDG	1ST	LARGE STORAGE AREA				Negative	2.52 < LOD		0.62 < LOD		0.62 < LOD		3.9
1212	10/19/2007 9:16	1.03	DOOR CASING	METAL	A	POOR	SILVER	BLDG 222 NE BLDG	1ST	LARGE STORAGE AREA				Negative	1.49 < LOD		0.45 < LOD		0.45 < LOD		5.55
1213	10/19/2007 9:17	1.03	WINDOW	WOOD	D	POOR	WHITE	BLDG 222 NE BLDG	1ST	LARGE STORAGE AREA				Positive	3.73 < LOD		6.45 < LOD		2.1 < LOD		6.45

Reading No	Time	Duration	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Res	Escale 1	Escler CT	Results	Depth Index	PbC	PbC Error	PbL	PbL Error	PbK	PbK Error
1214	10/19/2007 9:18	1.02	CEILING	PLASTER	D	POOR	GRAY	BLDG 222 NE BLDG	1ST	LARGE STORAGE AREA				Negative	1.75 < LOD		0.35 < LOD		0.35 < LOD		4.5
1215	10/19/2007 9:19	1.03	CEILING	PLASTER	D	POOR	GRAY	BLDG 222 NE BLDG	1ST	NORTH ROOM				Negative	1.01 < LOD		0.18 < LOD		0.18 < LOD		4.35
1216	10/19/2007 9:20	0.51	CEILING	PLASTER	D	POOR	GRAY	BLDG 222 NE BLDG	1ST	NORTH MIDDLE ROOM				Null	1.25 < LOD		0.35 < LOD		0.35 < LOD		7.17
1217	10/19/2007 9:20	2.6	CEILING	PLASTER	D	POOR	GRAY	BLDG 222 NE BLDG	1ST	NORTH MIDDLE ROOM				Negative	1.83 < LOD		0.18 < LOD		0.18 < LOD		2.25
1218	10/19/2007 9:21	2.05	WALL	CONCRETE	A	POOR	WHITE	BLDG 222 NE BLDG	1ST	BOILER ROOM				Negative	1 < LOD		0.03 < LOD		0.03 < LOD		2.37
1219	10/19/2007 9:22	1.54	WALL	CONCRETE	D	POOR	WHITE	BLDG 222 NE BLDG	1ST	BOILER ROOM				Negative	1.3 < LOD		0.05 < LOD		0.05 < LOD		3.35
1220	10/19/2007 9:22	2.05	WALL	BRICK	D	POOR	WHITE	BLDG 222 NE BLDG	1ST	BOILER ROOM				Negative	4.11 < LOD		0.19 < LOD		0.19 < LOD		2.47
1221	10/19/2007 9:23	0.52	WALL	BRICK	C	POOR	WHITE	BLDG 222 NE BLDG	1ST	BOILER ROOM				Null	1.3 < LOD		0.11 < LOD		0.11 < LOD		7.19
1222	10/19/2007 9:23	1.02	WALL	BRICK	C	POOR	WHITE	BLDG 222 NE BLDG	1ST	BOILER ROOM				Null	1 < LOD		0.04 < LOD		0.04 < LOD		4.56
1223	10/19/2007 9:23	1.53	WALL	BRICK	C	POOR	WHITE	BLDG 222 NE BLDG	1ST	BOILER ROOM				Negative	4.02 < LOD		0.18 < LOD		0.18 < LOD		2.99
1224	10/19/2007 9:23	1.54	DOOR CASING	WOOD	C	POOR	WHITE	BLDG 222 NE BLDG	1ST	BOILER ROOM				Positive	4.29	4	2.3	1.7	1	4	2.3
1225	10/19/2007 9:24	0.51	WALL	CONCRETE	B	POOR	WHITE	BLDG 222 NE BLDG	1ST	BOILER ROOM				Null	1 < LOD		0.06 < LOD		0.06 < LOD		8.27
1226	10/19/2007 9:25	2.05	WALL	CONCRETE	B	POOR	WHITE	BLDG 222 NE BLDG	1ST	BOILER ROOM				Null	5.42 < LOD		0.2 < LOD		0.2 < LOD		2.55
1227	10/19/2007 9:25	1.54	WALL	CONCRETE	B	POOR	WHITE	BLDG 222 NE BLDG	1ST	BOILER ROOM				Negative	1.24 < LOD		0.04 < LOD		0.04 < LOD		3.07
1228	10/19/2007 9:27	1.03	CEILING	WOOD		POOR	WHITE	BLDG 222 NE BLDG	1ST	BOILER ROOM				Positive	1.71	3.2	1.5	3.2	1.5 < LOD		5.85
1229	10/19/2007 9:28	0.53	DOOR	WOOD	A	POOR	GRAY	BLDG 222 NE BLDG	1ST	BOILER ROOM				Positive	1.63	8.1	5.3	8.1	5.3 < LOD		12.15
1230	10/19/2007 9:29	0.51	DOOR CASING	WOOD	A	POOR	GRAY	BLDG 222 NE BLDG	1ST	BOILER ROOM				Positive	1.61 < LOD		5.6 < LOD		5.6 < LOD		13.35
1231	10/19/2007 9:30	0.52	WINDOW	WOOD	D	POOR	GRAY	BLDG 222 NE BLDG	1ST	BOILER ROOM				Positive	1.42	5.8	3.5	5.8	3.5 < LOD		13.2
1232	10/19/2007 9:30	0.52	WINDOW CASING	WOOD	D	POOR	GRAY	BLDG 222 NE BLDG	1ST	BOILER ROOM				Positive	1.31	3.3	2	3.3	2 < LOD		8.25
1233	10/19/2007 9:40	1.03	WINDOW CASING	WOOD	D	POOR	GRAY	BLDG 222 EAST BLDG	BASEMENT	LARGE STORAGE AREA				Positive	3.03	8.7	5.6 < LOD		14.55	8.7	5.6
1234	10/19/2007 9:40	0.51	WINDOW	WOOD	D	POOR	GRAY	BLDG 222 EAST BLDG	BASEMENT	LARGE STORAGE AREA				Positive	2.48 < LOD		7.8 < LOD		7.8 < LOD		11.1
1235	10/19/2007 9:41	1.54	WALL	PLASTER	C	FAIR	WHITE	BLDG 222 EAST BLDG	BASEMENT	LARGE STORAGE AREA				Negative	1 < LOD		0.03 < LOD		0.03 < LOD		2.96
1236	10/19/2007 9:41	3.59	DOOR	WOOD	C	FAIR	WHITE	BLDG 222 EAST BLDG	BASEMENT	LARGE STORAGE AREA				Positive	4.89	1.7	0.7	1.7	0.7	1.5	0.7
1237	10/19/2007 9:42	2.04	WALL	PLASTER	D	FAIR	WHITE	BLDG 222 EAST BLDG	BASEMENT	LARGE STORAGE AREA				Negative	2.7 < LOD		0.06 < LOD		0.06 < LOD		2.73
1238	10/19/2007 9:42	2.05	WALL	CONCRETE	D	POOR	WHITE	BLDG 222 EAST BLDG	BASEMENT	LARGE STORAGE AREA				Negative	3.05 < LOD		0.14 < LOD		0.14 < LOD		2.88
1239	10/19/2007 9:43	1.54	WALL	PLASTER	B	POOR	WHITE	BLDG 222 EAST BLDG	BASEMENT	LARGE STORAGE AREA				Negative	1 < LOD		0.03 < LOD		0.03 < LOD		2.96
1240	10/19/2007 9:43	1.02	RADIATOR	METAL	B	POOR	WHITE	BLDG 222 EAST BLDG	BASEMENT	LARGE STORAGE AREA				Negative	1 < LOD		0.03 < LOD		0.03 < LOD		4.35
1241	10/19/2007 9:43	1.55	COLUMN	CONCRETE	B	POOR	WHITE	BLDG 222 EAST BLDG	BASEMENT	LARGE STORAGE AREA				Negative	1 < LOD		0.03 < LOD		0.03 < LOD		2.9
1242	10/19/2007 9:44	1.03	CEILING	WOOD		POOR	WHITE	BLDG 222 EAST BLDG	BASEMENT	LARGE STORAGE AREA				Negative	6.44 < LOD		0.92 < LOD		0.92 < LOD		2.97
1243	10/19/2007 9:45	1.02	STAIRS	WOOD	B	POOR	GRAY	BLDG 222 EAST BLDG	BASEMENT	LARGE STORAGE AREA				Negative	1 < LOD		0.16 < LOD		0.16 < LOD		3
1244	10/19/2007 9:45	1.03	STAIR RAILING	WOOD	B	POOR	BROWN	BLDG 222 EAST BLDG	BASEMENT	LARGE STORAGE AREA				Negative	1 < LOD		0.04 < LOD		0.04 < LOD		4.93
1245	10/19/2007 9:46	1.03	STAIR CASING	WOOD	B	FAIR	WHITE	BLDG 222 EAST BLDG	BASEMENT	LARGE STORAGE AREA				Negative	3.31 < LOD		0.31 < LOD		0.31 < LOD		2.56
1246	10/19/2007 9:47	0.52	WALL	PLASTER	A	POOR	WHITE	BLDG 222 EAST BLDG	BASEMENT	LARGE STORAGE AREA				Null	1 < LOD		0.05 < LOD		0.05 < LOD		6.81
1247	10/19/2007 9:47	1.54	WALL	PLASTER	A	POOR	WHITE	BLDG 222 EAST BLDG	BASEMENT	LARGE STORAGE AREA				Negative	1 < LOD		0.03 < LOD		0.03 < LOD		2.85
1248	10/19/2007 9:48	1.03	DOOR	WOOD	D	FAIR	GRAY	BLDG 222 EAST BLDG	BASEMENT	SOUTHWEST ROOM				Positive	4.7 < LOD		4.65 < LOD		4.65 < LOD		5.55
1249	10/19/2007 9:48	1.03	DOOR CASING	WOOD	D	FAIR	GRAY	BLDG 222 EAST BLDG	BASEMENT	SOUTHWEST ROOM				Negative	1.09 < LOD		0.28 < LOD		0.28 < LOD		3.12
1250	10/19/2007 9:49	1.03	WALL	WOOD	A	FAIR	BROWN	BLDG 222 EAST BLDG	BASEMENT	SOUTHWEST ROOM				Negative	1 < LOD		0.14 < LOD		0.14 < LOD		2.8
1251	10/19/2007 9:49	1.03	WALL	WOOD	B	FAIR	BROWN	BLDG 222 EAST BLDG	BASEMENT	SOUTHWEST ROOM				Negative	1 < LOD		0.09 < LOD		0.09 < LOD		2.5
1252	10/19/2007 9:49	1.03	WALL	WOOD	C	FAIR	BROWN	BLDG 222 EAST BLDG	BASEMENT	SOUTHWEST ROOM				Negative	1 < LOD		0.11 < LOD		0.11 < LOD		2.78
1253	10/19/2007 9:49	1.02	WALL	WOOD	D	FAIR	BROWN	BLDG 222 EAST BLDG	BASEMENT	SOUTHWEST ROOM				Negative	1.09 < LOD		0.11 < LOD		0.11 < LOD		2.48
1254	10/19/2007 9:50	1.03	CEILING	WOOD	D	FAIR	BROWN	BLDG 222 EAST BLDG	BASEMENT	SOUTHWEST ROOM				Negative	1.21 < LOD		0.15 < LOD		0.15 < LOD		2.39
1255	10/19/2007 9:50	1.03	PIPE	METAL	A	POOR	WHITE	BLDG 222 EAST BLDG	BASEMENT	LARGE STORAGE AREA				Negative	2.1 < LOD		0.17 < LOD		0.17 < LOD		5.4
1256	10/19/2007 9:51	1.04	CEILING BEAM	WOOD		POOR	WHITE	BLDG 222 EAST BLDG	BASEMENT	LARGE STORAGE AREA				Negative	4.04 < LOD		0.49 < LOD		0.49 < LOD		2.87
1257	10/19/2007 9:53	1.03	DOOR	WOOD	B	FAIR	GRAY	BLDG 222 EAST BLDG	BASEMENT	EAST MIDDLE ROOM				Positive	2.77	2.9	1.8	2.9	1.8 < LOD		5.55
1258	10/19/2007 9:53	1.54	DOOR CASING	WOOD	B	FAIR	GRAY	BLDG 222 EAST BLDG	BASEMENT	EAST MIDDLE ROOM				Positive	3.51	2.4	1.1	2.4	1.1 < LOD		2.7
1259	10/19/2007 9:53	1.55	WALL	WOOD	A	FAIR	WHITE	BLDG 222 EAST BLDG	BASEMENT	EAST MIDDLE ROOM				Positive	4.2	2.5	1.3	2.5	1.3 < LOD		2.7
1260	10/19/2007 9:54	2.06	WALL	WOOD	C	FAIR	WHITE	BLDG 222 EAST BLDG	BASEMENT	EAST MIDDLE ROOM				Positive	2.89	1.7	0.7	1.7	0.7 < LOD		2.55
1261	10/19/2007 9:54	1.54	WALL	WOOD	B	FAIR	WHITE	BLDG 222 EAST BLDG	BASEMENT	EAST MIDDLE ROOM				Positive	4.71	3.3	1.7	3.3	1.7 < LOD		3.15
1262	10/19/2007 9:55	19.56	WALL	CONCRETE	D	POOR	WHITE	BLDG 222 EAST BLDG	BASEMENT	EAST MIDDLE ROOM				Negative	3.41	0.08	0.03	0.08	0.03	0.8	0.3
1263	10/19/2007 9:56	0.52	WINDOW CASING	WOOD	D	FAIR	WHITE	BLDG 222 EAST BLDG	BASEMENT	EAST MIDDLE ROOM				Positive	2.15 < LOD		13.95 < LOD		6.15 < LOD		13.95
1264	10/19/2007 9:56	1.02	CEILING	WOOD	D	POOR	WHITE	BLDG 222 EAST BLDG	BASEMENT	EAST MIDDLE ROOM				Negative	2.3 < LOD		0.41 < LOD		0.41 < LOD		2.84
1265	10/19/2007 9:57	3.6	DOOR	METAL	A	FAIR	GRAY	BLDG 222 EAST BLDG	BASEMENT	ELEVATOR SHAFT				Positive	1.76	1.2	0.2	1.2	0.2 < LOD		1.35
1266	10/19/2007 9:58	1.03	DOOR CASING	METAL	A	FAIR	GRAY	BLDG 222 EAST BLDG	BASEMENT	ELEVATOR SHAFT				Negative	1 < LOD		0.12 < LOD		0.12 < LOD		5.31
1267	10/19/2007 9:58	1.54	WALL	PLASTER	A	FAIR	WHITE	BLDG 222 EAST BLDG	BASEMENT	ELEVATOR SHAFT				Negative	1 < LOD		0.03 < LOD		0.03 < LOD		2.98
1268	10/19/2007 9:59	2.05	WALL	PLASTER	D	FAIR	WHITE	BLDG 222 EAST BLDG	BASEMENT	ELEVATOR SHAFT				Negative	1 < LOD		0.03 < LOD		0.03 < LOD		2.41

Reading No	Time	Duration	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Res	Escale 1	Escl CT	Results	Depth Index	PbC	PbC Error	PbL	PbL Error	PbK	PbK Error
1269	10/19/2007 9:59	1.54	WALL	PLASTER	C	FAIR	WHITE	BLDG 222 EAST BLDG	BASEMENT	ELEVATOR SHAFT				Negative	1 < LOD		0.03 < LOD		0.03 < LOD		2.85
1270	10/19/2007 9:59	2.57	WALL	PLASTER	B	FAIR	WHITE	BLDG 222 EAST BLDG	BASEMENT	ELEVATOR SHAFT				Negative	1 < LOD		0.03 < LOD		0.03 < LOD		2.24
1271	10/19/2007 10:08	2.57	WALL	BRICK	B	FAIR	WHITE	BLDG 222 EAST BLDG	1ST	LARGE STORAGE AREA				Negative	4 < LOD		1.82 < LOD		0.13 < LOD		1.82
1272	10/19/2007 10:09	1.54	WALL	BRICK	D	FAIR	WHITE	BLDG 222 EAST BLDG	1ST	LARGE STORAGE AREA				Null	3.19 < LOD		0.17 < LOD		0.17 < LOD		2.75
1273	10/19/2007 10:09	3.06	WALL	BRICK	D	FAIR	WHITE	BLDG 222 EAST BLDG	1ST	LARGE STORAGE AREA				Negative	1.4 < LOD		0.04 < LOD		0.04 < LOD		1.88
1274	10/19/2007 10:09	0.51	WALL	PLASTER	C	FAIR	WHITE	BLDG 222 EAST BLDG	1ST	LARGE STORAGE AREA				Null	1.83 < LOD		0.25 < LOD		0.25 < LOD		7.18
1275	10/19/2007 10:09	3.1	WALL	PLASTER	C	FAIR	WHITE	BLDG 222 EAST BLDG	1ST	LARGE STORAGE AREA				Negative	3.88 < LOD		1.92 < LOD		0.18 < LOD		1.92
1276	10/19/2007 10:10	1.03	COLUMN	WOOD	C	FAIR	GRAY	BLDG 222 EAST BLDG	1ST	LARGE STORAGE AREA				Negative	1.33 < LOD		0.37 < LOD		0.37 < LOD		3.26
1277	10/19/2007 10:11	0.51	BEAM BRACKETS	METAL		FAIR	BLACK	BLDG 222 EAST BLDG	1ST	LARGE STORAGE AREA				Positive	1.31	2.9	1.7	2.9	1.7 < LOD		11.85
1278	10/19/2007 10:11	1.03	CEILING BEAM	WOOD		FAIR	BROWN	BLDG 222 EAST BLDG	1ST	LARGE STORAGE AREA				Negative	1 < LOD		0.1 < LOD		0.1 < LOD		3.34
1279	10/19/2007 10:12	1.03	CEILING BEAM	WOOD		FAIR	WHITE	BLDG 222 EAST BLDG	1ST	LARGE STORAGE AREA				Negative	1.08 < LOD		0.06 < LOD		0.06 < LOD		2.09
1280	10/19/2007 10:12	1.03	WINDOW	WOOD	B	FAIR	GRAY	BLDG 222 EAST BLDG	1ST	LARGE STORAGE AREA				Negative	1.24 < LOD		0.25 < LOD		0.25 < LOD		3.35
1281	10/19/2007 10:13	0.52	WINDOW CASING	WOOD	B	FAIR	GRAY	BLDG 222 EAST BLDG	1ST	LARGE STORAGE AREA				Positive	2.03 < LOD		4.8 < LOD		4.8 < LOD		8.4
1282	10/19/2007 10:14	1.03	WALL	WOOD	A	FAIR	BROWN	BLDG 222 EAST BLDG	1ST	LARGE STORAGE AREA				Negative	1 < LOD		0.12 < LOD		0.12 < LOD		2.8
1283	10/19/2007 10:15	0.51	GARAGE DOOR	WOOD	B	FAIR	GRAY	BLDG 222 EAST BLDG	1ST	LARGE STORAGE AREA				Positive	2.64 < LOD		19.95 < LOD		20.7 < LOD		19.95
1284	10/19/2007 10:15	0.52	GARAGE DOOR CASING	WOOD	B	FAIR	GRAY	BLDG 222 EAST BLDG	1ST	LARGE STORAGE AREA				Positive	2.23 < LOD		17.7 < LOD		14.55 < LOD		17.7
1285	10/19/2007 10:16	1.03	FLOOR	WOOD		POOR	BROWN	BLDG 222 EAST BLDG	1ST	LARGE STORAGE AREA				Negative	1 < LOD		0.06 < LOD		0.06 < LOD		3.48
1286	10/19/2007 10:17	1.03	STAIRWELL FRAME	WOOD	D	FAIR	BROWN	BLDG 222 EAST BLDG	1ST	LARGE STORAGE AREA				Negative	1.28 < LOD		0.11 < LOD		0.11 < LOD		2.46
1287	10/19/2007 10:17	1.03	STAIRWELL FRAME	WOOD	A	FAIR	BROWN	BLDG 222 EAST BLDG	1ST	LARGE STORAGE AREA				Negative	1 < LOD		0.08 < LOD		0.08 < LOD		2.59
1288	10/19/2007 10:18	1.03	STAIRWELL DOOR	WOOD	A	FAIR	BROWN	BLDG 222 EAST BLDG	1ST	LARGE STORAGE AREA				Negative	1.08 < LOD		0.07 < LOD		0.07 < LOD		2.6
1289	10/19/2007 10:19	1.03	FREEZER DOOR	WOOD	B	FAIR	BROWN	BLDG 222 EAST BLDG	1ST	LARGE STORAGE AREA				Negative	1 < LOD		0.07 < LOD		0.07 < LOD		3.51
1290	10/19/2007 10:19	1.02	FREEZER DOOR CASING	WOOD	B	FAIR	BROWN	BLDG 222 EAST BLDG	1ST	LARGE STORAGE AREA				Negative	2.01 < LOD		0.21 < LOD		0.21 < LOD		3.33
1291	10/19/2007 10:20	2.06	WALL	BRICK	B	POOR	GRAY	BLDG 222 EAST BLDG	1ST	LARGE STORAGE AREA				Null	3.48 < LOD		0.32 < LOD		0.32 < LOD		2.56
1292	10/19/2007 10:20	2.07	WALL	BRICK	B	POOR	GRAY	BLDG 222 EAST BLDG	1ST	LARGE STORAGE AREA				Negative	1.99 < LOD		0.15 < LOD		0.15 < LOD		2.52
1293	10/19/2007 10:21	2.04	WALL	BRICK	D	POOR	GRAY	BLDG 222 EAST BLDG	1ST	LARGE STORAGE AREA				Negative	1 < LOD		0.03 < LOD		0.03 < LOD		1.95
1294	10/19/2007 10:21	3.09	WALL	PLASTER	D	FAIR	WHITE	BLDG 222 EAST BLDG	1ST	LARGE STORAGE AREA				Negative	7.95 < LOD		2.05 < LOD		0.31 < LOD		2.05
1295	10/19/2007 10:22	2.05	WALL	PLASTER	D	FAIR	GRAY	BLDG 222 EAST BLDG	1ST	LARGE STORAGE AREA				Null	3.3 < LOD		0.27 < LOD		0.27 < LOD		2.7
1296	10/19/2007 10:22	3.6	WALL	PLASTER	D	FAIR	GRAY	BLDG 222 EAST BLDG	1ST	LARGE STORAGE AREA				Negative	3.07 < LOD		1.26	0.15	0.09 < LOD		1.26
1297	10/19/2007 10:24	3.6	ELEVATOR SHAFT DOORS	METAL	A	FAIR	GRAY	BLDG 222 EAST BLDG	1ST	LARGE STORAGE AREA				Negative	1.42	0.8	0.1	0.8	0.1 < LOD		1.2
1298	10/19/2007 10:24	1.03	ELEVATOR SHAFT DOOR CASING	METAL	A	FAIR	GRAY	BLDG 222 EAST BLDG	1ST	LARGE STORAGE AREA				Negative	1 < LOD		0.05 < LOD		0.05 < LOD		4.92
1299	10/19/2007 10:25	1.03	WALL	METAL	D	POOR	BLACK	BLDG 222 EAST BLDG	1ST	ELEVATOR				Negative	1 < LOD		0.03 < LOD		0.03 < LOD		5.11
1300	10/19/2007 10:25	1.04	WALL	METAL	B	POOR	BLACK	BLDG 222 EAST BLDG	1ST	ELEVATOR				Negative	1 < LOD		0.03 < LOD		0.03 < LOD		5.04
1301	10/19/2007 10:26	1.03	CEILING	METAL		POOR	BLACK	BLDG 222 EAST BLDG	1ST	ELEVATOR				Negative	1 < LOD		0.03 < LOD		0.03 < LOD		4.79
1302	10/19/2007 10:28	1.03	STAIRS	WOOD		POOR	GRAY	BLDG 222 EAST BLDG	2ND	STAIR TO ATTIC				Positive	1.29	8.6	5.4	6.8	2.8	8.6	5.4
1303	10/19/2007 10:30	2.05	WALL	BRICK	D	POOR	WHITE	BLDG 222 EAST BLDG	2ND	ATTIC				Negative	1 < LOD		0.06 < LOD		0.06 < LOD		2.44
1304	10/19/2007 10:30	1.54	WALL	BRICK	B	POOR	WHITE	BLDG 222 EAST BLDG	2ND	ATTIC				Negative	2.48 < LOD		0.28 < LOD		0.28 < LOD		2.68
1305	10/19/2007 10:42	2.08	WALL	BRICK	D	POOR	WHITE	BLDG 222 EAST BLDG	2ND	ATTIC				Negative	1.75 < LOD		0.12 < LOD		0.12 < LOD		2.37
1306	10/19/2007 10:42	2.07	WALL	BRICK	C	POOR	WHITE	BLDG 222 EAST BLDG	2ND	ATTIC				Negative	2.37 < LOD		0.15 < LOD		0.15 < LOD		2.43
1307	10/19/2007 10:43	0.51	WINDOW CASING	WOOD	D	FAIR	WHITE	BLDG 222 EAST BLDG	2ND	ATTIC				Positive	1.01	3.6	1.9	3.6	1.9 < LOD		10.95
1308	10/19/2007 10:44	1.54	ELEVATOR SHAFT DOOR	METAL	A	FAIR	GRAY	BLDG 222 EAST BLDG	2ND	ATTIC				Negative	1.26	0.7	0.3	0.7	0.3 < LOD		3.15
1309	10/19/2007 10:44	0.51	ELEVATOR SHAFT DOOR CASING	METAL	A	FAIR	GRAY	BLDG 222 EAST BLDG	2ND	ATTIC				Null	1 < LOD		0.09 < LOD		0.09 < LOD		7.95
1310	10/19/2007 10:44	1.03	ELEVATOR SHAFT DOOR CASING	METAL	A	FAIR	GRAY	BLDG 222 EAST BLDG	2ND	ATTIC				Negative	1.17 < LOD		0.1 < LOD		0.1 < LOD		5.41
1311	10/19/2007 10:45	1.03	WALL	WOOD	A	FAIR	BROWN	BLDG 222 EAST BLDG	2ND	ATTIC				Negative	1 < LOD		0.1 < LOD		0.1 < LOD		2.41
1312	10/19/2007 10:45	1.03	FLOOR	WOOD		FAIR	BROWN	BLDG 222 EAST BLDG	2ND	ATTIC				Negative	1.31 < LOD		0.14 < LOD		0.14 < LOD		3.17
1313	10/19/2007 10:48	2.55	WALL	CONCRETE	A	POOR	WHITE	BLDG 222 LINK	1ST	LOADING AREA				Negative	1 < LOD		0.03 < LOD		0.03 < LOD		2.55
1314	10/19/2007 10:48	1.54	WALL	CONCRETE	C	POOR	WHITE	BLDG 222 LINK	1ST	LOADING AREA				Negative	1 < LOD		0.03 < LOD		0.03 < LOD		3.27
1315	10/19/2007 10:49	1.03	DOOR	METAL	C	FAIR	BROWN	BLDG 222 LINK	1ST	LOADING AREA				Negative	1 < LOD		0.09 < LOD		0.09 < LOD		4.65
1316	10/19/2007 10:49	1.03	DOOR CASING	METAL	C	FAIR	BROWN	BLDG 222 LINK	1ST	LOADING AREA				Negative	1 < LOD		0.07 < LOD		0.07 < LOD		5.29

Reading No	Time	Duration	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Res	Escale 1	Escler CT	Results	Depth Index	PbC	PbC Error	PbL	PbL Error	PbK	PbK Error
1317	10/19/2007 10:50	1.03	GARAGE DOOR CASING	WOOD	D	FAIR	RED	BLDG 222 LINK	1ST	LOADING AREA				Negative	1 < LOD		0.03 < LOD		0.03 < LOD		5.29
1318	10/19/2007 10:50	1.03	GARAGE DOOR CASING	METAL	C	FAIR	BLACK	BLDG 222 LINK	1ST	LOADING AREA				Negative	1 < LOD		0.05 < LOD		0.05 < LOD		5.8
1319	10/19/2007 10:54	0.51	GARAGE DOOR CASING	METAL	B	POOR	GRAY	BLDG 222 LINK	1ST	LOADING AREA				Positive	1.67 < LOD		19.05 < LOD		9.9 < LOD		19.05
1320	10/19/2007 10:55	0.51	GARAGE DOOR	METAL	B	POOR	WHITE	BLDG 222 LINK	1ST	LOADING AREA				Positive	1.06 < LOD	3.3	1.8 < LOD	3.3	1.8 < LOD		9.15
1321	10/19/2007 10:55	1.03	GARAGE DOOR	WOOD	B	FAIR	GRAY	BLDG 222 LINK	1ST	LOADING AREA				Negative	1.07 < LOD		0.22 < LOD		0.22 < LOD		3.17
1322	10/19/2007 10:58	1.03	WINDOW	METAL	A	POOR	GRAY	BLDG 222 LINK	1ST	LOADING AREA				Negative	1 < LOD		0.15 < LOD		0.15 < LOD		5.11
1323	10/19/2007 11:03	1.02	WINDOW	METAL	B	POOR	SILVER	BLDG 222 WEST BLDG	3RD	STORAGE AREA				Positive	1.5 < LOD	3	1.4 < LOD	3	1.4 < LOD		7.95
1324	10/19/2007 11:03	2.05	WALL	BRICK	B	POOR	WHITE	BLDG 222 WEST BLDG	3RD	STORAGE AREA				Negative	1 < LOD		0.03 < LOD		0.03 < LOD		2.66
1325	10/19/2007 11:04	2.57	WALL	BRICK	C	POOR	WHITE	BLDG 222 WEST BLDG	3RD	STORAGE AREA				Negative	1 < LOD		0.03 < LOD		0.03 < LOD		2.68
1326	10/19/2007 11:04	1.06	RADIATOR	METAL	C	FAIR	SILVER	BLDG 222 WEST BLDG	3RD	STORAGE AREA				Negative	1 < LOD		0.09 < LOD		0.09 < LOD		6
1327	10/19/2007 11:05	1.03	RADIATOR PIPE	METAL	C	FAIR	SILVER	BLDG 222 WEST BLDG	3RD	STORAGE AREA				Negative	1 < LOD		0.03 < LOD		0.03 < LOD		5.7
1328	10/19/2007 11:05	1.54	WALL	BRICK	D	POOR	WHITE	BLDG 222 WEST BLDG	3RD	STORAGE AREA				Null	2.81 < LOD		0.22 < LOD		0.22 < LOD		3.39
1329	10/19/2007 11:06	2.06	WALL	BRICK	D	POOR	WHITE	BLDG 222 WEST BLDG	3RD	STORAGE AREA				Negative	2.03 < LOD		0.13 < LOD		0.13 < LOD		2.8
1330	10/19/2007 11:06	2.07	COLUMN	CONCRETE		FAIR	WHITE	BLDG 222 WEST BLDG	3RD	STORAGE AREA				Negative	1 < LOD		0.03 < LOD		0.03 < LOD		3.02
1331	10/19/2007 11:07	1.03	COLUMN	CONCRETE		FAIR	ORANGE	BLDG 222 WEST BLDG	3RD	STORAGE AREA				Positive	1.19 < LOD	1.9	0.8 < LOD	1.9	0.8 < LOD		7.05
1332	10/19/2007 11:07	1.54	CEILING	CONCRETE		FAIR	WHITE	BLDG 222 WEST BLDG	3RD	STORAGE AREA				Negative	1.3 < LOD		0.03 < LOD		0.03 < LOD		3.19
1333	10/19/2007 11:08	2.06	WALL	BRICK	A	FAIR	WHITE	BLDG 222 WEST BLDG	3RD	STORAGE AREA				Negative	1 < LOD		0.03 < LOD		0.03 < LOD		2.61
1334	10/19/2007 11:09	2.58	WALL	BRICK	A	FAIR	BEIGE	BLDG 222 WEST BLDG	3RD	STORAGE AREA STAIRWELL				Negative	1 < LOD		0.03 < LOD		0.03 < LOD		2.27
1335	10/19/2007 11:09	2.05	WALL	BRICK	D	FAIR	BEIGE	BLDG 222 WEST BLDG	3RD	STORAGE AREA STAIRWELL				Negative	1 < LOD		0.03 < LOD		0.03 < LOD		2.62
1336	10/19/2007 11:10	3.59	WALL	BRICK	C	FAIR	BEIGE	BLDG 222 WEST BLDG	3RD	STORAGE AREA STAIRWELL				Negative	1.13 < LOD		0.03 < LOD		0.03 < LOD		1.55
1337	10/19/2007 11:10	0.51	DOOR	METAL	D	POOR	ORANGE	BLDG 222 WEST BLDG	3RD	STORAGE AREA STAIRWELL				Positive	1.78 < LOD		6.45 < LOD		6.45 < LOD		13.65
1338	10/19/2007 11:11	0.51	DOOR CASING ELEVATOR DOOR	METAL	D	POOR	ORANGE	BLDG 222 WEST BLDG	3RD	STORAGE AREA STAIRWELL				Positive	1.74 < LOD		4.6 < LOD		4.6 < LOD		14.4
1339	10/19/2007 11:11	0.52	CASING	METAL	D	POOR	ORANGE	BLDG 222 WEST BLDG	3RD	STORAGE AREA STAIRWELL				Positive	1.7 < LOD	6.8	4.5 < LOD	6.8	4.5 < LOD		16.95
1340	10/19/2007 11:18	1.54	CEILING	CONCRETE		FAIR	WHITE	BLDG 222 WEST BLDG	3RD	STORAGE AREA				Negative	1 < LOD		0.03 < LOD		0.03 < LOD		3.06
1341	10/19/2007 11:22	1.54	CEILING	CONCRETE		FAIR	GRAY	BLDG 222 WEST BLDG	ROOF	ELEVATOR MECHANICAL ROOM				Negative	2.15 < LOD		0.12 < LOD		0.12 < LOD		3.26
1342	10/19/2007 11:22	1.54	FLOOR	CONCRETE		FAIR	GRAY	BLDG 222 WEST BLDG	ROOF	ELEVATOR MECHANICAL ROOM				Negative	1 < LOD		0.07 < LOD		0.07 < LOD		3.36
1343	10/19/2007 11:23	1.03	FLOOR	METAL		FAIR	GRAY	BLDG 222 WEST BLDG	ROOF	ELEVATOR MECHANICAL ROOM				Negative	1.36 < LOD		0.47 < LOD		0.47 < LOD		5.1
1344	10/19/2007 11:23	1.54	ELEVATOR MECHANICS	METAL		FAIR	GREEN	BLDG 222 WEST BLDG	ROOF	ELEVATOR MECHANICAL ROOM				Positive	1.78 < LOD	1.6	0.6 < LOD	1.6	0.6 < LOD		4.05
1345	10/19/2007 11:24	1.03	DOOR	WOOD	D	FAIR	GRAY	BLDG 222 WEST BLDG	ROOF	ELEVATOR MECHANICAL ROOM				Positive	1.36 < LOD	2.7	1.3 < LOD	2.7	1.3 < LOD		6.3
1346	10/19/2007 11:24	1.03	DOOR CASING	METAL	D	FAIR	GRAY	BLDG 222 WEST BLDG	ROOF	ELEVATOR MECHANICAL ROOM				Positive	1.21 < LOD	2.3	1.1 < LOD	2.3	1.1 < LOD		6.15
1347	10/19/2007 11:25	0.52	WINDOW	METAL	A	POOR	GRAY	BLDG 222 WEST BLDG	ROOF	ELEVATOR MECHANICAL ROOM				Positive	1.67 < LOD		3.8 < LOD		3.8 < LOD		14.55
1348	10/19/2007 11:25	1.03	CEILING BEAM	METAL	A	FAIR	GRAY	BLDG 222 WEST BLDG	ROOF	ELEVATOR MECHANICAL ROOM				Negative	3.21 < LOD		0.42 < LOD		0.42 < LOD		5.4
1349	10/19/2007 11:26	2.56	WALL	BRICK	A	FAIR	GRAY	BLDG 222 WEST BLDG	ROOF	ELEVATOR MECHANICAL ROOM				Negative	1.56 < LOD		0.06 < LOD		0.06 < LOD		2.44
1350	10/19/2007 11:26	2.06	WALL	BRICK	B	FAIR	GRAY	BLDG 222 WEST BLDG	ROOF	ELEVATOR MECHANICAL ROOM				Negative	3.04 < LOD		0.17 < LOD		0.17 < LOD		2.63
1351	10/19/2007 11:26	2.05	WALL	BRICK	C	FAIR	GRAY	BLDG 222 WEST BLDG	ROOF	ELEVATOR MECHANICAL ROOM				Negative	1.47 < LOD		0.07 < LOD		0.07 < LOD		2.51
1352	10/19/2007 11:27	3.61	WALL	BRICK	D	FAIR	GRAY	BLDG 222 WEST BLDG	ROOF	ELEVATOR MECHANICAL ROOM				Negative	1 < LOD		0.03 < LOD		0.03 < LOD		1.5
1353	10/19/2007 11:34	2.05	WALL	BRICK	C	POOR	BEIGE	BLDG 222 WEST BLDG	2ND	LARGE STORAGE AREA				Negative	1.07 < LOD		0.04 < LOD		0.04 < LOD		2.88
1354	10/19/2007 11:34	2.05	WALL	BRICK	B	POOR	BEIGE	BLDG 222 WEST BLDG	2ND	LARGE STORAGE AREA				Negative	1.62 < LOD		0.08 < LOD		0.08 < LOD		2.78
1355	10/19/2007 11:35	2.06	WALL	BRICK	D	POOR	BEIGE	BLDG 222 WEST BLDG	2ND	LARGE STORAGE AREA				Negative	5.15 < LOD		0.22 < LOD		0.22 < LOD		2.34
1356	10/19/2007 11:36	2.58	WALL	BRICK	A	FAIR	BEIGE	BLDG 222 WEST BLDG	2ND	LARGE STORAGE AREA				Negative	1 < LOD		0.03 < LOD		0.03 < LOD		2.25
1357	10/19/2007 11:36	1.03	PIPE	METAL	A	FAIR	SILVER	BLDG 222 WEST BLDG	2ND	LARGE STORAGE AREA				Negative	1 < LOD		0.25 < LOD		0.25 < LOD		4.95
1358	10/19/2007 11:37	3.06	WINDOW	METAL	B	POOR	BEIGE	BLDG 222 WEST BLDG	2ND	LARGE STORAGE AREA				Negative	5.79 < LOD		0.25 < LOD		0.25 < LOD		2.16
1359	10/19/2007 11:38	1.54	CEILING	CONCRETE		FAIR	BEIGE	BLDG 222 WEST BLDG	2ND	LARGE STORAGE AREA				Negative	1 < LOD		0.03 < LOD		0.03 < LOD		3.31
1360	10/19/2007 11:38	1.54	COLUMN	CONCRETE		FAIR	BEIGE	BLDG 222 WEST BLDG	2ND	LARGE STORAGE AREA				Negative	1 < LOD		0.03 < LOD		0.03 < LOD		3.25
1361	10/19/2007 11:39	0.52	DOOR CASING	WOOD	D	FAIR	BEIGE	BLDG 222 WEST BLDG	2ND	LARGE STORAGE AREA RESTROOM				Positive	2.02 < LOD		5.85 < LOD		5.85 < LOD		13.2
1362	10/19/2007 11:39	0.52	DOOR CASING	WOOD	D	FAIR	GREEN	BLDG 222 WEST BLDG	2ND	LARGE STORAGE AREA RESTROOM				Positive	1.8 < LOD		3.45 < LOD		3.45 < LOD		10.5
1363	10/19/2007 11:40	0.52	DOOR	WOOD	D	FAIR	GREEN	BLDG 222 WEST BLDG	2ND	LARGE STORAGE AREA RESTROOM				Positive	1.91 < LOD		6.6 < LOD		6.6 < LOD		13.95
1364	10/19/2007 11:40	0.52	DOOR	WOOD	D	FAIR	GRAY	BLDG 222 WEST BLDG	2ND	LARGE STORAGE AREA RESTROOM				Positive	1.55 < LOD	4.3	2.8 < LOD	4.3	2.8 < LOD		12.3
1365	10/19/2007 11:41	1.03	WALL	BRICK	C	POOR	GREEN	BLDG 222 WEST BLDG	2ND	LARGE STORAGE AREA RESTROOM				Positive	2.29 < LOD	2.5	1.4 < LOD	2.5	1.4 < LOD		7.5
1366	10/19/2007 11:41	1.03	WALL	BRICK	B	POOR	GREEN	BLDG 222 WEST BLDG	2ND	LARGE STORAGE AREA RESTROOM				Null	3.32 < LOD		1.8 < LOD		1.8 < LOD		6.45
1367	10/19/2007 11:41	1.03	WALL	BRICK	B	POOR	GREEN	BLDG 222 WEST BLDG	2ND	LARGE STORAGE AREA RESTROOM				Positive	3.13 < LOD	2.9	1.9 < LOD	2.9	1.9 < LOD		7.5

Reading No	Time	Duration	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Res	Escale 1	Escl CT	Results	Depth Index	PbC	PbC Error	PbL	PbL Error	PbK	PbK Error
1368	10/19/2007 11:41	1.03	WALL	WOOD	B	POOR	GREEN	BLDG 222 WEST BLDG	2ND	LARGE STORAGE AREA RESTROOM				Positive	4.31	7.8	5.1 < LOD	5.7	7.8	5.1	
1369	10/19/2007 11:41	0.52	WALL	WOOD	D	FAIR	GREEN	BLDG 222 WEST BLDG	2ND	LARGE STORAGE AREA RESTROOM				Positive	2.82 < LOD		5.55 < LOD	5.55 < LOD		11.1	
1370	10/19/2007 11:42	1.55	WINDOW CASING	METAL	B	POOR	GREEN	BLDG 222 WEST BLDG	2ND	LARGE STORAGE AREA RESTROOM				Positive	2.53	2.2	0.8	2.2	0.8 < LOD	4.2	
1371	10/19/2007 11:43	1.56	COLUMN	CONCRETE		FAIR	GRAY	BLDG 222 WEST BLDG	2ND	LARGE STORAGE AREA RESTROOM				Positive	1.48	1.6	0.5	1.6	0.5 < LOD	4.2	
1372	10/19/2007 11:44	1.55	COLUMN	CONCRETE		FAIR	ORANGE	BLDG 222 WEST BLDG	2ND	LARGE STORAGE AREA RESTROOM				Positive	1.18	1.8	0.5	1.8	0.5 < LOD	4.05	
1373	10/19/2007 11:44	0.52	DOOR	METAL	D	FAIR	GRAY	BLDG 222 WEST BLDG	2ND	LARGE STORAGE AREA RESTROOM				Positive	2.62 < LOD		7.65 < LOD	7.65 < LOD		12	
1374	10/19/2007 11:45	0.52	DOOR CASING	METAL	D	FAIR	GRAY	BLDG 222 WEST BLDG	2ND	LARGE STORAGE AREA RESTROOM				Positive	1.48	3.5	2.2	3.5	2.2 < LOD	12.3	
			ELEVATOR DOOR																		
1375	10/19/2007 11:45	0.51	CASING	METAL	D	FAIR	GRAY	BLDG 222 WEST BLDG	2ND	LARGE STORAGE AREA RESTROOM				Positive	1.83 < LOD		7.35 < LOD	7.35 < LOD		18.3	
1376	10/19/2007 11:45	1.02	ELEVATOR DOOR	METAL	D	FAIR	GRAY	BLDG 222 WEST BLDG	2ND	LARGE STORAGE AREA RESTROOM				Positive	2.45	4.1	2.2	4.1	2.2 < LOD	7.35	
1377	10/19/2007 11:46	2.57	WALL	BRICK	B	FAIR	GRAY	BLDG 222 WEST BLDG	2ND	LARGE STORAGE AREA RESTROOM				Negative	1.84 < LOD		0.03 < LOD	0.03 < LOD		2.41	
1378	10/19/2007 11:50	2.05	WALL	PLASTER	D	POOR	BEIGE	BLDG 222 EAST BLDG	1ST	NORTH FREEZER STORAGE				Negative	1.42 < LOD		0.06 < LOD	0.06 < LOD		2.84	
1379	10/19/2007 11:50	2.07	WALL	PLASTER	C	POOR	BEIGE	BLDG 222 EAST BLDG	1ST	NORTH FREEZER STORAGE				Negative	6.2 < LOD		0.37 < LOD	0.37 < LOD		2.72	
1380	10/19/2007 11:51	3.07	WALL	PLASTER	B	POOR	BEIGE	BLDG 222 EAST BLDG	1ST	NORTH FREEZER STORAGE				Negative	1.2 < LOD		0.03 < LOD	0.03 < LOD		2.15	
1381	10/19/2007 11:51	1.54	WALL	PLASTER	A	POOR	BEIGE	BLDG 222 EAST BLDG	1ST	NORTH FREEZER STORAGE				Negative	1.13 < LOD		0.05 < LOD	0.05 < LOD		3.22	
1382	10/19/2007 11:51	2.06	CEILING	PLASTER		POOR	BEIGE	BLDG 222 EAST BLDG	1ST	NORTH FREEZER STORAGE				Negative	1.72	0.6	0.3	0.6	0.3 < LOD	1.96	
1383	10/19/2007 11:52	1.03	DOOR	WOOD	A	POOR	BEIGE	BLDG 222 EAST BLDG	1ST	NORTH FREEZER STORAGE				Negative	1.41 < LOD		0.09 < LOD	0.09 < LOD		3.16	
1384	10/19/2007 11:52	1.02	DOOR CASING	WOOD	A	POOR	BEIGE	BLDG 222 EAST BLDG	1ST	NORTH FREEZER STORAGE				Negative	1.33 < LOD		0.13 < LOD	0.13 < LOD		2.57	
1385	10/19/2007 11:55	1.03	DOOR CASING	WOOD	B	FAIR	BROWN	BLDG 222 EAST BLDG	1ST	SOUTH EAST FREEZER STORAGE				Negative	1 < LOD		0.05 < LOD	0.05 < LOD		2.69	
1386	10/19/2007 11:55	1.03	DOOR	WOOD	B	FAIR	BROWN	BLDG 222 EAST BLDG	1ST	SOUTH EAST FREEZER STORAGE				Negative	1 < LOD		0.05 < LOD	0.05 < LOD		3.05	
1387	10/19/2007 12:39	0.52	CALIBRATION				YELLOW	BLDG 222 EAST BLDG	1ST					Positive	1.43	4.1	2.5	4.1	2.5 < LOD	8.7	
1388	10/19/2007 12:40	0.52	CALIBRATION				YELLOW	BLDG 222 EAST BLDG	1ST					Positive	1.25	3.3	1.9	3.3	1.9 < LOD	7.5	
1389	10/19/2007 12:40	1.03	CALIBRATION				ORANGE	BLDG 222 EAST BLDG	1ST					Null	1.04	1.3	0.6	1.3	0.6 < LOD	4.5	
1390	10/19/2007 12:40	1.54	CALIBRATION				ORANGE	BLDG 222 EAST BLDG	1ST					Positive	1.16	1.5	0.5	1.5	0.5 < LOD	2.7	
1391	10/19/2007 12:41	10.28	CALIBRATION				RED	BLDG 222 EAST BLDG	1ST					Negative	1.08	0.9	0.1	0.9	0.1	0.7	0.4
1392	10/19/2007 12:47	1.54	WALL	CONCRETE	C	FAIR	WHITE	BLDG 222 EAST BLDG	BASEMENT	VAULT				Negative	1 < LOD		0.03 < LOD	0.03 < LOD		3.01	
1393	10/19/2007 12:47	2.06	WALL	CONCRETE	D	FAIR	WHITE	BLDG 222 EAST BLDG	BASEMENT	VAULT				Negative	1 < LOD		0.03 < LOD	0.03 < LOD		2.56	
1394	10/19/2007 12:48	2.58	WALL	CONCRETE	A	FAIR	WHITE	BLDG 222 EAST BLDG	BASEMENT	VAULT				Negative	1.49 < LOD		0.03 < LOD	0.03 < LOD		2.34	
1395	10/19/2007 12:48	2.04	WALL	CONCRETE	B	FAIR	WHITE	BLDG 222 EAST BLDG	BASEMENT	VAULT				Negative	1.17 < LOD		0.03 < LOD	0.03 < LOD		2.67	
1396	10/19/2007 12:49	1.03	CEILING	CONCRETE		FAIR	WHITE	BLDG 222 EAST BLDG	BASEMENT	VAULT				Null	1 < LOD		0.04 < LOD	0.04 < LOD		4.93	
1397	10/19/2007 12:49	4.65	CEILING	CONCRETE		FAIR	WHITE	BLDG 222 EAST BLDG	BASEMENT	VAULT				Negative	1.18 < LOD		0.03 < LOD	0.03 < LOD		1.13	
1398	10/19/2007 12:50	1.03	DOOR CASING	METAL	A	FAIR	GRAY	BLDG 222 EAST BLDG	BASEMENT	VAULT				Negative	1.96 < LOD		0.11 < LOD	0.11 < LOD		4.96	
1399	10/19/2007 12:50	1.02	DOOR	METAL	A	FAIR	GRAY	BLDG 222 EAST BLDG	BASEMENT	VAULT				Negative	1.36 < LOD		0.13 < LOD	0.13 < LOD		4.86	
1400	10/19/2007 12:51	2.55	WALL	CONCRETE	D	FAIR	WHITE	BLDG 222 EAST BLDG	BASEMENT	STORAGE AREA				Negative	2.49 < LOD		0.08 < LOD	0.08 < LOD		2.53	
1401	10/19/2007 12:52	1.03	GARAGE DOOR CASING	METAL	D	FAIR	SILVER	BLDG 222 EAST BLDG	BASEMENT	STORAGE AREA				Negative	1 < LOD		0.03 < LOD	0.03 < LOD		4.8	
1402	10/19/2007 12:52	1.54	GARAGE DOOR	METAL	D	FAIR	SILVER	BLDG 222 EAST BLDG	BASEMENT	STORAGE AREA				Positive	1.15	2.9	1.8	0.9	0.3	2.9	1.8
1403	10/19/2007 12:53	2.06	WALL	CONCRETE	B	FAIR	WHITE	BLDG 222 EAST BLDG	BASEMENT	STORAGE AREA				Negative	1 < LOD		0.03 < LOD	0.03 < LOD		2.77	
1404	10/19/2007 12:53	2.06	WALL	CONCRETE	A	FAIR	WHITE	BLDG 222 EAST BLDG	BASEMENT	STORAGE AREA				Negative	1.04 < LOD		0.03 < LOD	0.03 < LOD		2.75	
1405	10/19/2007 12:54	1.54	WINDOW	GLASS	D	POOR	GRAY	BLDG 222 EAST BLDG	BASEMENT	STORAGE AREA				Negative	1 < LOD		0.05 < LOD	0.05 < LOD		2.81	
1406	10/19/2007 12:55	0.52	WINDOW CASING	METAL	D	FAIR	GRAY	BLDG 222 EAST BLDG	BASEMENT	STORAGE AREA				Positive	1.75 < LOD		13.05 < LOD	13.05 < LOD		18.15	
			WINDOW CASING																		
1407	10/19/2007 12:56	1.03	CAGE	METAL	D	POOR	BEIGE	BLDG 222 EAST BLDG	BASEMENT	STORAGE AREA				Negative	1.76 < LOD		0.12 < LOD	0.12 < LOD		5.22	
1408	10/19/2007 12:56	2.05	COLUMN	CONCRETE		FAIR	WHITE	BLDG 222 EAST BLDG	BASEMENT	STORAGE AREA				Negative	1.49 < LOD		0.03 < LOD	0.03 < LOD		2.66	
1409	10/19/2007 12:57	1.03	PIPE	METAL	B	FAIR	SILVER	BLDG 222 EAST BLDG	BASEMENT	STORAGE AREA				Negative	1 < LOD		0.03 < LOD	0.03 < LOD		5.13	
1410	10/19/2007 12:57	2.05	COLUMN	CONCRETE		FAIR	ORANGE	BLDG 222 EAST BLDG	BASEMENT	STORAGE AREA				Positive	1.11	1.4	0.3	1.4	0.3 < LOD	3.3	
1411	10/19/2007 12:58	1.54	CEILING	CONCRETE		FAIR	WHITE	BLDG 222 EAST BLDG	BASEMENT	STORAGE AREA				Negative	1 < LOD		0.03 < LOD	0.03 < LOD		2.95	
1412	10/19/2007 12:58	0.51	DOOR	METAL	D	FAIR	ORANGE	BLDG 222 EAST BLDG	BASEMENT	STORAGE AREA				Positive	1.51	3.5	2.3	3.5	2.3 < LOD	9.3	
1413	10/19/2007 12:59	0.53	DOOR CASING	METAL	D	FAIR	ORANGE	BLDG 222 EAST BLDG	BASEMENT	STORAGE AREA				Positive	1.35	3.1	1.8	3.1	1.8 < LOD	11.1	
1414	10/19/2007 13:00	0.52	GARAGE DOOR CASING	METAL	D	FAIR	ORANGE	BLDG 222 EAST BLDG	BASEMENT	STORAGE AREA				Positive	2.03 < LOD		19.8 < LOD	15.6 < LOD		19.8	
1415	10/19/2007 13:00	0.51	TRIM	METAL	D	FAIR	ORANGE	BLDG 222 EAST BLDG	BASEMENT	STORAGE AREA				Positive	1.8 < LOD		7.8 < LOD	7.8 < LOD		16.65	
1416	10/19/2007 13:01	5.17	ELEVATOR DOOR	METAL	D	FAIR	GRAY	BLDG 222 EAST BLDG	BASEMENT	STORAGE AREA				Positive	1.4	1.2	0.2	1.2	0.2	1.1	0.7
1417	10/19/2007 13:01	1.03	ELEVATOR DOOR	METAL	D	FAIR	YELLOW	BLDG 222 EAST BLDG	BASEMENT	STORAGE AREA				Positive	1.28	2.4	1.1	2.4	1.1 < LOD	5.85	
1418	10/19/2007 13:02	4.11	ELEVATOR DOOR	METAL	D	FAIR	BLACK	BLDG 222 EAST BLDG	BASEMENT	STORAGE AREA				Positive	1.17	1.3	0.3	1.3	0.3	1.5	0.8
1419	10/19/2007 13:02	2.06	WALL	BRICK	D	FAIR	BEIGE	BLDG 222 EAST BLDG	BASEMENT	STORAGE AREA				Negative	1 < LOD		0.03 < LOD	0.03 < LOD		2.65	

Reading No	Time	Duration	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Res	Escale 1	Escl CT	Results	Depth Index	PbC	PbC Error	PbL	PbL Error	PbK	PbK Error
1420	10/19/2007 13:09	1.55	WALL	WOOD	A	FAIR	BEIGE	BLDG 222 SOUTH BLDG	2ND	SOUTH STORAGE				Negative	4.95 < LOD		0.61 < LOD		0.61 < LOD		1.65
1421	10/19/2007 13:09	2.06	WALL	WOOD	D	FAIR	BEIGE	BLDG 222 SOUTH BLDG	2ND	SOUTH STORAGE				Null	3.41 < LOD		0.45 < LOD		0.45 < LOD		1.34
1422	10/19/2007 13:09	1.54	WALL	WOOD	D	FAIR	BEIGE	BLDG 222 SOUTH BLDG	2ND	SOUTH STORAGE				Negative	2.29 < LOD		0.33 < LOD		0.33 < LOD		1.56
1423	10/19/2007 13:10	1.54	WALL	WOOD	C	FAIR	BEIGE	BLDG 222 SOUTH BLDG	2ND	SOUTH STORAGE				Negative	2.62 < LOD		1.39 < LOD		0.4 < LOD		1.39
1424	10/19/2007 13:11	3.6	WALL	BRICK	C	FAIR	BEIGE	BLDG 222 SOUTH BLDG	2ND	SOUTH STORAGE				Negative	2.01 < LOD		1.24 < LOD		0.06 < LOD		1.24
1425	10/19/2007 13:11	1.03	DOOR	WOOD	D	FAIR	BEIGE	BLDG 222 SOUTH BLDG	2ND	SOUTH STORAGE				Negative	1.07 < LOD		0.18 < LOD		0.18 < LOD		2.47
1426	10/19/2007 13:11	1.54	DOOR CASING	WOOD	D	FAIR	BEIGE	BLDG 222 SOUTH BLDG	2ND	SOUTH STORAGE				Negative	4.74 < LOD		0.6 < LOD		0.6 < LOD		1.62
1427	10/19/2007 13:12	1.03	FLOOR	WOOD	D	FAIR	BROWN	BLDG 222 SOUTH BLDG	2ND	SOUTH STORAGE				Negative	1 < LOD		0.06 < LOD		0.06 < LOD		2.79
1428	10/19/2007 13:12	1.03	CEILING	WOOD		FAIR	BEIGE	BLDG 222 SOUTH BLDG	2ND	SOUTH STORAGE				Negative	1.45 < LOD		0.26 < LOD		0.26 < LOD		2.23
1429	10/19/2007 13:13	1.03	CEILING	WOOD		FAIR	BEIGE	BLDG 222 SOUTH BLDG	2ND	SOUTH MIDDLE STORAGE				Positive	1.13	9	5.5 < LOD		0.33	9	5.5
1430	10/19/2007 13:14	2.05	WALL	BRICK	C	FAIR	BEIGE	BLDG 222 SOUTH BLDG	2ND	SOUTH MIDDLE STORAGE				Negative	1.7	0.7	0.3	0.7	0.3 < LOD		2.25
1431	10/19/2007 13:14	0.51	WALL	BRICK	B	FAIR	BEIGE	BLDG 222 SOUTH BLDG	2ND	SOUTH MIDDLE STORAGE				Positive	1.99 < LOD		3.75 < LOD		3.75 < LOD		10.5
1432	10/19/2007 13:15	1.02	WALL	BRICK	A	FAIR	BEIGE	BLDG 222 SOUTH BLDG	2ND	SOUTH MIDDLE STORAGE				Negative	1.2 < LOD		0.35 < LOD		0.35 < LOD		4.49
1433	10/19/2007 13:15	0.51	WALL	WOOD	A	POOR	BEIGE	BLDG 222 SOUTH BLDG	2ND	SOUTH MIDDLE STORAGE				Positive	2.65 < LOD		16.65 < LOD		1.35 < LOD		16.65
1434	10/19/2007 13:15	1.03	WALL	WOOD	D	FAIR	BEIGE	BLDG 222 SOUTH BLDG	2ND	SOUTH MIDDLE STORAGE				Positive	3.44	4.7	3	4.7	3 < LOD		6.9
1435	10/19/2007 13:16	1.03	RADIATOR	METAL	C	FAIR	BEIGE	BLDG 222 SOUTH BLDG	2ND	SOUTH MIDDLE STORAGE				Negative	1 < LOD		0.03 < LOD		0.03 < LOD		4.59
1436	10/19/2007 13:16	0.51	DOOR	METAL	B	FAIR	SILVER	BLDG 222 SOUTH BLDG	2ND	SOUTH MIDDLE STORAGE				Positive	1.67 < LOD		15.3 < LOD		9.15 < LOD		15.3
1437	10/19/2007 13:17	0.51	DOOR CASING	METAL	B	FAIR	SILVER	BLDG 222 SOUTH BLDG	2ND	SOUTH MIDDLE STORAGE				Positive	2.36 < LOD		4.8 < LOD		4.8 < LOD		10.5
1438	10/19/2007 13:17	1.03	DOOR CASING	WOOD	D	FAIR	BEIGE	BLDG 222 SOUTH BLDG	2ND	SOUTH MIDDLE STORAGE				Positive	1.9	3.1	1.5	3.1	1.5 < LOD		5.4
1439	10/19/2007 13:17	0.52	DOOR	WOOD	D	FAIR	BEIGE	BLDG 222 SOUTH BLDG	2ND	SOUTH MIDDLE STORAGE				Positive	2.07 < LOD		4.95 < LOD		4.95 < LOD		9.6
1440	10/19/2007 13:18	1.03	DOOR	WOOD	B	FAIR	YELLOW	BLDG 222 SOUTH BLDG	2ND	MIDDLE ROOM				Negative	1.46 < LOD		0.25 < LOD		0.25 < LOD		3.15
1441	10/19/2007 13:18	1.54	WALL	WOOD	B	FAIR	YELLOW	BLDG 222 SOUTH BLDG	2ND	MIDDLE ROOM				Negative	2.36 < LOD		1.53 < LOD		0.25 < LOD		1.53
1442	10/19/2007 13:19	1.03	DOOR CASING	WOOD	B	FAIR	YELLOW	BLDG 222 SOUTH BLDG	2ND	MIDDLE ROOM				Negative	1.39 < LOD		0.2 < LOD		0.2 < LOD		2.18
1443	10/19/2007 13:19	1.54	WALL	WOOD	A	FAIR	BEIGE	BLDG 222 SOUTH BLDG	2ND	MIDDLE ROOM				Positive	3.52	3.6	2.3 < LOD		0.6	3.6	2.3
1444	10/19/2007 13:20	1.03	WALL	WOOD	D	FAIR	BEIGE	BLDG 222 SOUTH BLDG	2ND	MIDDLE ROOM				Negative	1 < LOD		0.14 < LOD		0.14 < LOD		2.72
1445	10/19/2007 13:20	1.03	WALL	WOOD	C	FAIR	BEIGE	BLDG 222 SOUTH BLDG	2ND	MIDDLE ROOM				Negative	1.86 < LOD		0.32 < LOD		0.32 < LOD		2.8
1446	10/19/2007 13:21	1.03	CEILING	WOOD		FAIR	BEIGE	BLDG 222 SOUTH BLDG	2ND	MIDDLE ROOM				Negative	1.44 < LOD		0.24 < LOD		0.24 < LOD		2.98
1447	10/19/2007 13:22	0.52	WINDOW	METAL	C	POOR	BEIGE	BLDG 222 SOUTH BLDG	2ND	MIDDLE ROOM				Positive	3.18 < LOD		7.95 < LOD		7.95 < LOD		15
1448	10/19/2007 13:24	1.03	WINDOW	BRICK	A	FAIR	WHITE	BLDG 222 SOUTH BLDG	2ND	HALL OUTSIDE RESTROOMS				Positive	9.38 < LOD		7.95 < LOD		13.95 < LOD		7.95
1449	10/19/2007 13:24	1.03	WINDOW	BRICK	B	FAIR	WHITE	BLDG 222 SOUTH BLDG	2ND	HALL OUTSIDE RESTROOMS				Positive	7.09	10.2	6.3 < LOD		5.85	10.2	6.3
1450	10/19/2007 13:25	1.03	WINDOW	WOOD	C	FAIR	BROWN	BLDG 222 SOUTH BLDG	2ND	HALL OUTSIDE RESTROOMS				Negative	2.57 < LOD		0.32 < LOD		0.32 < LOD		2.46
1451	10/19/2007 13:25	1.03	WINDOW	WOOD	D	FAIR	BROWN	BLDG 222 SOUTH BLDG	2ND	HALL OUTSIDE RESTROOMS				Negative	1.58 < LOD		0.2 < LOD		0.2 < LOD		2.45
1452	10/19/2007 13:25	0.52	DOOR	WOOD	B	FAIR	BEIGE	BLDG 222 SOUTH BLDG	2ND	HALL OUTSIDE RESTROOMS				Positive	4.96 < LOD		19.05 < LOD		10.8 < LOD		19.05
1453	10/19/2007 13:26	1.03	DOOR CASING	WOOD	B	FAIR	BEIGE	BLDG 222 SOUTH BLDG	2ND	HALL OUTSIDE RESTROOMS				Negative	1 < LOD		0.13 < LOD		0.13 < LOD		2.67
1454	10/19/2007 13:26	1.02	DOOR CASING	WOOD	B	FAIR	BROWN	BLDG 222 SOUTH BLDG	2ND	HALL OUTSIDE RESTROOMS				Negative	1.16 < LOD		0.19 < LOD		0.19 < LOD		2.47
1455	10/19/2007 13:26	1.03	COLUMN	WOOD		FAIR	BROWN	BLDG 222 SOUTH BLDG	2ND	HALL OUTSIDE RESTROOMS				Negative	1.29 < LOD		0.23 < LOD		0.23 < LOD		2.7
1456	10/19/2007 13:26	1.03	CEILING	WOOD		FAIR	BROWN	BLDG 222 SOUTH BLDG	2ND	HALL OUTSIDE RESTROOMS				Negative	1 < LOD		0.12 < LOD		0.12 < LOD		2.36
1457	10/19/2007 13:27	1.03	CEILING	WOOD		FAIR	BEIGE	BLDG 222 SOUTH BLDG	2ND	WEST RESTROOM				Negative	1.76 < LOD		0.17 < LOD		0.17 < LOD		2.42
1458	10/19/2007 13:28	1.54	WALL	WOOD	C	FAIR	BEIGE	BLDG 222 SOUTH BLDG	2ND	WEST RESTROOM				Negative	1.17 < LOD		0.05 < LOD		0.05 < LOD		1.52
1459	10/19/2007 13:28	1.54	WALL	WOOD	D	FAIR	BEIGE	BLDG 222 SOUTH BLDG	2ND	WEST RESTROOM				Negative	1.45 < LOD		0.08 < LOD		0.08 < LOD		1.52
1460	10/19/2007 13:28	1.03	WALL	WOOD	B	FAIR	BEIGE	BLDG 222 SOUTH BLDG	2ND	WEST RESTROOM				Negative	1.92 < LOD		0.17 < LOD		0.17 < LOD		2.74
1461	10/19/2007 13:28	1.54	WALL	WOOD	A	FAIR	BEIGE	BLDG 222 SOUTH BLDG	2ND	WEST RESTROOM				Negative	5.56 < LOD		0.52 < LOD		0.52 < LOD		1.8
1462	10/19/2007 13:29	1.03	WINDOW	WOOD	A	FAIR	BEIGE	BLDG 222 SOUTH BLDG	2ND	WEST RESTROOM				Negative	1 < LOD		0.04 < LOD		0.04 < LOD		3
1463	10/19/2007 13:29	1.03	WINDOW CASING	WOOD	A	FAIR	BEIGE	BLDG 222 SOUTH BLDG	2ND	WEST RESTROOM				Negative	1.64 < LOD		0.17 < LOD		0.17 < LOD		2.97
1464	10/19/2007 13:29	2.05	RADIATOR	METAL	A	FAIR	BEIGE	BLDG 222 SOUTH BLDG	2ND	WEST RESTROOM				Negative	5.1 < LOD		0.28 < LOD		0.28 < LOD		2.48
1465	10/19/2007 13:30	0.51	DOOR	METAL	C	FAIR	BEIGE	BLDG 222 SOUTH BLDG	2ND	WEST RESTROOM				Positive	10 < LOD		20.4 < LOD		20.85 < LOD		20.4
1466	10/19/2007 13:30	1.03	DOOR CASING	METAL	C	FAIR	BEIGE	BLDG 222 SOUTH BLDG	2ND	WEST RESTROOM				Negative	1 < LOD		0.07 < LOD		0.07 < LOD		2.97
1467	10/19/2007 13:30	1.03	DOOR CASING	WOOD	C	FAIR	BEIGE	BLDG 222 SOUTH BLDG	2ND	EAST RESTROOM				Negative	3.32 < LOD		0.33 < LOD		0.33 < LOD		2.94
1468	10/19/2007 13:31	1.55	DOOR	WOOD	C	FAIR	BEIGE	BLDG 222 SOUTH BLDG	2ND	EAST RESTROOM				Positive	5.82	4.2	2.1	4.2	2.1	4.2	2.3
1469	10/19/2007 13:31	1.03	CEILING	WOOD		FAIR	BEIGE	BLDG 222 SOUTH BLDG	2ND	EAST RESTROOM				Negative	3.5 < LOD		0.43 < LOD		0.43 < LOD		2.74
1470	10/19/2007 13:31	1.03	WALL	WOOD	A	FAIR	BEIGE	BLDG 222 SOUTH BLDG	2ND	EAST RESTROOM				Negative	2.45 < LOD		0.21 < LOD		0.21 < LOD		2.67
1471	10/19/2007 13:31	1.54	WALL	WOOD	D	FAIR	BEIGE	BLDG 222 SOUTH BLDG	2ND	EAST RESTROOM				Negative	2.72 < LOD		0.17 < LOD		0.17 < LOD		1.69
1472	10/19/2007 13:32	1.03	WALL	WOOD	C	FAIR	BEIGE	BLDG 222 SOUTH BLDG	2ND	EAST RESTROOM				Negative	1.93 < LOD		0.19 < LOD		0.19 < LOD		2.67
1473	10/19/2007 13:32	1.02	WALL	WOOD	B	FAIR	BEIGE	BLDG 222 SOUTH BLDG	2ND	EAST RESTROOM				Null	1.24 < LOD		0.11 < LOD		0.11 < LOD		2.53
1474	10/19/2007 13:32	1.54	WALL	WOOD	B	FAIR	BEIGE	BLDG 222 SOUTH BLDG	2ND	EAST RESTROOM				Negative	3.49 < LOD		1.49 < LOD		0.18 < LOD		1.49

Reading No	Time	Duration	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Res	Escale 1	Escler CT	Results	Depth Index	PbC	PbC Error	PbL	PbL Error	PbK	PbK Error
1475	10/19/2007 13:32	1.03	WINDOW	WOOD		FAIR	BEIGE	BLDG 222 SOUTH BLDG	2ND	EAST RESTROOM				Negative	4.56 < LOD		0.52 < LOD		0.52 < LOD		2.99
1476	10/19/2007 13:33	0.51	WINDOW CASING	WOOD	A	FAIR	BEIGE	BLDG 222 SOUTH BLDG	2ND	EAST RESTROOM				Null	4.18 < LOD		0.61 < LOD		0.61 < LOD		4.23
1477	10/19/2007 13:33	1.03	WINDOW CASING	WOOD	A	FAIR	BEIGE	BLDG 222 SOUTH BLDG	2ND	EAST RESTROOM				Negative	1 < LOD		0.07 < LOD		0.07 < LOD		3.15
1478	10/19/2007 13:34	1.03	WINDOW CASING	BRICK	A	FAIR	BEIGE	BLDG 222 SOUTH BLDG	2ND	SPACE EAST OF EAST RESTROOM				Negative	1 < LOD		0.11 < LOD		0.11 < LOD		4.15
1479	10/19/2007 13:34	1.03	WINDOW CASING	BRICK	D	FAIR	BEIGE	BLDG 222 SOUTH BLDG	2ND	SPACE EAST OF EAST RESTROOM				Negative	2.73 < LOD		0.36 < LOD		0.36 < LOD		3.81
1480	10/19/2007 13:36	1.03	RAILING	WOOD		FAIR	BROWN	BLDG 222 SOUTH BLDG	2ND	STAIR WELL				Negative	1 < LOD		0.06 < LOD		0.06 < LOD		3.3
1481	10/19/2007 13:36	0.52	RAILING	WOOD		FAIR	RED	BLDG 222 SOUTH BLDG	2ND	STAIR WELL				Positive	7.92	30.5	18.1 < LOD		14.4	30.5	18.1
1482	10/19/2007 13:36	1.54	STAIR TREAD	WOOD		FAIR	GRAY	BLDG 222 SOUTH BLDG	2ND	STAIR WELL				Negative	4.56 < LOD		0.57 < LOD		0.57 < LOD		2.13
1483	10/19/2007 13:44	1.03	WALL	WOOD	A	FAIR	BEIGE	BLDG 222 SOUTH BLDG	BASEMENT	EAST ROOM				Negative	1 < LOD		0.05 < LOD		0.05 < LOD		2.81
1484	10/19/2007 13:45	1.54	WALL	DRYWALL	B	FAIR	BEIGE	BLDG 222 SOUTH BLDG	BASEMENT	EAST ROOM				Negative	1 < LOD		0.03 < LOD		0.03 < LOD		1.65
1485	10/19/2007 13:45	1.03	WALL	WOOD	C	POOR	BEIGE	BLDG 222 SOUTH BLDG	BASEMENT	EAST ROOM				Negative	1 < LOD		0.03 < LOD		0.03 < LOD		2.36
1486	10/19/2007 13:45	1.03	WALL	WOOD	D	POOR	BEIGE	BLDG 222 SOUTH BLDG	BASEMENT	EAST ROOM				Negative	1.22 < LOD		0.1 < LOD		0.1 < LOD		2.7
1487	10/19/2007 13:46	1.03	DOOR	WOOD	A	POOR	BEIGE	BLDG 222 SOUTH BLDG	BASEMENT	EAST ROOM				Negative	1.04 < LOD		0.1 < LOD		0.1 < LOD		3.15
1488	10/19/2007 13:46	1.03	DOOR CASING	WOOD	A	POOR	BEIGE	BLDG 222 SOUTH BLDG	BASEMENT	EAST ROOM				Negative	2.13 < LOD		0.2 < LOD		0.2 < LOD		3.15
1489	10/19/2007 13:46	0.51	WINDOW	WOOD	A	FAIR	BEIGE	BLDG 222 SOUTH BLDG	BASEMENT	EAST ROOM				Positive	4.67 < LOD		13.95 < LOD		9.3 < LOD		13.95
1490	10/19/2007 13:47	1.03	WINDOW CASING	WOOD	A	FAIR	BEIGE	BLDG 222 SOUTH BLDG	BASEMENT	EAST ROOM				Negative	4.5 < LOD		0.61 < LOD		0.61 < LOD		3.45
1491	10/19/2007 13:47	1.03	CEILING	WOOD		FAIR	BEIGE	BLDG 222 SOUTH BLDG	BASEMENT	EAST ROOM				Negative	1 < LOD		0.03 < LOD		0.03 < LOD		2.14
1492	10/19/2007 13:47	1.55	FLOOR	CONCRETE		POOR	RED	BLDG 222 SOUTH BLDG	BASEMENT	EAST ROOM				Negative	1.11 < LOD		0.08 < LOD		0.08 < LOD		3.27
1493	10/19/2007 13:48	1.02	DOOR CASING	WOOD		POOR	BEIGE	BLDG 222 SOUTH BLDG	BASEMENT	NORTHEAST ROOM				Negative	1.54 < LOD		0.15 < LOD		0.15 < LOD		2.74
1494	10/19/2007 13:49	1.03	WINDOW	WOOD	B	FAIR	BEIGE	BLDG 222 SOUTH BLDG	BASEMENT	NORTHEAST ROOM				Negative	2.44 < LOD		0.27 < LOD		0.27 < LOD		2.49
1495	10/19/2007 13:49	1.03	WINDOW CASING	WOOD	B	FAIR	BEIGE	BLDG 222 SOUTH BLDG	BASEMENT	NORTHEAST ROOM				Negative	1 < LOD		0.1 < LOD		0.1 < LOD		2.75
1496	10/19/2007 13:49	1.03	WALL	WOOD	C	FAIR	TAN	BLDG 222 SOUTH BLDG	BASEMENT	NORTHEAST ROOM				Negative	1 < LOD		0.08 < LOD		0.08 < LOD		2.85
1497	10/19/2007 13:50	1.03	RADIATOR	METAL	C	FAIR	TAN	BLDG 222 SOUTH BLDG	BASEMENT	NORTHEAST ROOM				Negative	2.89 < LOD		0.29 < LOD		0.29 < LOD		5.21
1498	10/19/2007 13:50	1.03	WALL	WOOD	D	FAIR	BEIGE	BLDG 222 SOUTH BLDG	BASEMENT	NORTHEAST ROOM				Negative	2.37 < LOD		0.31 < LOD		0.31 < LOD		2.65
1499	10/19/2007 13:50	1.03	WALL	WOOD	A	FAIR	BEIGE	BLDG 222 SOUTH BLDG	BASEMENT	NORTHEAST ROOM				Negative	1 < LOD		0.07 < LOD		0.07 < LOD		2.38
1500	10/19/2007 13:51	1.03	RAMP	WOOD		POOR	RED	BLDG 222 SOUTH BLDG	BASEMENT	EAST ROOM				Negative	1 < LOD		0.09 < LOD		0.09 < LOD		3.36
1501	10/19/2007 13:52	1.03	WALL	WOOD	A	FAIR	BEIGE	BLDG 222 SOUTH BLDG	BASEMENT	MIDDLE ROOM				Negative	1 < LOD		0.1 < LOD		0.1 < LOD		2.78
1502	10/19/2007 13:53	1.03	WALL	WOOD	B	FAIR	BEIGE	BLDG 222 SOUTH BLDG	BASEMENT	MIDDLE ROOM				Negative	1.95 < LOD		0.24 < LOD		0.24 < LOD		2.73
1503	10/19/2007 13:53	1.03	WALL	WOOD	C	FAIR	TAN	BLDG 222 SOUTH BLDG	BASEMENT	MIDDLE ROOM				Negative	1.72 < LOD		0.2 < LOD		0.2 < LOD		2.82
1504	10/19/2007 13:53	2.05	WALL	DRYWALL	D	FAIR	BEIGE	BLDG 222 SOUTH BLDG	BASEMENT	MIDDLE ROOM				Negative	1.34 < LOD		0.08 < LOD		0.08 < LOD		1.85
1505	10/19/2007 13:54	1.03	WINDOW	WOOD	C	POOR	TAN	BLDG 222 SOUTH BLDG	BASEMENT	MIDDLE ROOM				Positive	5.02 < LOD		7.8 < LOD		7.65 < LOD		7.8
1506	10/19/2007 13:54	1.03	WINDOW	WOOD	A	POOR	BEIGE	BLDG 222 SOUTH BLDG	BASEMENT	MIDDLE ROOM				Positive	5.42	9.3	5.6 < LOD		8.85	9.3	5.6
1507	10/19/2007 13:54	1.03	DOOR	WOOD	C	POOR	BEIGE	BLDG 222 SOUTH BLDG	BASEMENT	MIDDLE ROOM				Negative	1.16 < LOD		0.14 < LOD		0.14 < LOD		2.82
1508	10/19/2007 13:55	1.03	DOOR CASING	WOOD	C	POOR	BEIGE	BLDG 222 SOUTH BLDG	BASEMENT	MIDDLE ROOM				Negative	2.24 < LOD		0.28 < LOD		0.28 < LOD		2.84
1509	10/19/2007 13:55	1.03	RADIATOR	METAL	A	FAIR	BEIGE	BLDG 222 SOUTH BLDG	BASEMENT	MIDDLE ROOM				Negative	1 < LOD		0.03 < LOD		0.03 < LOD		3.64
1510	10/19/2007 13:56	1.02	RADIATOR	METAL	A	FAIR	BEIGE	BLDG 222 SOUTH BLDG	BASEMENT	WEST ROOM				Negative	3.48 < LOD		0.57 < LOD		0.57 < LOD		4.47
1511	10/19/2007 13:57	2.05	WALL	WOOD	A	FAIR	BEIGE	BLDG 222 SOUTH BLDG	BASEMENT	WEST ROOM				Negative	2.62 < LOD		0.26 < LOD		0.26 < LOD		1.29
1512	10/19/2007 13:57	2.05	WALL	WOOD	D	FAIR	BEIGE	BLDG 222 SOUTH BLDG	BASEMENT	WEST ROOM				Negative	1.65 < LOD		0.14 < LOD		0.14 < LOD		1.35
1513	10/19/2007 13:57	1.54	WALL	WOOD	B	FAIR	BEIGE	BLDG 222 SOUTH BLDG	BASEMENT	WEST ROOM				Negative	2.63 < LOD		0.3 < LOD		0.3 < LOD		1.63
1514	10/19/2007 13:58	1.54	WALL	CONCRETE	C	FAIR	TAN	BLDG 222 SOUTH BLDG	BASEMENT	WEST ROOM				Negative	4.2 < LOD		0.6 < LOD		0.6 < LOD		3.27
1515	10/19/2007 13:58	0.52	CEILING	CONCRETE		FAIR	TAN	BLDG 222 SOUTH BLDG	BASEMENT	WEST ROOM				Null	1.71 < LOD		0.46 < LOD		0.46 < LOD		3.05
1516	10/19/2007 13:59	2.06	CEILING	WOOD		FAIR	TAN	BLDG 222 SOUTH BLDG	BASEMENT	WEST ROOM				Negative	2.67 < LOD		1.24 < LOD		0.32 < LOD		1.24
1517	10/19/2007 14:00	1.03	DOOR	METAL	B	FAIR	BEIGE	BLDG 222 SOUTH BLDG	BASEMENT	WEST ROOM				Negative	1 < LOD		0.03 < LOD		0.03 < LOD		4.36
1518	10/19/2007 14:00	1.02	DOOR CASING	METAL	B	FAIR	BEIGE	BLDG 222 SOUTH BLDG	BASEMENT	WEST ROOM				Negative	1 < LOD		0.03 < LOD		0.03 < LOD		4.67
1519	10/19/2007 14:00	1.03	STAIRS	WOOD	B	POOR	TAN	BLDG 222 SOUTH BLDG	BASEMENT	WEST ROOM				Negative	1.39 < LOD		0.18 < LOD		0.18 < LOD		2.79
1520	10/19/2007 14:01	1.03	STAIR RAILING	WOOD	B	POOR	TAN	BLDG 222 SOUTH BLDG	BASEMENT	WEST ROOM				Negative	2.51 < LOD		0.41 < LOD		0.41 < LOD		3.07
1521	10/19/2007 14:02	1.54	WALL	CONCRETE	A	FAIR	BEIGE	BLDG 222 SOUTH BLDG	BASEMENT	RESTROOM				Positive	3.31	2.7	1.1	2.7	1.1 < LOD		4.35
1522	10/19/2007 14:02	1.54	WALL	BRICK	B	FAIR	BEIGE	BLDG 222 SOUTH BLDG	BASEMENT	RESTROOM				Positive	5.23	2.4	1.3	2.4	1.3 < LOD		3.9
1523	10/19/2007 14:03	1.54	WALL	BRICK	C	FAIR	BEIGE	BLDG 222 SOUTH BLDG	BASEMENT	RESTROOM				Positive	3.93	2.1	1	2.1	1 < LOD		4.35
1524	10/19/2007 14:03	2.59	WALL	BRICK	D	FAIR	TAN	BLDG 222 SOUTH BLDG	BASEMENT	RESTROOM				Positive	4.1	1.8	0.7	1.8	0.7 < LOD		3
1525	10/19/2007 14:03	2.06	CEILING	CONCRETE		FAIR	BEIGE	BLDG 222 SOUTH BLDG	BASEMENT	RESTROOM				Positive	4.26	1.9	0.9	1.9	0.9 < LOD		3.3
1526	10/19/2007 14:04	1.55	DOOR	WOOD	B	FAIR	TAN	BLDG 222 SOUTH BLDG	BASEMENT	RESTROOM				Positive	4.39	4.4	2.4	1.4	0.8	4.4	2.4
1527	10/19/2007 14:04	1.03	DOOR CASING	WOOD	B	FAIR	BEIGE	BLDG 222 SOUTH BLDG	BASEMENT	RESTROOM				Positive	4.29 < LOD		4.8 < LOD		4.8 < LOD		5.55
1528	10/19/2007 14:05	3.6	WALL	WOOD	C	FAIR	BEIGE	BLDG 222 SOUTH BLDG	BASEMENT	SLOP SINK ROOM				Negative	6.85 < LOD		0.86	0.9	0.4 < LOD		0.86
1529	10/19/2007 14:05	3.58	WALL	CONCRETE	A	FAIR	BEIGE	BLDG 222 SOUTH BLDG	BASEMENT	SLOP SINK ROOM				Negative	3.26 < LOD		1.36	0.22	0.11 < LOD		1.36

Reading No	Time	Duration	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Res	Escale 1	Escler CT	Results	Depth Index	PbC	PbC Error	PbL	PbL Error	PbK	PbK Error
1530	10/19/2007 14:06	3.59	WALL	BRICK	D	FAIR	TAN	BLDG 222 SOUTH BLDG	BASEMENT	SLOP SINK ROOM				Negative	3.18 < LOD		1.27	0.13	0.09 < LOD		1.27
1531	10/19/2007 14:06	1.03	WALL	WOOD	B	FAIR	BEIGE	BLDG 222 SOUTH BLDG	BASEMENT	SLOP SINK ROOM				Negative	2.37 < LOD		0.18 < LOD		0.18 < LOD		3.28
1532	10/19/2007 14:07	1.03	DOOR CASING	METAL	C	POOR	BEIGE	BLDG 222 SOUTH BLDG	BASEMENT	SLOP SINK ROOM				Negative	1.17 < LOD		0.05 < LOD		0.05 < LOD		4.73
1533	10/19/2007 14:07	1.03	DOOR	METAL	C	FAIR	BEIGE	BLDG 222 SOUTH BLDG	BASEMENT	SLOP SINK ROOM				Negative	1 < LOD		0.08 < LOD		0.08 < LOD		4.99
1534	10/19/2007 14:08	2.05	WALL	CONCRETE	C	FAIR	WHITE	BLDG 222 SOUTH BLDG	BASEMENT	ROOM NORTH OF SLOP SINK				Negative	3 < LOD		0.07 < LOD		0.07 < LOD		2.66
1535	10/19/2007 14:08	1.02	WALL	CONCRETE	D	POOR	WHITE	BLDG 222 SOUTH BLDG	BASEMENT	ROOM NORTH OF SLOP SINK				Null	1 < LOD		0.05 < LOD		0.05 < LOD		5.04
1536	10/19/2007 14:09	0.52	WALL	CONCRETE	D	POOR	WHITE	BLDG 222 SOUTH BLDG	BASEMENT	ROOM NORTH OF SLOP SINK				Null	1 < LOD		0.03 < LOD		0.03 < LOD		7.09
1537	10/19/2007 14:09	4.61	WALL	CONCRETE	D	POOR	WHITE	BLDG 222 SOUTH BLDG	BASEMENT	ROOM NORTH OF SLOP SINK				Negative	2.91 < LOD		1.12 < LOD		0.04 < LOD		1.12
1538	10/19/2007 14:09	1.54	WALL	BRICK	A	POOR	WHITE	BLDG 222 SOUTH BLDG	BASEMENT	ROOM NORTH OF SLOP SINK				Negative	1 < LOD		0.03 < LOD		0.03 < LOD		3.03
1539	10/19/2007 14:09	3.07	WALL	PLASTER	A	POOR	BEIGE	BLDG 222 SOUTH BLDG	BASEMENT	ROOM NORTH OF SLOP SINK				Negative	1 < LOD		0.03 < LOD		0.03 < LOD		2.05
1540	10/19/2007 14:10	3.61	WALL	BRICK	B	FAIR	BEIGE	BLDG 222 SOUTH BLDG	BASEMENT	ROOM NORTH OF SLOP SINK				Negative	1 < LOD		0.03 < LOD		0.03 < LOD		1.15
1541	10/19/2007 14:10	1.54	CEILING	CONCRETE		FAIR	WHITE	BLDG 222 SOUTH BLDG	BASEMENT	ROOM NORTH OF SLOP SINK				Negative	1 < LOD		0.03 < LOD		0.03 < LOD		3.08
1542	10/19/2007 14:13	1.03	WALL	CONCRETE	A	POOR	BEIGE	BLDG 222 SOUTH BLDG	BASEMENT	BOILER ROOM				Null	1 < LOD		0.03 < LOD		0.03 < LOD		4.94
1543	10/19/2007 14:13	3.08	WALL	CONCRETE	A	POOR	BEIGE	BLDG 222 SOUTH BLDG	BASEMENT	BOILER ROOM				Negative	7.31 < LOD		0.21 < LOD		0.21 < LOD		2.11
1544	10/19/2007 14:14	2.55	WALL	CONCRETE	B	POOR	BEIGE	BLDG 222 SOUTH BLDG	BASEMENT	BOILER ROOM				Negative	1 < LOD		0.03 < LOD		0.03 < LOD		2.28
1545	10/19/2007 14:14	2.57	WALL	CONCRETE	C	POOR	BEIGE	BLDG 222 SOUTH BLDG	BASEMENT	BOILER ROOM				Negative	1.6 < LOD		0.04 < LOD		0.04 < LOD		2.35
1546	10/19/2007 14:14	3.08	WALL	CONCRETE	D	POOR	BEIGE	BLDG 222 SOUTH BLDG	BASEMENT	BOILER ROOM				Negative	1.25 < LOD		0.03 < LOD		0.03 < LOD		2.11
1547	10/19/2007 14:15	1.02	DOOR	METAL	A	POOR	BEIGE	BLDG 222 SOUTH BLDG	BASEMENT	BOILER ROOM				Positive	3.69	10.2	6.5	7.1	4.5	10.2	6.5
1548	10/19/2007 14:15	1.03	DOOR CASING	METAL	A	POOR	BEIGE	BLDG 222 SOUTH BLDG	BASEMENT	BOILER ROOM				Positive	1.66	2.7	1.4	2.7	1.4	< LOD	5.85
1549	10/19/2007 14:16	2.05	CEILING	CONCRETE		POOR	BEIGE	BLDG 222 SOUTH BLDG	BASEMENT	ELECTRICAL ROOM				Negative	1 < LOD		0.03 < LOD		0.03 < LOD		2.75
1550	10/19/2007 14:17	0.52	WALL	CONCRETE	A	POOR	BEIGE	BLDG 222 SOUTH BLDG	BASEMENT	ELECTRICAL ROOM				Null	1 < LOD		0.06 < LOD		0.06 < LOD		7.46
1551	10/19/2007 14:17	2.05	WALL	CONCRETE	A	POOR	BEIGE	BLDG 222 SOUTH BLDG	BASEMENT	ELECTRICAL ROOM				Negative	1 < LOD		0.03 < LOD		0.03 < LOD		2.65
1552	10/19/2007 14:17	0.52	WALL	CONCRETE	B	POOR	BEIGE	BLDG 222 SOUTH BLDG	BASEMENT	ELECTRICAL ROOM				Null	1 < LOD		0.03 < LOD		0.03 < LOD		7.37
1553	10/19/2007 14:17	1.54	WALL	CONCRETE	B	POOR	BEIGE	BLDG 222 SOUTH BLDG	BASEMENT	ELECTRICAL ROOM				Null	1 < LOD		0.03 < LOD		0.03 < LOD		3.1
1554	10/19/2007 14:17	1.54	WALL	CONCRETE	B	POOR	BEIGE	BLDG 222 SOUTH BLDG	BASEMENT	ELECTRICAL ROOM				Negative	1 < LOD		0.03 < LOD		0.03 < LOD		2.99
1555	10/19/2007 14:17	2.58	WALL	CONCRETE	C	POOR	BEIGE	BLDG 222 SOUTH BLDG	BASEMENT	ELECTRICAL ROOM				Negative	2.66 < LOD		0.06 < LOD		0.06 < LOD		2.41
1556	10/19/2007 14:18	2.05	WALL	CONCRETE	D	POOR	BEIGE	BLDG 222 SOUTH BLDG	BASEMENT	ELECTRICAL ROOM				Negative	3.02 < LOD		0.09 < LOD		0.09 < LOD		2.75
1557	10/19/2007 14:20	2.56	WALL	CONCRETE	A	POOR	BEIGE	BLDG 222 SOUTH BLDG	BASEMENT	HIGH VOLTAGE ROOM				Negative	1 < LOD		0.03 < LOD		0.03 < LOD		2.48
1558	10/19/2007 14:20	3.1	WALL	CONCRETE	B	POOR	BEIGE	BLDG 222 SOUTH BLDG	BASEMENT	HIGH VOLTAGE ROOM				Negative	7.18 < LOD		0.21 < LOD		0.21 < LOD		2.23
1559	10/19/2007 14:20	2.05	WALL	CONCRETE	D	POOR	BEIGE	BLDG 222 SOUTH BLDG	BASEMENT	HIGH VOLTAGE ROOM				Negative	4.43 < LOD		0.15 < LOD		0.15 < LOD		2.68
1560	10/19/2007 14:20	1.03	DOOR CASING	METAL	C	POOR	BLACK	BLDG 222 SOUTH BLDG	BASEMENT	HIGH VOLTAGE ROOM				Negative	1 < LOD		0.03 < LOD		0.03 < LOD		5.03
1561	10/19/2007 14:22	0.52	STAIR RAILING	METAL	B	POOR	BROWN	BLDG 222 SOUTH BLDG	BASEMENT	STAIRWELL TO BOILER				Positive	1.86 < LOD		6 < LOD		6 < LOD		17.25
1562	10/19/2007 14:23	1.03	WALL FRAME	WOOD	B	POOR	WHITE	BLDG 222 SOUTH BLDG	BASEMENT	STAIRWELL TO BOILER				Negative	1 < LOD		0.05 < LOD		0.05 < LOD		2.62
1563	10/19/2007 14:23	1.03	DOOR	METAL	A	FAIR	WHITE	BLDG 222 SOUTH BLDG	BASEMENT	STAIRWELL TO BOILER				Negative	1 < LOD		0.03 < LOD		0.03 < LOD		4.45
1564	10/19/2007 14:23	2.57	DOOR CASING	METAL	A	FAIR	WHITE	BLDG 222 SOUTH BLDG	BASEMENT	STAIRWELL TO BOILER				Negative	4.15 < LOD		0.05 < LOD		0.05 < LOD		2.1
1565	10/19/2007 14:24	1.03	CEILING	WOOD		FAIR	WHITE	BLDG 222 SOUTH BLDG	BASEMENT	STAIRWELL TO BOILER				Negative	1 < LOD		0.03 < LOD		0.03 < LOD		3.05
1566	10/19/2007 14:29	0.52			CALIBRATE		YELLOW	BLDG 222 SOUTH BLDG	BASEMENT	STAIRWELL TO BOILER				Positive	1.33	3.7	2.2	3.7	2.2	< LOD	9
1567	10/19/2007 14:30	15.9			CALIBRATE		RED	BLDG 222 SOUTH BLDG	BASEMENT	STAIRWELL TO BOILER				Null	1.1	1	0.1	1	0.1	< LOD	0.46
1568	10/19/2007 14:30	6.67			CALIBRATE		RED	BLDG 222 SOUTH BLDG	BASEMENT	STAIRWELL TO BOILER				Negative	1.03	0.9	0.1	0.9	0.1	< LOD	0.74
1569	10/19/2007 14:30	1.03			CALIBRATE		GREEN	BLDG 222 SOUTH BLDG	BASEMENT	STAIRWELL TO BOILER				Negative	1 < LOD		0.39 < LOD		0.39 < LOD		3.79
1	10/23/2007 7:54	42.05									426.54	4.56	2.32			10.73	0	1.42	0	0	0
2	10/23/2007 7:55	1.03			CALIBRATE		WHITE							Negative	1 < LOD		0.04 < LOD		0.04 < LOD		3.47
3	10/23/2007 7:55	10.27			CALIBRATE		RED							Positive	1.13	1.1	0.1	1.1	0.1	< LOD	0.64
4	10/23/2007 7:56	1.01			CALIBRATE		GREEN							Negative	1 < LOD		0.38 < LOD		0.38 < LOD		3.9
5	10/23/2007 7:56	1.02			CALIBRATE		GREEN							Negative	1.15 < LOD		0.46 < LOD		0.46 < LOD		4.21
6	10/23/2007 8:01	1.02	COAL TRAP	METAL	B	POOR	SILVER	BLDG 222 NORTHEAST BLDG		OUTSIDE				Negative	1 < LOD		0.03 < LOD		0.03 < LOD		5.1
7	10/23/2007 8:02	0.51	FASCIA	WOOD	B	POOR	WHITE	BLDG 222 NORTHEAST BLDG		OUTSIDE				Positive	2.64	33.4	19.4	< LOD	24	33.4	19.4
8	10/23/2007 8:02	0.51	SOFFIT	WOOD	B	POOR	WHITE	BLDG 222 NORTHEAST BLDG		OUTSIDE				Positive	2.38	32.8	19.8	< LOD	33.6	32.8	19.8
9	10/23/2007 8:03	0.51	WINDOW SILL	WOOD	B	POOR	WHITE	BLDG 222 NORTHEAST BLDG		OUTSIDE				Positive	4.05	40	21.9	< LOD	32.25	40	21.9
10	10/23/2007 8:03	0.51	WINDOW SILL	CONCRETE	B	POOR	WHITE	BLDG 222 NORTHEAST BLDG		OUTSIDE				Positive	6.49 < LOD		28.95 < LOD		372 < LOD		28.95
11	10/23/2007 8:03	0.51	WINDOW	WOOD	B	POOR	WHITE	BLDG 222 NORTHEAST BLDG		OUTSIDE				Positive	2.69 < LOD		21.45 < LOD		16.2 < LOD		21.45
12	10/23/2007 8:03	0.51	WINDOW CASING	WOOD	B	POOR	WHITE	BLDG 222 NORTHEAST BLDG		OUTSIDE				Positive	3.3	31.4	18.9	< LOD	618.9	31.4	18.9
13	10/23/2007 8:04	0.51	PANEL	WOOD	B	POOR	WHITE	BLDG 222 NORTHEAST BLDG		OUTSIDE				Positive	1.61 < LOD		21.9 < LOD		12 < LOD		21.9
14	10/23/2007 8:05	1.53	WALL	BRICK	B	POOR	WHITE	BLDG 222 NORTHEAST BLDG		OUTSIDE				Negative	1.15 < LOD		0.08 < LOD		0.08 < LOD		3.29
15	10/23/2007 8:06	2.05	EXHAUST PANEL	CONCRETE	B	FAIR	WHITE	BLDG 222 NORTHEAST BLDG		OUTSIDE				Negative	1.3 < LOD		0.04 < LOD		0.04 < LOD		2.82

Reading No	Time	Duration	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Res	Escale 1	Escler CT	Results	Depth Index	PbC	PbC Error	PbL	PbL Error	PbK	PbK Error
16	10/23/2007 8:07	1.03	CHIMNEY	METAL	B	POOR	WHITE	BLDG 222 NORTHEAST BLDG		OUTSIDE				Negative	1.78	< LOD	0.28	< LOD	0.28	< LOD	3.65
17	10/23/2007 8:07	0.51	CHIMNEY PANEL	WOOD	B	POOR	WHITE	BLDG 222 NORTHEAST BLDG		OUTSIDE				Positive	2.62	< LOD	21.3	< LOD	28.2	< LOD	21.3
18	10/23/2007 8:08	0.51	FASCIA	WOOD	C	POOR	WHITE	BLDG 222 NORTHEAST BLDG		OUTSIDE				Positive	2.19	42.4	23.1	< LOD	14.4	42.4	23.1
19	10/23/2007 8:08	0.51	SOFFIT	WOOD	C	POOR	WHITE	BLDG 222 NORTHEAST BLDG		OUTSIDE				Positive	2.17	36.1	20.1	< LOD	12.15	36.1	20.1
20	10/23/2007 8:09	0.51	SOFFIT	WOOD	D	POOR	WHITE	BLDG 222 NORTHEAST BLDG		OUTSIDE				Positive	2.76	43.3	23.8	< LOD	26.25	43.3	23.8
21	10/23/2007 8:09	0.52	FASCIA	WOOD	D	POOR	WHITE	BLDG 222 NORTHEAST BLDG		OUTSIDE				Positive	2.53	29.9	18	< LOD	17.85	29.9	18
22	10/23/2007 8:10	0.51	WINDOW	WOOD	D	POOR	WHITE	BLDG 222 NORTHEAST BLDG		OUTSIDE				Positive	2.18	< LOD	6.9	< LOD	6.9	< LOD	13.2
23	10/23/2007 8:10	1.03	WINDOW SILL	WOOD	D	POOR	WHITE	BLDG 222 NORTHEAST BLDG		OUTSIDE				Positive	2.02	3	1.6	3	1.6	< LOD	5.85
24	10/23/2007 8:11	1.02	WINDOW SILL	CONCRETE	D	POOR	WHITE	BLDG 222 NORTHEAST BLDG		OUTSIDE				Null	2.04	< LOD	1.05	< LOD	1.05	< LOD	6.94
25	10/23/2007 8:11	11.28	WINDOW SILL	CONCRETE	D	POOR	WHITE	BLDG 222 NORTHEAST BLDG		OUTSIDE				Negative	1.94	0.9	0.1	0.9	0.1	1	0.6
26	10/23/2007 8:12	1.02	WINDOW BARS	METAL	D	POOR	WHITE	BLDG 222 NORTHEAST BLDG		OUTSIDE				Positive	2.79	3.6	2	3.6	2	9.2	6.1
27	10/23/2007 8:12	0.51	DOOR	WOOD	D	POOR	WHITE	BLDG 222 NORTHEAST BLDG		OUTSIDE				Positive	2.57	26.9	16.6	< LOD	66.6	26.9	16.6
28	10/23/2007 8:12	0.51	DOOR CASING	WOOD	D	POOR	WHITE	BLDG 222 NORTHEAST BLDG		OUTSIDE				Positive	2.31	30.1	17.8	< LOD	28.8	30.1	17.8
29	10/23/2007 8:14	0.51	WINDOW	WOOD	D	POOR	WHITE	BLDG 222 EAST BLDG		OUTSIDE				Positive	2.42	35	20.2	< LOD	14.7	35	20.2
30	10/23/2007 8:14	0.51	WINDOW CASING	WOOD	D	POOR	WHITE	BLDG 222 EAST BLDG		OUTSIDE				Positive	2.45	37.2	21	< LOD	18.15	37.2	21
31	10/23/2007 8:15	1.03	WINDOW BARS	METAL	D	POOR	WHITE	BLDG 222 EAST BLDG		OUTSIDE				Negative	1.41	< LOD	0.48	< LOD	0.48	< LOD	5.01
32	10/23/2007 8:15	2.54	WINDOW SILL	CONCRETE	D	POOR	WHITE	BLDG 222 EAST BLDG		OUTSIDE				Null	2.06	0.6	0.3	0.6	0.3	< LOD	2.91
33	10/23/2007 8:15	3.58	WINDOW SILL	CONCRETE	D	POOR	WHITE	BLDG 222 EAST BLDG		OUTSIDE				Negative	2.18	0.8	0.2	0.8	0.2	< LOD	1.65
34	10/23/2007 8:16	0.52	DOWN SPOUT	METAL	D	POOR	WHITE	BLDG 222 EAST BLDG		OUTSIDE				Positive	1.94	< LOD	17.1	< LOD	9.3	< LOD	17.1
35	10/23/2007 8:16	1.03	DOWN SPOUT	METAL	D	POOR	BROWN	BLDG 222 EAST BLDG		OUTSIDE				Positive	1.6	2.2	1.1	2.2	1.1	< LOD	6.15
36	10/23/2007 8:16	0.51	GARAGE DOOR	WOOD	D	POOR	WHITE	BLDG 222 EAST BLDG		OUTSIDE				Positive	2.36	31.5	18.7	< LOD	66	31.5	18.7
37	10/23/2007 8:17	0.51	GARAGE DOOR CASING	WOOD	D	POOR	WHITE	BLDG 222 EAST BLDG		OUTSIDE				Positive	2.19	30.9	18.1	< LOD	27.45	30.9	18.1
38	10/23/2007 8:19	0.51	GARAGE DOOR CASING	WOOD	B	POOR	WHITE	BLDG 222 EAST BLDG		OUTSIDE				Positive	2.86	31.1	18.9	< LOD	29.4	31.1	18.9
39	10/23/2007 8:19	0.51	GARAGE DOOR	WOOD	B	POOR	WHITE	BLDG 222 EAST BLDG		OUTSIDE				Positive	2.58	26.9	16.8	< LOD	18	26.9	16.8
40	10/23/2007 8:19	0.51	WINDOW	WOOD	B	POOR	WHITE	BLDG 222 EAST BLDG		OUTSIDE				Positive	2	< LOD	20.85	< LOD	11.85	< LOD	20.85
41	10/23/2007 8:20	0.51	WINDOW SILL	WOOD	B	POOR	WHITE	BLDG 222 EAST BLDG		OUTSIDE				Positive	2.41	36.6	21.3	< LOD	47.55	36.6	21.3
42	10/23/2007 8:20	12.3	WINDOW SILL	CONCRETE	B	POOR	WHITE	BLDG 222 EAST BLDG		OUTSIDE				Negative	1.88	0.9	0.1	0.9	0.1	< LOD	0.9
43	10/23/2007 8:21	1.01	WINDOW BARS	METAL	B	POOR	WHITE	BLDG 222 EAST BLDG		OUTSIDE				Negative	1.87	< LOD	0.52	< LOD	0.52	< LOD	5.6
44	10/23/2007 8:21	0.51	DOWN SPOUT	METAL	B	POOR	WHITE	BLDG 222 EAST BLDG		OUTSIDE				Positive	1.49	< LOD	15.15	6.1	3.7	< LOD	15.15
45	10/23/2007 8:22	1.04	DOWN SPOUT	METAL	B	POOR	BROWN	BLDG 222 EAST BLDG		OUTSIDE				Negative	1	< LOD	0.06	< LOD	0.06	< LOD	3.67
46	10/23/2007 8:24	1.02	WALL	CONCRETE	C	POOR	RED	BLDG 222 LINK		OUTSIDE				Negative	1.21	< LOD	0.17	< LOD	0.17	< LOD	5.74
47	10/23/2007 8:24	1.02	DOOR	METAL	C	POOR	BROWN	BLDG 222 LINK		OUTSIDE				Negative	1	< LOD	0.06	< LOD	0.06	< LOD	5.1
48	10/23/2007 8:25	1.03	DOOR CASING	METAL	C	POOR	BROWN	BLDG 222 LINK		OUTSIDE				Negative	1	< LOD	0.04	< LOD	0.04	< LOD	5.49
49	10/23/2007 8:25	1.03	STAIR RAILING	METAL	C	POOR	BROWN	BLDG 222 LINK		OUTSIDE				Negative	1	< LOD	0.08	< LOD	0.08	< LOD	5.23
50	10/23/2007 8:25	1.03	STAIR RISER	METAL	C	POOR	BROWN	BLDG 222 LINK		OUTSIDE				Negative	1	< LOD	0.03	< LOD	0.03	< LOD	5.45
			LOADING DOCK																		
51	10/23/2007 8:27	1.01	BRACKETS	METAL	C	POOR	TAN	BLDG 222 LINK		OUTSIDE				Negative	1	< LOD	0.03	< LOD	0.03	< LOD	5.73
52	10/23/2007 8:28	0.51	WINDOW	METAL	D	POOR	WHITE	BLDG 222 WEST BLDG		OUTSIDE				Positive	1.83	< LOD	23.4	< LOD	13.2	< LOD	23.4
53	10/23/2007 8:29	1.54	WALL	CONCRETE	D	POOR	WHITE	BLDG 222 WEST BLDG		OUTSIDE				Negative	2.86	< LOD	0.33	< LOD	0.33	< LOD	3.61
54	10/23/2007 8:30	1.03	GARAGE DOOR	WOOD	D	POOR	WHITE	BLDG 222 WEST BLDG		OUTSIDE				Negative	1	< LOD	0.1	< LOD	0.1	< LOD	3.05
55	10/23/2007 8:30	0.52	GARAGE DOOR CASING	METAL	D	POOR	WHITE	BLDG 222 WEST BLDG		OUTSIDE				Positive	3.1	< LOD	21.45	< LOD	20.4	< LOD	21.45
56	10/23/2007 8:31	1.01	LADDER	METAL	D	POOR	SILVER	BLDG 222 WEST BLDG		OUTSIDE				Negative	1	< LOD	0.04	< LOD	0.04	< LOD	5.46
57	10/23/2007 8:33	0.51	GARAGE DOOR	WOOD	C	POOR	WHITE	BLDG 222 WEST BLDG		OUTSIDE				Positive	2.11	< LOD	10.95	< LOD	10.95	< LOD	12
58	10/23/2007 8:33	0.51	GARAGE DOOR CASING	WOOD	C	POOR	WHITE	BLDG 222 WEST BLDG		OUTSIDE				Positive	1.85	< LOD	14.55	5.8	3.8	< LOD	14.55
59	10/23/2007 8:36	4.09	RAILING	METAL	C	POOR	BROWN	BLDG 222 WEST BLDG		OUTSIDE				Positive	1.22	1.2	0.2	1.2	0.2	1.7	1
60	10/23/2007 8:37	0.51	WINDOW	METAL	B	POOR	WHITE	BLDG 222 WEST BLDG		OUTSIDE				Positive	2.2	< LOD	21.75	< LOD	13.05	< LOD	21.75
61	10/23/2007 8:38	1.03	WINDOW CAGE	METAL	B	FAIR	WHITE	BLDG 222 WEST BLDG		OUTSIDE				Negative	4.64	< LOD	0.43	< LOD	0.43	< LOD	5.67
62	10/23/2007 8:39	11.22	STAIR RAILING	METAL	B	FAIR	BROWN	BLDG 222 WEST BLDG		OUTSIDE				Positive	1.45	1.1	0.1	1.1	0.1	1.1	0.5
63	10/23/2007 8:39	1.01	DOOR	METAL	B	FAIR	BROWN	BLDG 222 WEST BLDG		OUTSIDE				Negative	1	< LOD	0.03	< LOD	0.03	< LOD	4.85
64	10/23/2007 8:39	1.02	DOOR CASING	METAL	B	FAIR	BROWN	BLDG 222 WEST BLDG		OUTSIDE				Negative	1	< LOD	0.03	< LOD	0.03	< LOD	5.93
65	10/23/2007 8:40	0.51	GARAGE DOOR	WOOD	B	POOR	WHITE	BLDG 222 WEST BLDG		OUTSIDE				Positive	2.23	< LOD	17.55	< LOD	10.5	< LOD	17.55
66	10/23/2007 8:40	0.51	GARAGE DOOR	METAL	B	POOR	WHITE	BLDG 222 WEST BLDG		OUTSIDE				Positive	2.89	< LOD	16.95	< LOD	18.15	< LOD	16.95

Reading No	Time	Duration	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Res	Escale 1	Escler CT	Results	Depth Index	PbC	PbC Error	PbL	PbL Error	PbK	PbK Error
67	10/23/2007 8:41	0.51	GARAGE DOOR CASING ELECTRICAL BOX	METAL	B	FAIR	WHITE	BLDG 222 WEST BLDG		OUTSIDE				Positive	2.51	34.3	20.6 < LOD	17.4	34.3	20.6	
68	10/23/2007 8:42	1.02	POSTS	METAL	B	POOR	YELLOW	BLDG 222 WEST BLDG		OUTSIDE				Negative	3.67	< LOD	1 < LOD	1 < LOD		6.33	
69	10/23/2007 8:43	1.01	STAIRWELL SOFFIT	WOOD	B	POOR	WHITE	BLDG 222 WEST BLDG		OUTSIDE				Negative	1	< LOD	0.05 < LOD	0.05 < LOD		2.7	
70	10/23/2007 8:43	1.01	STAIRWELL FASCIA	WOOD	B	POOR	WHITE	BLDG 222 WEST BLDG		OUTSIDE				Negative	1	< LOD	0.04 < LOD	0.04 < LOD		2.76	
71	10/23/2007 8:44	1.02	STAIRWELL DOOR STAIRWELL DOOR	METAL	A	FAIR	WHITE	BLDG 222 WEST BLDG		OUTSIDE				Negative	1	< LOD	0.03 < LOD	0.03 < LOD		4.95	
72	10/23/2007 8:44	1.03	CASING	METAL	A	FAIR	WHITE	BLDG 222 WEST BLDG		OUTSIDE				Negative	1	< LOD	0.03 < LOD	0.03 < LOD		5.1	
73	10/23/2007 8:45	0.51	WINDOW	WOOD	A	POOR	WHITE	BLDG 222 SOUTH BLDG		OUTSIDE				Positive	2.27	25	16 < LOD	31.65	25	16	
74	10/23/2007 8:46	0.51	WINDOW CASING	WOOD	A	POOR	WHITE	BLDG 222 SOUTH BLDG		OUTSIDE				Positive	2.04	36.9	20.7 < LOD	15	36.9	20.7	
75	10/23/2007 8:46	0.51	WINDOW SILL	WOOD	A	POOR	WHITE	BLDG 222 SOUTH BLDG		OUTSIDE				Positive	5.97	50.7	26.5 < LOD	689.55	50.7	26.5	
76	10/23/2007 8:46	3.05	WINDOW SILL	CONCRETE	A	POOR	WHITE	BLDG 222 SOUTH BLDG		OUTSIDE				Negative	1.55	< LOD	0.14 < LOD	0.14 < LOD		2.52	
77	10/23/2007 8:47	1.03	RAILING	METAL	A	POOR	BROWN	BLDG 222 SOUTH BLDG		OUTSIDE				Negative	1.96	< LOD	0.42 < LOD	0.42 < LOD		5.87	
78	10/23/2007 8:47	1.03	WINDOW PANEL	WOOD	A	POOR	WHITE	BLDG 222 SOUTH BLDG		OUTSIDE				Negative	1	< LOD	0.06 < LOD	0.06 < LOD		2.96	
79	10/23/2007 8:48	1.02	STAIRS	WOOD	A	POOR	RED	BLDG 222 SOUTH BLDG		OUTSIDE				Negative	1	< LOD	0.11 < LOD	0.11 < LOD		3.47	
80	10/23/2007 8:49	1.02	STAIR RISER	METAL	A	FAIR	BROWN	BLDG 222 SOUTH BLDG		OUTSIDE				Negative	1	< LOD	0.03 < LOD	0.03 < LOD		5.88	
81	10/23/2007 8:49	1.02	STAIR RAILING	METAL	A	FAIR	BROWN	BLDG 222 SOUTH BLDG		OUTSIDE				Negative	1	< LOD	0.1 < LOD	0.1 < LOD		6.15	
82	10/23/2007 8:50	1.01	DOOR	METAL	A	FAIR	WHITE	BLDG 222 SOUTH BLDG		OUTSIDE				Negative	1	< LOD	0.06 < LOD	0.06 < LOD		3.39	
83	10/23/2007 8:50	1.02	DOOR CASING	WOOD	A	POOR	WHITE	BLDG 222 SOUTH BLDG		OUTSIDE				Negative	1	< LOD	0.04 < LOD	0.04 < LOD		2.95	
84	10/23/2007 8:51	0.51	DOOR	WOOD	A	POOR	WHITE	BLDG 222 SOUTH BLDG		OUTSIDE				Positive	2.25	< LOD	20.55 < LOD	22.05 < LOD		20.55	
85	10/23/2007 8:51	0.51	DOOR CASING	WOOD	A	POOR	WHITE	BLDG 222 SOUTH BLDG		OUTSIDE				Positive	2.57	42.2	22.9 < LOD	33.6	42.2	22.9	
86	10/23/2007 8:52	0.51	SCREEN DOOR	WOOD	A	POOR	WHITE	BLDG 222 SOUTH BLDG		OUTSIDE				Positive	2.46	< LOD	20.55 < LOD	28.5 < LOD		20.55	
87	10/23/2007 8:52	1.02	PIPE	METAL	A	FAIR	WHITE	BLDG 222 SOUTH BLDG		OUTSIDE				Negative	1	< LOD	0.08 < LOD	0.08 < LOD		5.46	
88	10/23/2007 8:53	0.51	STAIRWELL SIDING	WOOD	D	POOR	WHITE	BLDG 222 SOUTH BLDG		OUTSIDE				Positive	1.99	31.7	18.6 < LOD	21.3	31.7	18.6	
89	10/23/2007 8:54	0.51	STAIRWELL SOFFIT	WOOD	D	POOR	WHITE	BLDG 222 SOUTH BLDG		OUTSIDE				Positive	2.13	29.4	17.7 < LOD	41.7	29.4	17.7	
90	10/23/2007 8:54	0.51	STAIRWELL FASCIA	WOOD	D	POOR	WHITE	BLDG 222 SOUTH BLDG		OUTSIDE				Positive	2.46	25.3	15.7 < LOD	52.35	25.3	15.7	
91	10/23/2007 8:54	0.51	STAIRWELL DOOR STAIRWELL DOOR	WOOD	D	POOR	WHITE	BLDG 222 SOUTH BLDG		OUTSIDE				Positive	2.91	< LOD	22.35 < LOD	21.9 < LOD		22.35	
92	10/23/2007 8:55	1.02	CASING STAIRWELL WINDOW	WOOD	D	POOR	WHITE	BLDG 222 SOUTH BLDG		OUTSIDE				Negative	1	< LOD	0.03 < LOD	0.03 < LOD		3.05	
93	10/23/2007 8:55	0.52	CASING	WOOD	D	POOR	WHITE	BLDG 222 SOUTH BLDG		OUTSIDE				Positive	2.98	33.4	19.1 < LOD	21.6	33.4	19.1	
94	10/23/2007 8:56	0.51	DOWN SPOUT	METAL	D	POOR	WHITE	BLDG 222 SOUTH BLDG		OUTSIDE				Positive	2.57	< LOD	21.6 < LOD	51 < LOD		21.6	
95	10/23/2007 8:57	1.01	DOOR CANOPY	WOOD	A	POOR	WHITE	BLDG 222 SOUTH BLDG		OUTSIDE				Negative	3.26	< LOD	0.21 < LOD	0.21 < LOD		2.7	
96	10/23/2007 9:07	0.51	WINDOW CASING	WOOD	C	POOR	WHITE	BLDG 222 SOUTH BLDG		OUTSIDE				Positive	1.88	25.5	16.1 < LOD	12.75	25.5	16.1	
97	10/23/2007 9:08	2.58	WINDOW SILL	CONCRETE	C	POOR	WHITE	BLDG 222 SOUTH BLDG		OUTSIDE				Positive	3.57	3.3	2.2 0.9	0.4 3.3		2.2	
98	10/23/2007 9:09	1.04	DOWN SPOUT	METAL	C	POOR	WHITE	BLDG 222 SOUTH BLDG		OUTSIDE				Negative	1	< LOD	0.1 < LOD	0.1 < LOD		3.93	
99	10/23/2007 9:09	0.51	WINDOW BARS	METAL	C	POOR	WHITE	BLDG 222 SOUTH BLDG		OUTSIDE				Positive	1.65	2.8	1.8 2.8	1.8 < LOD		10.8	
100	10/23/2007 9:10	0.51	WINDOW	WOOD	C	POOR	WHITE	BLDG 222 SOUTH BLDG		OUTSIDE				Positive	1.93	< LOD	4.05 < LOD	4.05 < LOD		10.2	
101	10/23/2007 9:10	0.51	WINDOW SILL	WOOD	C	POOR	WHITE	BLDG 222 SOUTH BLDG		OUTSIDE				Positive	2.29	< LOD	22.95 < LOD	40.95 < LOD		22.95	
102	10/23/2007 9:11	1.53	WALL	CONCRETE	D	FAIR	RED	BLDG 222 WEST BLDG		OUTSIDE				Negative	1.74	< LOD	0.15 < LOD	0.15 < LOD		3.56	
103	10/23/2007 9:12	1.03	STAIR RAILING	METAL	D	FAIR	SILVER	BLDG 222 WEST BLDG		OUTSIDE				Negative	1	< LOD	0.12 < LOD	0.12 < LOD		5.86	
104	10/23/2007 9:13	1.02	STAIR RISER	METAL	D	FAIR	SILVER	BLDG 222 WEST BLDG		OUTSIDE				Negative	2.47	< LOD	0.68 < LOD	0.68 < LOD		5.84	
105	10/23/2007 9:13	2.04	WALL	CONCRETE	A	FAIR	RED	BLDG 222 LINK		OUTSIDE				Negative	1.24	< LOD	0.09 < LOD	0.09 < LOD		3.04	
106	10/23/2007 9:14	0.51	WINDOW CASING	METAL	A	FAIR	SILVER	BLDG 222 LINK		OUTSIDE				Null	1.16	< LOD	0.34 < LOD	0.34 < LOD		8.53	
107	10/23/2007 9:15	1.02	WINDOW CASING	METAL	A	FAIR	SILVER	BLDG 222 LINK		OUTSIDE				Negative	1.11	< LOD	0.22 < LOD	0.22 < LOD		5.25	
108	10/23/2007 9:16	1.02	STAIR RAILING	METAL	A	FAIR	BROWN	BLDG 222 LINK		OUTSIDE				Negative	1	< LOD	0.03 < LOD	0.03 < LOD		5.4	
109	10/23/2007 9:17	1.02	STAIR RISER	METAL	A	FAIR	BROWN	BLDG 222 LINK		OUTSIDE				Negative	1.42	< LOD	0.1 < LOD	0.1 < LOD		5.63	
110	10/23/2007 9:28	1.53	WALL	BRICK	C	POOR	BEIGE	BLDG 222 WEST BLDG	1ST	NORTH STORAGE				Negative	1.64	< LOD	0.11 < LOD	0.11 < LOD		3.34	
111	10/23/2007 9:31	2.55	WALL	BRICK	D	POOR	BEIGE	BLDG 222 WEST BLDG	1ST	NORTH STORAGE				Negative	2.13	< LOD	0.12 < LOD	0.12 < LOD		2.57	
112	10/23/2007 9:32	2.03	WALL	BRICK	B	POOR	BEIGE	BLDG 222 WEST BLDG	1ST	NORTH STORAGE				Negative	2.65	< LOD	0.14 < LOD	0.14 < LOD		2.71	
113	10/23/2007 9:33	1.02	WALL	WOOD	A	FAIR	BEIGE	BLDG 222 WEST BLDG	1ST	NORTH STORAGE				Negative	1.84	< LOD	0.15 < LOD	0.15 < LOD		3.41	
114	10/23/2007 9:33	1.53	WINDOW	WOOD	A	FAIR	BEIGE	BLDG 222 WEST BLDG	1ST	NORTH STORAGE				Positive	2.73	2.4	0.9 2.4	0.9 < LOD		2.7	
115	10/23/2007 9:33	1.03	WINDOW CASING	WOOD	A	FAIR	BEIGE	BLDG 222 WEST BLDG	1ST	NORTH STORAGE				Negative	1	< LOD	0.08 < LOD	0.08 < LOD		3.43	
116	10/23/2007 9:34	1.02	DOOR	WOOD	A	POOR	WHITE	BLDG 222 WEST BLDG	1ST	NORTH STORAGE				Negative	2.94	< LOD	0.59 < LOD	0.59 < LOD		3.02	
117	10/23/2007 9:35	2.56	STAIRWELL WALL	BRICK	A	FAIR	BEIGE	BLDG 222 WEST BLDG	1ST	NORTH STORAGE				Negative	1.08	< LOD	0.05 < LOD	0.05 < LOD		2.41	

Reading No	Time	Duration	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Res	Escale 1	Escler CT	Results	Depth Index	PbC	PbC Error	PbL	PbL Error	PbK	PbK Error
118	10/23/2007 9:36	1.03	DOOR	METAL	D	FAIR	RED	BLDG 222 WEST BLDG	1ST	NORTH STORAGE				Negative	1 < LOD		0.36 < LOD		0.36 < LOD		5.18
119	10/23/2007 9:36	0.51	DOOR CASING	METAL	D	FAIR	GRAY	BLDG 222 WEST BLDG	1ST	NORTH STORAGE				Positive	1.82 < LOD		3.75 < LOD		3.75 < LOD		11.4
120	10/23/2007 9:37	0.51	ELEVATOR DOOR	METAL	D	FAIR	GRAY	BLDG 222 WEST BLDG	1ST	NORTH STORAGE				Positive	1.91 < LOD		4.95 < LOD		4.95 < LOD		10.2
121	10/23/2007 9:37	0.51	ELEVATOR DOOR	METAL	D	FAIR	YELLOW	BLDG 222 WEST BLDG	1ST	NORTH STORAGE				Positive	1.61	5.2	3.3	5.2	3.3 < LOD		12.3
122	10/23/2007 9:37	0.51	ELEVATOR DOOR	METAL	D	FAIR	BLACK	BLDG 222 WEST BLDG	1ST	NORTH STORAGE				Positive	1.64 < LOD		4.35 < LOD		4.35 < LOD		10.8
			ELEVATOR DOOR																		
123	10/23/2007 9:37	0.51	CASING	METAL	D	FAIR	GRAY	BLDG 222 WEST BLDG	1ST	NORTH STORAGE				Positive	2.11 < LOD		10.35 < LOD		10.35 < LOD		17.25
124	10/23/2007 9:38	1.53	COLUMN	CONCRETE		FAIR	BLUE	BLDG 222 WEST BLDG	1ST	NORTH STORAGE				Negative	1 < LOD		0.03 < LOD		0.03 < LOD		3.41
125	10/23/2007 9:38	1.53	COLUMN	CONCRETE		FAIR	RED	BLDG 222 WEST BLDG	1ST	NORTH STORAGE				Negative	1.24 < LOD		0.12 < LOD		0.12 < LOD		3.36
126	10/23/2007 9:38	1.02	COLUMN	CONCRETE		FAIR	GREEN	BLDG 222 WEST BLDG	1ST	NORTH STORAGE				Null	1 < LOD		0.08 < LOD		0.08 < LOD		5.73
127	10/23/2007 9:39	2.05	COLUMN	CONCRETE		FAIR	GREEN	BLDG 222 WEST BLDG	1ST	NORTH STORAGE				Negative	1.4 < LOD		0.06 < LOD		0.06 < LOD		2.97
128	10/23/2007 9:39	1.52	COLUMN	CONCRETE		FAIR	PURPLE	BLDG 222 WEST BLDG	1ST	NORTH STORAGE				Negative	1.8 < LOD		0.1 < LOD		0.1 < LOD		3.56
129	10/23/2007 9:40	2.03	COLUMN	CONCRETE		FAIR	YELLOW	BLDG 222 WEST BLDG	1ST	NORTH STORAGE				Negative	1.17 < LOD		0.05 < LOD		0.05 < LOD		2.71
130	10/23/2007 9:41	0.51	WINDOW	METAL	B	POOR	SILVER	BLDG 222 WEST BLDG	1ST	NORTH STORAGE				Positive	2.07 < LOD		4.95 < LOD		4.95 < LOD		13.95
131	10/23/2007 9:41	1.53	WINDOW	GLASS	B	POOR	SILVER	BLDG 222 WEST BLDG	1ST	NORTH STORAGE				Negative	1 < LOD		0.03 < LOD		0.03 < LOD		3.11
132	10/23/2007 9:42	1.01	PIPE	METAL	B	FAIR	SILVER	BLDG 222 WEST BLDG	1ST	NORTH STORAGE				Negative	1 < LOD		0.03 < LOD		0.03 < LOD		5.44
133	10/23/2007 9:42	0.51	WALL	CONCRETE	B	FAIR	SILVER	BLDG 222 WEST BLDG	1ST	NORTH STORAGE				Null	1 < LOD		0.11 < LOD		0.11 < LOD		8.01
134	10/23/2007 9:42	1.02	WALL	CONCRETE	B	FAIR	SILVER	BLDG 222 WEST BLDG	1ST	NORTH STORAGE				Null	1 < LOD		0.06 < LOD		0.06 < LOD		5.38
135	10/23/2007 9:43	2.04	WALL	CONCRETE	B	FAIR	SILVER	BLDG 222 WEST BLDG	1ST	NORTH STORAGE				Negative	1.64 < LOD		0.08 < LOD		0.08 < LOD		2.91
136	10/23/2007 9:44	3.6	WINDOW	METAL	D	POOR	SILVER	BLDG 222 WEST BLDG	1ST	NORTH STORAGE				Positive	1	2.1	1 < LOD		0.03	2.1	1
137	10/23/2007 9:44	0.51	GARAGE DOOR	WOOD	C	POOR	GRAY	BLDG 222 WEST BLDG	1ST	NORTH STORAGE				Positive	2.49 < LOD		5.55 < LOD		5.55 < LOD		9
138	10/23/2007 9:45	0.51	GARAGE DOOR CASING	WOOD	C	POOR	WHITE	BLDG 222 WEST BLDG	1ST	NORTH STORAGE				Positive	1.92 < LOD		8.7 < LOD		8.7 < LOD		13.65
139	10/23/2007 9:46	1.53	CEILING	CONCRETE		FAIR	WHITE	BLDG 222 WEST BLDG	1ST	NORTH STORAGE				Negative	1.56 < LOD		0.1 < LOD		0.1 < LOD		3.39
140	10/23/2007 9:47	1.02	RADIATOR	METAL	B	FAIR	GRAY	BLDG 222 WEST BLDG	1ST	NORTH STORAGE				Negative	1 < LOD		0.04 < LOD		0.04 < LOD		4.44
141	10/23/2007 9:49	0.53	WALL	WOOD	C	FAIR	BEIGE	BLDG 222 WEST BLDG	1ST	SOUTH STORAGE				Null	1 < LOD		0.09 < LOD		0.09 < LOD		3.78
142	10/23/2007 9:49	1.53	WALL	WOOD	C	FAIR	BEIGE	BLDG 222 WEST BLDG	1ST	SOUTH STORAGE				Negative	1 < LOD		0.03 < LOD		0.03 < LOD		1.47
143	10/23/2007 9:49	1.02	DOOR	WOOD	C	POOR	WHITE	BLDG 222 WEST BLDG	1ST	SOUTH STORAGE				Negative	1 < LOD		0.15 < LOD		0.15 < LOD		2.23
144	10/23/2007 9:50	1.04	DOOR CASING	WOOD	C	POOR	WHITE	BLDG 222 WEST BLDG	1ST	SOUTH STORAGE				Negative	1.92 < LOD		0.26 < LOD		0.26 < LOD		2.52
145	10/23/2007 9:50	4.08	WINDOW	WOOD	C	FAIR	BEIGE	BLDG 222 WEST BLDG	1ST	SOUTH STORAGE				Negative	3.1	0.7	0.2	0.7	0.2 < LOD		0.9
146	10/23/2007 9:51	1.02	WINDOW CASING	WOOD	C	FAIR	BEIGE	BLDG 222 WEST BLDG	1ST	SOUTH STORAGE				Negative	1 < LOD		0.05 < LOD		0.05 < LOD		2.89
147	10/23/2007 9:52	0.52	WINDOW	METAL	D	FAIR	SILVER	BLDG 222 WEST BLDG	1ST	SOUTH STORAGE				Positive	2.02 < LOD		9.75 < LOD		9.75 < LOD		17.4
148	10/23/2007 9:52	1.03	RADIATOR	METAL	D	FAIR	SILVER	BLDG 222 WEST BLDG	1ST	SOUTH STORAGE				Negative	1 < LOD		0.13 < LOD		0.13 < LOD		5.18
149	10/23/2007 9:53	1.53	WALL	BRICK	D	FAIR	BEIGE	BLDG 222 WEST BLDG	1ST	SOUTH STORAGE				Negative	4.81 < LOD		0.24 < LOD		0.24 < LOD		3.27
150	10/23/2007 9:53	1.02	DOOR	METAL	D	FAIR	GRAY	BLDG 222 WEST BLDG	1ST	SOUTH STORAGE				Negative	1 < LOD		0.18 < LOD		0.18 < LOD		4.65
151	10/23/2007 9:53	1.01	DOOR CASING	METAL	D	FAIR	GRAY	BLDG 222 WEST BLDG	1ST	SOUTH STORAGE				Negative	1.52 < LOD		0.27 < LOD		0.27 < LOD		4.39
152	10/23/2007 9:54	1.54	DOOR CASING	METAL	A	POOR	BEIGE	BLDG 222 WEST BLDG	1ST	SOUTH STORAGE				Positive	5.6	2.9	1.6	2.9	1.6	4	2.6
153	10/23/2007 9:55	1.53	DOOR	METAL	A	POOR	BEIGE	BLDG 222 WEST BLDG	1ST	SOUTH STORAGE				Positive	7.13	3.3	2	3.3	2	4.2	2.7
154	10/23/2007 9:55	20	WALL	BRICK	A	FAIR	BEIGE	BLDG 222 WEST BLDG	1ST	SOUTH STORAGE				Null	6.91	0.8	0.1	0.8	0.1	1.3	0.4
155	10/23/2007 9:56	3.55	WALL	BRICK	B	FAIR	BEIGE	BLDG 222 WEST BLDG	1ST	SOUTH STORAGE				Positive	6.05	1.5	0.5	1.5	0.5	2.5	1.1
156	10/23/2007 9:57	0.51	WINDOW	METAL	B	POOR	SILVER	BLDG 222 WEST BLDG	1ST	SOUTH STORAGE				Positive	1.84 < LOD		3 < LOD		3 < LOD		13.05
157	10/23/2007 9:57	1.53	WINDOW	GLASS	B	POOR	SILVER	BLDG 222 WEST BLDG	1ST	SOUTH STORAGE				Negative	1 < LOD		0.03 < LOD		0.03 < LOD		2.78
158	10/23/2007 9:59	4.61	RADIATOR	METAL	B	POOR	WHITE	BLDG 222 WEST BLDG	1ST	SOUTH STORAGE				Negative	3.06	0.8	0.2	0.8	0.2	1.3	0.8
159	10/23/2007 10:00	2.04	COLUMN	CONCRETE		FAIR	BEIGE	BLDG 222 WEST BLDG	1ST	SOUTH STORAGE				Negative	2.12 < LOD		0.17 < LOD		0.17 < LOD		2.92
160	10/23/2007 10:00	2.05	CEILING	CONCRETE		FAIR	WHITE	BLDG 222 WEST BLDG	1ST	SOUTH STORAGE				Negative	2.95 < LOD		0.27 < LOD		0.27 < LOD		3
161	10/23/2007 10:02	14.82	WALL	BRICK	B	FAIR	BEIGE	BLDG 222 WEST BLDG	1ST	SOUTH STORAGE NW OFFICE				Positive	5.67	1.5	0.5	1	0.2	1.5	0.5
162	10/23/2007 10:03	1.03	WINDOW	METAL	B	POOR	SILVER	BLDG 222 WEST BLDG	1ST	SOUTH STORAGE NW OFFICE				Positive	5.42 < LOD		7.8 < LOD		7.8 < LOD		7.5
163	10/23/2007 10:03	1.53	WINDOW	GLASS	B	POOR	SILVER	BLDG 222 WEST BLDG	1ST	SOUTH STORAGE NW OFFICE				Negative	1 < LOD		0.03 < LOD		0.03 < LOD		2.9
164	10/23/2007 10:03	1.02	SCREEN	WOOD	B	FAIR	WHITE	BLDG 222 WEST BLDG	1ST	SOUTH STORAGE NW OFFICE				Negative	5.43 < LOD		0.87 < LOD		0.87 < LOD		3.12
165	10/23/2007 10:04	4.1	WALL	WOOD	C	FAIR	BEIGE	BLDG 222 WEST BLDG	1ST	SOUTH STORAGE NW OFFICE				Negative	4.11	0.7	0.2	0.7	0.2 < LOD		0.6
166	10/23/2007 10:04	0.51	WALL	WOOD	C	FAIR	PINK	BLDG 222 WEST BLDG	1ST	SOUTH STORAGE NW OFFICE				Null	5.01 < LOD		2.25 < LOD		2.25 < LOD		5.4
167	10/23/2007 10:04	6.63	WALL	WOOD	C	FAIR	PINK	BLDG 222 WEST BLDG	1ST	SOUTH STORAGE NW OFFICE				Negative	4.82	0.7	0.2	0.7	0.2	0.7	0.4
168	10/23/2007 10:05	1.52	WINDOW	WOOD	C	FAIR	PINK	BLDG 222 WEST BLDG	1ST	SOUTH STORAGE NW OFFICE				Positive	3.88	2.1	1	2.1	1 < LOD		2.55
169	10/23/2007 10:05	3.59	WINDOW CASING	WOOD	C	FAIR	PINK	BLDG 222 WEST BLDG	1ST	SOUTH STORAGE NW OFFICE				Negative	4.29	0.7	0.2	0.7	0.2	1	0.6
170	10/23/2007 10:05	1.03	WINDOW	WOOD	B	FAIR	PINK	BLDG 222 WEST BLDG	1ST	SOUTH STORAGE NW OFFICE				Negative	1.63 < LOD		0.19 < LOD		0.19 < LOD		2.83

Reading No	Time	Duration	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Res	Escale 1	Escl CT	Results	Depth Index	PbC	PbC Error	PbL	PbL Error	PbK	PbK Error
171	10/23/2007 10:06	1.02	DOOR CASING	WOOD	B	FAIR	PINK	BLDG 222 WEST BLDG	1ST	SOUTH STORAGE NW OFFICE				Negative	1.69 < LOD		0.2 < LOD		0.2 < LOD		2.85
172	10/23/2007 10:06	1.53	WALL	WOOD	B	POOR	PINK	BLDG 222 WEST BLDG	1ST	SOUTH STORAGE NW OFFICE				Negative	1.47 < LOD		0.11 < LOD		0.11 < LOD		1.62
173	10/23/2007 10:06	1.03	WALL	WOOD	A	FAIR	PINK	BLDG 222 WEST BLDG	1ST	SOUTH STORAGE NW OFFICE				Negative	1.56 < LOD		0.21 < LOD		0.21 < LOD		3.22
174	10/23/2007 10:07	0.51	WINDOW	WOOD	A	FAIR	PINK	BLDG 222 WEST BLDG	1ST	SOUTH STORAGE NW OFFICE				Null	3.22 < LOD		3.3 < LOD		3.3 < LOD		7.05
175	10/23/2007 10:07	1.53	WINDOW	WOOD	A	FAIR	PINK	BLDG 222 WEST BLDG	1ST	SOUTH STORAGE NW OFFICE				Positive	4.03	3.1	1.4	3.1	1.4 < LOD		2.85
176	10/23/2007 10:07	1.03	CEILING	CONCRETE		FAIR	WHITE	BLDG 222 WEST BLDG	1ST	SOUTH STORAGE NW OFFICE				Null	6.43 < LOD		2.1 < LOD		2.1 < LOD		5.85
177	10/23/2007 10:08	8.66	CEILING	CONCRETE		FAIR	WHITE	BLDG 222 WEST BLDG	1ST	SOUTH STORAGE NW OFFICE				Negative	6.19 < LOD		0.92	0.9	0.2 < LOD		0.92
178	10/23/2007 10:11	3.07	WALL	DRYWALL	D	INTACT	WALLPAPER	BLDG 222 WEST BLDG	1ST	SOUTH STORAGE SW OFFICE				Negative	1.67	0.4	0.2	0.4	0.2 < LOD		1.63
179	10/23/2007 10:12	0.51	DOOR	METAL	D	INTACT	BEIGE	BLDG 222 WEST BLDG	1ST	SOUTH STORAGE SW OFFICE				Null	1 < LOD		0.07 < LOD		0.07 < LOD		4.56
180	10/23/2007 10:12	1.02	DOOR	WOOD	D	INTACT	BEIGE	BLDG 222 WEST BLDG	1ST	SOUTH STORAGE SW OFFICE				Negative	1.12 < LOD		0.08 < LOD		0.08 < LOD		3.33
181	10/23/2007 10:12	1.02	DOOR CASING	METAL	D	INTACT	BEIGE	BLDG 222 WEST BLDG	1ST	SOUTH STORAGE SW OFFICE				Negative	1 < LOD		0.03 < LOD		0.03 < LOD		4.79
182	10/23/2007 10:13	1.03	WALL	DRYWALL	C	FAIR	BEIGE	BLDG 222 WEST BLDG	1ST	SOUTH STORAGE SW OFFICE				Negative	1 < LOD		0.04 < LOD		0.04 < LOD		3.04
183	10/23/2007 10:13	8.66	WALL	BRICK	B	FAIR	BEIGE	BLDG 222 WEST BLDG	1ST	SOUTH STORAGE SW OFFICE				Positive	4.45	1.7	0.6	0.9	0.2	1.7	0.6
184	10/23/2007 10:14	0.51	WINDOW	METAL	B	POOR	BEIGE	BLDG 222 WEST BLDG	1ST	SOUTH STORAGE SW OFFICE				Positive	3.1 < LOD		8.1 < LOD		8.1 < LOD		15.3
185	10/23/2007 10:15	9.22	WALL	BRICK	A	FAIR	BEIGE	BLDG 222 WEST BLDG	1ST	SOUTH STORAGE SW OFFICE				Positive	7.32	1.6	0.6	1.2	0.3	1.6	0.6
186	10/23/2007 10:16	1.03	PIPE	METAL	A	POOR	BEIGE	BLDG 222 WEST BLDG	1ST	SOUTH STORAGE SW OFFICE				Negative	1 < LOD		0.04 < LOD		0.04 < LOD		5.1
187	10/23/2007 10:17	3.55	CEILING	CONCRETE	A	FAIR	BLACK	BLDG 222 WEST BLDG	1ST	SOUTH STORAGE SW OFFICE				Null	4.35	0.6	0.2	0.6	0.2 < LOD		1.5
188	10/23/2007 10:18	20	CEILING	CONCRETE	A	FAIR	BLACK	BLDG 222 WEST BLDG	1ST	SOUTH STORAGE SW OFFICE				Null	3.76	1	0.1	1	0.1	1	0.4
189	10/23/2007 10:19	1.03	DOOR	WOOD	B	FAIR	BEIGE	BLDG 222 WEST BLDG	1ST	SOUTH STORAGE RESTROOM				Positive	7.24 < LOD		7.65 < LOD		7.95 < LOD		7.65
190	10/23/2007 10:19	1.02	DOOR CASING	METAL	B	FAIR	BEIGE	BLDG 222 WEST BLDG	1ST	SOUTH STORAGE RESTROOM				Positive	10	9	5.7 < LOD		9.15	9	5.7
191	10/23/2007 10:21	1.03	DOOR CASING	METAL	B	FAIR	BEIGE	BLDG 222 WEST BLDG	1ST	SOUTH STORAGE RESTROOM				Positive	10	8.1	5.3 < LOD		8.7	8.1	5.3
192	10/23/2007 10:25	3.06	WALL	PLASTER	C	FAIR	BEIGE	BLDG 222 WEST BLDG	1ST	SOUTH STORAGE RESTROOM				Negative	1.02 < LOD		0.04 < LOD		0.04 < LOD		2.21
193	10/23/2007 10:25	10.72	WALL	BRICK	C	FAIR	BEIGE	BLDG 222 WEST BLDG	1ST	SOUTH STORAGE RESTROOM				Positive	3.68	1.2	0.2	1.2	0.2 < LOD		0.75
194	10/23/2007 10:26	6.12	WALL	BRICK	D	POOR	BEIGE	BLDG 222 WEST BLDG	1ST	SOUTH STORAGE RESTROOM				Positive	4.36	1.8	0.8	1.2	0.2	1.8	0.8
195	10/23/2007 10:26	9.15	WALL	BRICK	A	POOR	BEIGE	BLDG 222 WEST BLDG	1ST	SOUTH STORAGE RESTROOM				Positive	5.26	1.3	0.2	1.3	0.2	1.5	0.6
196	10/23/2007 10:27	20	WALL	BRICK	B	POOR	BEIGE	BLDG 222 WEST BLDG	1ST	SOUTH STORAGE RESTROOM				Null	4.08	1	0.1	1	0.1	1	0.4
197	10/23/2007 10:27	1.53	WALL	PLASTER	B	FAIR	BEIGE	BLDG 222 WEST BLDG	1ST	SOUTH STORAGE RESTROOM				Null	2.15 < LOD		0.14 < LOD		0.14 < LOD		3.23
198	10/23/2007 10:28	2.04	WALL	PLASTER	B	FAIR	BEIGE	BLDG 222 WEST BLDG	1ST	SOUTH STORAGE RESTROOM				Negative	2.94 < LOD		0.15 < LOD		0.15 < LOD		2.63
199	10/23/2007 10:28	5.11	CEILING	CONCRETE		FAIR	BEIGE	BLDG 222 WEST BLDG	1ST	SOUTH STORAGE RESTROOM				Positive	4.62	1.9	0.8	1.2	0.3	1.9	0.8
200	10/23/2007 10:29	1.01	WINDOW CASING	WOOD	D	POOR	BEIGE	BLDG 222 WEST BLDG	1ST	SOUTH STORAGE RESTROOM				Negative	1 < LOD		0.08 < LOD		0.08 < LOD		2.82
201	10/23/2007 10:29	1.02	SCREEN	WOOD	D	POOR	BEIGE	BLDG 222 WEST BLDG	1ST	SOUTH STORAGE RESTROOM				Negative	1.71 < LOD		0.17 < LOD		0.17 < LOD		2.84
202	10/23/2007 10:36	1.52	WALL	WOOD	A	INTACT	WALLPAPER	BLDG 222 SOUTH BLDG	1ST	NORTHEAST ROOM				Negative	2.58 < LOD		0.45 < LOD		0.45 < LOD		2.26
203	10/23/2007 10:36	2.56	WALL	WOOD	C	INTACT	WALLPAPER	BLDG 222 SOUTH BLDG	1ST	NORTHEAST ROOM				Negative	3.58	0.6	0.3	0.6	0.3 < LOD		1.74
204	10/23/2007 10:36	3.58	WALL	WOOD	B	INTACT	WALLPAPER	BLDG 222 SOUTH BLDG	1ST	NORTHEAST ROOM				Negative	3.68	0.7	0.2	0.7	0.2 < LOD		0.98
205	10/23/2007 10:36	1.53	WALL	WOOD	D	INTACT	WALLPAPER	BLDG 222 SOUTH BLDG	1ST	NORTHEAST ROOM				Negative	2.28 < LOD		0.35 < LOD		0.35 < LOD		2.23
206	10/23/2007 10:37	1.03	WALL TRIM	WOOD	D	INTACT	BROWN	BLDG 222 SOUTH BLDG	1ST	NORTHEAST ROOM				Negative	1.93 < LOD		0.24 < LOD		0.24 < LOD		4.1
207	10/23/2007 10:37	1.53	WALL TRIM	WOOD	C	INTACT	BROWN	BLDG 222 SOUTH BLDG	1ST	NORTHEAST ROOM				Negative	6.48 < LOD		0.63 < LOD		0.63 < LOD		2.12
208	10/23/2007 10:37	1.04	WALL TRIM	WOOD	B	INTACT	BROWN	BLDG 222 SOUTH BLDG	1ST	NORTHEAST ROOM				Negative	1.63 < LOD		0.12 < LOD		0.12 < LOD		4
209	10/23/2007 10:37	1.03	WALL TRIM	WOOD	A	INTACT	BROWN	BLDG 222 SOUTH BLDG	1ST	NORTHEAST ROOM				Negative	1 < LOD		0.06 < LOD		0.06 < LOD		3.72
210	10/23/2007 10:38	1.53	UPPER WALL	WOOD	A	FAIR	BEIGE	BLDG 222 SOUTH BLDG	1ST	NORTHEAST ROOM				Negative	1 < LOD		0.03 < LOD		0.03 < LOD		2.05
211	10/23/2007 10:38	1.02	UPPER WALL	WOOD	D	FAIR	BEIGE	BLDG 222 SOUTH BLDG	1ST	NORTHEAST ROOM				Negative	2.45 < LOD		0.2 < LOD		0.2 < LOD		3.09
212	10/23/2007 10:39	0.51	UPPER WALL	WOOD	C	FAIR	BEIGE	BLDG 222 SOUTH BLDG	1ST	NORTHEAST ROOM				Null	3.36 < LOD		0.4 < LOD		0.4 < LOD		3.67
213	10/23/2007 10:39	1.02	UPPER WALL	WOOD	C	FAIR	BEIGE	BLDG 222 SOUTH BLDG	1ST	NORTHEAST ROOM				Negative	1 < LOD		0.06 < LOD		0.06 < LOD		2.78
214	10/23/2007 10:39	1.53	UPPER WALL	WOOD	B	FAIR	BEIGE	BLDG 222 SOUTH BLDG	1ST	NORTHEAST ROOM				Negative	1 < LOD		0.03 < LOD		0.03 < LOD		2.04
215	10/23/2007 10:39	1.03	RADIATOR	METAL	D	FAIR	WHITE	BLDG 222 SOUTH BLDG	1ST	NORTHEAST ROOM				Negative	1 < LOD		0.03 < LOD		0.03 < LOD		4.46
216	10/23/2007 10:40	1.02	DUCTWORK	METAL		FAIR	RED	BLDG 222 SOUTH BLDG	1ST	NORTHEAST ROOM				Negative	1.58 < LOD		0.11 < LOD		0.11 < LOD		3.95
217	10/23/2007 10:43	1.02	CEILING	WOOD		FAIR	BEIGE	BLDG 222 SOUTH BLDG	1ST	NORTHEAST ROOM				Negative	2.69 < LOD		0.31 < LOD		0.31 < LOD		2.84
218	10/23/2007 10:43	1.02	DOOR CASING	METAL	A	FAIR	BROWN	BLDG 222 SOUTH BLDG	1ST	NORTHEAST ROOM				Negative	1.76 < LOD		0.15 < LOD		0.15 < LOD		4.92
219	10/23/2007 10:44	1.01	DOOR	WOOD	A	FAIR	BROWN	BLDG 222 SOUTH BLDG	1ST	NORTHEAST ROOM				Negative	1 < LOD		0.07 < LOD		0.07 < LOD		2.75
220	10/23/2007 10:57	1.02	DOOR	WOOD	C	FAIR	BEIGE	BLDG 222 SOUTH BLDG	1ST	NORTHWEST ROOM				Negative	4.11 < LOD		0.34 < LOD		0.34 < LOD		2.89
221	10/23/2007 10:57	1.02	DOOR CASING	WOOD	C	FAIR	BEIGE	BLDG 222 SOUTH BLDG	1ST	NORTHWEST ROOM				Negative	1 < LOD		0.07 < LOD		0.07 < LOD		2.88
222	10/23/2007 10:58	1.53	WALL	WOOD	C	INTACT	WALLPAPER	BLDG 222 SOUTH BLDG	1ST	NORTHWEST ROOM				Negative	1 < LOD		0.03 < LOD		0.03 < LOD		2.05
223	10/23/2007 11:00	2.56	WALL	WOOD	D	INTACT	WALLPAPER	BLDG 222 SOUTH BLDG	1ST	NORTHWEST ROOM				Negative	2.63	0.4	0.2	0.4	0.2 < LOD		1.8
224	10/23/2007 11:00	1.53	WALL	WOOD	A	INTACT	WALLPAPER	BLDG 222 SOUTH BLDG	1ST	NORTHWEST ROOM				Negative	2.29 < LOD		0.12 < LOD		0.12 < LOD		1.96
225	10/23/2007 11:00	1.53	WALL	WOOD	B	INTACT	WALLPAPER	BLDG 222 SOUTH BLDG	1ST	NORTHWEST ROOM				Negative	7.06 < LOD		2.22 < LOD		0.39 < LOD		2.22

Reading No	Time	Duration	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Res	Escal 1	Escle CT	Results	Depth Index	PbC	PbC Error	PbL	PbL Error	PbK	PbK Error
226	10/23/2007 11:01	1.53	WINDOW	WOOD	B	FAIR	BEIGE	BLDG 222 SOUTH BLDG	1ST	NORTHWEST ROOM				Positive	6.15	4.3	2.3	5.5	2.8	4.3	2.3
227	10/23/2007 11:01	1.01	WINDOW CASING	WOOD	B	FAIR	BEIGE	BLDG 222 SOUTH BLDG	1ST	NORTHWEST ROOM				Negative	1 < LOD		0.04 < LOD	0.04 < LOD			2.47
228	10/23/2007 11:01	2.56	WINDOW SILL	WOOD	B	FAIR	BEIGE	BLDG 222 SOUTH BLDG	1ST	NORTHWEST ROOM				Negative	7.79 < LOD		0.47 < LOD	0.47 < LOD			1.49
229	10/23/2007 11:02	1.03	DOOR	WOOD	A	FAIR	BROWN	BLDG 222 SOUTH BLDG	1ST	NORTHWEST ROOM				Negative	1 < LOD		0.03 < LOD	0.03 < LOD			2
230	10/23/2007 11:02	1.02	DOOR CASING	WOOD	A	FAIR	BROWN	BLDG 222 SOUTH BLDG	1ST	NORTHWEST ROOM				Negative	1 < LOD		0.04 < LOD	0.04 < LOD			2.77
231	10/23/2007 11:02	1.03	RADIATOR	METAL	B	FAIR	BEIGE	BLDG 222 SOUTH BLDG	1ST	NORTHWEST ROOM				Negative	1 < LOD		0.03 < LOD	0.03 < LOD			3.98
232	10/23/2007 11:03	1.01	RADIATOR	METAL	B	FAIR	BLUE	BLDG 222 SOUTH BLDG	1ST	SOUTHEAST AREA				Negative	1 < LOD		0.03 < LOD	0.03 < LOD			4.45
233	10/23/2007 11:04	0.51	WINDOW	WOOD	B	FAIR	BEIGE	BLDG 222 SOUTH BLDG	1ST	SOUTHEAST AREA				Null	6.52 < LOD		10.2 < LOD	10.05 < LOD			10.2
234	10/23/2007 11:04	0.51	WINDOW	WOOD	B	FAIR	BEIGE	BLDG 222 SOUTH BLDG	1ST	SOUTHEAST AREA				Null	5.43 < LOD		7.8 < LOD	7.8 < LOD			9.3
235	10/23/2007 11:04	1.53	WINDOW	WOOD	B	FAIR	BEIGE	BLDG 222 SOUTH BLDG	1ST	SOUTHEAST AREA				Positive	5.4	4.4	2.2	4.4	2.2	4.7	2.4
236	10/23/2007 11:04	1.01	WINDOW CASING	WOOD	B	FAIR	BEIGE	BLDG 222 SOUTH BLDG	1ST	SOUTHEAST AREA				Negative	1 < LOD		0.07 < LOD	0.07 < LOD			2.8
237	10/23/2007 11:04	2.05	WALL	WOOD	B	FAIR	BLUE	BLDG 222 SOUTH BLDG	1ST	SOUTHEAST AREA				Negative	4.05 < LOD		1.47 < LOD	0.34 < LOD			1.47
238	10/23/2007 11:05	1.02	PIPE	METAL	B	FAIR	BLUE	BLDG 222 SOUTH BLDG	1ST	SOUTHEAST AREA				Positive	10 < LOD		8.85 < LOD	3.3 < LOD			8.85
239	10/23/2007 11:05	1.53	PIPE	METAL	B	FAIR	WHITE	BLDG 222 SOUTH BLDG	1ST	SOUTHEAST AREA				Positive	10	7	3.5 < LOD	2.1	7	3.5	
240	10/23/2007 11:06	1.55	WALL	WOOD	C	FAIR	WHITE	BLDG 222 SOUTH BLDG	1ST	SOUTHEAST AREA				Negative	1 < LOD		0.03 < LOD	0.03 < LOD			2.06
241	10/23/2007 11:06	2.56	WALL	WOOD	C	FAIR	BROWN	BLDG 222 SOUTH BLDG	1ST	SOUTHEAST AREA				Negative	1.06	0.4	0.1	0.4	0.1 < LOD		1.8
242	10/23/2007 11:06	2.56	WALL	WOOD	D	FAIR	BLUE	BLDG 222 SOUTH BLDG	1ST	SOUTHEAST AREA				Null	2.19	1.1	0.4	1.1	0.4 < LOD		1.54
243	10/23/2007 11:06	11.75	WALL	WOOD	D	FAIR	BLUE	BLDG 222 SOUTH BLDG	1ST	SOUTHEAST AREA				Negative	1.92	0.9	0.1	0.9	0.1 < LOD		0.45
244	10/23/2007 11:07	1.03	DOOR	WOOD	D	POOR	WHITE	BLDG 222 SOUTH BLDG	1ST	SOUTHEAST AREA				Positive	8.72 < LOD		6.3 < LOD	6 < LOD			6.3
245	10/23/2007 11:07	1.53	DOOR CASING	WOOD	D	FAIR	WHITE	BLDG 222 SOUTH BLDG	1ST	SOUTHEAST AREA				Positive	4.5	3.3	1.6	3.3	1.6	4.2	2.5
246	10/23/2007 11:08	1.03	WINDOW	WOOD	D	FAIR	WHITE	BLDG 222 SOUTH BLDG	1ST	SOUTHEAST AREA				Positive	5.92 < LOD		6.45 < LOD	6.3 < LOD			6.45
247	10/23/2007 11:08	1.02	WINDOW CASING	WOOD	D	FAIR	WHITE	BLDG 222 SOUTH BLDG	1ST	SOUTHEAST AREA				Negative	5.73 < LOD		0.94 < LOD	0.94 < LOD			3.3
248	10/23/2007 11:09	1.02	WINDOW CASING	WOOD	A	FAIR	WHITE	BLDG 222 SOUTH BLDG	1ST	SOUTHEAST AREA				Negative	1.97 < LOD		0.17 < LOD	0.17 < LOD			2.88
249	10/23/2007 11:09	1.03	WINDOW	WOOD	A	FAIR	WHITE	BLDG 222 SOUTH BLDG	1ST	SOUTHEAST AREA				Positive	4.55 < LOD		6.9 < LOD	5.4 < LOD			6.9
250	10/23/2007 11:09	1.02	PIPE	METAL	A	FAIR	WHITE	BLDG 222 SOUTH BLDG	1ST	SOUTHEAST AREA				Negative	7.33 < LOD		0.73 < LOD	0.73 < LOD			5.55
251	10/23/2007 11:10	5.63	PIPE	METAL	A	POOR	GRAY	BLDG 222 SOUTH BLDG	1ST	SOUTHEAST AREA				Null	7.86	0.9	0.3	0.9	0.3 < LOD		0.8
252	10/23/2007 11:10	5.12	PIPE	METAL	A	POOR	GRAY	BLDG 222 SOUTH BLDG	1ST	SOUTHEAST AREA				Negative	6.49	0.7	0.3	0.7	0.3 < LOD		0.8
253	10/23/2007 11:11	1.02	RADIATOR	METAL	A	POOR	BLUE	BLDG 222 SOUTH BLDG	1ST	SOUTHEAST AREA				Negative	4.3 < LOD		0.3 < LOD	0.3 < LOD			4.87
254	10/23/2007 11:12	2.03	DUCTWORK	METAL		FAIR	RED	BLDG 222 SOUTH BLDG	1ST	SOUTHEAST AREA				Negative	10 < LOD		1.86 < LOD	0.81 < LOD			1.86
255	10/23/2007 11:12	1.02	COLUMN	WOOD		FAIR	GRAY	BLDG 222 SOUTH BLDG	1ST	SOUTHEAST AREA				Negative	1.32 < LOD		0.14 < LOD	0.14 < LOD			3.23
256	10/23/2007 11:13	0.51	COLUMN BRACKET	METAL		FAIR	WHITE	BLDG 222 SOUTH BLDG	1ST	SOUTHEAST AREA				Positive	10 < LOD		22.05 < LOD	35.4 < LOD			22.05
257	10/23/2007 11:14	1.02	WALL	WOOD	A	FAIR	BROWN	BLDG 222 SOUTH BLDG	1ST	SOUTHEAST AREA ROOM				Negative	1 < LOD		0.04 < LOD	0.04 < LOD			2.41
258	10/23/2007 11:14	1.01	WALL	WOOD	B	FAIR	BROWN	BLDG 222 SOUTH BLDG	1ST	SOUTHEAST AREA ROOM				Negative	1 < LOD		0.03 < LOD	0.03 < LOD			2.08
259	10/23/2007 11:14	1.01	WALL	WOOD	C	FAIR	BROWN	BLDG 222 SOUTH BLDG	1ST	SOUTHEAST AREA ROOM				Negative	1 < LOD		0.03 < LOD	0.03 < LOD			2.41
260	10/23/2007 11:14	2.55	WALL	WOOD	C	FAIR	BLUE	BLDG 222 SOUTH BLDG	1ST	SOUTHEAST AREA ROOM				Null	2.64	1.1	0.4	1.1	0.4 < LOD		1.95
261	10/23/2007 11:14	4.09	WALL	WOOD	C	FAIR	BLUE	BLDG 222 SOUTH BLDG	1ST	SOUTHEAST AREA ROOM				Positive	2.96	1.3	0.3	1.3	0.3 < LOD		0.9
262	10/23/2007 11:15	1.02	RADIATOR	METAL	C	FAIR	GRAY	BLDG 222 SOUTH BLDG	1ST	SOUTHEAST AREA ROOM				Negative	1 < LOD		0.03 < LOD	0.03 < LOD			4.75
263	10/23/2007 11:15	1.03	WALL	WOOD	A	FAIR	BROWN	BLDG 222 SOUTH BLDG	1ST	SOUTHEAST AREA ROOM				Negative	1 < LOD		0.05 < LOD	0.05 < LOD			2.28
264	10/23/2007 11:16	1.53	WALL	WOOD	D	FAIR	WHITE	BLDG 222 SOUTH BLDG	1ST	SOUTHEAST AREA STAIRWELL				Positive	8.44	3.7	2.3 < LOD	2.85	3.7	2.3	
265	10/23/2007 11:16	1.52	WALL	WOOD	C	FAIR	WHITE	BLDG 222 SOUTH BLDG	1ST	SOUTHEAST AREA STAIRWELL				Negative	4.22 < LOD		0.6 < LOD	0.6 < LOD			2.06
266	10/23/2007 11:17	1.53	WALL	BRICK	B	FAIR	WHITE	BLDG 222 SOUTH BLDG	1ST	SOUTHEAST AREA STAIRWELL				Positive	2.18	2	0.7	2	0.7 < LOD		3.9
267	10/23/2007 11:17	1.02	WALL	WOOD	A	FAIR	WHITE	BLDG 222 SOUTH BLDG	1ST	SOUTHEAST AREA STAIRWELL				Negative	4.64 < LOD		0.29 < LOD	0.29 < LOD			3.13
268	10/23/2007 11:17	2.56	WALL	CONCRETE	B	FAIR	WHITE	BLDG 222 SOUTH BLDG	1ST	SOUTHEAST AREA STAIRWELL				Negative	1.64 < LOD		0.15 < LOD	0.15 < LOD			2.65
269	10/23/2007 11:18	0.51	DOOR	WOOD	A	FAIR	WHITE	BLDG 222 SOUTH BLDG	1ST	SOUTHEAST AREA STAIRWELL				Positive	2.23 < LOD		10.5 < LOD	10.5 < LOD			14.1
270	10/23/2007 11:18	1.01	DOOR CASING	WOOD	A	FAIR	WHITE	BLDG 222 SOUTH BLDG	1ST	SOUTHEAST AREA STAIRWELL				Negative	1 < LOD		0.05 < LOD	0.05 < LOD			2.99
271	10/23/2007 11:18	0.51	STAIR RAILING	METAL	A	FAIR	WHITE	BLDG 222 SOUTH BLDG	1ST	SOUTHEAST AREA STAIRWELL				Null	1.88 < LOD		0.7 < LOD	0.7 < LOD			7.86
272	10/23/2007 11:18	1.03	STAIR RAILING	METAL	A	FAIR	WHITE	BLDG 222 SOUTH BLDG	1ST	SOUTHEAST AREA STAIRWELL				Null	2.9 < LOD		0.9 < LOD	0.9 < LOD			5.23
273	10/23/2007 11:18	0.51	STAIR RAILING	METAL	A	FAIR	WHITE	BLDG 222 SOUTH BLDG	1ST	SOUTHEAST AREA STAIRWELL				Null	1.82 < LOD		0.71 < LOD	0.71 < LOD			8.1
274	10/23/2007 11:19	1.53	STAIR RAILING	METAL	A	FAIR	WHITE	BLDG 222 SOUTH BLDG	1ST	SOUTHEAST AREA STAIRWELL				Negative	2.61 < LOD		0.46 < LOD	0.46 < LOD			3.3
275	10/23/2007 11:19	1.02	STAIRS	CONCRETE	A	FAIR	GRAY	BLDG 222 SOUTH BLDG	1ST	SOUTHEAST AREA STAIRWELL				Null	2.22 < LOD		0.41 < LOD	0.41 < LOD			5.57
276	10/23/2007 11:19	1.54	STAIRS	CONCRETE	A	FAIR	GRAY	BLDG 222 SOUTH BLDG	1ST	SOUTHEAST AREA STAIRWELL				Negative	2.19 < LOD		0.25 < LOD	0.25 < LOD			3.43
277	10/23/2007 11:20	1.52	WINDOW	WOOD	D	POOR	WHITE	BLDG 222 SOUTH BLDG	1ST	SOUTHEAST AREA STAIRWELL				Null	2.84	1.2	0.6	1.2	0.6 < LOD		2.55
278	10/23/2007 11:20	1.01	WINDOW	WOOD	D	POOR	WHITE	BLDG 222 SOUTH BLDG	1ST	SOUTHEAST AREA STAIRWELL				Positive	3.45 < LOD		3.3 < LOD	3.3 < LOD			5.1
279	10/23/2007 11:20	1.03	WINDOW CASING	WOOD	D	FAIR	WHITE	BLDG 222 SOUTH BLDG	1ST	SOUTHEAST AREA STAIRWELL				Positive	3.48	3.7	2.4	3.7	2.4 < LOD		5.25
280	10/23/2007 11:20	1.02	WINDOW CASING	WOOD	C	FAIR	WHITE	BLDG 222 SOUTH BLDG	1ST	SOUTHEAST											

Reading No	Time	Duration	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Res	Escale 1	Escl CT	Results	Depth Index	PbC	PbC Error	PbL	PbL Error	PbK	PbK Error
281	10/23/2007 11:21	1.03	WINDOW	WOOD	C	POOR	WHITE	BLDG 222 SOUTH BLDG	1ST	SOUTHEAST AREA STAIRWELL				Positive	2.03	2.7	1.4	2.7	1.4 < LOD		5.25
282	10/23/2007 11:21	0.51	CEILING	WOOD		FAIR	WHITE	BLDG 222 SOUTH BLDG	1ST	SOUTHEAST AREA STAIRWELL				Positive	5.25 < LOD		13.2 < LOD		6.15 < LOD		13.2
283	10/23/2007 11:21	0.51	DOOR	WOOD	B	FAIR	WHITE	BLDG 222 SOUTH BLDG	1ST	SOUTHEAST AREA STAIRWELL				Positive	2.55 < LOD		8.25 < LOD		8.25 < LOD		9.75
284	10/23/2007 11:22	0.51	DOOR CASING	METAL	B	FAIR	WHITE	BLDG 222 SOUTH BLDG	1ST	SOUTHEAST AREA STAIRWELL				Positive	2.93 < LOD		17.7 < LOD		6.9 < LOD		17.7
285	10/23/2007 11:23	3.58	WALL	PLASTER	A	FAIR	BLUE	BLDG 222 SOUTH BLDG	1ST	CENTER ROOM				Negative	10 < LOD		1.26 < LOD		0.45 < LOD		1.26
286	10/23/2007 11:23	1.02	WALL	PLASTER	C	FAIR	BLUE	BLDG 222 SOUTH BLDG	1ST	CENTER ROOM				Negative	7.11 < LOD		1.04 < LOD		1.04 < LOD		5.1
287	10/23/2007 11:24	1.02	WALL	PLASTER	D	FAIR	BLUE	BLDG 222 SOUTH BLDG	1ST	CENTER ROOM				Null	10 < LOD		3.15 < LOD		3.15 < LOD		9
288	10/23/2007 11:24	1.02	WALL	PLASTER	D	FAIR	BLUE	BLDG 222 SOUTH BLDG	1ST	CENTER ROOM				Positive	10 < LOD		9 < LOD		3.9 < LOD		9
289	10/23/2007 11:24	20	WALL	PLASTER	B	FAIR	BLUE	BLDG 222 SOUTH BLDG	1ST	CENTER ROOM				Null	4.4	0.6	0.1	0.6	0.1	1.2	0.4
290	10/23/2007 11:25	0.51	WINDOW	WOOD	C	FAIR	WHITE	BLDG 222 SOUTH BLDG	1ST	CENTER ROOM				Positive	4.11 < LOD		23.25 < LOD		1.95 < LOD		23.25
291	10/23/2007 11:25	0.51	WINDOW CASING	WOOD	C	FAIR	WHITE	BLDG 222 SOUTH BLDG	1ST	CENTER ROOM				Positive	4.02 < LOD		22.5 < LOD		2.1 < LOD		22.5
292	10/23/2007 11:26	0.51	WINDOW SILL	WOOD	C	POOR	WHITE	BLDG 222 SOUTH BLDG	1ST	CENTER ROOM				Positive	5.83 < LOD		20.55 < LOD		3 < LOD		20.55
293	10/23/2007 11:26	1.02	WINDOW SILL	WOOD	A	POOR	WHITE	BLDG 222 SOUTH BLDG	1ST	CENTER ROOM				Positive	9.88 < LOD		7.05 < LOD		3.75 < LOD		7.05
294	10/23/2007 11:26	0.51	WINDOW	WOOD	A	POOR	WHITE	BLDG 222 SOUTH BLDG	1ST	CENTER ROOM				Positive	5.59 < LOD		18 < LOD		2.4 < LOD		18
295	10/23/2007 11:26	0.51	WINDOW CASING	WOOD	A	FAIR	WHITE	BLDG 222 SOUTH BLDG	1ST	CENTER ROOM				Positive	5.83 < LOD		17.1 < LOD		2.4 < LOD		17.1
296	10/23/2007 11:27	1.03	DOOR	METAL	A	FAIR	WHITE	BLDG 222 SOUTH BLDG	1ST	CENTER ROOM				Negative	1 < LOD		0.05 < LOD		0.05 < LOD		3.01
297	10/23/2007 11:27	1.02	DOOR CASING	METAL	A	FAIR	WHITE	BLDG 222 SOUTH BLDG	1ST	CENTER ROOM				Negative	1 < LOD		0.04 < LOD		0.04 < LOD		2.61
298	10/23/2007 11:28	1.02	DUCTWORK	METAL		FAIR	RED	BLDG 222 SOUTH BLDG	1ST	CENTER ROOM				Negative	1.3 < LOD		0.1 < LOD		0.1 < LOD		3.57
299	10/23/2007 11:28	1.53	COLUMN	WOOD		FAIR	BLUE	BLDG 222 SOUTH BLDG	1ST	CENTER ROOM				Positive	4.42	3.7	2.4 < LOD		0.38	3.7	2.4
300	10/23/2007 11:28	0.51	COLUMN BRACKET	METAL		FAIR	WHITE	BLDG 222 SOUTH BLDG	1ST	CENTER ROOM				Positive	4.01 < LOD		17.7 < LOD		1.16 < LOD		17.7
301	10/23/2007 11:29	0.51	CEILING BEAM	WOOD		FAIR	WHITE	BLDG 222 SOUTH BLDG	1ST	CENTER ROOM				Positive	10 < LOD		16.65 < LOD		5.85 < LOD		16.65
302	10/23/2007 11:30	1.02	DOOR CASING	WOOD	D	FAIR	WHITE	BLDG 222 SOUTH BLDG	1ST	CENTER ROOM				Negative	1 < LOD		0.07 < LOD		0.07 < LOD		2.93
303	10/23/2007 11:30	0.51	STAIR RISER	WOOD	D	FAIR	WHITE	BLDG 222 SOUTH BLDG	1ST	CENTER ROOM				Positive	5.59	27.6	16.9 < LOD		9.75	27.6	16.9
304	10/23/2007 11:31	0.51	DOOR CASING	WOOD	D	FAIR	WHITE	BLDG 222 SOUTH BLDG	1ST	CENTER ROOM				Null	7.48 < LOD		4.35 < LOD		4.35 < LOD		6.3
305	10/23/2007 11:31	1.53	DOOR CASING	WOOD	D	FAIR	WHITE	BLDG 222 SOUTH BLDG	1ST	CENTER ROOM				Null	6.27 < LOD		1.5 < LOD		1.5 < LOD		2.7
306	10/23/2007 11:31	4.07	DOOR CASING	WOOD	D	FAIR	WHITE	BLDG 222 SOUTH BLDG	1ST	CENTER ROOM				Positive	5.47	1.8	0.7	1.1	0.3	1.8	0.7
307	10/23/2007 11:32	0.51	DOOR CASING	WOOD	B	POOR	WHITE	BLDG 222 SOUTH BLDG	1ST	STAIRWELL OFF OF CENTER ROOM				Positive	10 < LOD		19.05 < LOD		6 < LOD		19.05
308	10/23/2007 11:32	0.51	DOOR	WOOD	B	POOR	WHITE	BLDG 222 SOUTH BLDG	1ST	STAIRWELL OFF OF CENTER ROOM				Positive	5.64 < LOD		16.05 < LOD		6 < LOD		16.05
309	10/23/2007 11:33	4.09	WINDOW	WOOD	B	POOR	WHITE	BLDG 222 SOUTH BLDG	1ST	STAIRWELL OFF OF CENTER ROOM				Negative	2.14	0.8	0.2	0.8	0.2 < LOD		0.6
310	10/23/2007 11:33	5.6	WINDOW SILL	WOOD	B	POOR	WHITE	BLDG 222 SOUTH BLDG	1ST	STAIRWELL OFF OF CENTER ROOM				Null	3.09	1	0.2	1	0.2	1.2	0.5
311	10/23/2007 11:33	5.13	WINDOW SILL	WOOD	B	POOR	WHITE	BLDG 222 SOUTH BLDG	1ST	STAIRWELL OFF OF CENTER ROOM				Negative	2.71	0.8	0.2	0.8	0.2	1.1	0.5
312	10/23/2007 11:34	1.53	WINDOW CASING	WOOD	B	POOR	WHITE	BLDG 222 SOUTH BLDG	1ST	STAIRWELL OFF OF CENTER ROOM				Negative	2.27	0.5	0.3	0.5	0.3 < LOD		1.95
313	10/23/2007 11:34	19.93	WINDOW CASING	WOOD	D	POOR	WHITE	BLDG 222 SOUTH BLDG	1ST	STAIRWELL OFF OF CENTER ROOM				Positive	2.66	1	0.1	1	0.1	1	0.3
314	10/23/2007 11:35	2.56	WINDOW SILL	WOOD	D	POOR	WHITE	BLDG 222 SOUTH BLDG	1ST	STAIRWELL OFF OF CENTER ROOM				Negative	1.96	0.7	0.3	0.7	0.3 < LOD		1.8
315	10/23/2007 11:35	1.54	WINDOW	WOOD	D	POOR	WHITE	BLDG 222 SOUTH BLDG	1ST	STAIRWELL OFF OF CENTER ROOM				Negative	1.91	0.5	0.3	0.5	0.3 < LOD		2.4
316	10/23/2007 11:35	1.02	RAILING	METAL		POOR	TAN	BLDG 222 SOUTH BLDG	1ST	STAIRWELL OFF OF CENTER ROOM				Negative	1.04 < LOD		0.13 < LOD		0.13 < LOD		5.55
317	10/23/2007 11:36	7.13	WINDOW SILL	CONCRETE	B	FAIR	WHITE	BLDG 222 SOUTH BLDG	1ST	STAIRWELL OFF OF CENTER ROOM				Null	4.75	0.5	0.2	0.5	0.2 < LOD		1.05
318	10/23/2007 11:36	20	WINDOW SILL	CONCRETE	B	FAIR	WHITE	BLDG 222 SOUTH BLDG	1ST	STAIRWELL OFF OF CENTER ROOM				Negative	5.07	0.6	0.1	0.6	0.1	0.8	0.4
319	10/23/2007 11:37	3.06	WALL	CONCRETE	B	FAIR	WHITE	BLDG 222 SOUTH BLDG	1ST	STAIRWELL OFF OF CENTER ROOM				Negative	1.73 < LOD		0.08 < LOD		0.08 < LOD		2.32
320	10/23/2007 11:37	3.56	WALL	CONCRETE	C	FAIR	WHITE	BLDG 222 SOUTH BLDG	1ST	STAIRWELL OFF OF CENTER ROOM				Negative	2.27 < LOD		1.19	0.19	0.08 < LOD		1.19
321	10/23/2007 11:37	2.04	WALL	CONCRETE	D	FAIR	WHITE	BLDG 222 SOUTH BLDG	1ST	STAIRWELL OFF OF CENTER ROOM				Negative	1.73 < LOD		0.18 < LOD		0.18 < LOD		2.83
322	10/23/2007 11:38	3.55	FLOOR	CONCRETE	D	FAIR	GRAY	BLDG 222 SOUTH BLDG	1ST	STAIRWELL OFF OF CENTER ROOM				Negative	1.61	0.09	0.05	0.09	0.05 < LOD		1.35
323	10/23/2007 11:38	1.54	PIPE	METAL	C	POOR	WHITE	BLDG 222 SOUTH BLDG	1ST	STAIRWELL OFF OF CENTER ROOM				Positive	3.3	2.6	1.1	2.6	1.1 < LOD		4.05
324	10/23/2007 11:40	7.13	WALL	PLASTER	D	FAIR	WHITE	BLDG 222 SOUTH BLDG	1ST	WEST AREA				Negative	4.53 < LOD		0.9	0.22	0.09 < LOD		0.9
325	10/23/2007 11:40	19.92	DOOR CASING	WOOD	D	FAIR	BLUE	BLDG 222 SOUTH BLDG	1ST	WEST AREA				Negative	7.07	0.9	0.2	0.9	0.2	0.9	0.3
326	10/23/2007 11:41	4.07	WALL	PLASTER	A	FAIR	WHITE	BLDG 222 SOUTH BLDG	1ST	WEST AREA				Negative	5.62 < LOD		1.16	0.24	0.15 < LOD		1.16
327	10/23/2007 11:42	19.91	WINDOW SILL	WOOD	A	POOR	BLUE	BLDG 222 SOUTH BLDG	1ST	WEST AREA				Positive	6.69	1.1	0.2	1.1	0.2	1	0.3
328	10/23/2007 11:42	3.58	WINDOW CASING	WOOD	A	POOR	BLUE	BLDG 222 SOUTH BLDG	1ST	WEST AREA				Positive	8.89	2.3	0.8	2.2	0.7	2.3	0.8
329	10/23/2007 11:42	6.61	WINDOW	WOOD	A	POOR	BLUE	BLDG 222 SOUTH BLDG	1ST	WEST AREA				Positive	5.9	1.6	0.5	1	0.3	1.6	0.5
330	10/23/2007 11:43	1.03	RADIATOR	METAL	A	FAIR	BEIGE	BLDG 222 SOUTH BLDG	1ST	WEST AREA				Negative	2.91 < LOD		0.67 < LOD		0.67 < LOD		5.45
331	10/23/2007 11:43	1.01	RADIATOR	METAL	B	FAIR	BEIGE	BLDG 222 SOUTH BLDG	1ST	WEST AREA				Negative	1.57 < LOD		0.23 < LOD		0.23 < LOD		4.56
332	10/23/2007 11:44	3.6	WINDOW SILL	WOOD	B	POOR	BLUE	BLDG 222 SOUTH BLDG	1ST	WEST AREA				Negative	4.57	0.6	0.2	0.6	0.2 < LOD		1.05
333	10/23/2007 11:44	8.18	WINDOW	WOOD	B	POOR	BLUE	BLDG 222 SOUTH BLDG	1ST	WEST AREA				Positive	6.19	1.5	0.5	1.2	0.3	1.5	0.5
334	10/23/2007 11:44	6.64	WINDOW CASING	WOOD	B	POOR	BLUE	BLDG 222 SOUTH BLDG	1ST	WEST AREA				Positive	7.45	1.4	0.4	1.4	0.4	0.9	0.5
335	10/23/2007 11:45	5.1	WALL	PLASTER	B	FAIR	BEIGE	BLDG 222 SOUTH BLDG	1ST	WEST AREA				Negative	5.29 < LOD		1.1	0.24	0.13 < LOD		1.1

Reading No	Time	Duration	Component	Substrate	Side	Condition	Color	Site	Floor	Room	Res	Escale 1	Escle CT	Results	Depth Index	PbC	PbC Error	PbL	PbL Error	PbK	PbK Error
336	10/23/2007 11:45	3.06	WALL	WOOD	C	FAIR	BLUE	BLDG 222 SOUTH BLDG	1ST	WEST AREA				Negative	4.08 < LOD		1.43 < LOD		0.23 < LOD		1.43
337	10/23/2007 11:46	0.51	DOOR	WOOD	C	POOR	BLUE	BLDG 222 SOUTH BLDG	1ST	WEST AREA				Positive	10 < LOD		18.15 < LOD		13.95 < LOD		18.15
338	10/23/2007 11:46	4.07	DOOR CASING	WOOD	C	POOR	BLUE	BLDG 222 SOUTH BLDG	1ST	WEST AREA				Negative	5.74	0.7	0.3	0.7	0.3 < LOD		0.9
339	10/23/2007 11:47	13.24	WINDOW	WOOD	D	FAIR	BLUE	BLDG 222 SOUTH BLDG	1ST	WEST AREA				Null	5.07	1.2	0.3	0.6	0.1	1.2	0.3
340	10/23/2007 11:47	10.2	WINDOW	WOOD	D	FAIR	BLUE	BLDG 222 SOUTH BLDG	1ST	WEST AREA				Positive	4.87	1.4	0.4	1	0.2	1.4	0.4
341	10/23/2007 11:47	3.59	WINDOW CASING	WOOD	D	FAIR	BLUE	BLDG 222 SOUTH BLDG	1ST	WEST AREA				Positive	5.82	1.5	0.5	1.5	0.5	1.5	0.7
342	10/23/2007 11:48	3.58	WINDOW SILL	WOOD	D	FAIR	BLUE	BLDG 222 SOUTH BLDG	1ST	WEST AREA				Positive	7.96	1.8	0.6	1.8	0.6	1.2	0.7
343	10/23/2007 11:48	6.13	CEILING	METAL	D	FAIR	WHITE	BLDG 222 SOUTH BLDG	1ST	WEST AREA				Positive	8.38	1.6	0.6	1.2	0.4	1.6	0.6
344	10/23/2007 11:49	20	COLUMN	WOOD		POOR	RED	BLDG 222 SOUTH BLDG	1ST	WEST AREA				Null	8.05	1.4	0.2	1.4	0.2	1.2	0.3
345	10/23/2007 11:53	1.02	RADIATOR	METAL	D	POOR	YELLOW	BLDG 222 WEST BLDG	1ST	SOUTH STORAGE RESTROOM				Negative	2.77 < LOD		0.35 < LOD		0.35 < LOD		5.85
346	10/23/2007 11:53	1.02	PIPE	METAL	D	POOR	YELLOW	BLDG 222 WEST BLDG	1ST	SOUTH STORAGE RESTROOM				Negative	4.29 < LOD		0.82 < LOD		0.82 < LOD		5.37
347	10/23/2007 11:56	1.02			CALIBRATE		WHITE							Negative	1 < LOD		0.06 < LOD		0.06 < LOD		3.6
348	10/23/2007 11:56	1.03			CALIBRATE		WHITE							Negative	1 < LOD		0.06 < LOD		0.06 < LOD		3.78
349	10/23/2007 11:56	19.92			CALIBRATE		RED							Positive	1.13	1	0.1	1	0.1 < LOD		0.46
350	10/23/2007 11:57	0.51			CALIBRATE		YELLOW							Positive	1.34	3.5	2.1	3.5	2.1 < LOD		9