




Dallas - Radiology IRAngio Waiting Area







CORRIDOR
C3A-20

HAC
3A-336

SOILED LINEN
3A-334

EXAM ROOM
3A-111
108 SQ FT

CORRIDOR
C3A-11

CORRIDOR
C3A-17

EXAM ROOM
3A-110
130 SQ FT



STORAGE
3A-338

EXAM ROOM
3A-112

PURPOSE
RM
114

EXAM ROOM
3A-108

OFFICE
3A-106



CORRIDOR
C3A-6

ELEVATOR
LOBBY

C3T1

CORRIDOR

C3T1C

PATIENT
ROOMS

3T113

379 SQ FT

MRI CONTROL

3T112

