




Dead Leg Criteria Checklist

	Description	Pipe Length greater than three feet terminating at a cap, valve, or fitting	Pipe length greater than three feet terminating at an infrequently used plumbing fixture	Pipe length greater than 25 feet terminating at a frequently used plumbing fixture	
Dead Leg #	3-B-001-001				
Dead Leg Type		x			
Termination	Caps				
Fixture served	None				
Valve Type	Ball				
Pipe Length	6'				
Pipe Size	3/4"-3/4"-1/2"				
Pipe Function	DCW, DHW, DHWR				
Pipe Material	Copper				
Length of non insulated pipe	3'				
Building #	3		Comments		
Floor Number	Basement				
Room Number	1				
Location in Room	South				
Demo Needed? Y/N	No				
Drawing #					
Picture of Dead Leg					
					
Date of Inspection: 05/27/2014					


Dead Leg Criteria Checklist


	Description	Pipe Length greater than three feet terminating at a cap, valve, or fitting	Pipe length greater than three feet terminating at an infrequently used plumbing fixture	Pipe length greater than 25 feet terminating at a frequently used plumbing fixture	
Dead Leg #	3-B-002-001				
Dead Leg Type		x			
Termination	Caps				
Fixture served	None				
Valve Type	Ball				
Pipe Length	25'				
Pipe Size	3/4"-3/4"-1/2"				
Pipe Function	DCW, DHW, DHWR				
Pipe Material	Copper				
Length of non insulated pipe	3'				
Building #	3		Comments		
Floor Number	Basement				
Room Number	2				
Location in Room	South				
Demo Needed? Y/N	No				
Drawing #					
Picture of Dead Leg					
					
Date of Inspection: 05/27/2014					

Dead Leg Criteria Checklist


	Description	Pipe Length greater than three feet terminating at a cap, valve, or fitting	Pipe length greater than three feet terminating at an infrequently used plumbing fixture	Pipe length greater than 25 feet terminating at a frequently used plumbing fixture	
Dead Leg #	3-B-007-001				
Dead Leg Type		x			
Termination	Caps				
Fixture served	None				
Valve Type	Ball				
Pipe Length	6'				
Pipe Size	1"-1"-1/2"				
Pipe Function	DCW, DHW, DHWR				
Pipe Material	Copper				
Length of non insulated pipe	N/A				
Building #	3		Comments		
Floor Number	Basement				
Room Number	7				
Location in Room	Center				
Demo Needed? Y/N	No				
Drawing #					
Picture of Dead Leg					
					
Date of Inspection: 05/27/2014					

Dead Leg Criteria Checklist


	Description	Pipe Length greater than three feet terminating at a cap, valve, or fitting	Pipe length greater than three feet terminating at an infrequently used plumbing fixture	Pipe length greater than 25 feet terminating at a frequently used plumbing fixture	
Dead Leg #	3-B-007-002				
Dead Leg Type		x			
Termination	Valve/Caps				
Fixture served	None				
Valve Type	Ball				
Pipe Length	10'				
Pipe Size	1"-1"-1/2"				
Pipe Function	DCW, DHW, DHWR				
Pipe Material	Copper				
Length of non insulated pipe	N/A				
Building #	3		Comments		
Floor Number	Basement				
Room Number	7				
Location in Room	Center				
Demo Needed? Y/N	No				
Drawing #					
Picture of Dead Leg					
					
Date of Inspection: 05/27/2014					

Dead Leg Criteria Checklist					
	Description	Pipe Length greater than three feet terminating at a cap, valve, or fitting	Pipe length greater than three feet terminating at an infrequently used plumbing fixture	Pipe length greater than 25 feet terminating at a frequently used plumbing fixture	
Dead Leg #	3-B-007A-001				
Dead Leg Type		x			
Termination	Valve/Caps				
Fixture served	None				
Valve Type	Ball				
Pipe Length	26'				
Pipe Size	3/4", 3/4"-1/2"				
Pipe Function	DCW, DHW, DHWR				
Pipe Material	Copper				
Length of non insulated pipe	N/A				
Building #	3		Comments		
Floor Number	Basement				
Room Number	007A				
Location in Room	N				
Demo Needed? Y/N	Yes				
Drawing #					
Picture of Dead Leg					
					
Date of Inspection: 05/27/2014					


Dead Leg Criteria Checklist

	Description	Pipe Length greater than three feet terminating at a cap, valve, or fitting	Pipe length greater than three feet terminating at an infrequently used plumbing fixture	Pipe length greater than 25 feet terminating at a frequently used plumbing fixture	
Dead Leg #	3-1-110A-001				
Dead Leg Type		x			
Termination	Valve/Caps				
Fixture served	None				
Valve Type	Ball				
Pipe Length	6'				
Pipe Size	3/4"				
Pipe Function	DCW				
Pipe Material	Copper				
Length of non insulated pipe	N/A				
Building #	3		Comments		
Floor Number	1				
Room Number	110A				
Location in Room	WEST WALL				
Demo Needed? Y/N	Yes				
Drawing #					
Picture of Dead Leg					
					
Date of Inspection: 05/27/2014					

Dead Leg Criteria Checklist

	Description	Pipe Length greater than three feet terminating at a cap, valve, or fitting	Pipe length greater than three feet terminating at an infrequently used plumbing fixture	Pipe length greater than 25 feet terminating at a frequently used plumbing fixture							
Dead Leg #	3-1-110A-002										
Dead Leg Type		x									
Termination	Valve/Caps										
Fixture served	None										
Valve Type	Ball										
Pipe Length	6'										
Pipe Size	3/4", 3/4"										
Pipe Function	DCW, DHW										
Pipe Material	Copper										
Length of non insulated pipe	N/A										
Building #	3		Comments								
Floor Number	1										
Room Number	110A										
Location in Room											
Room	SOUTH WALL										
Demo Needed? Y/N	Yes										
Drawing #											
Picture of Dead Leg											
											
Date of Inspection: 05/27/2014											

Dead Leg Criteria Checklist

	Description	Pipe Length greater than three feet terminating at a cap, valve, or fitting	Pipe length greater than three feet terminating at an infrequently used plumbing fixture	Pipe length greater than 25 feet terminating at a frequently used plumbing fixture	
Dead Leg #	3-2-212-001				
Dead Leg Type			X		
Termination	Sink				
Fixture served	Mop Sink				
Valve Type	Ball				
Pipe Length					
Pipe Size					
Pipe Function	DCW/DHW				
Pipe Material	Copper				
Length of non insulated pipe					
Building #	3		Comments		
Floor Number	2		The floor appears to be vacant.		
Room Number	212				
Location in Room	center				
Demo Needed? Y/N	Yes				
Drawing #					
Picture of Dead Leg					
					
Date of Inspection: 05/27/2014					