



AIR PRESSURIZATION LEGEND:	
(+)	POSITIVELY PRESSURIZED
(-)	NEGATIVELY PRESSURIZED
(0)	NEUTRAL PRESSURE

TEST AND BALANCE (TAB) NOTES:	
1. After completion of final testing and balancing, contractor shall survey and record the readings on the 17 differential pressure monitors located as shown on drawing 1-H12.	
Submit report to VA COR following completion of survey.	
DIFFERENTIAL PRESSURE MONITOR LOCATIONS	
** ANIMAL WARDS (9 TOTAL) ** PROCEDURE ROOMS (4 TOTAL) ** ISOLATION ** QUARANTINE WARD ** ANIMAL RECEPTION ** HAZARDOUS WASTE	

RECORD DRAWINGS

Record Drawings	05-01-15
Revisions:	Date

CONSULTANTS:

**FREDRICK, FREDRICK & HELLER
ENGINEERS, INC.**
872 EAST ROYALTON ROAD
BROADVIEW HTS., OHIO 44147
TEL: (440) 346-9999
FAX: (440) 346-9999

ARCHITECT:

**Perspectus
architecture**
13212 Shaker Square Suite 204 Cleveland, Ohio 44120
P. 216.752.1800 F. 216.752.3833

Drawing Title
ROOM PRESSURIZATION PLAN

Approved: Project Director

Project Title
**ANIMAL RESEARCH
RENOVATIONS**

Location
VAMC - WAIDE PARK

Date: 05-01-15
Checked: BMW
Drawn: LDH

Project Number
541-08-1010

Building Number
1

Drawing Number
1-H12

Dwg. of

**Office of
Facilities
Management**