

PROJECT PHOTOS






PHOTO #2 - EXISTING DINING ROOM EXIT, 10' SLIDING GLASS DOOR AND EXIT RAMP



PHOTO #3 - EXISTING
DINING ROOM EXIT RAMP

PHOTO #4 -
LOOKING WEST
AT THE BACK OF
THE EXISTING
GARAGE - NOTE
THE OLD
EXISTING 3 LINE
ELECTRICAL FEED



PHOTO #5 -
EXISTING GARAGE
- NOTE THE
PROXIMITY OF
THE POOL



PHOTO #6 -
LOOKING EAST AT
THE INSIDE BACK
WALL OF THE
EXISTING GARAGE -
NOTE THE EXISTING
ELECTRICAL



PHOTO #7 - VETERAN'S
EXISTING BEDROOM
EMERGENCY EXIT



PHOTO #8 - EXISTING
BEDROOM EXIT WAY -
NOTE THE CRAWL
SPACE VENT/ ACCESS
DOOR



PHOTO #9 -
EXISTING FRONT
PATH FROM
VETERAN'S
BEDROOM
EMERGENCY EXIT



PHOTO #10 -
EXISTING FRONT
WROUGHT IRON
GATE AND EXIT
PATH




PHOTO #11 - EXISTING
FAUX WOOD GLAZED
PORCELAIN TILE

NOTE - TILE TO BE
MATCHED WHERE
CARPETING IS REMOVED



PHOTO #12 - EXISTING
GATE BETWEEN
VETERAN'S BEDROOM
EMERGENCY EXIT AND
POOL

