

## ?## SCOPE OF WORK PICTURES

### PICTURES



**Figure 1:** A1.3 to be removed and replaced



**Figure 2:** A1.4 to be removed and replaced  
(New sign to be installed further into the circle.)



**Figure 3:** A1.5 to be repaired



**Figure 4:** A1.6 to be removed and replaced



**Figure 5:** A1.7 to be repaired



**Figure 6:** A1.7 (reverse) to be repaired



**Figure 7:** A1.8 to be repaired



**Figure 8:** A1.9 to be repaired



**Figure 9:** A1.10 to be repaired



**Figure 10:** A2.1 to be repaired



**Figure 11:** A2.2 to be repaired



**Figure 12:** C1.1 to be repaired



**Figure 13:** C1.2 (reverse) to be repaired



**Figure 14:** C1.3 to be repaired



**Figure 15:** C1.4 to be repaired



**Figure 16:** C1.5 to be repaired



**Figure 17:** C1.6 to be repaired



**Figure 18:** C1.7 to be repaired



**Figure 19:** D1.1 to be removed and replaced



**Figure 20:** D2.1 to be removed and replaced



**Figure 21:** D2.2 to be removed and replaced



**Figure 22:** D2.2 to be removed and replaced



**Figure 23:** Floral Regulations sign to be removed and replaced.



**Figure 24:** Floral Regulations (reverse)



**Figure 25:** Typical flower vase box to be replaced