

# Device Type List Report



**PROGRESSIVE ELECTRONICS** inc.

6102 Arlington, Raytown, MO 64133 | 816.765.5750 | Fax 816.765.9266 | www.peikc.com

**Inspection** VA Medical Center **Inspection Number** 0

**Inspection Date** 6/23/2016 **Inspector** Bill Brown

Device Tested				Test Date		Comments
Address	Description	FailReason	P/F/NT	Current	Previous	
DeviceType	Tamper	Standard	EC.02.03.05 EP 1/NFPA7			
N20L1M84	Bldg 26 PIV Bldg 26		Pass	6/30/2016		

**Inspection** VA Medical Center  
**Inspection Date** 6/23/2016

**Inspection Number** 0  
**Inspector** Bill Brown

Device Tested		Test Date		P/F/NT	Current	Previous	Comments
Address	Description	FailReason					
DeviceType	Track Superv	Standard	EC.02.03.05 EP 1				
N10L1M27	Basement Stair-8 East			Pass	6/24/2016		
N10L1M51	Basement West Center			Pass	6/24/2016		
N10L1M53	Basement North Center			Pass	6/24/2016		
N10L1M55	South ISO Valve Center			Pass	6/24/2016		
N10L1M71	Basement IRM ISO East			Pass	6/24/2016		
N10L1M72	Basement Prosethics South East			Pass	6/24/2016		
N10L1M73	Pipe Chase Linen Rm Bldg 1			Pass	6/24/2016		
N10L1M75	Basement Morgue Bldg1			Pass	6/24/2016		
N10L1M90	Basement Stair-5 East			Pass	6/24/2016		
N10L1M91	Basement Stair-4 East			Pass	6/24/2016		
N10L1M92	Basement R Dock South V.T.			Pass	6/24/2016		Glycol Sys
N10L1M93	Basement R Dock South V.T.			Pass	6/24/2016		Glycol Sys
N10L1M110	Sub Bsmt City Side Shut Off			Pass	6/23/2016		
N10L1M111	Sub Bsmt City Side Back Flow			Pass	6/23/2016		

**Inspection** VA Medical Center  
**Inspection Date** 6/23/2016

**Inspection Number** 0  
**Inspector** Bill Brown

Device Tested		Test Date		P/F/NT	Current	Previous	Comments
Address	Description	FailReason					
DeviceType	Track Superv	Standard	EC.02.03.05 EP 1				
N10L1M112	Sub Bsmnt Systm Side Back Flow			Pass	6/23/2016		
N10L1M113	Sub Bsmnt City Bypas Center			Pass	6/23/2016		
N10L1M114	Sub Bsmnt FP Feed Center			Pass	6/23/2016		
N10L1M115	Sub Bsmnt City Bypas Center			Pass	6/23/2016		
N10L1M116	Sub Bsmnt Sys Side Pump Bypass			Pass	6/23/2016		
N10L1M117	Sub Bsmnt Main Riser Center			Pass	6/23/2016		
N10L1M118	Sub Bsmnt Test Head Center			Not Tested			Test Header Normally Closed Valve
N10L1M119	Sub Basement St-1 Center			Pass	6/23/2016		
N10L1M124	Fire Pump Run Bldg-1 Center			Pass	6/23/2016		
N10L1M125	Fire Pump A/C Fail Center			Pass	6/23/2016		
N10L1M127	Sub Bsmnt City Main Center			Pass	7/1/2016		
N10L1M128	Sub Bsmnt City Feed Back Flow			Pass	7/1/2016		
N10L2M25	Basement Room B243 West			Pass	6/24/2016		Closed Valve Electrical Test only
N10L2M26	Basement Locker Rm West V.T.			Pass	7/1/2016		Dry Sys

**Inspection** VA Medical Center  
**Inspection Date** 6/23/2016

**Inspection Number** 0  
**Inspector** Bill Brown

Device Tested		Test Date		P/F/NT	Current	Previous	Comments
Address	Description	FailReason					
DeviceType	Track Superv	Standard	EC.02.03.05 EP 1				
N10L2M27	Basement Locker Rm West L.A.			Pass	7/1/2016		Dry Sys
N10L2M32	Basement Canteen Stor West			Pass	6/24/2016		Rm 236 Canteen Storage
N10L2M33	Basement Room MB214 West			Pass	6/24/2016		
N10L2M41	1st Floor Stair-3 South West			Pass	6/23/2016		
N10L2M42	1st Floor Stair-3 North West			Pass	6/23/2016		
N10L2M81	2nd Floor Stair-3 SW 2 West			Pass	6/23/2016		
N10L2M82	2nd Floor Stair-3 NW 2 West			Pass	6/23/2016		
N10L3M14	1st Floor Str-5 SEW East			Pass	7/1/2016		
N10L3M16	1st Floor Str-5 SEE East			Pass	7/1/2016		
N10L3M19	2nd Flor Stair-5 SEE East			Pass	7/1/2016		
N10L3M21	2nd Flor Stair-5 SEW East			Pass	7/1/2016		
N10L3M34	1st Floor Stair 2 Center			Pass	6/24/2016		
N10L3M40	1st Floor Stair-6 East			Pass	6/24/2016		
N10L3M41	Bsmnt St-1 Cntr East			Pass	6/23/2016		

**Inspection** VA Medical Center  
**Inspection Date** 6/23/2016

**Inspection Number** 0  
**Inspector** Bill Brown

Device Tested		Test Date		P/F/NT	Current	Previous	Comments
Address	Description	FailReason					
DeviceType	Track Superv	Standard	EC.02.03.05 EP 1				
N10L3M42	Bsmnt St-1 Cntr East			Pass	6/23/2016		
N10L3M45	Bsmnt St-1 Riser East			Pass	6/23/2016		
N10L3M46	Bsmnt St-1 B433/34 East	Valve is Normally Closed Ele		Pass	6/24/2016		
N10L3M47	Bsmnt STAIR 1 ISO East			Pass	6/23/2016		
N10L3M50	Building 1 PIV East			Pass	6/30/2016		
N10L3M58	1st Floor B Health East			Pass	6/24/2016		
N10L3M61	1st Floor Stair-1 C East			Pass	6/23/2016		
N10L3M62	1st Floor Stair-1 NE East			Pass	6/23/2016		
N10L3M101	2nd Floor Stair-1 SE East			Pass	6/23/2016		
N10L3M102	2nd Floor Stair-1 NE East			Pass	6/23/2016		
N10L4M1	3rd Floor Stair-3 SW West			Pass	6/23/2016		
N10L4M2	3rd Floor Stair-3 NW West			Pass	6/23/2016		
N10L4M41	4th Floor Stair-3 SW West			Pass	6/23/2016		
N10L4M42	4th Floor Stair-3 NW West			Pass	6/23/2016		

**Inspection** VA Medical Center  
**Inspection Date** 6/23/2016

**Inspection Number** 0  
**Inspector** Bill Brown

Device Tested				Test Date		Comments
Address	Description	FailReason	P/F/NT	Current	Previous	
DeviceType	Track Superv	Standard	EC.02.03.05 EP 1			
N10L4M81	5th Floor Stair-3 SW West		Pass	6/23/2016		
N10L4M82	5th Floor Stair-3 NW West		Pass	6/23/2016		
N10L5M21	3rd Floor Stair-1 SE East		Pass	6/23/2016		
N10L5M22	3rd Floor Stair-1 NE East		Pass	6/23/2016		
N10L5M41	Stair-13 Dry System East L.A.	Dry Sys	Pass	7/1/2016		
N10L5M43	Stair-13 Dry System East V.T.	Dry Sys	Pass	7/1/2016		
N10L5M46	Stair-4 Dry System S.E. L.A.	Dry Sys	Pass	7/1/2016		
N10L5M47	Stair-4 Dry System S.E V.T.	Dry Sys	Pass	7/1/2016		
N10L5M48	3rd Flr St-6 Dry Sys S.W. L.A.	Dry Sys	Pass	7/1/2016		
N10L5M50	3rd Flr St-6 Dry Sys S.W. V.T	Dry Sys	Pass	7/1/2016		
N10L5M53	4th Flr St-5 Dry Sys South L.A.	Dry Sys	Pass	7/1/2016		
N10L5M54	4th Flr St-5 Dry Sys South VT	Dry Sys	Pass	7/1/2016		
N10L5M61	4th Floor Stair-1 SE East		Pass	6/23/2016		
N10L5M62	4th Floor Stair-1 NE East		Pass	6/23/2016		

**Inspection** VA Medical Center  
**Inspection Date** 6/23/2016

**Inspection Number** 0  
**Inspector** Bill Brown

Device Tested		Test Date		P/F/NT	Current	Previous	Comments
Address	Description	FailReason					
DeviceType	Track Superv	Standard	EC.02.03.05 EP 1				
N10L5M101	5th Floor Stair-1 SE East			Pass	6/23/2016		
N10L5M102	5th Floor Stair-1 NE East			Pass	6/23/2016		
N10L6M1	6th Floor Stair-3 SW West			Pass	6/23/2016		
N10L6M2	6th Floor Stair-3 NW West			Pass	6/23/2016		
N10L6M41	7th Floor Stair-3 SW West			Pass	6/23/2016		
N10L6M42	7th Floor Stair-3 NW West			Pass	6/23/2016		
N10L6M81	8th Floor Stair-3 SW West			Pass	6/23/2016		
N10L6M82	8th Floor Stair-3 NW West			Pass	6/23/2016		
N10L7M21	6th Floor Stair-1 SE East			Pass	6/23/2016		
N10L7M22	6th Floor Stair-1 NE East			Pass	6/23/2016		
N10L7M61	7th Floor Stair-1 SE East			Pass	6/23/2016		
N10L7M62	7th Floor Stair-1 NE East			Pass	6/23/2016		
N10L7M101	8th Floor Stair-1 SE East			Pass	6/23/2016		
N10L7M102	8th Floor Stair-1 NE East			Pass	6/23/2016		

**Inspection** VA Medical Center  
**Inspection Date** 6/23/2016

**Inspection Number** 0  
**Inspector** Bill Brown

Device Tested		Test Date				
Address	Description	FailReason	P/F/NT	Current	Previous	Comments
DeviceType	Track Superv	Standard	EC.02.03.05 EP 1			
N10L8M1	9th Floor Stair-3 SW West		Pass	6/23/2016		
N10L8M2	9th Floor Stair-3 NW West		Pass	6/23/2016		
N10L8M41	10th Flor Stair-3 SW West		Pass	6/23/2016		
N10L8M42	10th Flor Stair-3 NW West		Pass	6/23/2016		
N10L8M81	11th Flor Stair-3 SW West		Pass	6/23/2016		
N10L8M82	11th Flor Stair-3 NW West		Pass	6/23/2016		
N10L9M21	9th Floor Stair SE East		Pass	6/23/2016		
N10L9M22	9th Floor Stair-1 NE East		Pass	6/23/2016		
N10L9M51	P.H. Isolation Valve Center	Dry Sys	Pass	7/1/2016		
N10L9M52	East P.H. Dry System Center	Dry Sys	Pass	7/1/2016		
N10L9M53	West P.H. Dry System Center	Dry Sys	Pass	7/1/2016		
N10L9M54	East P.H. Low Air Center	Dry Sys	Pass	7/1/2016		
N10L9M55	West P.H, Low Air Center	Dry Sys	Pass	7/1/2016		
N10L9M61	10th Flor Stair-1 SE East		Pass	6/23/2016		



**Inspection** VA Medical Center  
**Inspection Date** 6/23/2016

**Inspection Number** 0  
**Inspector** Bill Brown

Device Tested		Test Date		P/F/NT	Current	Previous	Comments
Address	Description	FailReason					
DeviceType	Track Superv	Standard	EC.02.03.05 EP 1				
N10L9M62	10th Flor Stair-1 NE East			Pass	6/23/2016		
N10L9M101	11th Flor Stair-1 SE East			Pass	6/23/2016		
N10L9M102	11th Flor Stair-1 NE East			Pass	6/23/2016		
N10L9M126	Freight Elev Eq Rm P.H. Center			Pass	6/24/2016		
N10L9M148	P.H. Stair 2 L 13 Center			Pass	6/24/2016		
N10L9M149	P.H. Stair 2 L 14 Center			Pass	6/24/2016		
N20L1M1	Basement Stair 16 Bldg 26			Pass	6/23/2016		
N20L1M2	Basement Stair 16 Bldg 26			Pass	6/23/2016		
N20L1M7	Basement Stair 17 Bldg 26			Pass	6/23/2016		
N20L1M8	Basement Stair 17 Bldg 26			Pass	6/23/2016		
N20L1M14	1st Flr Stair 16 Bldg 26			Pass	6/23/2016		
N20L1M20	1st Flr St-17 Bldg 26			Pass	6/23/2016		
N20L1M23	1st Floor Stair 18 Bldg 26			Pass	6/23/2016		
N20L1M29	ELEV EQUIPMENT ISO BLDG 26 MECH			Pass	6/24/2016		

**Inspection** VA Medical Center  
**Inspection Date** 6/23/2016

**Inspection Number** 0  
**Inspector** Bill Brown

Device Tested		Test Date		P/F/NT	Current	Previous	Comments
Address	Description	FailReason					
DeviceType	Track Superv	Standard	EC.02.03.05 EP 1				
N20L1M81	Basement Stair 18 Bldg 26			Pass	6/24/2016		
N20L1M82	Basement Stair 18 Bldg 26			Pass	6/23/2016		
N20L1M85	Service Entry Bldg 26			Pass	6/24/2016		
N20L1M120	1st Floor Stair 18 Bldg 26			Pass	6/23/2016		
N20L2M1	2nd Flr Stair 16 Bldg 26			Pass	6/23/2016		
N20L2M8	2nd Flr Stair 17 Bldg 26			Pass	6/23/2016		
N20L2M12	2nd Flr Stair 18 SE Bldg 26			Pass	6/23/2016		
N20L2M13	2nd Flr Stair 18 NE Bldg 26			Pass	6/23/2016		
N20L3M1	3rd Flr Stair 16 Bldg 26			Pass	6/23/2016		
N20L3M5	3rd Flr Stair 17 Bldg 26			Pass	6/23/2016		
N20L3M8	3rd Flr Stair 18 Bldg 26			Pass	6/23/2016		
N20L4M1	4th Flr Stair 16 Bldg 26			Pass	6/23/2016		
N20L4M6	4th Flr Stair 17 Bldg 26			Pass	6/23/2016		
N20L4M9	4th Flr Stair 18 Bldg 26			Pass	6/23/2016		

**Inspection** VA Medical Center  
**Inspection Date** 6/23/2016

**Inspection Number** 0  
**Inspector** Bill Brown

Device Tested		Test Date		P/F/NT	Current	Previous	Comments
Address	Description	FailReason					
DeviceType	Track Superv	Standard	EC.02.03.05 EP 1				
N20L4M51	5th Flr Stair 16 Bldg 26			Pass	6/23/2016		
N20L4M76	Stair 18 PH 1 BLDG 26			Pass	6/23/2016		
N20L4M77	Stair 18 PH 2 BLDG 26			Pass	6/23/2016		
N20L5M6	5th Flr Stair 17 Bldg 26			Pass	6/23/2016		
N20L5M58	5th Floor Stair 18			Pass	6/23/2016		
N30L1M2	Basement Stair 14 Bldg 15			Pass	6/30/2016		
N30L1M5	Bldg 15 PIV Bldg 15			Pass	6/30/2016		
N30L1M6	City Side Fire Pump Bldg 15			Pass	6/30/2016		
N30L1M11	1st Floor Stair 14 Bldg 15			Pass	6/30/2016		
N30L1M19	2nd Floor Stair 14 Bldg 15 S			Pass	6/30/2016		
N30L1M21	2nd Floor Stair 20 Bldg 15 N			Pass	6/30/2016		
N30L1M24	2nd Floor Stair 20 Bldg 15 N			Pass	6/30/2016		
N30L1M31	3rd Floor Stair 14 Bldg 15 S			Pass	6/30/2016		
N30L1M33	3rd Floor Stair 14 Bldg 15 S			Pass	6/30/2016		

**Inspection** VA Medical Center  
**Inspection Date** 6/23/2016

**Inspection Number** 0  
**Inspector** Bill Brown

Device Tested		Test Date		P/F/NT	Current	Previous	Comments
Address	Description	FailReason					
DeviceType	Track Superv	Standard	EC.02.03.05 EP 1				
N30L1M36	3rd Floor Stair 20 Bldg 15 N			Pass	6/30/2016		
N30L1M45	ISO Valve Basement Bldg 15			Pass	6/30/2016		
N30L1M104	1st Floor Locker Rm Bldg 15			Pass	6/30/2016		
N30L1M106	1ST Floor Stair 14 Bldg 15			Pass	6/30/2016		
N30L1M112	Fire Pump Running Bldg 15			Pass	6/30/2016		
N30L1M114	Fire Pump A/C Fail Bldg 15			Pass	6/15/2016		
N30L1M115	Systm Riser Feed Bldg 15			Pass	6/30/2016		
N30L1M117	Basement Bldg 15			Pass	6/30/2016		
N30L2M2	4th Floor South Bldg 15			Pass	6/30/2016		
N30L2M6	4th Floor South Bldg 15			Pass	6/30/2016		
N30L2M9	4th Floor North Bldg 15			Pass	6/30/2016		
N30L2M16	5th Floor South Bldg 15			Pass	6/30/2016		
N30L2M19	5th Floor North Bldg 15			Pass	6/30/2016		
N30L2M26	6th Stair 14 Bldg 15			Pass	6/30/2016		

**Inspection** VA Medical Center  
**Inspection Date** 6/23/2016

**Inspection Number** 0  
**Inspector** Bill Brown

Device Tested		Test Date		P/F/NT	Current	Previous	Comments
Address	Description	FailReason					
DeviceType	Track Superv	Standard	EC.02.03.05 EP 1				
N30L2M29	6th Stair 20 Bldg 15			Pass	6/30/2016		
N30L2M36	7th Stair 14 Bldg 15			Pass	6/30/2016		
N30L2M39	7th Stair 14 Bldg 15			Pass	6/30/2016		
N30L2M44	8th Floor South Bldg 15			Pass	6/30/2016		
N30L2M49	8th Floor Bldg 15			Pass	6/30/2016		
N50L1M96	Outside PIV Bldg 6			Pass	6/30/2016		
N50L1M98	Receiving/Facilities Bldg 6			Pass	6/24/2016		
N50L1M99	Receiving/Facilities Bldg 6			Pass	6/24/2016		
N80L1M25	Sprinkler Room Bldg 2			Pass	6/24/2016		
N80L1M26	Sprinkler Room Bldg 2			Pass	6/24/2016		
N80L1M27	1st Flr Closet 2-103 Bldg 2			Pass	6/24/2016		
N80L1M28	2nd Flr Closet 2-204 Bldg 2			Pass	6/24/2016		

**Inspection** VA Medical Center  
**Inspection Date** 6/23/2016

**Inspection Number** 0  
**Inspector** Bill Brown

Device Tested		Test Date		Comments
Address	Description	FailReason	P/F/NT	
DeviceType	Waterflow	Standard	EC.02.03.05 EP 2/NFPA7	
N10L1M28	Basement Stair-8 East		Pass	6/24/2016
N10L1M52	Basement West Center		Pass	6/24/2016
N10L1M54	Basement North Center		Pass	6/24/2016
N10L1M74	Pipe Chase Linen Rm Bldg 1		Pass	6/24/2016
N10L1M94	Basement R Dock South W.F.		Pass	6/24/2016 Glycol Sys
N10L1M120	Sub Basement St-1 Center		Pass	6/23/2016
N10L2M28	Basement Locker Rm West W.F.		Pass	7/1/2016 Dry Sys
N10L2M34	Basement Room MB214 West		Pass	6/24/2016
N10L2M43	1st Floor Stair-3 South West		Pass	6/23/2016
N10L2M44	1st Floor Stair-3 North West		Pass	6/23/2016
N10L2M45	PBX PHONE ROOM FACP West		Pass	7/1/2016
N10L2M83	2nd Floor Stair-3 SW 2 West		Pass	6/23/2016
N10L2M84	2nd Floor Stair-3 NW 2 West		Pass	6/23/2016
N10L3M15	1st Floor Str-5 SEW East		Pass	7/1/2016

**Inspection** VA Medical Center  
**Inspection Date** 6/23/2016

**Inspection Number** 0  
**Inspector** Bill Brown

Device Tested		Test Date		Comments
Address	Description	FailReason	P/F/NT	
DeviceType	Waterflow	Standard	EC.02.03.05 EP 2/NFPA7	
N10L3M17	1st Floor Str-5 SEE East		Pass	7/1/2016
N10L3M20	2nd Flor Stair-5 SEE East		Pass	7/1/2016
N10L3M22	2nd Flor Stair-5 SEW East		Pass	7/1/2016
N10L3M35	1st Floor Stair 2 Center		Pass	6/24/2016
N10L3M43	Bsmnt St-1 Cntr East		Pass	6/23/2016
N10L3M44	Bsmnt St-1 NE East		Pass	6/23/2016
N10L3M63	1st Floor Stair-1 C East		Pass	6/23/2016
N10L3M64	1st Floor Stair-1 NE East		Pass	6/23/2016
N10L3M103	2nd Floor Stair-1 SE East		Pass	6/23/2016
N10L3M104	2nd Floor Stair-1 NE East		Pass	6/23/2016
N10L4M3	3rd Floor Stair-3 SW West		Pass	6/23/2016
N10L4M4	3rd Floor Stair-3 NW West		Pass	6/23/2016
N10L4M43	4th Floor Stair-3 SW West		Pass	6/23/2016
N10L4M44	4th Floor Stair-3 NW West		Pass	6/23/2016

**Inspection** VA Medical Center  
**Inspection Date** 6/23/2016

**Inspection Number** 0  
**Inspector** Bill Brown

Device Tested				Test Date		Comments
Address	Description	FailReason	P/F/NT	Current	Previous	
DeviceType	Waterflow	Standard	EC.02.03.05 EP 2/NFPA7			
N10L4M83	5th Floor Stair-3 SW West		Pass	6/23/2016		
N10L4M84	5th Floor Stair-3 NW West		Pass	6/23/2016		
N10L5M23	3rd Floor Stair-1 SE East		Pass	6/23/2016		
N10L5M24	3rd Floor Stair-1 NE East		Pass	6/23/2016		
N10L5M42	Stair-13 Dry System East W.F.	Dry Sys	Pass	7/1/2016		
N10L5M45	Stair-4 Dry System S.E. W.F.	Dry Sys	Pass	7/1/2016		
N10L5M49	3rd Flr St-6 Dry Sys S.W. W.F.	Dry Sys	Pass	7/1/2016		
N10L5M52	4th Flr St-5 Dry Sys South W.F.	Dry Sys	Pass	7/1/2016		
N10L5M63	4th Floor Stair-1 SE East		Pass	6/23/2016		
N10L5M64	4th Floor Stair-1 NE East		Pass	6/23/2016		
N10L5M103	5th Floor Stair-1 SE East		Pass	6/23/2016		
N10L5M104	5th Floor Stair-1 NE East		Pass	6/23/2016		
N10L6M3	6th Floor Stair-3 SW West		Pass	6/23/2016		
N10L6M4	6th Floor Stair-3 NW West		Pass	6/23/2016		



**Inspection** VA Medical Center  
**Inspection Date** 6/23/2016

**Inspection Number** 0  
**Inspector** Bill Brown

Device Tested		Test Date		Comments
Address	Description	FailReason	P/F/NT	
DeviceType	Waterflow	Standard	EC.02.03.05 EP 2/NFPA7	
N10L6M43	7th Floor Stair-3 SW West		Pass	6/23/2016
N10L6M44	7th Floor Stair-3 NW West		Pass	6/23/2016
N10L6M83	8th Floor Stair-3 SW West		Pass	6/23/2016
N10L6M84	8th Floor Stair-3 NW West		Pass	6/23/2016
N10L7M23	6th Floor Stair-1 SE East		Pass	6/23/2016
N10L7M24	6th Floor Stair-1 NE East		Pass	6/23/2016
N10L7M63	7th Floor Stair-1 SE East		Pass	6/23/2016
N10L7M64	7th Floor Stair-1 NE East		Pass	6/23/2016
N10L7M103	8th Floor Stair-1 SE East		Pass	6/23/2016
N10L7M104	8th Floor Stair-1 NE East		Pass	6/23/2016
N10L8M3	9th Floor Stair-3 SW West		Pass	6/23/2016
N10L8M4	9th Floor Stair-3 NW West		Pass	6/23/2016
N10L8M43	10th Flor Stair-3 SW West		Pass	6/23/2016
N10L8M44	10th Flor Stair-3 NW West		Pass	6/23/2016

**Inspection** VA Medical Center  
**Inspection Date** 6/23/2016

**Inspection Number** 0  
**Inspector** Bill Brown

Device Tested		Test Date				
Address	Description	FailReason	P/F/NT	Current	Previous	Comments
DeviceType	Waterflow	Standard	EC.02.03.05 EP 2/NFPA7			
N10L8M83	11th Flor Stair-3 SW West		Pass	6/23/2016		
N10L8M84	11th Flor Stair-3 NW West		Pass	6/23/2016		
N10L9M23	9th Floor Stair SE East		Pass	6/23/2016		
N10L9M24	9th Floor Stair-1 NE East		Pass	6/23/2016		
N10L9M56	East P.H. Water Flow Center	Dry Sys	Pass	7/1/2016		
N10L9M57	West P.H. Water Flow Center	Dry Sys	Pass	7/1/2016		
N10L9M63	10th Flor Stair-1 SE East		Pass	6/23/2016		
N10L9M64	10th Flor Stair-1 NE East		Pass	6/23/2016		
N10L9M103	11th Flor Stair-1 SE East		Pass	6/23/2016		
N10L9M104	11th Flor Stair-1 NE East		Pass	6/23/2016		
N10L9M146	Penthouse Stair 2 13th Fl.		Pass	6/24/2016		
N10L9M147	Penthouse Stair 2 14th Fl.		Pass	6/24/2016		
N20L1M3	Basement Stair 16 Bldg 26		Pass	6/23/2016		
N20L1M9	Basement Stair 17 Bldg 26		Pass	6/23/2016		

**Inspection** VA Medical Center  
**Inspection Date** 6/23/2016

**Inspection Number** 0  
**Inspector** Bill Brown

Device Tested		Test Date		Comments
Address	Description	FailReason	P/F/NT	
DeviceType	Waterflow	Standard	EC.02.03.05 EP 2/NFPA7	
N20L1M15	1st Flr Stair 16 Bldg 26		Pass	6/23/2016
N20L1M21	1st Flr St-17 Bldg 26		Pass	6/23/2016
N20L1M24	1st Floor Stair 18 Bldg 26		Pass	6/23/2016
N20L1M83	Basement Stair 18 Bldg 26		Pass	6/23/2016
N20L1M121	1st Floor Stair 18 Bldg 26		Pass	6/23/2016
N20L2M2	2nd Flr Stair 16 Bldg 26		Pass	6/23/2016
N20L2M9	2nd Flr Stair 17 Bldg 26		Pass	6/23/2016
N20L2M14	2nd Flr Stair 18 SE Bldg 26	Leaky Valve. Valve Repaired	Pass	6/24/2016
N20L2M15	2nd Flr Stair 18 NE Bldg 26	Leaky Valve. Valve Repaired	Pass	6/24/2016
N20L3M2	3rd Flr Stair 16 Bldg 26		Pass	6/23/2016
N20L3M6	3rd Flr Stair 17 Bldg 26		Pass	6/23/2016
N20L3M9	3rd Flr Stair 18 Bldg 26		Pass	6/23/2016
N20L4M2	4th Flr Stair 16 Bldg 26		Pass	6/23/2016
N20L4M7	4th Flr Stair 17 Bldg 26		Pass	6/23/2016

**Inspection** VA Medical Center  
**Inspection Date** 6/23/2016

**Inspection Number** 0  
**Inspector** Bill Brown

Device Tested		Test Date				
Address	Description	FailReason	P/F/NT	Current	Previous	Comments
DeviceType	Waterflow	Standard	EC.02.03.05 EP 2/NFPA7			
N20L4M10	4th Flr Stair 18 Bldg 26		Pass	6/23/2016		
N20L4M52	5th Flr Stair 16 Bldg 26		Pass	6/23/2016		
N20L4M78	Stair 18 PH 1 BLDG 26		Pass	6/23/2016		
N20L4M79	Stair 18 PH 2 BLDG 26		Pass	6/23/2016		
N20L5M7	5th Flr Stair 17 Bldg 26		Pass	6/23/2016		
N20L5M59	5th Floor Stair 18		Pass	6/23/2016		
N30L1M12	1st Floor Stair 14 Bldg 15	Failed Trip Time Limit	Fail	6/30/2016		
N30L1M20	2nd Floor Stair 14 Bldg 15 S		Pass	6/30/2016		
N30L1M22	2nd Floor Stair 20 Bldg 15 N		Pass	6/30/2016		
N30L1M25	2nd Floor Stair 20 Bldg 15 N		Pass	6/30/2016		
N30L1M32	3rd Floor Stair 14 Bldg 15 S	Failed Trip Time Limit	Fail	6/30/2016		
N30L1M34	3rd Floor Stair 14 Bldg 15 S		Pass	6/30/2016		
N30L1M37	3rd Floor Stair 20 Bldg 15 N		Pass	6/30/2016		
N30L1M105	1st Floor Locker Rm Bldg 15 Nrth	Sticky Hard to Reset	Pass	6/30/2016		

**Inspection** VA Medical Center  
**Inspection Date** 6/23/2016

**Inspection Number** 0  
**Inspector** Bill Brown

Device Tested		Test Date				
Address	Description	FailReason	P/F/NT	Current	Previous	Comments
DeviceType	Waterflow	Standard	EC.02.03.05 EP 2/NFPA7			
N30L1M107	1st Floor Satir 14 Bldg 15		Pass	6/30/2016		
N30L1M116	Basement Flow Bldg 15		Pass	6/30/2016		
N30L2M3	4th Floor South Bldg 15		Pass	6/30/2016		
N30L2M7	4th Floor South Bldg 15		Pass	6/30/2016		
N30L2M10	4th Floor North Bldg 15		Pass	6/30/2016		
N30L2M17	5th Floor South Bldg 15	Failed trip in time limit	Fail	6/30/2016		
N30L2M20	5th Floor North Bldg 15		Pass	6/30/2016		
N30L2M27	6th Stair 14 Bldg 15		Pass	6/30/2016		
N30L2M30	6th Stair 20 Bldg 15		Pass	6/30/2016		
N30L2M37	7th Stair 14 Bldg 15		Pass	6/30/2016		
N30L2M40	7th Stair 14 Bldg 15		Pass	6/30/2016		
N30L2M45	8th Floor Bldg 15		Pass	6/30/2016		
N30L2M50	8th FLOOR Bldg 15		Pass	6/30/2016		
N50L1M97	Receiving/Facilities Bldg 6		Pass	6/24/2016		

**Inspection**    VA Medical Center

---

**Inspection Date**    6/23/2016

---

**Inspection Number**    0

---

**Inspector**    Bill Brown

---

Device Tested		Test Date			
Address	Description	FailReason	P/F/NT	Current	Previous
DeviceType		Standard	EC.02.03.05 EP 2/NFPA7		Comments
N80L1M24	Sprinkler Room Bldg 2		Pass	6/24/2016	