

VAMC - Reno, NV - Building 7 - Lead Based Paint

GENERAL ABBREVIATIONS:

NA = NOT APPLICABLE

NOD = NOT ON DRAWING (i.e. This Room # listed in VA Database but not present on the Cadd Files provided to SELC as attached and presented in the associated report by SELC)

LBP ABBREVIATIONS:

GR = PAINT APPLIED TO METAL GUARD RAIL AROUND VERTICAL PIPING

HR = PAINT APPLIED TO METAL HANDRAILS

L = PAINT APPLIED TO METAL LADDER TO ROOF

LD = PAINT APPLIED TO METAL SUPPORTS, HANDRAILS, GUARD RAILS OF LOADING DOCK AND LOADING DOCK CANOPY

PL = PAINT APPLIED TO METAL PLATFORM COMPONENTS

SK = GLAZING ON PORCELAIN MOP SINK

SS = PAINT APPLIED TO STRUCTURAL STEEL

STATUS ABBREVIATIONS:

A = (ACTIVE) / LBP STILL FULLY IN PLACE

B = (BETWEEN) / LBP ENCLOSED, ENCAPSULATED, OR PARTIALLY REMOVED

C = (CLOSED) / LBP NOT PRESENT OR FULLY REMOVED

CONDITION ABBREVIATIONS:

GOOD = SUBSTANTIALLY INTACT

FAIR = MOSTLY INTACT WITH SCATTERED SMALL AREAS OF MINOR DAMAGE

POOR = LARGE AREAS OR MANY SMALL AREAS OF SIGNIFICANT DAMAGE OR DETERIORATION

VAMC - Reno, NV - Building 7 - Lead Based Paint

| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 |
|--------------------------|---------|------------|------------|--------------------|------------------|------------------------|---------------------------|----------------------|
| Current LBP Status | Floor # | New Room # | Old Room # | LBP Description | LBP Condition | LBP Action Taken | LBP Photo | LBP Drawing |
| A | 1 | Exterior | Exterior | HR, LD | Good | None | \\r01renhsm01.r01.med.va. | \\r01renhsm01.r01.me |
| A | 1 | N201 | 117 | SS, PLF, HR, L, GR | Fair | None | \\r01renhsm01.r01.med.va. | \\r01renhsm01.r01.me |
| A | 1 | N202 | 116 | SS | Good | None | | \\r01renhsm01.r01.me |
| A | 1 | N210 | 115 | SS | Good | None | | \\r01renhsm01.r01.me |
| A | 1 | N211 | 114 | SS | Good | None | | \\r01renhsm01.r01.me |
| A | 1 | N212 | 112 | SS | Good | None | | \\r01renhsm01.r01.me |
| A | 1 | N213 | 111 | SS | Good | None | | \\r01renhsm01.r01.me |
| A | 1 | N214 | 110 | SS | Good | None | | \\r01renhsm01.r01.me |
| A | 1 | N215 | 109 | SS | Good | None | | \\r01renhsm01.r01.me |
| A | 1 | N220 | 108 | SS | Good | None | \\r01renhsm01.r01.med.va. | \\r01renhsm01.r01.me |
| A | 1 | N222 | 101 | SS | Good | None | | \\r01renhsm01.r01.me |
| A | 1 | N223 | 102 | SS | Good | None | | \\r01renhsm01.r01.me |
| A | 1 | N223A | 103 | SS | Good | None | | \\r01renhsm01.r01.me |

v.d.æ

v.d.æ

v.d.æ

v.d.æ

v.d.æ

v.d.æ

v.d.æ

v.d.æ

v.d.æ

v.d.æ

v.d.æ

v.d.æ

v.d.æ

VAMC - Reno, NV - Building 7 - Lead Based Paint

| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 |
|--------------------------|---------|------------------|------------|-----------------|------------------|------------------------|---------------------------|----------------------|
| Current LBP Status | Floor # | New Room # | Old Room # | LBP Description | LBP Condition | LBP Action Taken | LBP Photo | LBP Drawing |
| A | 1 | N224 | 104 | SK, SS | Good | None | \\r01renhsm01.r01.med.va. | \\r01renhsm01.r01.me |
| A | 1 | N225 | 106 | SS | Good | None | | \\r01renhsm01.r01.me |
| A | 1 | N225A | 105 | SS | Good | None | | \\r01renhsm01.r01.me |
| A | 1 | N226 | 107 | SS | Good | None | | \\r01renhsm01.r01.me |
| A | 1 | None Assigned | File Room | HR, SS | Good | None | | \\r01renhsm01.r01.me |

v.p.d.æ

v.p.d.æ

v.p.d.æ

v.p.d.æ

v.p.d.æ