

**Attachment A (rev 8-11-2017)****ROOF LEAKS – Lake Nona Facility****A. Building 1 &2, Hospital & Clinic**

1. Cafeteria
2. Nurse Manager's Office, Emergency Department (1F503)
3. Cardiology offices (1F106 a, 1F 104, & 1F 408)

**B. Building 5, Warehouse**

1. Entire west wall, multiple area
2. Both walkways between warehouse (Bldg. 5) and Hospital (Bldg. 1&2)

**C. Building 7, Central Energy Plant (CEP)**

1. Main electrical/mechanical room (room 1A101B & 1A118b)
2. Hallway (near rest room)

**D. Building 11, Community living Center (CLC)**

1. Conference room (1A102)
2. Multi-purpose room (1A508)
3. Chief Nurse Room (1A112 & 1A112C)
4. PT Gym (1A611)
5. Hallway (main entrance)