

SECTION 1
SURVEY SUMMARY

ACM SURVEY RESULTS

Facility Wide Survey - 1620913 AS
5901 East 7th Street
Long Beach, California 90822

The following materials were Asbestos Containing and the total quantity in the building referenced below is an accumulation of all materials in that group found within the referenced building.

Building 3	
Material	Square Footage
Floor Tile	4,200
Mastic	4,200
Plaster	1,000
Joint Compound	4,300
Plastic Roof Cement	450
Stucco	8,000
Insulation Debris	10,500
Total	32,650

*Quantity Not Provided in previous survey data provided by VA Long Beach environmental department.

**SECTION 1
SURVEY SUMMARY**

ACM SURVEY RESULTS

**Facility Wide Survey - 1620913 AS
5901 East 7th Street
Long Beach, California 90822**

The following materials were Asbestos Containing and the total quantity in the building referenced below is an accumulation of all materials in that group found within the referenced building.

Building 11	
Material	Square Footage
NA	

*Quantity Not Provided in previous survey data provided by VA Long Beach environmental department.

SECTION 1
SURVEY SUMMARY

ACM SURVEY RESULTS

Facility Wide Survey - 1620913 AS
5901 East 7th Street
Long Beach, California 90822

The following materials were Asbestos Containing and the total quantity in the building referenced below is an accumulation of all materials in that group found within the referenced building.

Building 150-	
Material	Square Footage
All Samples "ND"	

*Quantity Not Provided in previous survey data provided by VA Long Beach environmental department.