

Current Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT							
					Asbestos Present	Contractor Sample No.	PreviouslySampled (Y/N)	HA #	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	SignificantlyDamaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc
110-101-112-102-111-114	Ceiling	Acoutstic Ceiling Tile Pinhole Big Worm	2x2		N	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	Wall(s)	Wallboard With Joint Compound		Beige	N	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	Floor	Carpet		Blue/Purple	N	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	Door/Door Frame	Wood/Metal		Bare/Beige	N	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	Misc	Covebase & Mastic	4"	Tan & Tan	N	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	Misc															
	Misc															
103-105	Ceiling	Acoutstic Ceiling Tile Pin Hole Big Worm	2x2		N	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	Wall(s)	Wallboard With Joint Compound		Beige	N	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	Floor	Ceramic Tile & Grout	12x12	Tan & Tan	N	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	Door/Door Frame	Wood/Metal		Bare/Beige	N	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	Misc	Ceramic Tile & Grout	12x12	Beige & Tan	N	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	Misc															
	Misc															
104-107-108	Ceiling	Acoutstic Ceiling Tile Pin Hole Big Worm	2x2x			N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	Wall(s)	Wallboard With Joint Compound		Beige	N	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	Floor	Resilient Floor Tile & Mastic	12x12	Tan	N	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	Door/Door Frame	Wood/Metal		Bare/Beige	N	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	Misc	Covebase & Mastic Mastic	4"	Tan & Tan	N	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	Misc															
	Misc															
109	Ceiling	Acoutstic Ceiling Tile Pin Hole Big Worm	2x2		N	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	Wall(s)	Wallboard With Joint Compound		Off White	N	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	Floor	Carpet		Blue/Purple	N	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	Door/Door Frame	Wood/Metal	Not Suspect	Bare/Beige	N	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	Misc	Covebase & Mastic	4"	Tan & Tan	N	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	Misc															
	Misc															
	Ceiling	Acoutstic Ceiling Tile Pin Hole Big Worm	2x2			N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	Wall(s)	Wallboard With Joint Compound		Beige	N	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	Floor	Resilient Floor Tile x2	12x12	Tan/White	N	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Current Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT							
					Asbestos Present	Contractor Sample No.	PreviouslySampled (Y/N)	HA #	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	SignificantlyDamaged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc
116	Ceiling	Acoutstic Ceiling Tile Pin Hole Big Worm	2x2		N	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	Wall(s)	Wallboard With Joint Compound			N	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	Floor	Resilient Floor Tile	12x12	White	N	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	Door/Door Frame	Wood/Metal		Tan	N	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	Misc	Covebase & Mastic	4"	Bare/Beige	N	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	Misc	Covebase and Glue		Tan & Tan	N	N	Y	N	N							
	Misc															
115	Ceiling	Acoutstic Ceiling Tile Pin Hole Big Worm	2x2		N	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	Wall(s)	Wallboard With Joint Compound Copper Lined		Beige	N	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	Floor	Resilient Floor Tile	12x12	tan	N	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	Door/Door Frame	Wood/Metal		Bare/Beige	N	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	Misc	Covebase & Mastic	4"	Tan & Tan	N	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	Misc				N	N	Y	N	N	N/A						
	Misc															
Ext.	Ceiling	Stucco		Beige	N	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	Wall(s)	Window Sealant		Beige & Black	N	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	Floor															
	Door/Door Frame															
	Misc															
	Misc															
	Misc															
Outdoor Corridor	Ceiling	Acoutstic Ceiling Tile Pin Hole Big Worm	2x4		N	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	Wall(s)	Wallboard With joint Compound		Green/Beige	N	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	Floor	Resiliet Floor Tile	12x12	White/Gray	N	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	Door/Door Frame				N	N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	Misc	Covebase & Mastic	4"	Tan & White	N	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	Misc				N	N	Y	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	Misc															
Roof	Ceiling	Built Up Roof White Sealed Membrane		White		N	N	N	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	Wall(s)	Parapit Sealant		White	N	R2.1-R2.3	N	R2	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	Floor	Roof Penetration Mastic		White	N	R1.1-R1.3	N	R1	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	Door/Door Frame	HVAC Duct Sealant		Gray	N	R3.1-R3.3	N	R3	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A

Current Rm Name/No.	Surface	Material	Size	Color	Sample Info				HAZARD ASSESSMENT							
					Asbestos Present	Contractor Sample No.	PreviouslySa mpled (Y/N)	HA #	Friable	Good - No Damage	Damaged (10% overall or 25% localized)	SignificantlyDa maged >10% overall OR >25% localized)	Potential for Damage (vibration, Access, Erosion)	TSI	Surfacing	Misc
	Misc	Parapit Sealant on 160 Corridor		Black	Y (5%)	R4.1-4.3	N	R4	N	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	Misc															
	Misc															