

B.4 SCHEDULE OF SERVICES AND PRICE (revised 09-20-2017)

a) CLINs 1001 through 1016, 1019, 2001 through 2016, 2019, 3001 through 3016, 3019, 4001 through 4016, 4019, 5001 through 5016, and 5019 are firm fixed priced, definite-quantity CLINs and shall be invoiced upon acceptance of services rendered.

b) CLINs 1017 through 1018, 2017 through 2018, 3017 through 3018, 4017 through 4018, and 5017 through 5018 are firm fixed priced, indefinite-quantity CLINs for labor and parts. Authorization to perform services will be made through a modification, task order, or authorization from the Contracting Officer (CO). The contractor shall not perform work under these CLINs that exceed the stated quantities.

ORDERING PERIOD 1: September 30, 2017 through August 31, 2018

CLIN	DESCRIPTION	QTY	UNIT	UNIT PRICE	TOTAL PRICE
1001	Lake Nona Cat-3516/GA-1 KHD00222/SBK00962 2500kW	-	-	NSP	NSP
1001A	Semi-Annual Inspection	1	JB		
1001B	Annual Inspection	1	JB		
1002	Lake Nona Cat-3516/GA-2 KHD00223/SBK00961 2500kW	-	-	NSP	NSP
1002A	Semi-Annual Inspection	1	JB		
1002B	Annual Inspection	1	JB		
1003	Lake Nona Cat-3516/GA-3 KHD00220/SBK00958 2500kW	-	-	NSP	NSP
1003A	Semi-Annual Inspection	1	JB		
1003B	Annual Inspection	1	JB		
1004	Lake Nona Cat-3516/GA-4 KHD00221/SBK00957 2500kW	-	-	NSP	NSP
1004A	Semi-Annual Inspection	1	JB		
1004B	Annual Inspection	1	JB		

1005	Lake Nona Cat-3516/GB-1 KHD00224/SBK00963 2500kW	-	-	NSP	NSP
1005A	Semi-Annual Inspection	1	JB		
1005B	Annual Inspection	1	JB		
1006	Lake Nona Cat-3516/GB-2 KHD00226/SBK00964 2500kW	-	-	NSP	NSP
1006A	Semi-Annual Inspection	1	JB		
1006B	Annual Inspection	1	JB		
1007	Lake Nona Cat-3516/GB-3 KHD00225/SBK00965 2500kW	-	-	NSP	NSP
1007A	Semi-Annual Inspection	1	JB		
1007B	Annual Inspection	1	JB		
1008	Lake Nona Cat-3516/GB-4 KHD00227/SBK00966 2500kW	-	-	NSP	NSP
1008A	Semi-Annual Inspection	1	JB		
1008B	Annual Inspection	1	JB		
1009	Lake Baldwin Cat-C27 CAT00C27VGDS00900 750kW	-	-	NSP	NSP
1009A	Semi-Annual Inspection	1	JB		
1009B	Annual Inspection	1	JB		
1009C	Load-bank Testing	1	JB		
1010	Lake Baldwin Cat-C27 CAT00C27HGDS00898 750kW	-	-	NSP	NSP
1010A	Semi-Annual Inspection	1	JB		

1010B	Annual Inspection	1	JB		
1010C	Load-bank Testing	1	JB		
1011	Lake Baldwin Cat-C27 CAT00C27VGDS00296 750kW	-	-	NSP	NSP
1011A	Semi-Annual Inspection	1	JB		
1011B	Annual Inspection	1	JB		
1011C	Load-bank Testing	1	JB		
1012	Lake Baldwin Cummins/Onan GGHE-S 60kW	-	-	NSP	NSP
1012A	Semi-Annual Inspection	1	JB		
1012B	Annual Inspection	1	JB		
1012C	Load-bank Testing	1	JB		
1013	Lake Baldwin Cat-APS100 A-60526049 100kW	-	-	NSP	NSP
1013A	Semi-Annual Inspection	1	JB		
1013B	Annual Inspection	1	JB		
1013C	Load-bank Testing	1	JB		
1014	Viera Detroit (DDC) 750ROZD-R 750kW	-	-	NSP	NSP
1014A	Semi-Annual Inspection	1	JB		
1014B	Annual Inspection	1	JB		
1014C	Load-bank Testing	1	JB		
1015	Lakemont Cat-3512C SBG00204 1500kW	-	-	NSP	NSP

1015A	Semi-Annual Inspection	1	JB		
1015B	Annual Inspection	1	JB		
1015C	Load-bank Testing	1	JB		
1016	Lakemont Cat-600 CAT0048LNAW00156 600kW	-	-	NSP	NSP
1016A	Semi-Annual Inspection	1	JB		
1016B	Annual Inspection	1	JB		
1016C	Load-bank Testing	1	JB		
1017	Labor Rate	-	-	NSP	NSP
1017A	Labor Rate - Normal Hours	0	HR		
1017B	Labor Rate - After hours	20	HR		
1017C	Labor Rate - Sunday / Holiday	0	HR		
1018	Parts	1	LT		
1019	Fuel Analysis Testing & Reporting	-	-	NSP	NSP
1019A	Underground Storage Tank (UST) 25,000 gallons (diesel) Lake Nona	8	EA		
1019B	UST 4,000 gallons (diesel) Lake Nona	1	EA		
1019C	UST 4,000 gallons (unleaded) Lake Nona	1	EA		
1019D	Aboveground Storage Tank (AST) 8,000 gallons (diesel) Lake Baldwin	2	EA		
1019E	AST 3,000 gallons (diesel) Lakemont	1	EA		
1019F	AST (underbelly) 1,200 gallons (diesel) Lakemont	1	EA		
1019G	AST (underbelly) 1,000 gallons Viera	1	EA		

TOTAL PRICE FOR ORDERING PERIOD 1: _____

ORDERING PERIOD 2: September 01, 2018 through August 31, 2019

CLIN	DESCRIPTION	QTY	UNIT	UNIT PRICE	TOTAL PRICE
2001	Lake Nona Cat-3516/GA-1 KHD00222/SBK00962 2500kW	-	-	NSP	NSP
2001A	Semi-Annual Inspection	1	JB		
2001B	Annual Inspection	1	JB		
2001C	Triennial Service / Inspection	1	JB		
2001D	Battery Replacement	0	JB		
2002	Lake Nona Cat-3516/GA-2 KHD00223/SBK00961 2500kW	-	-	NSP	NSP
2002A	Semi-Annual Inspection	1	JB		
2002B	Annual Inspection	1	JB		
2002C	Triennial Service / Inspection	1	JB		
2002D	Battery Replacement	0	JB		
2003	Lake Nona Cat-3516/GA-3 KHD00220/SBK00958 2500kW	-	-	NSP	NSP
2003A	Semi-Annual Inspection	1	JB		
2003B	Annual Inspection	1	JB		
2003C	Triennial Service / Inspection	1	JB		
2003D	Battery Replacement	0	JB		
2004	Lake Nona Cat-3516/GA-4 KHD00221/SBK00957 2500kW	-	-	NSP	NSP

2004A	Semi-Annual Inspection	1	JB		
2004B	Annual Inspection	1	JB		
2004C	Triennial Service / Inspection	1	JB		
2004D	Battery Replacement	0	JB		
2005	Lake Nona Cat-3516/GB-1 KHD00224/SBK00963 2500kW	-	-	NSP	NSP
2005A	Semi-Annual Inspection	1	JB		
2005B	Annual Inspection	1	JB		
2005C	Triennial Service / Inspection	1	JB		
2005D	Battery Replacement	0	JB		
2006	Lake Nona Cat-3516/GB-2 KHD00226/SBK00964 2500kW	-	-	NSP	NSP
2006A	Semi-Annual Inspection	1	JB		
2006B	Annual Inspection	1	JB		
2006C	Triennial Service / Inspection	1	JB		
2006D	Battery Replacement	0	JB		
2007	Lake Nona Cat-3516/GB-3 KHD00225/SBK00965 2500kW	-	-	NSP	NSP
2007A	Semi-Annual Inspection	1	JB		
2007B	Annual Inspection	1	JB		
2007C	Triennial Service / Inspection	1	JB		
2007D	Battery Replacement	0	JB		
2008	Lake Nona Cat-3516/GB-4	-	-	NSP	NSP

	KHD00227/SBK00966 2500kW				
2008A	Semi-Annual Inspection	1	JB		
2008B	Annual Inspection	1	JB		
2008C	Triennial Service / Inspection	1	JB		
2008D	Battery Replacement	0	JB		
2009	Lake Baldwin Cat-C27 CAT00C27VGDS00900 750kW	-	-	NSP	NSP
2009A	Semi-Annual Inspection	1	JB		
2009B	Annual Inspection	1	JB		
2009C	Load-bank Testing	1	JB		
2009D	Triennial Service / Inspection	1	JB		
2009E	Battery Replacement	1	JB		
2010	Lake Baldwin Cat-C27 CAT00C27HGDS00898 750kW	-	-	NSP	NSP
2010A	Semi-Annual Inspection	1	JB		
2010B	Annual Inspection	1	JB		
2010C	Load-bank Testing	1	JB		
2010D	Triennial Service / Inspection	1	JB		
2010E	Battery Replacement	1	JB		
2011	Lake Baldwin Cat-C27 CAT00C27VGDS00296 750kW	-	-	NSP	NSP
2011A	Semi-Annual Inspection	1	JB		
2011B	Annual Inspection	1	JB		

2011C	Load-bank Testing	1	JB		
2011D	Triennial Service / Inspection	1	JB		
2011E	Battery Replacement	1	JB		
2012	Lake Baldwin Cummins/Onan GGHE-S 60kW	-	-	NSP	NSP
2012A	Semi-Annual Inspection	1	JB		
2012B	Annual Inspection	1	JB		
2012C	Load-bank Testing	1	JB		
2012D	Triennial Service / Inspection	1	JB		
2012E	Battery Replacement	1	JB		
2013	Lake Baldwin Cat-APS100 A-60526049 100kW	-	-	NSP	NSP
2013A	Semi-Annual Inspection	1	JB		
2013B	Annual Inspection	1	JB		
2013C	Load-bank Testing	1	JB		
2013D	Triennial Service / Inspection	1	JB		
2013E	Battery Replacement	1	JB		
2014	Viera Detroit (DDC) 750ROZD-R 750kW	-	-	NSP	NSP
2014A	Semi-Annual Inspection	1	JB		
2014B	Annual Inspection	1	JB		
2014C	Load-bank Testing	1	JB		
2014D	Triennial Service / Inspection	1	JB		

2014E	Battery Replacement	1	JB		
2015	Lakemont Cat-3512C SBG00204 1500kW	-	-	NSP	NSP
2015A	Semi-Annual Inspection	1	JB		
2015B	Annual Inspection	1	JB		
2015C	Load-bank Testing	1	JB		
2015D	Triennial Service / Inspection	1	JB		
2015E	Battery Replacement	1	JB		
2016	Lakemont Cat-600 CAT0048LNAW00156 600kW	-	-	NSP	NSP
2016A	Semi-Annual Inspection	1	JB		
2016B	Annual Inspection	1	JB		
2016C	Load-bank Testing	1	JB		
2016D	Triennial Service / Inspection	1	JB		
2016E	Battery Replacement	1	JB		
2017	Labor Rate	-	-	NSP	NSP
2017A	Labor Rate - Normal Hours	0	HR		
2017B	Labor Rate - After hours	20	HR		
2017C	Labor Rate - Sunday / Holiday	0	HR		
2018	Parts	1	LT		
2019	Fuel Analysis Testing & Reporting	-	-	NSP	NSP
2019A	Underground Storage Tank (UST) 25,000 gallons (diesel) Lake Nona	8	EA		
2019B	UST 4,000 gallons (diesel)	1	EA		

	Lake Nona				
2019C	UST 4,000 gallons (unleaded) Lake Nona	1	EA		
2019D	Aboveground Storage Tank (AST) 8,000 gallons (diesel) Lake Baldwin	2	EA		
2019E	AST 3,000 gallons (diesel) Lakemont	1	EA		
2019F	AST (underbelly) 1,200 gallons (diesel) Lakemont	1	EA		
2019G	AST (underbelly) 1,000 gallons (diesel) Viera	1	EA		

TOTAL PRICE FOR ORDERING PERIOD 2: _____

ORDERING PERIOD 3: September 01, 2019 through August 31, 2020

CLIN	DESCRIPTION	QTY	UNIT	UNIT PRICE	TOTAL PRICE
3001	Lake Nona Cat-3516/GA-1 KHD00222/SBK00962 2500kW	-	-	NSP	NSP
3001A	Semi-Annual Inspection	1	JB		
3001B	Annual Inspection	1	JB		
3002	Lake Nona Cat-3516/GA-2 KHD00223/SBK00961 2500kW	-	-	NSP	NSP
3002A	Semi-Annual Inspection	1	JB		
3002B	Annual Inspection	1	JB		
3003	Lake Nona Cat-3516/GA-3 KHD00220/SBK00958 2500kW	-	-	NSP	NSP
3003A	Semi-Annual Inspection	1	JB		
3003B	Annual Inspection	1	JB		

3004	Lake Nona Cat-3516/GA-4 KHD00221/SBK00957 2500kW	-	-	NSP	NSP
3004A	Semi-Annual Inspection	1	JB		
3004B	Annual Inspection	1	JB		
3005	Lake Nona Cat-3516/GB-1 KHD00224/SBK00963 2500kW	-	-	NSP	NSP
3005A	Semi-Annual Inspection	1	JB		
3005B	Annual Inspection	1	JB		
3006	Lake Nona Cat-3516/GB-2 KHD00226/SBK00964 2500kW	-	-	NSP	NSP
3006A	Semi-Annual Inspection	1	JB		
3006B	Annual Inspection	1	JB		
3007	Lake Nona Cat-3516/GB-3 KHD00225/SBK00965 2500kW	-	-	NSP	NSP
3007A	Semi-Annual Inspection	1	JB		
3007B	Annual Inspection	1	JB		
3008	Lake Nona Cat-3516/GB-4 KHD00227/SBK00966 2500kW	-	-	NSP	NSP
3008A	Semi-Annual Inspection	1	JB		
3008B	Annual Inspection	1	JB		
3009	Lake Baldwin Cat-27 CAT00C27VGDS00900 750kW	-	-	NSP	NSP
3009A	Semi-Annual Inspection	1	JB		

3009B	Annual Inspection	1	JB		
3009C	Load-bank Testing	1	JB		
3010	Lake Baldwin Cat-C27 CAT00C27HGDS00898 750kW	-	-	NSP	NSP
3010A	Semi-Annual Inspection	1	JB		
3010B	Annual Inspection	1	JB		
3010C	Load-bank Testing	1	JB		
3011	Lake Baldwin Cat-C27 CAT00C27VGDS00296 750kW	-	-	NSP	NSP
3011A	Semi-Annual Inspection	1	JB		
3011B	Annual Inspection	1	JB		
3011C	Load-bank Testing	1	JB		
3012	Lake Baldwin Cummins/Onan GGHE-S 60kW	-	-	NSP	NSP
3012A	Semi-Annual Inspection	1	JB		
3012B	Annual Inspection	1	JB		
3012C	Load-bank Testing	1	JB		
3013	Lake Baldwin Cat-APS100 A-60526049 100kW	-	-	NSP	NSP
3013A	Semi-Annual Inspection	1	JB		
3013B	Annual Inspection	1	JB		
3013C	Load-bank Testing	1	JB		
3014	Viera Detroit (DDC)	-	-	NSP	NSP

	750ROZD-R 750kW				
3014A	Semi-Annual Inspection	1	JB		
3014B	Annual Inspection	1	JB		
3014C	Load-bank Testing	1	JB		
3015	Lakemont Cat-3512C SBG00204 1500kW	-	-	NSP	NSP
3015A	Semi-Annual Inspection	1	JB		
3015B	Annual Inspection	1	JB		
3015C	Load-bank Testing	1	JB		
3016	Lakemont Cat-600 CAT0048LNAW00156 600kW	-	-	NSP	NSP
3016A	Semi-Annual Inspection	1	JB		
3016B	Annual Inspection	1	JB		
3016C	Load-bank Testing	1	JB		
3017	Labor Rate	-	-	NSP	NSP
3017A	Labor Rate - Normal Hours	0	HR		
3017B	Labor Rate - After hours	20	HR		
3017C	Labor Rate - Sunday / Holiday	0	HR		
3018	Parts	1	LT		
3019	Fuel Analysis Testing & Reporting	-	-	NSP	NSP
3019A	Underground Storage Tank (UST) 25,000 gallons (diesel) Lake Nona	8	EA		
3019B	UST 4,000 gallons (diesel) Lake Nona	1	EA		

3019C	UST 4,000 gallons (unleaded) Lake Nona	1	EA		
3019D	Aboveground Storage Tank (AST) 8,000 gallons (diesel) Lake Baldwin	2	EA		
3019E	AST 3,000 gallons (diesel) Lakemont	1	EA		
3019F	AST (underbelly) 1,200 gallons (diesel) Lakemont	1	EA		
3019G	AST (underbelly) 1,000 gallons (diesel) Viera	1	EA		

TOTAL PRICE FOR ORDERING PERIOD 3: _____

ORDERING PERIOD 4: September 01, 2020 through August 31, 2021

CLIN	DESCRIPTION	QTY	UNIT	UNIT PRICE	TOTAL PRICE
4001	Lake Nona Cat-3516/GA-1 KHD00222/SBK00962 2500kW	-	-	NSP	NSP
4001A	Semi-Annual Inspection	1	JB		
4001B	Annual Inspection	1	JB		
4002	Lake Nona Cat-3516/GA-2 KHD00223/SBK00961 2500kW	-	-	NSP	NSP
4002A	Semi-Annual Inspection	1	JB		
4002B	Annual Inspection	1	JB		
4003	Lake Nona Cat-3516/GA-3 KHD00220/SBK00958 2500kW	-	-	NSP	NSP
4003A	Semi-Annual Inspection	1	JB		

4003B	Annual Inspection	1	JB		
4004	Lake Nona Cat-3516/GA-4 KHD00221/SBK00957 2500kW	-	-	NSP	NSP
4004A	Semi-Annual Inspection	1	JB		
4004B	Annual Inspection	1	JB		
4005	Lake Nona Cat-3516/GB-1 KHD00224/SBK00963 2500kW	-	-	NSP	NSP
4005A	Semi-Annual Inspection	1	JB		
4005B	Annual Inspection	1	JB		
4006	Lake Nona Cat-3516/GB-2 KHD00226/SBK00964 2500kW	-	-	NSP	NSP
4006A	Semi-Annual Inspection	1	JB		
4006B	Annual Inspection	1	JB		
4007	Lake Nona Cat-3516/GB-3 KHD00225/SBK00965 2500kW	-	-	NSP	NSP
4007A	Semi-Annual Inspection	1	JB		
4007B	Annual Inspection	1	JB		
4008	Lake Nona Cat-3516/GB-4 KHD00227/SBK00966 2500kW	-	-	NSP	NSP
4008A	Semi-Annual Inspection	1	JB		
4008B	Annual Inspection	1	JB		
4009	Lake Baldwin Cat27 CAT00C27VGDS00900 750kW	-	-	NSP	NSP

4009A	Semi-Annual Inspection	1	JB		
4009B	Annual Inspection	1	JB		
4009C	Load-bank Testing	1	JB		
4010	Lake Baldwin Cat-C27 CAT00C27HGDS00898 750kW	-	-	NSP	NSP
4010A	Semi-Annual Inspection	1	JB		
4010B	Annual Inspection	1	JB		
4010C	Load-bank Testing	1	JB		
4011	Lake Baldwin Cat-C27 CAT00C27VGDS00296 750kW	-	-	NSP	NSP
4011A	Semi-Annual Inspection	1	JB		
4011B	Annual Inspection	1	JB		
4011C	Load-bank Testing	1	JB		
4012	Lake Baldwin Cummins/Onan GGHE-S 60kW	-	-	NSP	NSP
4012A	Semi-Annual Inspection	1	JB		
4012B	Annual Inspection	1	JB		
4012C	Load-bank Testing	1	JB		
4013	Lake Baldwin Cat-APS100 A-60526049 100kW	-	-	NSP	NSP
4013A	Semi-Annual Inspection	1	JB		
4013B	Annual Inspection	1	JB		
4013C	Load-bank Testing	1	JB		

4014	Viera Detroit (DDC) 750ROZD-R 750kW	-	-	NSP	NSP
4014A	Semi-Annual Inspection	1	JB		
4014B	Annual Inspection	1	JB		
4014C	Load-bank Testing	1	JB		
4015	Lakemont Cat-3512C SBG00204 1500kW	-	-	NSP	NSP
4015A	Semi-Annual Inspection	1	JB		
4015B	Annual Inspection	1	JB		
4015C	Load-bank Testing	1	JB		
4016	Lakemont Cat-600 CAT0048LNAW00156 600kW	-	-	NSP	NSP
4016A	Semi-Annual Inspection	1	JB		
4016B	Annual Inspection	1	JB		
4016C	Load-bank Testing	1	JB		
4017	Labor Rate	-	-	NSP	NSP
4017A	Labor Rate - Normal Hours	0	HR		
4017B	Labor Rate - After hours	20	HR		
4017C	Labor Rate - Sunday / Holiday	0	HR		
4018	Parts	1	LT		
4019	Fuel Analysis Testing & Reporting	-	-	NSP	NSP
4019A	Underground Storage Tank (UST) 25,000 gallons (diesel) Lake Nona	8	EA		
4019B	UST 4,000 gallons (diesel)	1	EA		

	Lake Nona				
4019C	UST 4,000 gallons (unleaded) Lake Nona	1	EA		
4019D	Aboveground Storage Tank (AST) 8,000 gallons (diesel) Lake Baldwin	2	EA		
4019E	AST 3,000 gallons (diesel) Lakemont	1	EA		
4019F	AST (underbelly) 1,200 gallons (diesel) Lakemont	1	EA		
4019G	AST (underbelly) 1,000 gallons (diesel) Viera	1	EA		

TOTAL PRICE FOR ORDERING PERIOD 4: _____

ORDERING PERIOD 5: September 01, 2021 through August 31, 2022

CLIN	DESCRIPTION	QTY	UNIT	UNIT PRICE	TOTAL PRICE
5001	Lake Nona Cat-3516/GA-1 KHD00222/SBK00962 2500kW	-	-	NSP	NSP
5001A	Semi-Annual Inspection	1	JB		
5001B	Annual Inspection	1	JB		
5001C	Triennial Service / Inspection	1	JB		
5001D	Battery Replacement	1	JB		
5002	Lake Nona Cat-3516/GA-2 KHD00223/SBK00961 2500kW	-	-	NSP	NSP
5002A	Semi-Annual Inspection	1	JB		
5002B	Annual Inspection	1	JB		
5002C	Triennial Service / Inspection	1	JB		

5002D	Battery Replacement	1	JB		
5003	Lake Nona Cat-3516/GA-3 KHD00220/SBK00958 2500kW	-	-	NSP	NSP
5003A	Semi-Annual Inspection	1	JB		
5003B	Annual Inspection	1	JB		
5003C	Triennial Service / Inspection	1	JB		
5003D	Battery Replacement	1	JB		
5004	Lake Nona Cat-3516/GA-4 KHD00221/SBK00957 2500kW	-	-	NSP	NSP
5004A	Semi-Annual Inspection	1	JB		
5004B	Annual Inspection	1	JB		
5004C	Triennial Service / Inspection	1	JB		
5004D	Battery Replacement	1	JB		
5005	Lake Nona Cat-3516/GB-1 KHD00224/SBK00963 2500kW	-	-	NSP	NSP
5005A	Semi-Annual Inspection	1	JB		
5005B	Annual Inspection	1	JB		
5005C	Triennial Service / Inspection	1	JB		
5005D	Battery Replacement	1	JB		
5006	Lake Nona Cat-3516/GB-2 KHD00226/SBK00964 2500kW	-	-	NSP	NSP
5006A	Semi-Annual Inspection	1	JB		
5006B	Annual Inspection	1	JB		

5006C	Triennial Service / Inspection	1	JB		
5006D	Battery Replacement	1	JB		
5007	Lake Nona Cat-3516/GB-3 KHD00225/SBK00965 2500kW	-	-	NSP	NSP
5007A	Semi-Annual Inspection	1	JB		
5007B	Annual Inspection	1	JB		
5007C	Triennial Service / Inspection	1	JB		
5007D	Battery Replacement	0	EA		
5008	Lake Nona Cat-3516/GB-4 KHD00227/SBK00966 2500kW	-	-	NSP	NSP
5008A	Semi-Annual Inspection	1	JB		
5008B	Annual Inspection	1	JB		
5008C	Triennial Service / Inspection	1	JB		
5008D	Battery Replacement	1	JB		
5009	Lake Baldwin Cat-C27 CAT00C27VGDS00900 750kW	-	-	NSP	NSP
5009A	Semi-Annual Inspection	1	JB		
5009B	Annual Inspection	1	JB		
5009C	Load-bank Testing	1	JB		
5009D	Triennial Service / Inspection	1	JB		
5009E	Battery Replacement	1	JB		
5010	Lake Baldwin Cat-C27 CAT00C27HGDS00898 750kW	-	-	NSP	NSP

5010A	Semi-Annual Inspection	1	JB		
5010B	Annual Inspection	1	JB		
5010C	Load-bank Testing	1	JB		
5010D	Triennial Service / Inspection	1	JB		
5010E	Battery Replacement	1	JB		
5011	Lake Baldwin Cat-C27 CAT00C27VGDS00296 750kW	-	-	NSP	NSP
5011A	Semi-Annual Inspection	1	JB		
5011B	Annual Inspection	1	JB		
5011C	Load-bank Testing	1	JB		
5011D	Triennial Service / Inspection	1	JB		
5011E	Battery Replacement	1	JB		
5012	Lake Baldwin Cummins/Onan GGHE-S 60kW	-	-	NSP	NSP
5012A	Semi-Annual Inspection	1	JB		
5012B	Annual Inspection	1	JB		
5012C	Load-bank Testing	1	JB		
5012D	Triennial Service / Inspection	1	JB		
5012E	Battery Replacement	1	JB		
5013	Lake Baldwin Cat-APS100 A-60526049 100kW	-	-	NSP	NSP
5013A	Semi-Annual Inspection	1	JB		
5013B	Annual Inspection	1	JB		

5013C	Load-bank Testing	1	JB		
5013D	Triennial Service / Inspection	1	JB		
5013E	Battery Replacement	1	JB		
5014	Viera Detroit (DDC) 750ROZD-R 750kW	-	-	NSP	NSP
5014A	Semi-Annual Inspection	1	JB		
5014B	Annual Inspection	1	JB		
5014C	Load-bank Testing	1	JB		
5014D	Triennial Service / Inspection	1	JB		
5014E	Battery Replacement	1	JB		
5015	Lakemont Cat-3512C SBG00204 1500kW	-	-	NSP	NSP
5015A	Semi-Annual Inspection	1	JB		
5015B	Annual Inspection	1	JB		
5015C	Load-bank Testing	1	JB		
5015D	Triennial Service / Inspection	1	JB		
5015E	Battery Replacement	1	JB		
5016	Lakemont Cat-600 CAT0048LNAW00156 600kW	-	-	NSP	NSP
5016A	Semi-Annual Inspection	1	JB		
5016B	Annual Inspection	1	JB		
5016C	Load-bank Testing	1	JB		
5016D	Triennial Service / Inspection	1	JB		

5016E	Battery Replacement	1	JB		
5017	Labor Rate	-	-	NSP	NSP
5017A	Labor Rate - Normal Hours	0	HR		
5017B	Labor Rate - After hours	20	HR		
5017C	Labor Rate - Sunday / Holiday	0	HR		
5018	Parts	1	LT		
5019	Fuel Analysis Testing & Reporting	-	-	NSP	NSP
5019A	Underground Storage Tank (UST) 25,000 gallons (diesel) Lake Nona	8	EA		
5019B	UST 4,000 gallons (diesel) Lake Nona	1	EA		
5019C	UST 4,000 gallons (unleaded) Lake Nona	1	EA		
5019D	Aboveground Storage Tank (AST) 8,000 gallons (diesel) Lake Baldwin	2	EA		
5019E	AST 3,000 gallons (diesel) Lakemont	1	EA		
5019F	AST (underbelly) 1,200 gallons (diesel) Lakemont	1	EA		
5019G	AST (underbelly) 1,000 gallons (diesel) Viera	1	EA		

TOTAL PRICE FOR ORDERING PERIOD 5: _____

AGGREGATE TOTAL PRICE FOR ALL ORDERING PERIODS: _____