

Exhibit 1: Tank Integrity Program - Requiring Steel Tank Institute SP001 Inspection by Certified SPI Inspector

Tank Location	Contents and Capacity	Comments and Details	Inspection Due	Type of Inspection
West Los Angeles MC	Tank 12	<u>Tank Configuration:</u> Double-Walled, Horizontal Tank	2018	5 Year
	5000 Gallon Diesel	<u>Inspection or Test Method Comments:</u> Tank is equipped with interstitial monitoring device. Monthly Visual Tank Inspections Performed. Integrity Testing Conducted in Accordance with STI Standards-001. External Tank inspections performed every 5 years by an authorized inspector. Internal inspection shall be performed every 20 years.		
West Los Angeles MC	Tank 215	<u>Tank Configuration:</u> Double-Walled, Horizontal Tank	2018	5 Year
	20,000 gallon Diesel	<u>Inspection or Test Method Comments:</u> Tank is equipped with interstitial monitoring device. Monthly Visual Tank Inspections Performed. Integrity Testing Conducted in Accordance with STI Standards-001. External Tank inspections performed every 5 years by an authorized inspector. Internal inspection shall be performed every 20 years.		
West Los Angeles MC	Tank 222	<u>Tank Configuration:</u> Double-Walled, Horizontal Tank	2018	5 Year
	1525 gallons Diesel	<u>Inspection or Test Method Comments:</u> Tank is equipped with interstitial monitoring device. Monthly Visual Tank Inspections Performed. Integrity Testing Conducted in Accordance with STI Standards-001. External Tank inspections performed every 5 years by an authorized inspector. Internal inspection shall be performed every 20 years.		
West Los Angeles MC	Tank 299	<u>Tank Configuration:</u> Double-Walled, Horizontal Tank	2018	5 Year
	2000 gallons Diesel	<u>Inspection or Test Method Comments:</u> Tank is equipped with interstitial monitoring device. Monthly Visual Tank Inspections Performed. Integrity Testing Conducted in Accordance with STI Standards-001. External Tank inspections performed every 5 years by an authorized inspector. Internal inspection shall be performed every 20 years.		
West Los Angeles MC	Tank 501	<u>Tank Configuration:</u> Double-Walled, Horizontal Tank	2018	5 Year
	20,000 gallons diesel	<u>Inspection or Test Method Comments:</u> Tank is equipped with interstitial monitoring device. Monthly Visual Tank Inspections Performed. Integrity Testing Conducted in Accordance with STI Standards-001. External Tank inspections performed every 5 years by an authorized inspector. Internal inspection shall be performed every 20 years.		
Los Angeles Ambulatory Clinic	Tank 1	<u>Tank Configuration:</u> Single Wall Horizontal Tank with berm	2018	20 Year
	5,000 gallons diesel	<u>Inspection or Test Method Comments:</u> Tank is equipped with interstitial monitoring device. Monthly Visual Tank Inspections Performed. Integrity Testing Conducted in Accordance with STI Standards-001. External Tank inspections performed every 5 years by an authorized inspector. Internal inspection shall be performed every 20 years.		