

SVAHCS UST ACTIVE Inventory/Regulatory Requirements

WDEQ	Local Description	Tank Capacity (Gal)	Material	Product	Tank Leak Detection	Line Leak Detection	Install Date	Status
9	Building 64	500	Steel	Diesel	Interstitial	Suction-N/A		
12	Building 71S	2500	Steel	Diesel	Interstitial	Suction-N/A		
13	Building 42	1000	Steel/Fiberglass Clad	Diesel	Interstitial	Interstitial/MLLD		
14	Building 42	2500	Steel/Fiberglass Clad	Unleaded	Interstitial	Interstitial/MLLD		
15	Building 86	1000	Steel	Diesel	Interstitial	Suction-N/A		
16	Building 71N	1500	Steel/Fiberglass Clad	Diesel	Interstitial	Suction-N/A	10/1/2009	
17	Building 7	5000	Fiberglass	Diesel	Interstitial	Suction-N/A	5/15/2014	
18	Building 42	5000	Fiberglass	E-85/Unleaded	Interstitial	Interstitial/MLLD	1/5/2016	
19	Building 90	2500	Fiberglass	Diesel	Interstitial	Suction-N/A	4/2/2014	Replaced #10