

Replace Nurses Stations in Building 217

Images of project area of work, (Flooring, Electrical and partial desk images.)



Existing Flooring

Existing Nurse Millwork Stations – For Demolition



Existing Nurse Millwork Stations – For Demolition



Existing furniture on Back wall of station. (This is to remain)

Image shows location of power coming from ceiling above....and down through wall to floor and to electrical stubs in floor at stations.



Hines In-house electricians have noted location of electrical in ceiling above project area.

Partially assembled new modular nurse stations – Bldg 9



Existing electrical/Data/Phone – in existing millwork knee wall



Image shows electrical feeds and conduit running in millwork wood curb along floor.



Curb in Knee wall
of millwork.