

Client Name: HDH Technical, Inc.

PLM Bulk Asbestos Report

VAMC - Boiler #3 Burner Repl.; Clarksburg, WV

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
BM-3.2	112081104-06	No	NAD
Location: Baseboard Mastic			(by CVES) by William M. Dunstan on 08/02/12
Analyst Description: Cream, Heterogeneous, Non-Fibrous, Bulk Material			
Asbestos Types:			
Other Material: Non-fibrous 100 %			
WG-4.1	112081104-07	Yes	5 %
Location: Window Glazing - Doors			(by CVES) by William M. Dunstan on 08/02/12
Analyst Description: Black, Heterogeneous, Non-Fibrous, Bulk Material			
Asbestos Types: Chrysotile 5.0 %			
Other Material: Non-fibrous 95 %			
WG-4.2	112081104-08	Yes	5 %
Location: Window Glazing - Doors			(by CVES) by William M. Dunstan on 08/02/12
Analyst Description: Black, Heterogeneous, Non-Fibrous, Bulk Material			
Asbestos Types: Chrysotile 5.0 %			
Other Material: Non-fibrous 95 %			
TI-5.1	112081104-09	No	NAD
Location: Tank Insulation - Cond. Storage			(by CVES) by William M. Dunstan on 08/02/12
Analyst Description: Lt. Gray, Heterogeneous, Fibrous, Bulk Material			
Asbestos Types:			
Other Material: Fibrous glass 40 %, Non-fibrous 60 %			
TI-5.2	112081104-10	No	NAD
Location: Tank Insulation - Cond. Storage Old			(by CVES) by William M. Dunstan on 08/02/12
Analyst Description: Lt. Gray, Heterogeneous, Fibrous, Bulk Material			
Asbestos Types:			
Other Material: Fibrous glass 40 %, Non-fibrous 60 %			
TI-6.1	112081104-11	No	NAD
Location: Tank Insulation - DA Tank			(by CVES) by William M. Dunstan on 08/02/12
Analyst Description: Lt. Gray, Heterogeneous, Fibrous, Bulk Material			
Asbestos Types:			
Other Material: Fibrous glass 40 %, Non-fibrous 60 %			