

Server # 1 Exterior PTZ Standard Resolution

Building #	Floor #	Camera #	Name	PTZ/Fixed	Model #
7	1st	13	PL-6 East Side Bldg 7	PTZ	Axis 233
18	1st	11	PL-17 E. Bldg. 18	PTZ	Axis 233
18	1st	12	Bldg 18 West Side	PTZ	Axis 233
20	1st	7	Engr. W. Bldg. 20	PTZ	Axis 233
21	1st	8	Engr. N. Bldg 21	PTZ	Axis 233
24	1st	2	PL-13 SW Bldg 24	PTZ	Axis 233
26	1st	1	PL-9 North Bldg 26	PTZ	Axis 233
28	1st	5	PL-6 S. Bldg 28	PTZ	Axis 233
28	1st	6	PL-2 N. Bldg 28	PTZ	Axis 233
30	1st	4	PL-15 & 16 SE Bldg 30	PTZ	Axis 233
31	1st	3	PL-1 East Bldg 31	PTZ	Axis 233
212	1st	9	PL-4 S. Bldg 212	PTZ	Axis 233
212	1st	10	Bldg 212 East Side	PTZ	Axis 233

Server # 1 Interior PTZ Standard Resolution

Building #	Floor #	Camera #	Name	PTZ/Fixed	Model #
18	1st	115	Bldg 18 Lobby	PTZ	Axis 231
24	Basement	16	Bldg 24 Near SPD	PTZ	Axis 231
26	Basement	15	Bldg 26 Basement P-1 Elevator	PTZ	Axis 231
27	Basement	14	Bldg 27 Basement P-2 Elevator	PTZ	Axis 231
28	Basement	24	Retail Store At Entrance	PTZ	Axis 231
28	Basement	25	Retail Store North East Side	PTZ	Axis 231
28	Basement	26	Retail Store SE Side	PTZ	Axis 231
28	Basement	27	Retail Store SW Side	PTZ	Axis 231
30	Basement	21	Bldg 30 Basement P-1 Elevator	PTZ	Axis 231
31	Basement	17	Bldg 31 Basement P-1 Elevator	PTZ	Axis 231
31	Basement	18	Admissions-Nursing	PTZ	Axis 231
31	Basement	19	AOD Admissions	PTZ	Axis 231
31	1st	20	Blue/Green and Red Gold Teams	PTZ	Axis 231
211	Basement	22	Bldg 211 Basement P-1 Elevator	PTZ	Axis 231

removed for repair 10/-/11

Server # 2 Exterior Fixed MegaPixel Cameras

Building #	Floor #	Camera #	Name	PTZ/Fixed	Model #
1	1st	90	Bldg 1 East Side	Fixed	Axis 223M
1	1st	91	Bldg 1 East Side	Fixed	Axis 223M
1	1st	92	Bldg 1 East Side	Fixed	Axis 223M
1	1st	93	Bldg 1 West Side	Fixed	Axis 223M
1	1st	94	Bldg 1 West Side	Fixed	Axis 223M
1	1st	95	Bldg 1 West Side facing bldg 5	Fixed	Axis 223M
7	1st	96	Bldg 7 West side back	Fixed	Axis 223M
18	1st	28	Bldg 18 West Side	Fixed	Axis 223M
18	1st	97	Bldg 18 E. Side back.	Fixed	Axis 223M

not working 2/2/12

rebooted cameras now working

18	1st	98	Bldg 18 E. Side back.	Fixed	Axis 223M
36	1st	100	Bldg 36 SE Corner	Fixed	Axis 223M
24	1st	111	NE Wing	Fixed	Axis 223M
27	1st	112	Bldg 27 Inner Circle	Fixed	Axis 223M
30	1st	113	SW Wing	Fixed	Axis 223M
31	1st	102	Bldg 31, Pharmacy South Side	Fixed	Axis 223M
31	1st	103	Bldg 31, Pharmacy North Side	Fixed	Axis 223M
259	1st	101	Bldg 259 Boiler Plant South Side	Fixed	Axis 223M
211	1st	23	Bldg 211 inner circle	Fixed	Axis 223M
26	1st	30	Bldg 26 Courtyard	Fixed	Axis 223M
26			Bldg 26	Fixed	q1755
26			Bldg 26	Fixed	q1755
26			bldg 26	Fixed	q1755
24	1st	114	Bldg 24 Inner circle	Fixed	Axis 223M

rebooted cameras now working

not working 2/2/12

rebooted cameras now working

not working 2/2/12

Building #	Floor #	Camera #	Name	PTZ/Fixed	Model #
1	Basement	72	Bldg 1 Basement A	Fixed	Axis 216MFD
1	Basement	75	Bldg 1 Basement B	Fixed	Axis 216MFD
18	Basement	36	Bldg 18 Basement Entrance	Fixed	Axis 216MFD
18	Basement	37	Arms Room	Fixed	Axis 216MFD
18	2nd	38	Bldg 18 2nd Fl. Hallway	Fixed	Axis 216MFD
18	Basement	39	Bldg 18 Telephone Switch Room	Fixed	Axis 216MFD
24	1st	52	Bldg 24 A/B 1	Fixed	Axis 216MFD
24	1st	53	Bldg 24 A/B 2	Fixed	Axis 216MFD
24	1st	54	Bldg 24 A/B 3	Fixed	Axis 216MFD
24	1st	55	Bldg 24 A/B 4	Fixed	Axis 216MFD
24	1st	56	Bldg 24 A/B 5	Fixed	Axis 216MFD
24	1st	57	Bldg 24 A/B 6	Fixed	Axis 216MFD
24	2nd	58	Bldg 24 C/D 1	Fixed	Axis 216MFD
24	2nd	59	Bldg 24 C/D 2	Fixed	Axis 216MFD
24	2nd	60	Bldg 24 C/D 3	Fixed	Axis 216MFD
24	2nd	61	Bldg 24 C/D 4	Fixed	Axis 216MFD
24	2nd	62	Bldg 24 C/D 5	Fixed	Axis 216MFD
24	2nd	63	Bldg 24 C/D 6	Fixed	Axis 216MFD
26	1st	40	Bldg 26 A/B 1	Fixed	Axis 216MFD
26	1st	41	Bldg 26 A/B 2	Fixed	Axis 216MFD
26	1st	42	Bldg 26 A/B 3	Fixed	Axis 216MFD
26	1st	43	Bldg 26 A/B 4	Fixed	Axis 216MFD
26	1st	44	Bldg 26 A/B 5	Fixed	Axis 216MFD
26	1st	45	Bldg 26 A/B 6	Fixed	Axis 216MFD
26	2nd	46	Bldg 26 C/D 1	Fixed	Axis 216MFD
26	2nd	47	Bldg 26 C/D 2	Fixed	Axis 216MFD
26	2nd	48	Bldg 26 C/D 3	Fixed	Axis 216MFD
26	2nd	49	Bldg 26 C/D 4	Fixed	Axis 216MFD
26	2nd	50	Bldg 26 C/D 5	Fixed	Axis 216MFD
26	2nd	51	Bldg 26 C/D 6	Fixed	Axis 216MFD
26	1st		bldg 26 1st fir elev lobby		
26	1st		bldg 26 1st fir nw hallway		
26	1st		bldg 26 1st fir rm 152 treatment		
26	1st		bldg 26 1st fir tv room		
26	1st		bldg 26 1st fir rm 151 treatment		
26	1st		bldg 26 1st fir breakroom hall		
26	1st		bldg 26 1st fir north main hall		
26	1st		bldg 26 dining rm south		
26	1st		bldg 26 1st fir entry exit		
26	1st		bldg 26 dining rm north		
26	1st		bldg 26 1st fir south hallway		
26	1st		Bldg 26 1st fir hallway sw		
26	1st		Bldg 26 1st fir hallway SE		
26	1st		bldg 26 courtyard		
27	Basement	29	Bldg 27 Vending Area	Fixed	Axis 216MFD
28	Basement	32	Bldg 28 Bsmnt Hall	Fixed	Axis 216MFD
28	Basement	33	Bldg 28 Stockroom	Fixed	Axis 216MFD

removed for construction 2011

connection in and out

connection in and out

connection in and out  
connection in and out  
not working 2/2/12

connection in and out  
removed for repair

connection in and out  
connection in and out

needs cleaned

DLK #  
4541962011c15287  
9e7fafb25b48bbba  
592c5ee9c27e2626

30	2nd	64	Bldg 30 A/B 1	Fixed	Axis 216MFD
----	-----	----	---------------	-------	-------------

30	2nd	65	Bldg 30 A/B 2	Fixed	Axis 216MFD	
30	2nd	66	Bldg 30 A/B 3	Fixed	Axis 216MFD	
30	2nd	67	Bldg 30 A/B 4	Fixed	Axis 216MFD	
30	2nd	68	Bldg 30 A/B 5	Fixed	Axis 216MFD	
30	2nd	69	Bldg 30 A/B 6	Fixed	Axis 216MFD	
30	1st	70	Bldg 30 ICU 1	Fixed	Axis 216MFD	
30	1st	71	Bldg 30 ICU 2	Fixed	Axis 216MFD	
31	Basement	34	Bldg 31 Agent Cashier/PT Funds	Fixed	Axis 216MFD	removed for repair
31	Sub-Basement	35	Bldg 31 Sub-Basement (Audiology)	Fixed	Axis 216MFD	
31	1st	104	Bldg 31, West Side	Fixed	Axis 216MFD-V	
31	2nd	105	Bldg 31, Pharmacy by Elevator	Fixed	Axis 216MFD	
31	2nd	106	Bldg 31, Pharmacy Entrance	Fixed	Axis 216MFD	
31	2nd	107	Bldg 31, Dental Entrance	Fixed	Axis 216MFD	
31	2nd	108	Bldg 31, Pharmacy Vault A	Fixed	Axis 216MFD	connection in and out
31	2nd	109	Bldg 31, Pharmacy Vault B	Fixed	Axis 216MFD	
35	Basement	31	Bldg 31 Basement Entrance	Fixed	Axis 216MFD	
35	Basement	73	Bldg 35 N Hall Basement	Fixed	Axis 216MFD	
35	Basement	74	Bldg 35 Basement Vending	Fixed	Axis 216MFD	
211	1st	78	Bldg 211 A/B 1	Fixed	Axis 216MFD	removed for construction 2/3/12
211	1st	79	Bldg 211 A/B 2	Fixed	Axis 216MFD	removed for construction 2/3/12
211	1st	80	Bldg 211 A/B 3	Fixed	Axis 216MFD	removed for construction 2/3/12
211	1st	81	Bldg 211 A/B 4	Fixed	Axis 216MFD	removed for construction 2/3/12
211	1st	82	Bldg 211 A/B 5	Fixed	Axis 216MFD	removed for construction 2/3/12
211	1st	83	Bldg 211 A/B 6	Fixed	Axis 216MFD	removed for construction 2/3/12
211	2nd	84	Bldg 211 C/D 1	Fixed	Axis 216MFD	removed for construction 2/3/12
211	2nd	85	Bldg 211 C/D 2	Fixed	Axis 216MFD	removed for construction 2/3/12
211	2nd	86	Bldg 211 C/D 3	Fixed	Axis 216MFD	removed for construction 2/3/12
211	2nd	87	Bldg 211 C/D 4	Fixed	Axis 216MFD	removed for construction 2/3/12
211	2nd	88	Bldg 211 C/D 5	Fixed	Axis 216MFD	removed for construction 2/3/12
211	2nd	89	Bldg 211 C/D 6	Fixed	Axis 216MFD	removed for construction 2/3/12
212	Basement	99	Bldg 212 Basement Hallway 1	Fixed	Axis 216MFD	
212	Basement	110	Bldg 212 Basement Hallway 2	Fixed	Axis 216MFD	